




**LAPORAN
KUNJUNGAN -
Pakuwon Mall
Yogyakarta
PT. CAREFASTINDO**

Terimakasih sudah bertemu dengan tim kami, **Ifan Soehendra**, pada tanggal: **Selasa, 25 November 2025**.

Sub Kategori	Aktifitas	Keterangan	File
MESIN	ASSET CHECKING	perbaikan mesin vacum	 A technician in a blue shirt is working on a green and silver vacuum machine. The timestamp 14:51:25 25-Nov-2025 is visible in the bottom right corner of the photo.
MESIN	ASSET CHECKING	perbaikan mesin scruber	 A technician in a blue shirt is working on a white and silver scrubber machine. The timestamp 15:51:17 25-Nov-2025 is visible in the bottom right corner of the photo.
INSPEKSI	INSPEKSI AREA	inspeksi kebersihan area loading	 A wide-angle shot of a loading dock area with a concrete floor, metal pillars, and orange traffic cones. The timestamp 17:11:06 25-Nov-2025 is visible in the bottom right corner of the photo.
INSPEKSI	INSPEKSI AREA	inspeksi kebersihan area toilet	 A view of a clean, modern toilet area with white tiles, a urinal, and a mirror. The timestamp 17:13:34 25-Nov-2025 is visible in the bottom right corner of the photo.

SUPERVISI	COACHING TEAM AREA	coaching personil terkait detail dusting wastafel nursery room	
-----------	-----------------------	--	---

Diharapkan dengan adanya laporan ini menjadi bahan referensi bagi pihak-pihak terkait untuk memahami isi dan hasil pertemuan.



Powered and Approved by:
Carefast One – Level up people
PT. CAREFASTINDO