

**LAPORAN
KUNJUNGAN -
PASAR ATOM
SURABAYA
PT. CAREFASTINDO**

Terimakasih sudah bertemu dengan tim kami, **Slamet Arianto**, pada tanggal: **Jumat, 10 Oktober 2025**.

Sub Kategori	Aktifitas	Keterangan	File
INSPEKSI	INSPEKSI AREA	cek kebersihan gutter area luar	 A photograph showing a close-up of a metal gutter on the exterior of a building. The gutter appears to be clean and free of debris. A timestamp '12:44:48 10-Okt-2025' is visible in the bottom right corner of the image.
INSPEKSI	INSPEKSI AREA	cek kebersihan grill ac	 A photograph showing a close-up of an air conditioning (AC) grill on a wall. The grill is clean and free of dust. A timestamp '12:46:01 10-Okt-2025' is visible in the bottom right corner of the image.
INSPEKSI	INSPEKSI AREA	cek koridor lantai 1	 A photograph showing a long, brightly lit corridor on the first floor. The floor is polished and reflects the overhead lights. A timestamp '12:46:30 10-Okt-2025' is visible in the bottom right corner of the image.
INSPEKSI	INSPEKSI AREA	cek kebersihan pintu masuk utara	 A photograph showing a glass entrance door with a green frame. The door is clean and free of dirt. A timestamp '12:47:34 10-Okt-2025' is visible in the bottom right corner of the image.

Diharapkan dengan adanya laporan ini menjadi bahan referensi bagi pihak-pihak terkait untuk memahami isi dan hasil pertemuan.



Powered and Approved by:
Carefast One – Level up people
PT. CAREFASTINDO