

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket									
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A								
KORIDOR LG MALL																																																
1	STAINLESS LOBBY LG ENTRANCE	POLISHING	0	4	0	0							P	A						P	X						P	X											4	1	Oke							
2	KACA LOBBY LG ENTRANCE	GLASS CLEANING	0	4	0	0								P							P							P												4	0	Oke						
3	KACA LOBBY CONECTING	GLASS CLEANING	0	5	0	0			P							P						P								P	A										5	1	Oke					
4	KACA LOBBY TAXI LOUNGE	GLASS CLEANING	0	4	0	0				P	A						P	X						P	X						P	A											4	2	Oke			
5	AC GRILL DIFFUSER, EXHAUSE FAN TAXI LONGE	DUSTING	0	4	0	0											P	X							P	X					P	X											4	0	Oke			
6	DINDING DAN ACCESORIES TAXI LOUNGE	DUSTING	0	4	0	0												P	X							P	X					P	X										4	0	Oke			
7	CEILLING AC GRILL DAN SHOPRONT	GENERAL CLEANING	0	2	0	0												P	X												P	X											2	0	Oke			
8	DAK CEILLING DAK PARAVED	DUSTING	0	4	0	0												P	X										P														4	0	Oke			
9	DINDING BODY LUAR ESCALATOR	DUSTING	0	4	0	0														P	A																							4	1	Oke		
10	HAND RAILLING ESCALATOR	POLISHING	0	4	0	0					P	A																																	4	1	Oke	
11	KACA RAILLING BAG. LUAR	WALL DUSTER	0	4	0	0				P																																			4	0	Oke	
12	PILAR BETON	SPOTING	0	5	0	0			P																																					5	0	Oke
13	DINDING LORONG KORIDOR EXIT	WALL DUSTER	0	4	0	0																																								4	0	Oke
14	RAILLING VOID KACA STAINLESS DAK	GLASS CLEANING	0	4	0	0																																								4	0	Oke
15	DINDING MARMER DEPAN LIFT PANORAMA	WALL CLEANING	0	5	0	0			P																																					5	0	Oke
16	DUSTBIN	POLISHING	0	5	0	0			P																																					5	1	Oke
17	SHOFTRONT COUNTER	DUSTING	0	4	0	0				P	X																																			4	0	Oke
18	HANGING SIGN	DUSTING	0	4	0	0					P																																			4	1	Oke
19	RELL LIFT	VACUMMING	0	4	0	0																																								4	0	Oke
20	LANTAI DALAM RUANG TUNGGU TAXI LOUNGE	BRUSHING	0	4	0	0																																								4	2	Oke
21	KARPET NOMED LOBBY	SHAMPOING CARPET	0	4	0	0																																								4	1	Oke
22	SELA KACA RAILLING	AIR KOMPRESOR	0	4	0	0																																								4	0	Oke
23	LORONG KORIDOR EXIT	BRUSHING	0	4	0	0																																								4	2	Oke
24	LIST FRAME PINTU EXIT	DUSTING	0	4	0	0																																								4	1	Oke
25	PINTU BESI LORONG LIFT S2 3	SPOTING	0	3	0	0																																								3	0	Oke
26	DOOR LIFT	POLISHING	0	4	0	0																																								4	1	Oke
27	STAINLEES ATM GALERY	POLISHING	0	4	0	0					P	A																																		4	2	Oke
TOILET LGB																																																
1	LANTAI	BRUSHING	0	4	0	0																																								4	0	Oke
2	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN	DUSTING	0	4	0	0																																								4	0	Oke
3	DINDING DAN ACCESORIES	WALL CLEANING	0	4	0	0																																								4	1	Oke
4	PARTISI CUBICLE	GLASS CLEANING	0	3	0	0																																								3	0	Oke

TOILET LGD

[illegible]

Warna	Keterangan
P	: Planning
A	: Actual / Terealisasi
X	: Tidak Terealisasi