

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	JML	Ke	
							MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN			
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A			P
AREA LOBBY																																							
1	KACA AUTOMATIC	GLASS CLEANING	0	3	0	0		P	A													P	A													P	A	3	3
2	PINTU KACA DEPAN	GLASS CLEANING	0	3	0	0		P	A													P	A													P	A	3	3
3	PINTU KACA BELAKANG	GLASS CLEANING	0	3	0	0		P	A													P	A													P	A	3	3
4	STAINLESS BARRY GATE AKSES DEPAN	POLISHING	0	0	1	0			P	A																											1	1	
5	STAINLESS BARRY GATE AKSES BELAKANG	POLISHING	0	0	1	0			P	A																											1	1	
6	STAINLESS BARRY GATE AKSES BASEMENT	POLISHING	0	0	1	0			P	A																											1	1	
7	DINDING MARMER KORIDOR LOBBY LIFT	WALL CLEANING	0	0	1	0				P	A																										1	1	
8	PINTU-PINTU LIFT PASSANGER	WALL CLEANING	0	1	0	0				P	A																										1	1	
9	CERMIN KORIDOR LOBBY LIFT	GLASS CLEANING	0	1	0	0					P	A																									1	1	
10	KUNINGAN FRAME CERMIN KORIDOR LOBBY LIFT	POLISHING	0	0	1	0					P	A																									1	1	
11	MEJA CARCALL	DUSTING	0	2	0	0									P	A													P	A							2	2	
12	LAMPU DINDING KORIDOR LOBBY LIFT	DUSTING	0	2	0	0									P	A													P	A							2	2	
13	MONITOR TV KORIDOR LOBBY LIFT	DUSTING	0	2	0	0									P	A													P	A							2	2	

[illegible]

[illegible]