

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket			
							SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM					
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A		P	A	P
KORIDOR LT2																																										
1	CEILING AC GRILL DAN SHOPRONT	DUSTING	0	3	0	0							P	X	P	X	P	X																				3	0			
2	CEILLING KAYU MOTIF ATRIUM	GENERAL CLEANING	0	3	0	0				P		P	X	P																									3	0		
3	CEILLING KAYU MOTIF DEPAN TIRTALI	GENERAL CLEANING	0	3	0	0			P		P		P	X																									3	0		
4	KACA BAGIAN ATAS LIFT CP3 CP4	DUSTING	0	4	0	0						P	X					P							P	X						P	X						4	0		
5	KACA BALKON MITRA SEHAT	GLASS CLEANING	0	4	0	0							P	X					P	X						P	X						P	X					4	0		
6	LANTAI BALKON MITRA SEHAT	GLASS CLEANING	0	4	0	0								P	X					P	X						P	X						P	X					4	0	
7	HAND RAILLING ESCALATOR	BRUSHING	0	5	0	0	P								P						P							P	X						P	X				5	0	
8	KACA RAILLING BAGIAN LUAR	POLISHING	0	5	0	0			P							P						P							P							P				5	0	
9	DINDING CORRIDOR EXIT	DUSTING	0	5	0	0			P							P						P							P								P				5	0
10	PILAR BETON	WALL CLEANING	0	4	0	0				P								P	X					P							P									4	0	
11	LIST FRAME PINTU EXIT	SPOTING	0	4	0	0					P								P						P							P								4	0	
12	DINDING MARMER DEPAN LIFT PANORAMA	POLISHING	0	4	0	0					P								P						P							P								4	0	
13	KERANGKA GEROBAK TENANT BAGIAN ATAS	DUSTING	0	4	0	0							P							P	X					P	X							P	X					4	0	
14	SUDUT SUDUT LANTAI	SPOTING	0	5	0	0			P							P						P							P								P				5	0
15	LANTAI KULIT JERUK DEPAN MANAGEMENT OFFICE	BRUSHING	0	5	0	0			P	X						P						P							P								P				5	0
16	RELL LIFT	VACUMMING	0	5	0	0			P							P						P							P								P				5	0

17	NOMAD LIFT S6 S7	SHAMPOING CARPET	0	4	0	0								P X																				4	0	
18	SELA KACA RAILLING	AIR KOMPRESOR	0	1	0	0			P																									1	0	
19	HANGING SIGN	DUSTING	0	4	0	0						P																						4	0	
20	KACA RALLING BALKON BAGIAN LUAR	GLASS CLEANING	0	5	0	0			P X					P X																					5	0
21	DINDING WALLPAPER	DUSTING	0	5	0	0			P					P																					5	0
22	DINDING KERAMIK DEPAN LIFT CP3 CP4	WALL CLEANING	0	5	0	0			P X					P X																					5	0
23	CORIDOR RUANG AHU SAMPING LIFT S6 S7	BRUSHING	0	4	0	0								P X																					4	0
24	ALL DOOR LIFT	POLISHING	0	4	0	0								P																					4	0
25	DUSTBIN	WASHING	0	4	0	0								P																					4	0
TOILET LT 2B																																				
1	LANTAI	BRUSHING	0	5	0	0			P																										5	0
2	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN	DUSTING	0	5	0	0			P																										5	0
3	DINDING DAN ACCESORIES	WALL CLEANING	0	4	0	0				P																									4	0
4	PARTISI CUBICLE	GLASS CLEANING	0	4	0	0									P X																				4	0
TOILET LT 2D																																				
1	LANTAI	BRUSHING	0	5	0	0	P X																												5	0
2	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN	DUSTING	0	4	0	0																													4	0
3	DINDING DAN ACCESORIES	WALL CLEANING	0	4	0	0																													4	0
4	PARTISI CUBICLE	GLASS CLEANING	0	4	0	0																													4	0
TOILET LT 2E																																				
1	LANTAI	BRUSHING	0	4	0	0																													4	0
2	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN	DUSTING	0	4	0	0																													4	0
3	DINDING DAN ACCESORIES	WALL CLEANING	0	4	0	0																													4	0

[illegible]