

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket			
							K	M	SB	MG	SN	SL	RB	K	M	SB	MG	SN	SL	RB	K	M	SB	MG	SN	SL	RB	K	M	SB	MG	SN	SL	RB	K	M	SB					
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A		
KORIDOR LT2																																										
1	CEILLING AC GRILL DAN SHOPRONT	DUSTING	0	3	0	0								P	A	P	P																					3	1	Oke		
2	CEILLING KAYU MOTIF ATRIUM	GENERAL CLEANING	0	3	0	0					P	A	P	X	P	X																							3	1	Oke	
3	CEILLING KAYU MOTIF DEPAN TIRTALI	GENERAL CLEANING	0	3	0	0				P	X	P	X	P	X																								3	0	Oke	
4	KACA BAGIAN ATAS LIFT CP3 CP4	DUSTING	0	4	0	0						P						P							P														4	0	Oke	
5	KACA BALKON MITRA SEHAT	GLASS CLEANING	0	4	0	0							P	A					P	A						P													4	2	Oke	
6	LANTAI BALKON MITRA SEHAT	GLASS CLEANING	0	4	0	0								P	X					P	X						P	X											4	0	Oke	
7	HAND RAILLING ESCALATOR	BRUSHING	0	5	0	0	P								P							P						P											5	0	Oke	
8	KACA RAILLING BAGIAN LUAR	POLISHING	0	5	0	0				P	A						P						P						P	A									5	2	Oke	
9	DINDING CORRIDOR EXIT	DUSTING	0	5	0	0				P	A							P						P						P										5	1	Oke
10	PILAR BETON	WALL CLEANING	0	4	0	0					P	A						P							P							P	A							4	2	Oke
11	LIST FRAME PINTU EXIT	SPOTING	0	4	0	0						P							P							P														4	0	Oke
12	DINDING MARMER DEPAN LIFT PANORAMA	POLISHING	0	4	0	0						P							P							P														4	0	Oke
13	KERANGKA GEROBAK TENANT BAGIAN ATAS	DUSTING	0	4	0	0							P	A						P	A						P													4	2	Oke
14	SUDUT SUDUT LANTAI	SPOTING	0	5	0	0					P	A						P											P	A										5	2	Oke
15	LANTAI KULIT JERUK DEPAN MANAGEMENT OFFICE	BRUSHING	0	5	0	0					P	A						P											P	A										5	2	Oke
16	RELL LIFT	VACUMMING	0	5	0	0					P	A						P											P											5	1	Oke
17	NOMAD LIFT S6 S7	SHAMPOING CARPET	0	4	0	0					P	X						P	X							P	X													4	0	Oke
18	SELA KACA RAILLING	AIR KOMPRESOR	0	1	0	0				P	A																												1	1	Oke	
19	HANGING SIGN	DUSTING	0	4	0	0								P	A					P	A						P													4	2	Oke
20	KACA RALLING BALKON BAGIAN LUAR	GLASS CLEANING	0	5	0	0				P	A							P	X										P	X									5	1	Oke	
21	DINDING WALLPAPER	DUSTING	0	5	0	0				P	A							P											P											5	1	Oke
22	DINDING KERAMIK DEPAN LIFT CP3 CP4	WALL CLEANING	0	5	0	0				P	A							P											P											5	1	Oke
23	CORIDOR RUANG AHU SAMPING LIFT S6 S7	BRUSHING	0	4	0	0				P								P	X						P															4	0	Oke
24	ALL DOOR LIFT	POLISHING	0	4	0	0					P								P							P														4	0	Oke
25	DUSTBIN	WASHING	0	4	0	0					P								P							P														4	0	Oke
TOILET LT 2B																																										
1	LANTAI	BRUSHING	0	5	0	0				P	A							P											P	X									5	1	Oke	
2	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN	DUSTING	0	5	0	0				P	A							P											P										5	1	Oke	
3	DINDING DAN ACCESORIES	WALL CLEANING	0	4	0	0					P	A							P																					4	1	Oke
4	PARTISI CUBICLE	GLASS CLEANING	0	4	0	0					P								P																					4	0	Oke

TOILET LT 2D

[illegible]

TOILET LT 2E

[illegible]

Total Rencana :	
-----------------	--

Total Realisasi :	
-------------------	--

Tidak Terealisasi :

Warna	Keterangan
P	: Planning
A	: Actual / Terealisasi
X	: Tidak Terealisasi