

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	JML	Ket	
							SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB			
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A			P
Lift Attendance																																							
1	DINDING DALAM	POLISHING	0	2	0	0			P	A							P	A																		2	2		
2	DINDING LUAR	POLISHING	0	2	0	0			P	A							P	A																		2	2		
3	KAP LAMPU	ROC	0	2	0	0																P	A							P	A					2	2		
Lift High Zone Gedung Utama																																							
1	EXHAUSFAN	ROC	0	2	0	0																P	A							P	A					2	2		
2	REILL LIFT	DRY VACUMING	0	2	0	0																P	A							P	A					2	2		
Lift Gedung Parkir																																							
1	DINDING DALAM	POLISHING	0	2	0	0					P	A						P	A																	2	2		
2	DINDING LUAR	POLISHING	0	2	0	0					P	A						P	A																	2	2		
Total Rencana :							0	0	2	0	2	0	0	0	0	2	0	2	0	0	0	0	3	0	0	0	0	0	0	0	3	0	0	0	0	0	0	14	14 100%
Total Realisasi :							0	0	2	0	2	0	0	0	0	0	2	0	2	0	0	0	0	3	0	0	0	0	0	0	3	0	0	0	0	0	0	0	
Tidak Terealisasi :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Warna	Keterangan																																						
P	: Planning																																						
A	: Actual / Terealisasi																																						
X	: Tidak Terealisasi																																						