


No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
1	CF1/49/HISP/387	HIGH SPEED POLISHER	LG			-	RUSAK
2	CF1/38/AC/3704	AIR CONDITIONER	DENPOO			BAIK	-