


LAPORAN MESIN - Project : ORANGE GROOVES PIK2 (01142901)

PERIODE : 2024-06-01 - 2024-06-30

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
1	CF1 - LOSP-ORANGE-0001	LOW SPEED POLISHER	REDWIND			BAIK	-
2	CF1 - SCRB-ORANGE-0001	AUTOMATIC SCRUBBER	INNOTECH			BAIK	-
3	CF1 - VC60L-ORANGE-0001	WET & DRY VACUUM CLEANER 60 LITER	INNOTECH			BAIK	-
4	CF1 - HPRE-ORANGE-0001	HIGH PRESSURE	KARVA			BAIK	-