

Laporan Bulanan Proyek

Periode : 01 August 2024 - 31 August 2024

Chief Supervisor	Supervisor	Team Leader	Cleaner	Gardener	Gondola	Total
Awal Periode : 1	Awal Periode : 4	Awal Periode : 8	Awal Periode : 237	Awal Periode : 0	Awal Periode : 16	Awal Periode : 266
Masuk : 1	Masuk : 4	Masuk : 8	Masuk : 237	Masuk : 0	Masuk : 16	Masuk : 266
Keluar : 0	Keluar : 0	Keluar : 0	Keluar : 2	Keluar : 0	Keluar : 3	Keluar : 5
Akhir Periode : 1	Akhir Periode : 4	Akhir Periode : 8	Akhir Periode : 235	Akhir Periode : 0	Akhir Periode : 13	Akhir Periode : 261

Permasalahan / Kendala SDM	TEST SDM
----------------------------	----------

Obyek	Permasalahan	Keterangan
SOP	TEST SOP	TEST SOP
Administrasi	TEST ADMIN	TEST ADMIN
Chemical	TEST CHECMICAL	TEST CHEMICAL
Peralatan	TEST PERALATAN	TEST PERALATAN
Mesin	TEST MESIN	
Training	TEST TARAING	
HRD & Payroll	TESTT	
Perbaikan Kualitas Area	TESS	

No.	NUC	Nama Karyawan	Jabatan Terakhir	Tipe Turnover	Tanggal Keluar	Tanggal Masuk	Keterangan
RESIGN							
1	1034721	ASEP HAMBALI	CLEANER	RESIGN	2024-08-01	-	-
2	1022262	MOHAMAD HIDHAR	CS-GONDOLA	RESIGN	2024-08-09	-	-
NEW COMER							
1	1039507	YUSUP	CS-GONDOLA	NEW	-	2024-08-07	-
2	1039506	SULASTRI	CLEANER	NEW	-	2024-08-07	-
MUTASI / TRANSFER							

[illegible]

Rekapitulasi Absensi Karyawan - GANDARIA CITY MALL (071221301)

Periode : 01 August 2024 - 31 August 2024

OPERATOR

Tanggal		Shift Pagi					Shift Siang					Shift Malam					Jadwal Off (MP)	Total Actual (MP)	Total MP (per hari)	KEHADIRAN		HADIR LEMBUR	KETIDAKHADIRAN		Selisih				
		Actual (MP)	H	S	I	A	Lembur	Actual (MP)	H	S	I	A	Lembur	Actual (MP)	H	S				I	A		Lembur	Total	%	Total	%	Total	%
1	Aug-24	51	51	0	0	0	0	45	45	0	0	0	0	10	10	0	0	0	0	18	106	124	106	100%	0	0	0%	0	0%
2	Aug-24	49	48	0	0	1	0	44	43	1	0	0	1	9	9	0	0	0	0	22	102	124	100	98%	1	2	2%	1	1%
3	Aug-24	56	55	0	0	1	0	50	50	0	0	0	0	11	11	0	0	0	0	8	117	125	116	99%	0	1	1%	1	1%
4	Aug-24	49	49	0	0	0	0	49	49	0	0	0	1	8	8	0	0	0	0	18	106	124	106	100%	1	0	0%	-1	-1%
5	Aug-24	51	49	0	0	2	0	46	46	0	0	0	0	8	8	0	0	0	0	20	105	125	103	98%	0	2	2%	2	2%
6	Aug-24	52	50	0	0	2	0	45	45	0	0	0	0	10	10	0	0	0	0	18	107	125	105	98%	0	2	2%	2	2%
7	Aug-24	52	51	0	0	1	0	43	43	0	0	0	0	11	10	0	0	1	0	20	106	126	104	98%	0	2	2%	2	2%
8	Aug-24	50	50	0	0	0	0	44	43	1	0	0	1	11	10	0	0	1	0	20	105	125	103	98%	1	2	2%	1	1%
9	Aug-24	50	50	0	0	0	0	44	42	2	0	0	2	10	9	0	0	1	0	22	104	126	101	97%	2	3	3%	1	1%
10	Aug-24	55	54	0	0	1	0	50	50	0	0	0	0	11	11	0	0	0	0	10	116	126	115	99%	0	1	1%	1	1%
11	Aug-24	51	50	0	0	1	0	51	50	0	0	1	1	9	8	0	0	1	0	15	111	126	108	97%	1	3	3%	2	2%
12	Aug-24	52	52	0	0	0	0	45	45	0	0	0	0	9	8	0	0	1	0	20	106	126	105	99%	0	1	1%	1	1%
13	Aug-24	52	52	0	0	0	0	45	45	0	0	0	0	11	10	0	0	1	0	18	108	126	107	99%	0	1	1%	1	1%
14	Aug-24	52	50	0	0	2	0	43	43	0	0	0	0	11	10	0	0	1	0	20	106	126	103	97%	0	3	3%	3	3%
15	Aug-24	51	49	0	0	2	1	44	44	0	0	0	0	11	10	0	0	1	0	20	106	126	103	97%	1	3	3%	2	2%
16	Aug-24	50	50	0	0	0	0	44	44	0	0	0	0	10	9	0	0	1	0	22	104	126	103	99%	0	1	1%	1	1%
17	Aug-24	54	54	0	0	0	0	50	50	0	0	0	0	12	11	0	0	1	0	10	116	126	115	99%	0	1	1%	1	1%
18	Aug-24	51	51	0	0	0	0	51	51	0	0	0	0	9	8	0	0	1	0	15	111	126	110	99%	0	1	1%	1	1%

19	Aug-24	52	51	0	0	1	0	46	46	0	0	0	0	8	8	0	0	0	0	20	106	126	105	99%	0	1	1%	1	1%
20	Aug-24	51	51	0	0	0	0	46	45	1	0	0	1	11	10	0	0	1	0	18	108	126	106	98%	1	2	2%	1	1%
21	Aug-24	52	51	0	0	1	0	43	42	1	0	0	1	11	10	0	0	1	0	20	106	126	103	97%	1	3	3%	2	2%
22	Aug-24	51	50	0	0	1	0	44	44	0	0	0	0	11	9	1	0	1	1	20	106	126	103	97%	1	3	3%	2	2%
23	Aug-24	51	49	0	0	2	0	44	44	0	0	0	1	9	9	0	0	0	0	22	104	126	102	98%	1	2	2%	1	1%
24	Aug-24	54	53	0	0	1	1	50	50	0	0	0	0	12	11	0	0	1	0	10	116	126	114	98%	1	2	2%	1	1%
25	Aug-24	51	50	0	0	1	1	51	51	0	0	0	0	9	8	0	0	1	0	15	111	126	109	98%	1	2	2%	1	1%
26	Aug-24	52	51	0	0	1	0	46	46	0	0	0	0	8	8	0	0	0	0	20	106	126	105	99%	0	1	1%	1	1%
27	Aug-24	53	52	0	0	1	0	45	45	0	0	0	0	10	10	0	0	0	0	18	108	126	107	99%	0	1	1%	1	1%
28	Aug-24	52	51	0	0	1	0	43	43	0	0	0	0	11	10	0	0	1	0	20	106	126	104	98%	0	2	2%	2	2%
29	Aug-24	51	49	1	0	1	1	43	43	0	0	0	0	11	10	0	0	1	0	20	105	125	102	97%	1	3	3%	2	2%
30	Aug-24	51	49	0	1	1	0	44	44	0	0	0	0	9	9	0	0	0	1	22	104	126	102	98%	1	2	2%	1	1%
31	Aug-24	54	52	0	0	2	0	50	50	0	0	0	0	12	11	0	0	1	0	10	116	126	113	97%	0	3	3%	3	3%

[illegible]

Warna	Keterangan
A	: Actual / Terealisasi
X	: Tidak Terealisasi

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket			
							KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB					
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P			A	P	A
Total Rencana :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total Realisasi :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Tidak Terealisasi :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Warna												Keterangan																														
P												: Planning																														
A												: Actual / Terealisasi																														
X												: Tidak Terealisasi																														

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket			
							KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB					
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P			A	P	A
Total Rencana :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total Realisasi :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Tidak Terealisasi :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Warna												Keterangan																														
P												: Planning																														
A												: Actual / Terealisasi																														
X												: Tidak Terealisasi																														

TOILET LT 2D

TOILET LT 2E

Total Rencana :	
-----------------	--

Total Realisasi :	
-------------------	--

Tidak Terealisasi :

Warna	Keterangan
P	: Planning
A	: Actual / Terealisasi
X	: Tidak Terealisasi

TOILET LGD	
------------	--

[illegible]

Warna	Keterangan
P	: Planning
A	: Actual / Terealisasi
X	: Tidak Terealisasi

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket			
							KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB					
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P			A	P	A
Total Rencana :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total Realisasi :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Tidak Terealisasi :							0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Warna												Keterangan																														
P												: Planning																														
A												: Actual / Terealisasi																														
X												: Tidak Terealisasi																														

[illegible]

[illegible]

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket					
							K	M	S	B	M	G	S	N	S	L	R	B	K	M	S	B	M	G	S	N	S	L	R	B	K	M	S	B	M	G	S			N	S	L	R	B
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A
KORIDOR UG																																												
1	CEILLING,AC GRILL DAN SHOPRONT	GENERAL CLEANING	0	3	0	0																										P	X	P	X	P	X					3	0	Oke
2	KORIDOR STORAGE/GUDANG BELAKANG ZONA A	BRUSHING	0	4	0	0					P							P								P	X						P									4	0	Oke
3	PILAR & DINDING ALUCUBONE LOBBY NORTH MAINSTREET	WALL CLEANING	0	4	0	0						P	X						P	X						P	X							P	X							4	0	Oke
4	KACA BALOSTREET (KACA RAILLING)	DUSTING	0	4	0	0							P	X						P								P	X						P	X						4	0	Oke
5	CELLING KAYU MOTIF ATRIUM	GENERAL CLEANING	0	4	0	0																		P	X	P		P		P	X											4	0	Oke
6	KAP LAMPU,SMOKE DETEKTOR,SPRINGKLER	DUSTING	0	4	0	0													P	X									P	X	P	X	P	X	P	X					4	0	Oke	
7	KACA BAGIAN ATAS LIFT CP 3-4	GLASS CLEANING	0	2	0	0													P	X												P	X							2	0	Oke		
8	HAND RAILLING ESCALATOR	POLISHING	0	5	0	0		P								P	X						P						P									P	X			5	0	Oke
9	DINDING CORRIDOR EXIT	WALL CLEANING	0	5	0	0		P							P	X					P	X							P							P					5	0	Oke	
10	LIST FRAME & DOOR CLOSER PINTU EXIT / AHU	DUSTING	0	5	0	0		P								P	X						P	X					P	X						P					5	0	Oke	
11	PILAR MOTIF ZONA UTARA	SPOTING	0	5	0	0			P	A							P							P	X						P							P			5	1	Oke	
12	CINCIN PILAR	POLISHING	0	4	0	0				P	A							P							P							P	A							4	2	Oke		
13	RAILLING VOID(KACA, STAINLESS ,DAK)	GLASS CLEANING	0	4	0	0					P	X							P	X						P	X						P	X							4	0	Oke	
14	DUSTBIN	POLISHING	0	4	0	0						P	A							P							P							P							4	1	Oke	
15	DINDING MARMER DEPAN LIFT PANORAMA	WALL CLEANING	0	4	0	0						P	X							P	X							P							P						4	0	Oke	
16	PLUMBING HITAM LIFT MF 1-2	DUSTING	0	4	0</																																							

[illegible]

TOILET UGC

[illegible]

Total Rencana :

Total Realisasi :

Tidak Terealisasi :

Warna	Keterangan
P	: Planning
A	: Actual / Terealisasi
X	: Tidak Terealisasi

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket	
							KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB	MG	SN	SL	RB	KM	JM	SB			
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P			A
STAIRCASE MALL																																								
1	NO 1 LT 3 - B2 (SAMPING JOE&DOGH)	GENERAL CLEANING	0	1	0	0	P	X																													1	0	Oke	
2	NO 2 LT 2 - B2 (SAMPING STARBUCK)	GENERAL CLEANING	0	1	0	0		P	X																													1	0	Oke
3	NO 3 LT 3 - LG (AREA LOBBY EAST)	GENERAL CLEANING	0	1	0	0			P	X																												1	0	Oke
4	NO 4 GF - B2 (SAMPING PINTU KARYAWAN LOTTE)	GENERAL CLEANING	0	1	0	0				P	X																											1	0	Oke
5	NO 5 LT 3 - B 2 (AREA LUAR SAMPING HOSHINO COFFE)	GENERAL CLEANING	0	1	0	0					P	X																										1	0	Oke
6	NO 6 LT 3 - GF (SAMPING LIFT CP3 CP4)	GENERAL CLEANING	0	1	0	0						P	X																									1	0	Oke
7	NO 7 LT 2 - B 2 (AREA LUAR TENANT RR CHOCOLATE)	GENERAL CLEANING	0	1	0	0							P	X																								1	0	Oke
8	NO 8 GF - B 2 (AREA LUAR BACILICO)	GENERAL CLEANING	0	1	0	0								P	X																							1	0	Oke
9	NO 9 LT 3 - B 2 (SAMPING OPTIK MELAWAI)	GENERAL CLEANING	0	1	0	0									P	X																						1	0	Oke
10	NO 10 LT 3 - B 2 (SAMPING TOILET D)	GENERAL CLEANING	0	1	0	0										P	X																					1	0	Oke
11	NO 11 LT 3 - B 2 (SAMPING S6 - S7)	GENERAL CLEANING	0	1	0	0											P	X																				1	0	Oke
12	NO 12 LT 3 - GF (SAMPING CONSIERGE SORTH)	GENERAL CLEANING	0	1	0	0												P	X																			1	0	Oke
13	NO 14 .LT 3 - B 2 (SAMPING LIFT S4 S5)	GENERAL CLEANING	0	1	0	0													P	X																		1	0	Oke
14	NO 15 LT 2 - LG (SAMPING TOILET B)	GENERAL CLEANING	0	1	0	0														P	X																	1	0	Oke
15	NO 16 LT 2 - LG (SAMPING MANGO))	GENERAL CLEANING	0	1	0	0															P	X																1	0	Oke
16	NO 17 GF - B 2 (DALAM AREA BASS ROOM)	GENERAL CLEANING	0	1	0	0																P	X															1	0	Oke
17	EXIT PARKIR LG TIMUR S/D B2	GENERAL CLEANING	0	1	0	0																																		

[illegible]

No	Area	Pekerjaan	D	W	M	Y	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	JML	Ket							
							P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A	P	A						
EXTERNAL PLANTERBOX																																														
1	NORTH SD FCC	WASHING	0	3	0	0	P	X														P	X												P	X	3	0	Oke							
2	DEPAN LOBBY WEST SD FLOW GENSET	WASHING	0	3	0	0		P	X														P	X											P	X	3	0	Oke							
3	DEPAN LOBBY SOUTH SD FLOW GENSET	WASHING	0	3	0	0			P	X														P	X											P	X	3	0	Oke						
4	CAR CHECK NORTH SD LOGO GANCI	WASHING	0	2	0	0				P	X														P	X													2	0	Oke					
5	BELAKANG MADURA SD CAR CHECK WEST	WASHING	0	2	0	0					P	X														P	X													2	0	Oke				
6	PINTU MASUK PREMIUM SD PIAZZA	WASHING	0	2	0	0						P	X														P	X												2	0	Oke				
DINDING RAMP																																														
1	DINDING RAM MASUK NORTH	SPOTING	0	0	4	0						P	X							P	X					P	X													4	0	Oke				
2	DINDING RAM KELUAR NORTH	SPOTING	0	0	4	0							P	X						P	X						P	X						P							4	0	Oke			
3	DINDING RAM MASUK WEST	SPOTING	0	0	4	0								P	X						P	X						P	X						P	X						4	0	Oke		
4	DINDING RAM KELUAR WEST	SPOTING	0	0	5	0	P								P							P	X					P	X						P	X						5	0	Oke		
5	DINDING RAM TUNEL LOTTE	SPOTING	0	0	5	0		P	X							P	X						P	X					P	X							P	X					5	0	Oke	
6	DINDING RAM KELUAR TRUCK WAY	SPOTING	0	0	5	0			P	X							P	X						P	X						P	X							P	X	5	0	Oke			
AREA LAINNYA																																														
1	KACA RAILLING CAR CHECK NORTH	GLASS CLEANING	0	4	0	0						P	X							P	X					P	X															4	0	Oke		
2	KACA RAILLING RAM KELUAR MASUK NORTH	GLASS CLEANING	0	4	0	0							P	A						P							P	X						P								4	1	Oke		
3	TANGGA PEJALAN KAKI WEST	BRUSHING	0	4	0	0								P	A						P							P							P								4	1	Oke	
4	RAMBU JALAN	DUSTING	0	5	0	0	P								P	X						P	X					P	X							P								5	0	Oke
5	TOILET EXIT 17	GENERAL CLEANING	0	5	0	0		P								P							P	X					P								P							5	0	Oke
6	TOILET PREMIUM	DUSTING	0	5	0	0			P	X							P	X						P	X						P													5	0	Oke
7	TOILET DAMKAR	WASHING	0	4	0	0				P	A						P	X						P	X						P	A												4	2	Oke
8	LAMPU TAMAN	WASHING	0	4	0	0					P	X						P	X						P	X						P	X											4	0	Oke
Total Rencana :							3	3	3	2	4	3	2	2	2	2	1	3	2	2	3	3	3	2	4	3	2	2	2	2	2	1	3	2	2	3	3	3								
Total Realisasi :							0	0	0	1	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	77	4	5%			
Tidak Terealisasi :							1	2	3	1	4	2	1	1	1	2	1	3	1	1	3	3	3	2	4	3	1	2	1	1	0	3	0	1	2	2	3									
Warna		Keterangan																																												
P		: Planning																																												
A		: Actual / Terealisasi																																												
X		: Tidak Terealisasi																																												

[illegible]

[illegible]

AREA ESKALATOR


[illegible]




[illegible]


AREA BATU PALIMANAN

[illegible]



LANTAI VINYL

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	03-08-2024	LG MALL	GLASS CLEANING	KACA LOBBY TAXI LOUNGE	 10:36:10 03-Agu-2024	 10:37:48 03-Agu-2024	 10:46:56 03-Agu-2024
2	03-08-2024	LG MALL	POLISHING	STAINLEES ATM GALERY	 08:05:50 03-Agu-2024	 08:06:58 03-Agu-2024	 08:10:41 03-Agu-2024
3	03-08-2024	MSCP	BRUSHING	TANGGA MANUAL	 14:13:08 03-Agu-2024	 14:20:11 03-Agu-2024	 14:26:56 03-Agu-2024
4	03-08-2024	LANTAI 2 MALL	POLISHING	KACA RAILLING BAGIAN LUAR	 11:00:56 03-Agu-2024	 11:01:40 03-Agu-2024	 11:01:57 03-Agu-2024
5	03-08-2024	LANTAI 2 MALL	DUSTING	DINDING CORRIDOR EXIT	 07:51:40 03-Agu-2024	 08:24:31 03-Agu-2024	 08:24:53 03-Agu-2024
6	03-08-2024	LANTAI 2 MALL	SPOTING	SUDUT SUDUT LANTAI	 11:03:02 03-Agu-2024	 11:03:19 03-Agu-2024	 11:03:45 03-Agu-2024

No	Tangga	Area	ItemPekerjaan	Detail Pekerjaan	Before	Progress	After
7	03-08-2024	LANTAI 2 MALL	BRUSHING	LANTAI KULIT JERUK DEPAN MANAGEMENT OFFICE	 07:46:00 03-Agu-2024	 07:46:47 03-Agu-2024	 07:55:50 03-Agu-2024
8	03-08-2024	LANTAI 2 MALL	VACUMMING	RELL LIFT	 08:23:16 03-Agu-2024	 08:25:11 03-Agu-2024	 08:26:14 03-Agu-2024
9	03-08-2024	LANTAI 2 MALL	AIR KOMPRESOR	SELA KACA RAILLING	 08:36:25 03-Agu-2024	 11:38:30 03-Agu-2024	 11:38:30 03-Agu-2024
10	03-08-2024	LANTAI 2 MALL	GLASS CLEANING	KACA RALLING BALKON BAGIAN LUAR	 09:50:29 03-Agu-2024	 09:52:10 03-Agu-2024	 10:42:56 03-Agu-2024
11	03-08-2024	LANTAI 2 MALL	DUSTING	DINDING WALLPAPER	 09:12:30 03-Agu-2024	 09:13:33 03-Agu-2024	 09:20:37 03-Agu-2024
12	03-08-2024	LANTAI 2 MALL	WALL CLEANING	DINDING KERAMIK DEPAN LIFT CP3 CP4	 09:23:16 03-Agu-2024	 09:24:00 03-Agu-2024	 09:27:39 03-Agu-2024
13	03-08-2024	LANTAI 2 MALL	BRUSHING	LANTAI	 09:30:22 03-Agu-2024	 09:42:42 03-Agu-2024	 09:50:38 03-Agu-2024

No	Tangga	Area	ItemPekerjaan	Detail Pekerjaan	Before	Progress	After
14	03-08-2024	LANTAI 2 MALL	DUSTING	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN	 09:15:37 03-Agu-2024	 09:18:38 03-Agu-2024	 09:51:40 03-Agu-2024
15	03-08-2024	LANTAI 1 MALL	SPOTING	PILAR BETON CINCIN PILAR	 09:18:15 03-Agu-2024	 09:29:47 03-Agu-2024	 09:34:11 03-Agu-2024
16	03-08-2024	LANTAI 1 MALL	WALL CLEANING	DINDING DAN ACCESORIES	 11:09:59 03-Agu-2024	 11:10:33 03-Agu-2024	 11:17:34 03-Agu-2024
17	03-08-2024	LANTAI 1 MALL	DUSTING	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN	 10:29:33 03-Agu-2024	 10:31:10 03-Agu-2024	 10:32:10 03-Agu-2024
18	03-08-2024	LANTAI 1 MALL	BRUSHING	LANTAI	 20:23:36 03-Agu-2024	 20:23:53 03-Agu-2024	 20:24:09 03-Agu-2024
19	03-08-2024	GF MALL	POLISHING	WEST ENTRANCE	 07:27:52 03-Agu-2024	 07:28:59 03-Agu-2024	 07:29:59 03-Agu-2024
20	03-08-2024	GF MALL	POLISHING	TEMPAT PAYUNG LOBBY2	 21:05:37 03-Agu-2024	 21:06:35 03-Agu-2024	 21:06:56 03-Agu-2024




REPORT PERIODIC - Project : GANDARIA CITY MALL (071221301)

No	Tangga	Area	ItemPekerjaan	Detail Pekerjaan	Before	Progress	After
21	03-08-2024	GF MALL	WALL CLEANING	DINDING DAN ACCESORIES			
22	03-08-2024	GF MALL	DUSTING	CEILLING KAP LAMPU GRILL FAN DAN EXHAUSE FAN			
23	03-08-2024	UG MALL	SPOTING	PILAR MOTIF ZONA UTARA			
24	03-08-2024	UG MALL	VACUMMING	RELL LIFT			
25	03-08-2024	UG MALL	DUSTING	CEILLING,KAP LAMPU, GRILL FAN DAN EXHAUSE FAN			
26	03-08-2024	UG MALL	BRUSHING	LANTAI			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	04-08-2024	LG MALL	POLISHING	HAND RAILLING ESCALATOR			
2	04-08-2024	LANTAI 2 MALL	GENERAL CLEANING	CEILLING KAYU MOTIF ATRIUM			
3	04-08-2024	LANTAI 2 MALL	WALL CLEANING	PILAR BETON			
4	04-08-2024	LANTAI 2 MALL	WALL CLEANING	DINDING DAN ACCESORIES			
5	04-08-2024	LANTAI 2 MALL	BRUSHING	LANTAI			
6	04-08-2024	LANTAI 1 MALL	SPOTING	HAND RAILLING ESCALATOR			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	04-08-2024	LANTAI 1 MALL	GLASS CLEANING	PARTISI CUBICLE			
8	04-08-2024	LANTAI 1 MALL	WALL CLEANING	DINDING DAN ACCESORIES			
9	04-08-2024	GF MALL	POLISHING	DUSTBIN			
10	04-08-2024	GF MALL	GLASS CLEANING	PARTISI CUBICLE			
11	04-08-2024	UG MALL	POLISHING	CINCIN PILAR			
12	04-08-2024	UG MALL	GLASS CLEANING	KACA TENANT H&M			

REPORT PERIODIC - Project : GANDARIA CITY MALL (071221301)

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	04-08-2024	UG MALL	DUSTING	PILAR STAINLESS AREA MANSTREET	 09:41:40 04-Agu-2024	 09:53:27 04-Agu-2024	 09:58:13 04-Agu-2024
14	04-08-2024	UG MALL	GLASS CLEANING	PARTISI CUBICLE	 07:47:16 04-Agu-2024	 07:48:05 04-Agu-2024	 08:11:25 04-Agu-2024
15	04-08-2024	UG MALL	WALL CLEANING	DINDING DAN ACCESORIES	 11:02:41 04-Agu-2024	 11:05:49 04-Agu-2024	 11:13:19 04-Agu-2024
16	04-08-2024	EKSTERNAL	WASHING	TOILET DAMKAR	 13:22:22 04-Agu-2024	 13:23:35 04-Agu-2024	 13:28:02 04-Agu-2024

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	24-08-2024	LG MALL	GLASS CLEANING	KACA LOBBY TAXI LOUNGE	 09:40:54 24-Agu-2024	 09:43:12 24-Agu-2024	 09:50:03 24-Agu-2024
2	24-08-2024	LG MALL	POLISHING	STAINLEES ATM GALERY	 09:54:59 24-Agu-2024	 09:57:43 24-Agu-2024	 10:02:30 24-Agu-2024
3	24-08-2024	LG MALL	GLASS CLEANING	PARTISI CUBICLE	 07:48:56 24-Agt-2024	 09:00:12 24-Agt-2024	 11:13:55 24-Agt-2024

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	25-08-2024	LG MALL	DUSTING	HANGING SIGN	 07:45:18 25-Agt-2024	 08:06:55 25-Agt-2024	 08:57:23 25-Agt-2024
2	25-08-2024	LANTAI 2 MALL	WALL CLEANING	PILAR BETON	 07:40:05 25-Agu-2024	 07:41:56 25-Agu-2024	 07:44:57 25-Agu-2024
3	25-08-2024	LANTAI 1 MALL	GLASS CLEANING	DINDING MARMER DEPAN LIFT PANORAMA	 08:31:02 25-Agu-2024	 08:32:15 25-Agu-2024	 08:33:28 25-Agu-2024
4	25-08-2024	LANTAI 1 MALL	SPOTING	HAND RAILLING ESCALATOR	 10:12:37 25-Agu-2024	 10:14:06 25-Agu-2024	 10:15:37 25-Agu-2024
5	25-08-2024	LANTAI 1 MALL	WALL CLEANING	DINDING DAN ACCESORIES	 10:05:34 25-Agu-2024	 10:07:34 25-Agu-2024	 10:10:21 25-Agu-2024
6	25-08-2024	GF MALL	GLASS CLEANING	PARTISI CUBICLE	 11:16:27 25-Agu-2024	 11:33:18 25-Agu-2024	 11:49:35 25-Agu-2024

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	25-08-2024	UG MALL	POLISHING	CINCIN PILAR	 10:10:45 25-Agu-2024	 10:13:21 25-Agu-2024	 10:16:25 25-Agu-2024
8	25-08-2024	UG MALL	DUSTING	PILAR STAINLESS AREA MANSTREET	 10:06:43 25-Agu-2024	 10:08:03 25-Agu-2024	 10:15:02 25-Agu-2024
9	25-08-2024	UG MALL	GLASS CLEANING	PARTISI CUBICLE	 08:37:45 25-Agu-2024	 08:38:27 25-Agu-2024	 09:03:10 25-Agu-2024
10	25-08-2024	UG MALL	WALL CLEANING	DINDING DAN ACCESORIES	 07:45:16 25-Agu-2024	 07:47:02 25-Agu-2024	 07:47:55 25-Agu-2024
11	25-08-2024	EKSTERNAL	WASHING	TOILET DAMKAR	 13:26:51 25-Agu-2024	 13:26:09 25-Agu-2024	 13:33:43 25-Agu-2024


LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan		Foto Samping		Status Baik	Status Rusak
1	CF1 - HPRE-0001	HIGH PRESSURE	GOLDIE					-	RUSAK
2	CF1 - HPRE-0001	HIGH PRESSURE	GOLDIE					-	RUSAK
3	CF1 - HPRE-0001	HIGH PRESSURE	GOLDIE					-	RUSAK
4	CF1 - RION-0001	RIDE ON SCRUBBER	GOLDIE					-	RUSAK

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
5	CF1 - RION-0001	RIDE ON SCRUBBER	GOLDIE			-	RUSAK
6	CF1 - SCRB-0001	AUTOMATIC SCRUBBER	GOLDIE			-	RUSAK
7	CF1 - L3210	PRINTER	EPSON			-	RUSAK
8	CF1 - GANCIT-SCRB-0002	AUTOMATIC SCRUBBER	GOLDIE			-	RUSAK

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
9	CF1 - GANCIT-SCRB-0001	AUTOMATIC SCRUBBER	GOLDIE			-	RUSAK
10	CF1 - LOSP-0001	LOW SPEED POLISHER	KRISBOW			-	RUSAK
11	CF1 - LOSP-0002	LOW SPEED POLISHER	KRISBOW			BAIK	-
12	CF1 - LOSP-0003	LOW SPEED POLISHER	KRISBOW			BAIK	-

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
13	CF1 - LOSP-0004	LOW SPEED POLISHER	KRISBOW			BAIK	-
14	CF1 - LOSP-0005	LOW SPEED POLISHER	KRISBOW			BAIK	-
15	CF1 - LOSP-0006	LOW SPEED POLISHER	KRISBOW			BAIK	-
16	CF1 - LOSP-0007	LOW SPEED POLISHER	KRISBOW			-	RUSAK



LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
17	CF1 - LOSP-0008	LOW SPEED POLISHER	KRISBOW			-	RUSAK
18	CF1 - VC20-0001	DRY VACUUM CLEANER 20 LITER	KRISBOW			BAIK	-
19	CF1 - VC20-0002	DRY VACUUM CLEANER 20 LITER	KRISBOW			BAIK	-
20	CF1 - VC30-0001	WET & DRY VACUUM CLEANER 30 LITER	KRISBOW			BAIK	-

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
21	CF1 - VC30-0002	WET & DRY VACUUM CLEANER 30 LITER	KRISBOW			BAIK	-
22	CF1 - HPRE-0001	HIGH SPEED POLISHER	INNOTECH			BAIK	-
23	CF1 - HPRE-0002	HIGH SPEED POLISHER	INNOTECH			BAIK	-
24	CF1 - KOMP-0001	COMPUTER SET AREA	LG			BAIK	-

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
25	CF1 - EPSON-L3210	PRINTER	EPSON			BAIK	-
26	CF1 - HPRE-0001	HIGH PRESSURE	GOLDIE			BAIK	-
27	CF1 - HANDPOLISH-0001	HAND POLISHER	DONGCHENG			BAIK	-
28	CF1 - SCRUB-0001	AUTOMATIC SCRUBBER	GOLDIE			BAIK	-



LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
29	CF1 - GANCIT-SCRB-0002	AUTOMATIC SCRUBBER	GOLDIE			BAIK	-
30	CF1 - KABEL ROLL	KABEL ROLL 50 METER	KRISBOW			BAIK	-
31	CF1 - BLOWER-0001	CARPET BLOWER	KRISBOW			BAIK	-
32	CF1 - RION-0001	RIDE ON SCRUBBER	KRISBOW			BAIK	-

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
33	CF1 - SCRB-0001	AUTOMATIC SCRUBBER	INNOTECH			-	RUSAK
34	CF1 - B9936 BAW	MOBIL OPERASIONAL	DAIHATSU			-	RUSAK
35	CF1 - LOSP-0001	LOW SPEED POLISHER	INNOTECH			BAIK	-
36	CF1 - LOSP-0007	LOW SPEED POLISHER	INNOTECH			BAIK	-

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan		Foto Samping	Status Baik	Status Rusak
37	CF1 - LOSP-0008	LOW SPEED POLISHER	INNOTECH				BAIK	-
38	CF1 - VC-0030	WET & DRY VACUUM CLEANER 30 LITER	INNOTECH				-	RUSAK
39	CF1 - VC30-0004	WET & DRY VACUUM CLEANER 30 LITER	INNOTECH				BAIK	-
40	CF1 - VC30-0003	WET & DRY VACUUM CLEANER 30 LITER	INNOTECH				BAIK	-

LAPORAN MESIN - Project : GANDARIA CITY MALL (071221301)

PERIODE : 2024-08-01 - 2024-08-31

No	Kode Mesin	Jenis Mesin	Merk Mesin	Foto Depan	Foto Samping	Status Baik	Status Rusak
41	CF1 - LOSP-0003	LOW SPEED POLISHER	INNOTECH			BAIK	-
42	CF1 - LOSP-0001	WET & DRY VACUUM CLEANER 30 LITER	INNOTECH			BAIK	-
43	CF1 - VC20-0001	DRY VACUUM CLEANER 20 LITER	INNOTECH			BAIK	-
44	CF1 - VC20-0002	DRY VACUUM CLEANER 20 LITER	INNOTECH			BAIK	-