








No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	04-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			
2	04-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)			
3	04-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LV.LG&UG			
4	04-01-2025	CARPARK	GENERAL CLEANING	DETAIL CLEANING TOILET CARPARK LV.LG			
5	04-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI OUT MOBIL			
6	04-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P6A & P6B			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	04-01-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA SHOFRONT SISI DEPAN EX TENANT MR.FOX LV.UG	 10:28:51 04-Jan-2025	 10:31:51 04-Jan-2025	 10:32:01 04-Jan-2025
8	04-01-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA SHOFRONT SISI DEPAN EX TENANT TOBY'S LV.UG	 10:32:28 04-Jan-2025	 10:32:38 04-Jan-2025	 10:33:51 04-Jan-2025
9	04-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN,SELA SELA HAND RALLING LV.1-5	 10:24:28 04-Jan-2025	 10:24:45 04-Jan-2025	 10:25:11 04-Jan-2025
10	04-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING TANAMAN HIAS POT HPL LV.4	 10:19:14 04-Jan-2025	 10:19:57 04-Jan-2025	 10:21:27 04-Jan-2025
11	04-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.UG	 22:06:49 04-Jan-2025	 22:06:05 04-Jan-2025	 22:11:28 04-Jan-2025
12	04-01-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.6	 00:58:28 04-Jan-2025	 00:57:50 04-Jan-2025	 02:00:07 04-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	06-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA SISI DEPAN TENANT BENEFIT S/D LED PROMO	 07:29:10 06-Jan-2025	 01:22:04 06-Jan-2025	 07:30:11 06-Jan-2025
2	06-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP& DOWN)	 07:31:06 06-Jan-2025	 07:31:46 06-Jan-2025	 07:32:42 06-Jan-2025
3	06-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 21:37:51 06-Jan-2025	 21:38:27 06-Jan-2025	 21:39:24 06-Jan-2025
4	06-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 10:35:32 06-Jan-2025	 10:37:25 06-Jan-2025	 10:38:06 06-Jan-2025
5	06-01-2025	GUTTER	SWEEPING	GUTTER SISI IN MOBIL SISI TOTEM	 07:22:02 06-Jan-2025	 07:23:44 06-Jan-2025	 07:24:21 06-Jan-2025
6	06-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI CONECTION TP4	 07:36:04 06-Jan-2025	 07:37:36 06-Jan-2025	 07:36:55 06-Jan-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	06-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI MARGOYOSO	 07:33:38 06-Jan-2025	 07:34:26 06-Jan-2025	 07:35:00 06-Jan-2025
8	06-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI SPIRAL UP&DOWN	 07:38:23 06-Jan-2025	 07:38:48 06-Jan-2025	 07:39:29 06-Jan-2025
9	06-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P7A & P7B	 02:13:32 06-Jan-2025	 02:13:52 06-Jan-2025	 02:14:13 06-Jan-2025
10	06-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI GRANIT BAKAR SISI MR.FOX - SISI TOBY'S LV.UG	 04:16:41 06-Jan-2025	 04:23:18 06-Jan-2025	 04:34:20 06-Jan-2025
11	06-01-2025	CARPARK	DUSTING	DUSTING ATAU DETAIL CLEANING TANAMAN AREA ENTRANCE LOBBY (TANAMAN BESAR)	 07:48:43 06-Jan-2025	 07:49:43 06-Jan-2025	 07:48:36 06-Jan-2025
12	06-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 07:35:57 06-Jan-2025	 07:36:58 06-Jan-2025	 07:38:11 06-Jan-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	06-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 22:31:26 06-Jan-2025	 22:31:37 06-Jan-2025	 22:31:59 06-Jan-2025
14	06-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 14:03:45 06-Jan-2025	 14:04:52 06-Jan-2025	 14:06:07 06-Jan-2025
15	06-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SERVICE LV.1-5	 13:59:57 06-Jan-2025	 14:02:15 06-Jan-2025	 14:00:59 06-Jan-2025
16	06-01-2025	KORIDOR SHOPPING	POLISHING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 10:37:39 06-Jan-2025	 10:39:53 06-Jan-2025	 10:46:10 06-Jan-2025
17	06-01-2025	KORIDOR SHOPPING	POLISHING	BUSHING KORIDOR EXIT 24 LV.4	 21:39:53 06-Jan-2025	 21:41:23 06-Jan-2025	 21:42:29 06-Jan-2025
18	06-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA MEJA WASTAFEL TOILET MALE & FEMALE LV.1	 07:51:24 06-Jan-2025	 07:53:40 06-Jan-2025	 07:51:37 06-Jan-2025




No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	06-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA MEJA WASTAFEL TOILET MALE & FEMALE LV.1			
20	06-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA MEJA WASTAFEL TOILET MALE & FEMALE LV.1			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	07-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MEJA VALET			
2	07-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)			
3	07-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5			
4	07-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3			
5	07-01-2025	GUTTER	SWEEPING	GUTTER RUMP UP DROP OUT			
6	07-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P7A & P7B			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	07-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN SPIRAL UP&DOWN LV.6-4	 03:39:04 07-Jan-2025	 03:39:17 07-Jan-2025	 03:39:29 07-Jan-2025
8	07-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ATAP PLAFON / HPL LV.UG	 08:13:53 07-Jan-2025	 08:14:29 07-Jan-2025	 08:14:58 07-Jan-2025
9	07-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:17:35 07-Jan-2025	 20:17:55 07-Jan-2025	 20:21:54 07-Jan-2025
10	07-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 12:13:36 07-Jan-2025	 12:13:10 07-Jan-2025	 12:14:03 07-Jan-2025
11	07-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN RUANG BASS ROOM LV.7	 10:15:36 07-Jan-2025	 10:16:16 07-Jan-2025	 10:15:59 07-Jan-2025
12	07-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 03:42:44 07-Jan-2025	 03:42:56 07-Jan-2025	 03:43:09 07-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	07-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:47:35 07-Jan-2025	 21:49:13 07-Jan-2025	 21:51:41 07-Jan-2025
14	07-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ORNAMENT PLAFON HPL LV.5	 03:33:02 07-Jan-2025	 03:32:44 07-Jan-2025	 03:33:16 07-Jan-2025
15	07-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:40:03 07-Jan-2025	 03:31:17 07-Jan-2025	 03:40:16 07-Jan-2025
16	07-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:40:31 07-Jan-2025	 03:32:13 07-Jan-2025	 03:40:43 07-Jan-2025
17	07-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 07:51:17 07-Jan-2025	 03:31:44 07-Jan-2025	 07:51:37 07-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	08-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING			
2	08-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)			
3	08-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.6&7			
4	08-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5			
5	08-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER ENTRANCE			
6	08-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P8A			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	08-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN SPIRAL UP&DOWN LV.4-2	 23:42:41 07-Jan-2025	 02:54:21 08-Jan-2025	 23:43:07 07-Jan-2025
8	08-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN RUANG GREASE TRAP	 00:43:21 08-Jan-2025	 00:55:56 08-Jan-2025	 00:56:38 08-Jan-2025
9	08-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 23:11:14 08-Jan-2025	 23:11:25 08-Jan-2025	 23:11:37 08-Jan-2025
10	08-01-2025	KORIDOR SHOPPING	WASHING	PEMBERSIHAN TRASHCAN LV.UG-LV.10	 14:09:30 08-Jan-2025	 14:12:35 08-Jan-2025	 14:22:21 08-Jan-2025
11	08-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5	 13:24:32 08-Jan-2025	 13:25:09 08-Jan-2025	 13:26:48 08-Jan-2025
12	08-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.5	 21:47:46 08-Jan-2025	 21:49:20 08-Jan-2025	 21:53:54 08-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	08-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3			
14	08-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4			
15	08-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			
16	08-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			
17	08-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	09-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA LIFT PASSENGER A DAN B	 01:50:02 09-Jan-2025	 01:58:07 09-Jan-2025	 01:50:51 09-Jan-2025
2	09-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 00:07:44 09-Jan-2025	 00:07:22 09-Jan-2025	 00:08:14 09-Jan-2025
3	09-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.9&10	 22:56:51 09-Jan-2025	 22:57:15 09-Jan-2025	 22:57:28 09-Jan-2025
4	09-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 13:46:00 09-Jan-2025	 13:47:03 09-Jan-2025	 13:46:38 09-Jan-2025
5	09-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI BAWAH MR.FOX	 06:27:02 09-Jan-2025	 06:27:17 09-Jan-2025	 06:29:18 09-Jan-2025
6	09-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P8A	 23:00:24 08-Jan-2025	 01:17:17 09-Jan-2025	 03:06:16 09-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	09-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN SPIRAL UP&DOWN LV.2-LG	 02:02:21 09-Jan-2025	 02:02:41 09-Jan-2025	 02:03:44 09-Jan-2025
8	09-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 13:39:11 09-Jan-2025	 13:40:23 09-Jan-2025	 13:40:59 09-Jan-2025
9	09-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:56:12 09-Jan-2025	 22:56:22 09-Jan-2025	 22:56:34 09-Jan-2025
10	09-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 13:49:19 09-Jan-2025	 13:51:39 09-Jan-2025	 13:50:03 09-Jan-2025
11	09-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.4	 21:38:43 09-Jan-2025	 21:38:07 09-Jan-2025	 21:52:29 09-Jan-2025
12	09-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 23:18:29 08-Jan-2025	 23:15:23 08-Jan-2025	 23:20:25 08-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	09-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA LIFT SERVICE A DAN B	 01:51:34 09-Jan-2025	 01:58:31 09-Jan-2025	 01:51:50 09-Jan-2025
14	09-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 01:52:42 09-Jan-2025	 01:59:26 09-Jan-2025	 01:53:04 09-Jan-2025
15	09-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA LIFT SERVICE A DAN B	 02:06:19 09-Jan-2025	 02:08:17 09-Jan-2025	 02:06:36 09-Jan-2025
16	09-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 01:53:53 09-Jan-2025	 01:55:41 09-Jan-2025	 01:54:10 09-Jan-2025
17	09-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA LIFT SERVICE A DAN B	 02:06:59 09-Jan-2025	 02:08:00 09-Jan-2025	 02:07:12 09-Jan-2025
18	09-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 01:54:35 09-Jan-2025	 01:56:28 09-Jan-2025	 01:55:02 09-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	10-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA DARI LANDING ESCALATOR TENANT COTTON ON - ARAH KE CONNECTION TP4 LV.2	 03:22:26 10-Jan-2025	 03:23:03 10-Jan-2025	 03:22:40 10-Jan-2025
2	10-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)	 01:12:09 10-Jan-2025	 00:48:29 10-Jan-2025	 01:12:23 10-Jan-2025
3	10-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.1&2	 20:44:45 10-Jan-2025	 20:46:24 10-Jan-2025	 20:46:38 10-Jan-2025
4	10-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 09:14:58 10-Jan-2025	 09:15:21 10-Jan-2025	 09:15:41 10-Jan-2025
5	10-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P8A	 03:22:34 10-Jan-2025	 03:23:16 10-Jan-2025	 03:23:32 10-Jan-2025
6	10-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.3	 22:03:16 10-Jan-2025	 22:05:56 10-Jan-2025	 22:07:47 10-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	10-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:23:50 10-Jan-2025	 00:12:05 10-Jan-2025	 03:24:05 10-Jan-2025
8	10-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:24:38 10-Jan-2025	 00:19:56 10-Jan-2025	 03:24:59 10-Jan-2025
9	10-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:25:28 10-Jan-2025	 00:33:01 10-Jan-2025	 03:26:04 10-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	11-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA DARI LANDING ESCALATOR TENANT GEOX - ARAH KE CONNECTION TP4 LV.1	 03:45:17 11-Jan-2025	 03:45:51 11-Jan-2025	 03:45:38 11-Jan-2025
2	11-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 03:51:57 11-Jan-2025	 03:52:29 11-Jan-2025	 03:52:10 11-Jan-2025
3	11-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LV.LG&UG	 21:38:14 11-Jan-2025	 21:39:31 11-Jan-2025	 21:41:56 11-Jan-2025
4	11-01-2025	CARPARK	GENERAL CLEANING	DETAIL CLEANING TOILET CARPARK LV.LG	 09:28:36 11-Jan-2025	 09:30:44 11-Jan-2025	 09:38:26 11-Jan-2025
5	11-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI OUT MOBIL	 03:54:09 11-Jan-2025	 03:54:22 11-Jan-2025	 03:54:34 11-Jan-2025
6	11-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA LG	 03:55:47 11-Jan-2025	 03:56:00 11-Jan-2025	 03:56:11 11-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	11-01-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA CANOPY + GUTTER LV.UG	 11:58:28 11-Jan-2025	 11:58:41 11-Jan-2025	 11:59:01 11-Jan-2025
8	11-01-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING GRANIT SISI DEPAN LIFT PASSENGER LV.UG-10	 12:14:23 11-Jan-2025	 12:14:39 11-Jan-2025	 12:15:00 11-Jan-2025
9	11-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SELA SELA PINTU LIFT PASSENGER LV.UG-10	 12:17:16 11-Jan-2025	 12:17:24 11-Jan-2025	 12:17:33 11-Jan-2025
10	11-01-2025	KORIDOR SHOPPING	CELLING	CELLING AREA KORIDOR SHOPPING LV.1-5	 12:01:06 11-Jan-2025	 12:01:37 11-Jan-2025	 12:02:06 11-Jan-2025
11	11-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5	 12:16:35 11-Jan-2025	 12:16:48 11-Jan-2025	 12:16:59 11-Jan-2025
12	11-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SELA SELA PINTU LIFT SERVICE LV.LG-10	 12:03:21 11-Jan-2025	 12:03:34 11-Jan-2025	 12:03:44 11-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	11-01-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR SERVICE LV.LG-10			
14	11-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 24 SISI MR.FOX,LC WAIKIKI,KID STATION,SUSHI TEI LV.LG-10			
15	11-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING TANAMAN HIAS POT HPL LV.4			
16	11-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.UG-1			
17	11-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.UG			
18	11-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			







No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	11-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			
20	11-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			







No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	13-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MEJA WASTAFEL TOILET MALE & FEMALE LV.3	 02:38:55 13-Jan-2025	 02:31:26 13-Jan-2025	 02:39:19 13-Jan-2025
2	13-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 23:19:59 12-Jan-2025	 23:20:45 12-Jan-2025	 23:20:17 12-Jan-2025
3	13-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 22:08:04 13-Jan-2025	 22:09:32 13-Jan-2025	 22:10:36 13-Jan-2025
4	13-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 10:32:00 13-Jan-2025	 10:33:22 13-Jan-2025	 10:33:40 13-Jan-2025
5	13-01-2025	GUTTER	SWEEPING	GUTTER SISI IN MOBIL SISI TOTEM	 07:26:21 13-Jan-2025	 07:26:56 13-Jan-2025	 07:27:29 13-Jan-2025
6	13-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI CONECTION TP4	 02:31:55 13-Jan-2025	 02:32:13 13-Jan-2025	 02:32:39 13-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	13-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI MARGOYOSO	 02:33:13 13-Jan-2025	 02:33:28 13-Jan-2025	 02:33:40 13-Jan-2025
8	13-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA LG	 02:33:58 13-Jan-2025	 02:34:33 13-Jan-2025	 02:34:46 13-Jan-2025
9	13-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI GRANIT BAKAR SISI MR.FOX - SISI TOBY'S LV.UG	 02:49:46 13-Jan-2025	 02:52:01 13-Jan-2025	 03:05:33 13-Jan-2025
10	13-01-2025	KORIDOR SHOPPING	CELLING	CELLING AREA LOBBY LV.UG	 08:20:46 13-Jan-2025	 08:21:37 13-Jan-2025	 08:22:48 13-Jan-2025
11	13-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 07:38:14 13-Jan-2025	 07:40:55 13-Jan-2025	 07:40:00 13-Jan-2025
12	13-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 22:16:00 13-Jan-2025	 22:16:43 13-Jan-2025	 22:17:28 13-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	13-01-2025	KORIDOR SHOPPING	SWEEPING	SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10			
14	13-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5			
15	13-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10			
16	13-01-2025	KORIDOR SHOPPING	POLISHING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5			
17	13-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10			
18	13-01-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR EXIT			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	13-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5	 11:40:15 13-Jan-2025	 11:40:55 13-Jan-2025	 11:40:39 13-Jan-2025
20	13-01-2025	KORIDOR SHOPPING	POLISHING	BUSHING KORIDOR EXIT 24 LV.4	 22:13:19 13-Jan-2025	 22:14:01 13-Jan-2025	 22:14:55 13-Jan-2025
21	13-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA DARI DEPAN TENANT BRAUN N BUFFEL - LANDING ESCALATOR DEPAN M&S	 02:35:31 13-Jan-2025	 23:38:37 12-Jan-2025	 02:35:43 13-Jan-2025
22	13-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA DARI DEPAN TENANT BRAUN N BUFFEL - LANDING ESCALATOR DEPAN M&S	 02:36:02 13-Jan-2025	 23:38:50 12-Jan-2025	 02:36:15 13-Jan-2025
23	13-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA DARI DEPAN TENANT BRAUN N BUFFEL - LANDING ESCALATOR DEPAN M&S	 02:36:43 13-Jan-2025	 23:39:15 12-Jan-2025	 02:36:57 13-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	14-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MEJA CONCIERGE	 06:44:58 14-Jan-2025	 01:34:33 14-Jan-2025	 06:45:21 14-Jan-2025
2	14-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 00:00:56 14-Jan-2025	 00:11:53 14-Jan-2025	 00:06:17 14-Jan-2025
3	14-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:17:44 14-Jan-2025	 21:19:52 14-Jan-2025	 21:24:29 14-Jan-2025
4	14-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 07:49:21 14-Jan-2025	 07:50:25 14-Jan-2025	 07:49:39 14-Jan-2025
5	14-01-2025	GUTTER	SWEEPING	GUTTER RUMP UP DROP OUT	 07:25:03 14-Jan-2025	 07:26:02 14-Jan-2025	 07:30:37 14-Jan-2025
6	14-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ATAP PLAFON / HPL LV.UG	 07:42:32 14-Jan-2025	 07:43:58 14-Jan-2025	 07:44:19 14-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	14-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:14:47 14-Jan-2025	 20:15:16 14-Jan-2025	 20:33:48 14-Jan-2025
8	14-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 10:14:57 14-Jan-2025	 10:15:24 14-Jan-2025	 10:16:41 14-Jan-2025
9	14-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN RUANG BASS ROOM LV.7	 10:08:15 14-Jan-2025	 10:07:56 14-Jan-2025	 10:08:32 14-Jan-2025
10	14-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7	 11:25:57 14-Jan-2025	 11:26:12 14-Jan-2025	 11:26:40 14-Jan-2025
11	14-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 23:58:26 13-Jan-2025	 00:10:59 14-Jan-2025	 00:05:06 14-Jan-2025
12	14-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:37:19 14-Jan-2025	 21:35:05 14-Jan-2025	 21:36:47 14-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	14-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN HPL AREA LOBBY LV.UG			
14	14-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG			
15	14-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG			
16	14-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	15-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING	 03:12:31 15-Jan-2025	 03:13:08 15-Jan-2025	 03:13:33 15-Jan-2025
2	15-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 01:55:06 15-Jan-2025	 02:06:53 15-Jan-2025	 02:07:31 15-Jan-2025
3	15-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.6&7	 22:41:14 15-Jan-2025	 22:41:48 15-Jan-2025	 22:42:19 15-Jan-2025
4	15-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5	 13:42:35 15-Jan-2025	 13:44:07 15-Jan-2025	 13:44:27 15-Jan-2025
5	15-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER ENTRANCE	 07:18:37 15-Jan-2025	 07:22:19 15-Jan-2025	 08:28:21 15-Jan-2025
6	15-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN RUANG GREASE TRAP	 03:22:58 15-Jan-2025	 03:23:16 15-Jan-2025	 03:23:29 15-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	15-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 22:39:22 15-Jan-2025	 22:39:40 15-Jan-2025	 22:39:58 15-Jan-2025
8	15-01-2025	KORIDOR SHOPPING	WASHING	PEMBERSIHAN TRASHCAN LV.UG-LV.10	 14:02:17 15-Jan-2025	 14:03:39 15-Jan-2025	 14:04:23 15-Jan-2025
9	15-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5	 13:39:56 15-Jan-2025	 13:40:54 15-Jan-2025	 13:41:30 15-Jan-2025
10	15-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.5	 21:55:22 15-Jan-2025	 21:58:34 15-Jan-2025	 22:13:01 15-Jan-2025
11	15-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9	 13:49:37 15-Jan-2025	 13:53:26 15-Jan-2025	 13:50:48 15-Jan-2025
12	15-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 23:28:25 14-Jan-2025	 01:55:21 15-Jan-2025	 01:27:22 15-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	15-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 23:34:09 14-Jan-2025	 01:51:46 15-Jan-2025	 01:54:00 15-Jan-2025
14	15-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:14:12 15-Jan-2025	 03:14:50 15-Jan-2025	 03:14:28 15-Jan-2025
15	15-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:15:48 15-Jan-2025	 03:15:27 15-Jan-2025	 03:16:09 15-Jan-2025
16	15-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:18:02 15-Jan-2025	 03:17:11 15-Jan-2025	 03:18:16 15-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	16-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 01:41:12 16-Jan-2025	 06:34:29 16-Jan-2025	 01:54:19 16-Jan-2025
2	16-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.9&10	 21:46:30 16-Jan-2025	 21:47:05 16-Jan-2025	 21:47:48 16-Jan-2025
3	16-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 13:34:58 16-Jan-2025	 13:35:59 16-Jan-2025	 13:35:21 16-Jan-2025
4	16-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI BAWAH MR.FOX	 06:01:41 16-Jan-2025	 06:00:13 16-Jan-2025	 06:02:33 16-Jan-2025
5	16-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 13:38:54 16-Jan-2025	 13:39:14 16-Jan-2025	 13:39:44 16-Jan-2025
6	16-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:19:45 16-Jan-2025	 22:20:19 16-Jan-2025	 22:20:44 16-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	16-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10			
8	16-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.4			
9	16-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10			
10	16-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5			
11	16-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2			
12	16-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2			

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
13	16-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 06:32:12 16-Jan-2025	 06:28:52 16-Jan-2025	 06:32:34 16-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	17-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 01:18:35 17-Jan-2025	 01:19:00 17-Jan-2025	 01:19:36 17-Jan-2025
2	17-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)	 01:20:26 17-Jan-2025	 01:25:33 17-Jan-2025	 01:27:57 17-Jan-2025
3	17-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.1&2	 20:44:59 17-Jan-2025	 20:46:20 17-Jan-2025	 20:47:57 17-Jan-2025
4	17-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 12:25:01 17-Jan-2025	 12:25:54 17-Jan-2025	 12:26:53 17-Jan-2025
5	17-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.3	 21:59:39 17-Jan-2025	 22:01:05 17-Jan-2025	 22:26:08 17-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	18-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 02:49:01 18-Jan-2025	 02:51:03 18-Jan-2025	 02:49:17 18-Jan-2025
2	18-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 02:45:13 18-Jan-2025	 02:45:30 18-Jan-2025	 02:45:42 18-Jan-2025
3	18-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LV.LG&UG	 21:39:54 18-Jan-2025	 21:41:59 18-Jan-2025	 21:44:32 18-Jan-2025
4	18-01-2025	CARPARK	GENERAL CLEANING	DETAIL CLEANING TOILET CARPARK LV.LG	 09:25:46 18-Jan-2025	 09:28:15 18-Jan-2025	 09:32:51 18-Jan-2025
5	18-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI OUT MOBIL	 07:25:01 18-Jan-2025	 07:25:17 18-Jan-2025	 07:25:32 18-Jan-2025
6	18-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5	 08:24:20 18-Jan-2025	 08:24:28 18-Jan-2025	 19:53:29 18-Jan-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	18-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING TANAMAN HIAS POT HPL LV.4	 08:23:22 18-Jan-2025	 08:23:40 18-Jan-2025	 08:24:03 18-Jan-2025
8	18-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.UG	 21:48:31 18-Jan-2025	 21:49:21 18-Jan-2025	 21:54:29 18-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	20-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MEJA WASTAFEL TOILET MALE & FEMALE LV.5	 06:02:21 20-Jan-2025	 06:03:19 20-Jan-2025	 06:02:41 20-Jan-2025
2	20-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 06:05:00 20-Jan-2025	 06:05:31 20-Jan-2025	 06:06:04 20-Jan-2025
3	20-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 22:35:38 20-Jan-2025	 22:35:55 20-Jan-2025	 22:36:25 20-Jan-2025
4	20-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 06:15:09 20-Jan-2025	 08:19:24 20-Jan-2025	 08:20:03 20-Jan-2025
5	20-01-2025	GUTTER	SWEEPING	GUTTER SISI IN MOBIL SISI TOTEM	 07:30:30 20-Jan-2025	 07:33:21 20-Jan-2025	 07:36:47 20-Jan-2025
6	20-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI CONECTION TP4	 08:08:25 20-Jan-2025	 06:09:30 20-Jan-2025	 06:09:45 20-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	20-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI MARGOYOSO	 06:10:07 20-Jan-2025	 06:10:24 20-Jan-2025	 06:10:40 20-Jan-2025
8	20-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P6A & P6B	 06:11:08 20-Jan-2025	 06:11:21 20-Jan-2025	 06:12:01 20-Jan-2025
9	20-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI GRANIT BAKAR SISI MR.FOX - SISI TOBY'S LV.UG	 02:58:06 20-Jan-2025	 03:08:37 20-Jan-2025	 04:13:28 20-Jan-2025
10	20-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 08:08:01 20-Jan-2025	 08:10:36 20-Jan-2025	 08:11:52 20-Jan-2025
11	20-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 22:32:58 20-Jan-2025	 22:33:13 20-Jan-2025	 22:33:43 20-Jan-2025
12	20-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 11:32:58 20-Jan-2025	 11:34:15 20-Jan-2025	 11:36:55 20-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	20-01-2025	KORIDOR SHOPPING	POLISHING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 10:47:48 20-Jan-2025	 10:48:10 20-Jan-2025	 11:29:39 20-Jan-2025
14	20-01-2025	KORIDOR SHOPPING	POLISHING	BUSHING KORIDOR EXIT 24 LV.4	 22:36:42 20-Jan-2025	 22:36:54 20-Jan-2025	 22:37:12 20-Jan-2025
15	20-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA DARI LANDING ESCALATOR DEPAN TENANT M&S - ARAH KE TENANT COAST / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.1	 06:12:49 20-Jan-2025	 07:34:31 20-Jan-2025	 06:13:09 20-Jan-2025
16	20-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA DARI LANDING ESCALATOR DEPAN TENANT M&S - ARAH KE TENANT COAST / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.1	 06:13:49 20-Jan-2025	 07:35:23 20-Jan-2025	 06:15:09 20-Jan-2025
17	20-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA DARI LANDING ESCALATOR DEPAN TENANT M&S - ARAH KE TENANT COAST / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.1	 06:14:17 20-Jan-2025	 07:36:04 20-Jan-2025	 06:14:38 20-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	21-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MEJA VALET			
2	21-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)			
3	21-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5			
4	21-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3			
5	21-01-2025	GUTTER	SWEEPING	GUTTER RUMP UP DROP OUT			
6	21-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P6A & P6B			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	21-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN SPIRAL UP&DOWN LV.6-4			
8	21-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ATAP PLAFON / HPL LV.UG			
9	21-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2			
10	21-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10			
11	21-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN RUANG BASS ROOM LV.7			
12	21-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	21-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:33:52 21-Jan-2025	 21:35:41 21-Jan-2025	 21:38:22 21-Jan-2025
14	21-01-2025	KORIDOR SHOPPING	DUSTING	DINDING BAGIAN LUAR LOBBY LV.UG	 13:38:05 21-Jan-2025	 13:38:51 21-Jan-2025	 13:38:36 21-Jan-2025
15	21-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 05:56:59 21-Jan-2025	 05:59:34 21-Jan-2025	 05:57:15 21-Jan-2025
16	21-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 05:58:19 21-Jan-2025	 05:59:17 21-Jan-2025	 05:58:34 21-Jan-2025
17	21-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 05:57:36 21-Jan-2025	 05:59:56 21-Jan-2025	 05:57:51 21-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	22-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING	 02:47:20 22-Jan-2025	 02:47:44 22-Jan-2025	 02:48:00 22-Jan-2025
2	22-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 23:26:41 21-Jan-2025	 23:34:15 21-Jan-2025	 23:26:56 21-Jan-2025
3	22-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.6&7	 22:23:09 22-Jan-2025	 22:23:29 22-Jan-2025	 22:23:47 22-Jan-2025
4	22-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5	 12:00:22 22-Jan-2025	 12:01:51 22-Jan-2025	 12:01:25 22-Jan-2025
5	22-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER ENTRANCE	 07:19:04 22-Jan-2025	 07:20:13 22-Jan-2025	 07:34:01 22-Jan-2025
6	22-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P6A & P6B	 02:58:00 22-Jan-2025	 02:58:16 22-Jan-2025	 02:58:34 22-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	22-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN SPIRAL UP&DOWN LV.4-2			
8	22-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN RUANG GREASE TRAP			
9	22-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3			
10	22-01-2025	KORIDOR SHOPPING	WASHING	PEMBERSIHAN TRASHCAN LV.UG-LV.10			
11	22-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5			
12	22-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.5			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	22-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 02:44:59 22-Jan-2025	 02:45:16 22-Jan-2025	 02:45:33 22-Jan-2025
14	22-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 02:43:45 22-Jan-2025	 02:44:14 22-Jan-2025	 02:44:35 22-Jan-2025
15	22-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 02:53:32 22-Jan-2025	 02:54:05 22-Jan-2025	 02:53:45 22-Jan-2025
16	22-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 02:54:29 22-Jan-2025	 02:54:57 22-Jan-2025	 02:54:41 22-Jan-2025
17	22-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 02:55:35 22-Jan-2025	 02:56:27 22-Jan-2025	 02:55:51 22-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	23-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA LIFT PASSENGER A DAN B	 02:18:29 23-Jan-2025	 02:20:30 23-Jan-2025	 02:18:50 23-Jan-2025
2	23-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 02:27:26 23-Jan-2025	 02:27:43 23-Jan-2025	 02:27:59 23-Jan-2025
3	23-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.9&10	 22:21:57 23-Jan-2025	 22:22:59 23-Jan-2025	 22:22:29 23-Jan-2025
4	23-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 13:25:28 23-Jan-2025	 13:26:45 23-Jan-2025	 13:26:16 23-Jan-2025
5	23-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI BAWAH MR.FOX	 07:27:08 23-Jan-2025	 07:28:19 23-Jan-2025	 07:30:10 23-Jan-2025
6	23-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P7A & P7B	 08:16:07 23-Jan-2025	 08:16:23 23-Jan-2025	 08:16:42 23-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	23-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN SPIRAL UP&DOWN LV.2-LG			
8	23-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG			
9	23-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4			
10	23-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10			
11	23-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.4			
12	23-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5			






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	23-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA LIFT SERVICE A DAN B	 02:21:59 23-Jan-2025	 02:22:31 23-Jan-2025	 02:22:15 23-Jan-2025
14	23-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 02:12:14 23-Jan-2025	 00:42:17 23-Jan-2025	 02:12:32 23-Jan-2025
15	23-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA LIFT SERVICE A DAN B	 02:22:59 23-Jan-2025	 02:23:41 23-Jan-2025	 02:23:20 23-Jan-2025
16	23-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 02:14:05 23-Jan-2025	 00:49:59 23-Jan-2025	 02:14:19 23-Jan-2025
17	23-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA LIFT SERVICE A DAN B	 02:24:24 23-Jan-2025	 02:24:51 23-Jan-2025	 02:24:38 23-Jan-2025
18	23-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 02:15:07 23-Jan-2025	 00:53:54 23-Jan-2025	 02:15:20 23-Jan-2025






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	24-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 02:12:08 24-Jan-2025	 02:11:47 24-Jan-2025	 02:12:26 24-Jan-2025
2	24-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)	 02:14:43 24-Jan-2025	 02:14:59 24-Jan-2025	 02:15:15 24-Jan-2025
3	24-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.1&2	 20:32:15 24-Jan-2025	 20:33:24 24-Jan-2025	 20:32:28 24-Jan-2025
4	24-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 08:18:00 24-Jan-2025	 08:19:07 24-Jan-2025	 08:18:53 24-Jan-2025
5	24-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P7A & P7B	 23:16:11 23-Jan-2025	 04:35:05 24-Jan-2025	 04:36:55 24-Jan-2025
6	24-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.3	 22:19:46 24-Jan-2025	 22:20:32 24-Jan-2025	 22:21:22 24-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	25-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA SISI LED PROMO/DEPAN TENANT SALAD STOP S/D TRAP TANGGA OMEGA	 03:04:16 25-Jan-2025	 03:03:26 25-Jan-2025	 03:04:33 25-Jan-2025
2	25-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 00:09:41 25-Jan-2025	 00:10:14 25-Jan-2025	 00:10:00 25-Jan-2025
3	25-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LV.LG&UG	 21:54:53 25-Jan-2025	 21:56:22 25-Jan-2025	 21:59:17 25-Jan-2025
4	25-01-2025	CARPARK	GENERAL CLEANING	DETAIL CLEANING TOILET CARPARK LV.LG	 09:39:30 25-Jan-2025	 09:39:52 25-Jan-2025	 09:40:06 25-Jan-2025
5	25-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI OUT MOBIL	 03:07:21 25-Jan-2025	 03:07:37 25-Jan-2025	 03:07:51 25-Jan-2025
6	25-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P7A & P7B	 03:19:25 25-Jan-2025	 03:19:46 25-Jan-2025	 03:20:01 25-Jan-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	25-01-2025	KORIDOR SHOPPING	CELLING	CELLING AREA KORIDOR SHOPPING LV.1-5	 19:18:29 25-Jan-2025	 19:18:52 25-Jan-2025	 19:19:04 25-Jan-2025
8	25-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5	 09:40:33 25-Jan-2025	 09:40:51 25-Jan-2025	 09:41:02 25-Jan-2025
9	25-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SELA SELA PINTU LIFT SERVICE LV.LG-10	 14:37:02 25-Jan-2025	 14:37:18 25-Jan-2025	 14:37:37 25-Jan-2025
10	25-01-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR SERVICE LV.LG-10	 09:41:31 25-Jan-2025	 09:41:45 25-Jan-2025	 09:41:57 25-Jan-2025
11	25-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 24 SISI MR.FOX, LC WAIKIKI, KID STATION, SUSHI TEI LV.LG-10	 19:08:56 25-Jan-2025	 19:10:26 25-Jan-2025	 19:11:06 25-Jan-2025
12	25-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING TANAMAN HIAS POT HPL LV.4	 09:42:15 25-Jan-2025	 09:42:31 25-Jan-2025	 09:42:54 25-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	25-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.UG-1	 14:35:50 25-Jan-2025	 14:36:02 25-Jan-2025	 14:36:30 25-Jan-2025
14	25-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.UG	 09:44:02 25-Jan-2025	 09:44:16 25-Jan-2025	 09:44:31 25-Jan-2025
15	25-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:05:15 25-Jan-2025	 03:01:36 25-Jan-2025	 03:05:30 25-Jan-2025
16	25-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:05:51 25-Jan-2025	 03:01:56 25-Jan-2025	 03:06:03 25-Jan-2025
17	25-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:06:21 25-Jan-2025	 03:02:34 25-Jan-2025	 03:06:34 25-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	26-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA SISI DEPAN TENANT MR.FOX DAN DEPAN TENANT TOBBY'S & AREA DEPAN CONCIERGE	 03:03:26 26-Jan-2025	 03:01:57 26-Jan-2025	 03:03:42 26-Jan-2025
2	26-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.7-9 (UP&DOWN)	 00:14:26 26-Jan-2025	 00:14:57 26-Jan-2025	 00:14:41 26-Jan-2025
3	26-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.3	 21:57:00 26-Jan-2025	 22:00:05 26-Jan-2025	 22:02:21 26-Jan-2025
4	26-01-2025	CARPARK	GENERAL CLEANING	DETAIL CLEANING TOILET CARPARK LV.8	 08:58:33 26-Jan-2025	 08:59:53 26-Jan-2025	 09:10:32 26-Jan-2025
5	26-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P8A	 01:32:04 26-Jan-2025	 01:31:39 26-Jan-2025	 01:49:05 26-Jan-2025
6	26-01-2025	KORIDOR SHOPPING	CELLING	CELLING AREA KORIDOR SHOPPING LV.6-10	 11:14:08 26-Jan-2025	 11:14:21 26-Jan-2025	 11:14:35 26-Jan-2025







No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	26-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.6-10	 11:10:33 26-Jan-2025	 11:10:51 26-Jan-2025	 11:11:24 26-Jan-2025
8	26-01-2025	KORIDOR SHOPPING	CELLING	CELLING AREA KORIDOR SERVICE LV.LG-10	 20:13:28 26-Jan-2025	 20:15:15 26-Jan-2025	 20:15:43 26-Jan-2025
9	26-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 22 SISI BELAKANG LIFT PASSENGER LV.LG-10	 11:15:06 26-Jan-2025	 11:15:19 26-Jan-2025	 11:15:32 26-Jan-2025
10	26-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING TANAMAN HIAS SISI PILLAR KOTAK TENANT KIDS STATION LV.4 (4 PCS) LV.4	 11:09:26 26-Jan-2025	 11:09:44 26-Jan-2025	 11:09:59 26-Jan-2025
11	26-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.2-3	 11:12:48 26-Jan-2025	 11:13:01 26-Jan-2025	 11:13:17 26-Jan-2025
12	26-01-2025	KORIDOR SHOPPING	POLISHING	BUSHING KORIDOR EXIT 24 LV.3	 22:10:20 26-Jan-2025	 22:11:31 26-Jan-2025	 22:10:47 26-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	27-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP& DOWN)	 04:37:27 27-Jan-2025	 04:37:49 27-Jan-2025	 04:38:21 27-Jan-2025
2	27-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 22:23:32 27-Jan-2025	 22:24:10 27-Jan-2025	 22:24:37 27-Jan-2025
3	27-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 07:55:20 27-Jan-2025	 07:56:58 27-Jan-2025	 07:57:19 27-Jan-2025
4	27-01-2025	GUTTER	SWEEPING	GUTTER SISI IN MOBIL SISI TOTEM	 07:21:08 27-Jan-2025	 07:27:13 27-Jan-2025	 07:30:14 27-Jan-2025
5	27-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI CONECTION TP4	 04:39:38 27-Jan-2025	 04:47:12 27-Jan-2025	 04:39:57 27-Jan-2025
6	27-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI MARGOYOSO	 04:48:06 27-Jan-2025	 04:48:26 27-Jan-2025	 04:48:44 27-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	27-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P8A			
8	27-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI GRANIT BAKAR SISI MR.FOX - SISI TOBY'S LV.UG			
9	27-01-2025	KORIDOR SHOPPING	CELLING	CELLING AREA LOBBY LV.UG			
10	27-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG			
11	27-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1			
12	27-01-2025	KORIDOR SHOPPING	SWEEPING	SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	27-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 11:31:03 27-Jan-2025	 11:31:23 27-Jan-2025	 11:31:55 27-Jan-2025
14	27-01-2025	KORIDOR SHOPPING	POLISHING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 10:15:38 27-Jan-2025	 10:18:19 27-Jan-2025	 10:17:50 27-Jan-2025
15	27-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10	 11:41:43 27-Jan-2025	 11:42:21 27-Jan-2025	 11:42:06 27-Jan-2025
16	27-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5	 11:37:12 27-Jan-2025	 11:37:51 27-Jan-2025	 11:37:32 27-Jan-2025
17	27-01-2025	KORIDOR SHOPPING	POLISHING	BUSHING KORIDOR EXIT 24 LV.4	 22:22:05 27-Jan-2025	 22:22:30 27-Jan-2025	 22:22:57 27-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	28-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MEJA CONCIERGE	 05:59:12 28-Jan-2025	 02:17:27 28-Jan-2025	 05:59:36 28-Jan-2025
2	28-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 00:20:11 28-Jan-2025	 00:02:30 28-Jan-2025	 00:20:27 28-Jan-2025
3	28-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 22:23:33 28-Jan-2025	 22:11:13 28-Jan-2025	 21:57:30 28-Jan-2025
4	28-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 08:16:58 28-Jan-2025	 08:22:19 28-Jan-2025	 08:19:30 28-Jan-2025
5	28-01-2025	GUTTER	SWEEPING	GUTTER RUMP UP DROP OUT	 07:32:33 28-Jan-2025	 07:34:30 28-Jan-2025	 07:36:17 28-Jan-2025
6	28-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA P8A	 06:00:26 28-Jan-2025	 06:00:58 28-Jan-2025	 06:01:18 28-Jan-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	28-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ATAP PLAFON / HPL LV.UG	 08:10:24 28-Jan-2025	 08:11:34 28-Jan-2025	 08:12:05 28-Jan-2025
8	28-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:27:34 28-Jan-2025	 20:27:56 28-Jan-2025	 20:31:23 28-Jan-2025
9	28-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 14:42:41 28-Jan-2025	 14:43:33 28-Jan-2025	 14:43:46 28-Jan-2025
10	28-01-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN RUANG BASS ROOM LV.7	 10:15:25 28-Jan-2025	 10:17:06 28-Jan-2025	 10:15:57 28-Jan-2025
11	28-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7	 14:44:06 28-Jan-2025	 14:44:40 28-Jan-2025	 14:44:24 28-Jan-2025
12	28-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 00:25:07 28-Jan-2025	 00:43:41 28-Jan-2025	 00:28:18 28-Jan-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	28-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR EXIT 24 LV.5	 22:23:53 28-Jan-2025	 22:03:22 28-Jan-2025	 21:59:10 28-Jan-2025
14	28-01-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA BAGIAN LUAR LOBBY UTAMA LV.UG	 06:17:22 28-Jan-2025	 06:17:40 28-Jan-2025	 06:17:57 28-Jan-2025
15	28-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 06:12:13 28-Jan-2025	 06:05:47 28-Jan-2025	 06:12:32 28-Jan-2025
16	28-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 06:11:05 28-Jan-2025	 06:06:45 28-Jan-2025	 06:11:22 28-Jan-2025
17	28-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 06:09:51 28-Jan-2025	 06:08:07 28-Jan-2025	 06:10:05 28-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	29-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING	 04:03:29 29-Jan-2025	 04:04:21 29-Jan-2025	 04:04:50 29-Jan-2025
2	29-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 00:09:06 28-Jan-2025	 00:16:39 29-Jan-2025	 00:16:21 29-Jan-2025
3	29-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.6&7	 22:28:52 29-Jan-2025	 22:29:07 29-Jan-2025	 22:29:53 29-Jan-2025
4	29-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5	 13:37:29 29-Jan-2025	 13:38:53 29-Jan-2025	 13:38:30 29-Jan-2025
5	29-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER ENTRANCE	 07:17:56 29-Jan-2025	 07:18:45 29-Jan-2025	 07:36:35 29-Jan-2025
6	29-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA LG	 06:36:33 29-Jan-2025	 06:37:09 29-Jan-2025	 06:37:30 29-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	29-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN RUANG GREASE TRAP			
8	29-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3			
9	29-01-2025	KORIDOR SHOPPING	WASHING	PEMBERSIHAN TRASHCAN LV.UG-LV.10			
10	29-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5			
11	29-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.5			
12	29-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	29-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 23:46:24 28-Jan-2025	 00:47:18 29-Jan-2025	 00:23:26 29-Jan-2025
14	29-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 00:26:00 29-Jan-2025	 00:52:45 29-Jan-2025	 01:03:35 29-Jan-2025
15	29-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 04:06:30 29-Jan-2025	 04:07:34 29-Jan-2025	 04:06:48 29-Jan-2025
16	29-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 04:08:04 29-Jan-2025	 04:05:35 29-Jan-2025	 04:08:25 29-Jan-2025
17	29-01-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 04:08:54 29-Jan-2025	 04:05:59 29-Jan-2025	 04:09:14 29-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	30-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 07:27:45 30-Jan-2025	 07:28:26 30-Jan-2025	 07:28:08 30-Jan-2025
2	30-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 07:29:09 30-Jan-2025	 07:29:25 30-Jan-2025	 07:29:44 30-Jan-2025
3	30-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.9&10	 22:18:53 30-Jan-2025	 22:20:47 30-Jan-2025	 22:19:37 30-Jan-2025
4	30-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 14:26:27 30-Jan-2025	 14:28:09 30-Jan-2025	 14:27:06 30-Jan-2025
5	30-01-2025	GUTTER	SWEEPING	PEMBERSIHAN GUTTER SISI BAWAH MR.FOX	 07:17:47 30-Jan-2025	 07:20:18 30-Jan-2025	 07:20:45 30-Jan-2025
6	30-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA LG	 00:54:20 30-Jan-2025	 00:54:42 30-Jan-2025	 00:55:46 30-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	30-01-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 14:41:19 30-Jan-2025	 14:41:39 30-Jan-2025	 14:43:11 30-Jan-2025
8	30-01-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:26:22 30-Jan-2025	 22:26:53 30-Jan-2025	 22:27:20 30-Jan-2025
9	30-01-2025	KORIDOR SHOPPING	SPOTTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 14:29:00 30-Jan-2025	 14:30:18 30-Jan-2025	 14:29:55 30-Jan-2025
10	30-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.4	 22:22:20 30-Jan-2025	 22:24:18 30-Jan-2025	 22:22:47 30-Jan-2025
11	30-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10	 14:39:05 30-Jan-2025	 14:39:47 30-Jan-2025	 14:39:25 30-Jan-2025
12	30-01-2025	KORIDOR SHOPPING	POLISHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 07:31:02 30-Jan-2025	 07:31:22 30-Jan-2025	 07:31:38 30-Jan-2025

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
13	30-01-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.UG	 23:33:14 29-Jan-2025	 03:50:54 30-Jan-2025	 05:27:10 30-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	31-01-2025	KRISTALISASI KORIDOR LT.UG	KRISTALISASI	KRISTALISASI AREA TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG			
2	31-01-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)			
3	31-01-2025	CARPARK	POLISHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.1&2			
4	31-01-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9			
5	31-01-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN CARPARK AREA LG			
6	31-01-2025	KORIDOR SHOPPING	POLISHING	GENERAL CLEANING AREA TOILET LV.3			

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
7	31-01-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.5	 02:24:17 31-Jan-2025	 07:53:10 31-Jan-2025	 07:55:17 31-Jan-2025