










No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	05-01-2025	BASEMANT 2	DUSTING	SPRINKLER	 14:51:09 05-Jan-2025	 14:51:25 05-Jan-2025	 14:52:56 05-Jan-2025
2	05-01-2025	LOBBY GF	GENERAL CLEANING	TOILET LOBBY	 14:44:50 05-Jan-2025	 14:45:07 05-Jan-2025	 14:47:50 05-Jan-2025
3	05-01-2025	CARPARK P1 -LM	SCRUBBING	LANTAI CONCRETE	 15:09:41 05-Jan-2025	 15:11:12 05-Jan-2025	 15:11:51 05-Jan-2025
4	05-01-2025	CARPARK P1 -LM	SCRUBBING	LANTAI CONCRETE	 14:56:37 05-Jan-2025	 15:00:02 05-Jan-2025	 15:01:09 05-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	06-01-2025	CARPARK P4 - P2	BRUSHING	CAR STOPPER	 16:57:43 06-Jan-2025	 16:58:17 06-Jan-2025	 16:59:39 06-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	07-01-2025	BASEMANT 1	BRUSHING	DAK ISLAND	 10:31:31 07-Jan-2025	 10:33:50 07-Jan-2025	 10:35:47 07-Jan-2025
2	07-01-2025	BASEMANT 1	WASHING	CANSTEEN	 13:06:17 07-Jan-2025	 13:05:58 07-Jan-2025	 13:07:16 07-Jan-2025
3	07-01-2025	CARPARK P4 - P2	JET SPRAYING	RAMP NAIK TURUN	 15:46:31 07-Jan-2025	 15:46:50 07-Jan-2025	 15:47:18 07-Jan-2025
4	07-01-2025	KORIDOR LANTAI 2-18	DUSTING	KAP LAMPU	 10:36:13 07-Jan-2025	 10:36:42 07-Jan-2025	 10:38:11 07-Jan-2025
5	07-01-2025	KORIDOR LANTAI 2-18	HIGH DUSTING	SPEAKER	 10:41:37 07-Jan-2025	 10:42:08 07-Jan-2025	 10:42:40 07-Jan-2025
6	07-01-2025	KORIDOR LANTAI 2-18	HIGH DUSTING	GRILL AC	 10:35:43 07-Jan-2025	 10:37:06 07-Jan-2025	 10:37:36 07-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	09-01-2025	BASEMANT 2	SPOTTING	DAK RAMP			
2	09-01-2025	LOBBY GF	WALL CLEANING	DINDING			
3	09-01-2025	CARPARK P1 -LM	HIGH DUSTING	PIPAPLUMBING			
4	09-01-2025	HALAMAN1	GENERAL CLEANING	LOGO			
5	09-01-2025	CARPARK P1 -LM	HIGH DUSTING	PIPAPLUMBING			
6	09-01-2025	KORIDOR LANTAI 2-18	WALL CLEANING	DINDING KORIDOR			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	10-01-2025	CARPARK P1 -LM	HIGH DUSTING	SIGNAGE GANTUNG			
2	10-01-2025	CARPARK P4 - P2	HIGH DUSTING	PIPA PLUMBING			
3	10-01-2025	CARPARK P1 -LM	HIGH DUSTING	SIGNAGE GANTUNG			
4	10-01-2025	KORIDOR LANTAI 2-18	POLISHING	LIFT			
5	10-01-2025	CARPARK P4 - P2	HIGH DUSTING	PIPA PLUMBING			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	11-01-2025	BASEMANT 2	DUSTING	PIPA PVC	 07:38:20 11-Jan-2025	 07:40:37 11-Jan-2025	 08:29:49 11-Jan-2025
2	11-01-2025	LOBBY GF	ROC	CEILING	 08:34:14 11-Jan-2025	 08:34:56 11-Jan-2025	 08:35:15 11-Jan-2025
3	11-01-2025	LOBBY GF	HIGH DUSTING	EXHAUST GRILL	 08:24:05 11-Jan-2025	 08:24:24 11-Jan-2025	 08:24:42 11-Jan-2025
4	11-01-2025	CARPARK P1 -LM	WASHING	DAK ISLAND	 13:09:25 11-Jan-2025	 13:10:44 11-Jan-2025	 13:13:03 11-Jan-2025
5	11-01-2025	CARPARK P4 - P2	HIGH DUSTING	SIGNAGE GANTUNG	 13:17:34 11-Jan-2025	 13:17:52 11-Jan-2025	 13:18:21 11-Jan-2025
6	11-01-2025	HALAMAN1	GENERAL CLEANING	FOUNTAIN-KOLAM	 08:26:14 11-Jan-2025	 08:26:52 11-Jan-2025	 08:27:15 11-Jan-2025






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	11-01-2025	HALAMAN1	BRUSHING	LANTAI BATU ANDESIT	 13:26:09 11-Jan-2025	 13:28:12 11-Jan-2025	 13:28:35 11-Jan-2025
8	11-01-2025	CARPARK P1 -LM	WASHING	DAK ISLAND	 13:14:47 11-Jan-2025	 13:20:03 11-Jan-2025	 13:22:41 11-Jan-2025
9	11-01-2025	CARPARK P4 - P2	HIGH DUSTING	SIGNAGE GANTUNG	 07:35:36 11-Jan-2025	 07:36:10 11-Jan-2025	 07:36:34 11-Jan-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	12-01-2025	BASEMANT 1	JET SPRAYING	RAMP NAIK TURUN	 08:34:07 12-Jan-2025	 08:34:35 12-Jan-2025	 09:45:24 12-Jan-2025
2	12-01-2025	BASEMANT 2	DUSTING	SPRINKLER	 13:25:38 12-Jan-2025	 13:29:30 12-Jan-2025	 13:30:21 12-Jan-2025
3	12-01-2025	LOBBY GF	GENERAL CLEANING	TOILET LOBBY	 08:15:11 12-Jan-2025	 08:15:57 12-Jan-2025	 08:18:36 12-Jan-2025
4	12-01-2025	CARPARK P1 -LM	SCRUBBING	LANTAI CONCRETE	 13:04:42 12-Jan-2025	 13:05:38 12-Jan-2025	 13:05:58 12-Jan-2025
5	12-01-2025	CARPARK P4 - P2	SPOTTING	PILAR	 13:06:34 12-Jan-2025	 13:06:48 12-Jan-2025	 13:07:23 12-Jan-2025
6	12-01-2025	CARPARK P1 -LM	SCRUBBING	LANTAI CONCRETE	 13:07:57 12-Jan-2025	 13:12:37 12-Jan-2025	 13:13:16 12-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	13-01-2025	CARPARK P4 - P2	BRUSHING	CAR STOPPER			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	14-01-2025	BASEMANT 1	WASHING	CANSTEEN			
2	14-01-2025	KORIDOR LANTAI 2-18	HIGH DUSTING	SPEAKER			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	15-01-2025	BASEMANT 1	HIGH DUSTING	PIPA PLUMBING			
2	15-01-2025	BASEMANT 2	SCRUBBING	LOT PARKIR			
3	15-01-2025	BASEMANT 2	SCRUBBING	JALUR DRIVEWAY			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	16-01-2025	BASEMANT 1	SPOTTING	DINDING	 10:54:37 16-Jan-2025	 10:55:00 16-Jan-2025	 10:55:20 16-Jan-2025
2	16-01-2025	BASEMANT 2	SPOTTING	DINDING RAMP	 12:02:36 16-Jan-2025	 12:03:12 16-Jan-2025	 12:04:24 16-Jan-2025
3	16-01-2025	CARPARK P1 -LM	HIGH DUSTING	PIPA PLUMBING	 12:37:36 16-Jan-2025	 12:38:15 16-Jan-2025	 12:38:46 16-Jan-2025
4	16-01-2025	HALAMAN 1	GENERAL CLEANING	LOGO	 10:57:59 16-Jan-2025	 10:58:23 16-Jan-2025	 10:58:44 16-Jan-2025
5	16-01-2025	CARPARK P1 -LM	HIGH DUSTING	PIPA PLUMBING	 17:01:13 16-Jan-2025	 17:02:04 16-Jan-2025	 17:02:31 16-Jan-2025
6	16-01-2025	KORIDOR LANTAI 2-18	GLASS CLEANING	KACA	 10:52:08 16-Jan-2025	 10:52:46 16-Jan-2025	 10:53:18 16-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	17-01-2025	BASEMANT 1	HIGH DUSTING	SIGNAGE GANTUNG	 21:52:05 17-Jan-2025	 21:50:59 17-Jan-2025	 21:52:30 17-Jan-2025
2	17-01-2025	CARPARK P1-LM	HIGH DUSTING	SIGNAGE GANTUNG	 13:20:11 17-Jan-2025	 13:20:51 17-Jan-2025	 13:24:30 17-Jan-2025
3	17-01-2025	CARPARK P1-LM	HIGH DUSTING	SIGNAGE GANTUNG	 13:32:14 17-Jan-2025	 13:37:03 17-Jan-2025	 13:40:15 17-Jan-2025
4	17-01-2025	KORIDOR LANTAI 2-18	POLISHING	LIFT	 19:37:21 17-Jan-2025	 19:38:06 17-Jan-2025	 19:38:41 17-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	19-01-2025	CARPARK P1 -LM	SCRUBBING	LANTAI CONCRETE	 13:42:35 19-Jan-2025	 13:43:51 19-Jan-2025	 14:27:32 19-Jan-2025
2	19-01-2025	CARPARK P4 - P2	SPOTTING	PILAR	 12:46:21 19-Jan-2025	 12:47:24 19-Jan-2025	 12:48:02 19-Jan-2025
3	19-01-2025	CARPARK P1 -LM	SCRUBBING	LANTAI CONCRETE	 09:49:36 19-Jan-2025	 12:32:44 19-Jan-2025	 13:10:24 19-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	20-01-2025	CARPARK P4 - P2	BRUSHING	CAR STOPPER			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	21-01-2025	BASEMANT 1	BRUSHING	DAK ISLAND	 15:50:20 21-Jan-2025	 15:50:45 21-Jan-2025	 15:52:18 21-Jan-2025
2	21-01-2025	CARPARK P4 - P2	JET SPRAYING	RAMP NAIK TURUN	 08:57:33 21-Jan-2025	 08:57:49 21-Jan-2025	 08:58:20 21-Jan-2025
3	21-01-2025	KORIDOR LANTAI 2-18	DUSTING	KAP LAMPU	 09:11:46 21-Jan-2025	 09:12:07 21-Jan-2025	 09:12:29 21-Jan-2025
4	21-01-2025	KORIDOR LANTAI 2-18	HIGH DUSTING	SPEAKER	 08:55:39 21-Jan-2025	 08:56:01 21-Jan-2025	 08:56:31 21-Jan-2025
5	21-01-2025	KORIDOR LANTAI 2-18	HIGH DUSTING	GRILL AC	 09:08:13 21-Jan-2025	 09:08:40 21-Jan-2025	 09:09:53 21-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	23-01-2025	BASEMANT 2	SPOTTING	DAK RAMP			
2	23-01-2025	LOBBY GF	WALL CLEANING	DINDING			
3	23-01-2025	KORIDOR LANTAI 2-18	WALL CLEANING	DINDING KORIDOR			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	24-01-2025	CARPARK P4 - P2	HIGH DUSTING	PIPA PLUMBING			
2	24-01-2025	CARPARK P4 - P2	HIGH DUSTING	PIPA PLUMBING			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	26-01-2025	BASEMANT 1	JET SPRAYING	RAMP NAIK TURUN	 08:12:37 26-Jan-2025	 08:17:14 26-Jan-2025	 08:17:31 26-Jan-2025
2	26-01-2025	BASEMANT 2	DUSTING	SPRINKLER	 14:25:24 26-Jan-2025	 14:26:03 26-Jan-2025	 14:26:32 26-Jan-2025
3	26-01-2025	LOBBY GF	GENERAL CLEANING	TOILET LOBBY	 11:55:36 26-Jan-2025	 11:56:11 26-Jan-2025	 11:57:08 26-Jan-2025
4	26-01-2025	CARPARK P4 - P2	SPOTTING	PILAR	 11:51:50 26-Jan-2025	 11:52:31 26-Jan-2025	 11:53:37 26-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	28-01-2025	BASEMANT 1	BRUSHING	DAK ISLAND	 15:26:29 28-Jan-2025	 15:26:50 28-Jan-2025	 15:27:09 28-Jan-2025
2	28-01-2025	BASEMANT 1	WASHING	CANSTEEN	 15:24:59 28-Jan-2025	 15:25:35 28-Jan-2025	 15:26:04 28-Jan-2025
3	28-01-2025	CARPARK P4 - P2	JET SPRAYING	RAMP NAIK TURUN	 13:58:11 28-Jan-202	 13:58:30 28-Jan-202	 13:58:46 28-Jan-202
4	28-01-2025	KORIDOR LANTAI 2-18	DUSTING	KAP LAMPU	 13:54:55 28-Jan-202	 13:55:27 28-Jan-202	 13:56:26 28-Jan-202
5	28-01-2025	KORIDOR LANTAI 2-18	HIGH DUSTING	GRILL AC	 13:59:32 28-Jan-202	 13:59:51 28-Jan-202	 14:00:25 28-Jan-202

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	29-01-2025	BASEMANT 1	HIGH DUSTING	PIPA PLUMBING	 17:30:27 29-Jan-2025	 17:30:45 29-Jan-2025	 17:31:17 29-Jan-2025
2	29-01-2025	BASEMANT 2	SCRUBBING	LOT PARKIR	 10:42:42 29-Jan-2025	 10:56:34 29-Jan-2025	 13:32:30 29-Jan-2025
3	29-01-2025	BASEMANT 2	SCRUBBING	JALUR DRIVEWAY	 10:34:21 29-Jan-2025	 10:38:03 29-Jan-2025	 13:26:59 29-Jan-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	30-01-2025	BASEMANT 1	SPOTTING	DINDING			
2	30-01-2025	BASEMANT 2	SPOTTING	DINDING RAMP			
3	30-01-2025	KORIDOR LANTAI 2-18	GLASS CLEANING	KACA			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	31-01-2025	BASEMANT 1	HIGH DUSTING	SIGNAGE GANTUNG			