














No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	02-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 12:37:54 02-Jun-2025	 12:38:07 02-Jun-2025	 12:38:21 02-Jun-2025
2	02-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4	 07:03:33 02-Jun-2025	 07:03:48 02-Jun-2025	 07:04:00 02-Jun-2025
3	02-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 07:04:30 02-Jun-2025	 07:04:45 02-Jun-2025	 07:04:56 02-Jun-2025
4	02-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI SPIRAL UP&DOWN	 08:25:22 02-Jun-2025	 08:26:34 02-Jun-2025	 08:28:15 02-Jun-2025
5	02-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 07:02:30 02-Jun-2025	 07:02:42 02-Jun-2025	 07:02:53 02-Jun-2025
6	02-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 07:05:55 02-Jun-2025	 07:05:29 02-Jun-2025	 07:06:07 02-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	02-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A	 07:06:44 02-Jun-2025	 07:06:53 02-Jun-2025	 07:07:05 02-Jun-2025
8	02-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 20:13:46 02-Jun-2025	 20:14:00 02-Jun-2025	 20:14:17 02-Jun-2025
9	02-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 02:39:50 02-Jun-2025	 02:41:56 02-Jun-2025	 03:49:47 02-Jun-2025
10	02-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 11:26:55 02-Jun-2025	 11:27:30 02-Jun-2025	 11:27:57 02-Jun-2025
11	02-06-2025	KORIDOR SHOPPING	CELLING	CELLING AREA LOBBY LV.UG	 12:39:11 02-Jun-2025	 12:39:22 02-Jun-2025	 12:39:34 02-Jun-2025
12	02-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 11:17:24 02-Jun-2025	 11:20:51 02-Jun-2025	 11:18:34 02-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	02-06-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT UNION LV.UG	 08:07:25 02-Jun-2025	 08:07:39 02-Jun-2025	 08:07:53 02-Jun-2025
14	02-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:16:00 02-Jun-2025	 20:07:14 02-Jun-2025	 20:15:15 02-Jun-2025
15	02-06-2025	KORIDOR SHOPPING	SWEEPING	SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10	 12:41:05 02-Jun-2025	 12:41:15 02-Jun-2025	 12:41:24 02-Jun-2025
16	02-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 11:46:14 02-Jun-2025	 11:47:00 02-Jun-2025	 11:48:53 02-Jun-2025
17	02-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5	 11:50:16 02-Jun-2025	 11:50:46 02-Jun-2025	 11:50:33 02-Jun-2025
18	02-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 12:37:10 02-Jun-2025	 12:37:21 02-Jun-2025	 12:37:33 02-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	02-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 20:05:41 02-Jun-2025	 20:06:03 02-Jun-2025	 20:06:45 02-Jun-2025
20	02-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 11:40:20 02-Jun-2025	 11:40:44 02-Jun-2025	 11:41:06 02-Jun-2025
21	02-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 11:44:46 02-Jun-2025	 11:45:13 02-Jun-2025	 11:45:00 02-Jun-2025
22	02-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 11:38:29 02-Jun-2025	 11:38:58 02-Jun-2025	 11:39:10 02-Jun-2025
23	02-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10	 20:07:59 02-Jun-2025	 20:08:18 02-Jun-2025	 20:08:51 02-Jun-2025
24	02-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10	 12:40:02 02-Jun-2025	 12:40:16 02-Jun-2025	 12:40:28 02-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	02-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR EXIT LV.LG-10	 11:51:41 02-Jun-2025	 11:52:07 02-Jun-2025	 11:52:19 02-Jun-2025
26	02-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4	 11:23:48 02-Jun-2025	 11:24:13 02-Jun-2025	 11:24:35 02-Jun-2025
27	02-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 20:12:22 02-Jun-2025	 20:13:02 02-Jun-2025	 20:13:21 02-Jun-2025
28	02-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 20:20:29 02-Jun-2025	 20:21:03 02-Jun-2025	 20:21:14 02-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	03-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:07:30 03-Jun-2025	 07:07:56 03-Jun-2025	 07:09:35 03-Jun-2025
2	03-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 08:00:55 03-Jun-2025	 08:01:18 03-Jun-2025	 08:02:09 03-Jun-2025
3	03-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA VALET LV.UG	 08:03:38 03-Jun-2025	 08:02:32 03-Jun-2025	 08:03:48 03-Jun-2025
4	03-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 08:04:15 03-Jun-2025	 08:04:28 03-Jun-2025	 08:04:44 03-Jun-2025
5	03-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:55:43 03-Jun-2025	 22:02:16 03-Jun-2025	 22:02:34 03-Jun-2025
6	03-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 11:52:48 03-Jun-2025	 11:53:04 03-Jun-2025	 11:53:20 03-Jun-2025



No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
7	03-06-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT TOBY'S LV.UG	 07:59:07 03-Jun-2025	 07:59:25 03-Jun-2025	 07:59:40 03-Jun-2025
8	03-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 01:03:30 03-Jun-2025	 01:27:57 03-Jun-2025	 01:43:26 03-Jun-2025
9	03-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:48:20 03-Jun-2025	 20:49:03 03-Jun-2025	 20:50:24 03-Jun-2025
10	03-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 12:03:58 03-Jun-2025	 12:04:09 03-Jun-2025	 12:04:19 03-Jun-2025
11	03-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7	 12:03:02 03-Jun-2025	 12:03:15 03-Jun-2025	 12:03:28 03-Jun-2025
12	03-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 11:56:55 03-Jun-2025	 11:57:05 03-Jun-2025	 11:57:20 03-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	03-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 11:55:18 03-Jun-2025	 11:54:57 03-Jun-2025	 11:55:32 03-Jun-2025
14	03-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 11:55:57 03-Jun-2025	 11:56:08 03-Jun-2025	 11:56:24 03-Jun-2025
15	03-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 11:58:24 03-Jun-2025	 11:58:13 03-Jun-2025	 11:57:57 03-Jun-2025
16	03-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 11:53:50 03-Jun-2025	 11:54:08 03-Jun-2025	 11:54:21 03-Jun-2025
17	03-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 22:04:16 03-Jun-2025	 22:05:36 03-Jun-2025	 22:11:13 03-Jun-2025
18	03-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:09:17 03-Jun-2025	 10:10:03 03-Jun-2025	 10:09:34 03-Jun-2025



No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	03-06-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG	 08:37:03 03-Jun-2025	 08:38:22 03-Jun-2025	 08:37:23 03-Jun-2025
20	03-06-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG	 08:40:01 03-Jun-2025	 08:39:34 03-Jun-2025	 08:40:30 03-Jun-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	04-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE			
2	04-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)			
3	04-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG			
4	04-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG			
5	04-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG			
6	04-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	04-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 09:20:47 04-Jun-2025	 10:27:30 04-Jun-2025	 09:21:34 04-Jun-2025
8	04-06-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 01:48:31 04-Jun-2025	 01:48:47 04-Jun-2025	 01:49:10 04-Jun-2025
9	04-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 01:44:55 04-Jun-2025	 01:45:08 04-Jun-2025	 01:45:20 04-Jun-2025
10	04-06-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA ATAS PINTU REVOLVING LOBBY LV.UG	 01:49:48 04-Jun-2025	 01:50:02 04-Jun-2025	 01:50:18 04-Jun-2025
11	04-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 01:42:33 04-Jun-2025	 01:42:49 04-Jun-2025	 01:43:04 04-Jun-2025
12	04-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 01:43:27 04-Jun-2025	 01:43:39 04-Jun-2025	 01:43:51 04-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	04-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3			
14	04-06-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10			
15	04-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5			
16	04-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9			
17	04-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5			
18	04-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	04-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10	 09:12:54 04-Jun-2025	 10:25:54 04-Jun-2025	 09:13:24 04-Jun-2025
20	04-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10	 09:11:15 04-Jun-2025	 10:25:02 04-Jun-2025	 09:11:46 04-Jun-2025
21	04-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5	 22:40:19 04-Jun-2025	 22:40:41 04-Jun-2025	 22:42:21 04-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	05-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI BAWAH UNION	 07:12:20 05-Jun-2025	 07:12:59 05-Jun-2025	 07:14:44 05-Jun-2025
2	05-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 06:46:47 05-Jun-2025	 06:47:07 05-Jun-2025	 06:48:05 05-Jun-2025
3	05-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SISI DEPAN TENANT UNION DAN DEPAN TENANT TOBBY'S & AREA DEPAN CONCIERGE LV.UG	 06:51:13 05-Jun-2025	 06:50:53 05-Jun-2025	 06:51:24 05-Jun-2025
4	05-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 06:56:39 05-Jun-2025	 06:55:29 05-Jun-2025	 06:56:50 05-Jun-2025
5	05-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 06:57:31 05-Jun-2025	 06:57:42 05-Jun-2025	 06:57:56 05-Jun-2025
6	05-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10	 22:43:49 05-Jun-2025	 22:43:57 05-Jun-2025	 22:44:07 05-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	05-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10	 11:16:02 05-Jun-2025	 11:16:41 05-Jun-2025	 11:17:10 05-Jun-2025
8	05-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P6A	 06:59:19 05-Jun-2025	 06:59:29 05-Jun-2025	 06:59:41 05-Jun-2025
9	05-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 22:42:08 05-Jun-2025	 22:42:20 05-Jun-2025	 22:42:30 05-Jun-2025
10	05-06-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA CANOPY + GUTTER LV.UG	 07:01:53 05-Jun-2025	 07:02:15 05-Jun-2025	 07:02:31 05-Jun-2025
11	05-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 23:49:32 04-Jun-2025	 23:53:55 04-Jun-2025	 00:25:25 05-Jun-2025
12	05-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:41:41 05-Jun-2025	 22:41:49 05-Jun-2025	 22:41:57 05-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	05-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 11:26:43 05-Jun-2025	 11:29:29 05-Jun-2025	 11:27:27 05-Jun-2025
14	05-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10	 11:33:27 05-Jun-2025	 11:33:59 05-Jun-2025	 11:33:39 05-Jun-2025
15	05-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 11:21:37 05-Jun-2025	 11:22:47 05-Jun-2025	 11:22:07 05-Jun-2025
16	05-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4	 22:42:52 05-Jun-2025	 22:43:02 05-Jun-2025	 22:43:10 05-Jun-2025
17	05-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.4	 22:41:12 05-Jun-2025	 22:41:21 05-Jun-2025	 22:41:31 05-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	06-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)	 03:38:17 06-Jun-2025	 03:38:37 06-Jun-2025	 03:39:06 06-Jun-2025
2	06-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SISI DALAM CONCIERGE S/D DEPAN SERVICE KORIDOR LV.UG	 03:36:45 06-Jun-2025	 03:35:30 06-Jun-2025	 03:37:07 06-Jun-2025
3	06-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 03:41:32 06-Jun-2025	 03:40:24 06-Jun-2025	 03:41:51 06-Jun-2025
4	06-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2	 20:48:21 06-Jun-2025	 20:47:42 06-Jun-2025	 20:48:42 06-Jun-2025
5	06-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2	 11:39:35 06-Jun-2025	 11:40:05 06-Jun-2025	 11:40:43 06-Jun-2025
6	06-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7A	 00:10:15 06-Jun-2025	 00:11:19 06-Jun-2025	 00:10:58 06-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	06-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 11:42:28 06-Jun-2025	 11:43:00 06-Jun-2025	 11:42:38 06-Jun-2025
8	06-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG	 11:35:33 06-Jun-2025	 11:36:19 06-Jun-2025	 11:36:57 06-Jun-2025
9	06-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.3	 20:49:40 06-Jun-2025	 20:51:19 06-Jun-2025	 20:50:48 06-Jun-2025
10	06-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN HPL AREA LOBBY LV.UG	 03:44:04 06-Jun-2025	 03:45:05 06-Jun-2025	 03:44:45 06-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	07-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI OUT MOBIL	 19:15:23 07-Jun-2025	 19:15:32 07-Jun-2025	 19:15:41 07-Jun-2025
2	07-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 06:45:53 07-Jun-2025	 06:46:07 07-Jun-2025	 06:46:29 07-Jun-2025
3	07-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)	 06:47:23 07-Jun-2025	 06:48:02 07-Jun-2025	 06:48:14 07-Jun-2025
4	07-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SISI DEPAN TENANT BENEFIT S/D LED PROMO LV.UG	 06:55:22 07-Jun-2025	 06:48:58 07-Jun-2025	 06:55:35 07-Jun-2025
5	07-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 06:54:31 07-Jun-2025	 06:51:24 07-Jun-2025	 06:54:46 07-Jun-2025
6	07-06-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LT.1 & 2	 06:52:20 07-Jun-2025	 06:52:33 07-Jun-2025	 06:52:45 07-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	07-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI KURSI BENCH MARMER LV.UG			
8	07-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
9	07-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
10	07-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.LG			
11	07-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7B			
12	07-06-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN SELA SELA PINTU LIFT PASSENGER LV.UG-10			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	07-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5	 11:01:17 07-Jun-2025	 11:02:15 07-Jun-2025	 11:01:42 07-Jun-2025
14	07-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.10	 11:03:08 07-Jun-2025	 11:03:35 07-Jun-2025	 11:03:17 07-Jun-2025
15	07-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5	 10:35:10 07-Jun-2025	 10:35:25 07-Jun-2025	 10:36:36 07-Jun-2025
16	07-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LED PROMO LV.1 S.D LV.4	 10:55:32 07-Jun-2025	 10:59:57 07-Jun-2025	 10:59:10 07-Jun-2025
17	07-06-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN PLANTER BOX LV.UG	 10:45:16 07-Jun-2025	 10:46:07 07-Jun-2025	 10:45:45 07-Jun-2025
18	07-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1	 10:43:59 07-Jun-2025	 10:44:25 07-Jun-2025	 10:44:13 07-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	07-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.UG S.D LV.5	 19:17:13 07-Jun-2025	 19:17:25 07-Jun-2025	 19:17:35 07-Jun-2025
20	07-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.5	 10:32:48 07-Jun-2025	 10:33:23 07-Jun-2025	 10:34:12 07-Jun-2025
21	07-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SERVICE LV.6-10	 19:16:37 07-Jun-2025	 19:16:47 07-Jun-2025	 19:16:56 07-Jun-2025
22	07-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.UG	 10:40:43 07-Jun-2025	 10:41:15 07-Jun-2025	 10:41:48 07-Jun-2025
23	07-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.UG	 21:00:34 07-Jun-2025	 20:37:43 07-Jun-2025	 21:10:31 07-Jun-2025
24	07-06-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2	 10:53:05 07-Jun-2025	 10:53:37 07-Jun-2025	 10:53:22 07-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	07-06-2025	KORIDOR SHOPPING	DUSTING	DINDING BAGIAN LUAR LOBBY LV.UG	 06:59:21 07-Jun-2025	 06:59:32 07-Jun-2025	 06:59:52 07-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	08-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.7-9 (UP&DOWN)			
2	08-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.9-10 (UP&DOWN)			
3	08-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SISI LED PROMO/DEPAN TENANT SALAD STOP S/D TRAP TANGGA OMEGA LV.UG			
4	08-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.UG			
5	08-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			
6	08-06-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR TOILET LV.UG			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	08-06-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.UG	 08:20:42 08-Jun-2025	 08:18:51 08-Jun-2025	 08:20:57 08-Jun-2025
8	08-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 04:11:21 08-Jun-2025	 04:11:35 08-Jun-2025	 04:11:47 08-Jun-2025
9	08-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.3	 20:54:21 08-Jun-2025	 21:10:08 08-Jun-2025	 20:54:08 08-Jun-2025
10	08-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.3	 10:43:25 08-Jun-2025	 10:43:34 08-Jun-2025	 10:44:00 08-Jun-2025
11	08-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.8	 08:39:06 08-Jun-2025	 08:40:55 08-Jun-2025	 08:51:27 08-Jun-2025
12	08-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P8A	 04:18:46 08-Jun-2025	 04:19:01 08-Jun-2025	 04:19:12 08-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	08-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.6- 10	 10:58:32 08-Jun-2025	 10:59:12 08-Jun-2025	 10:58:43 08-Jun-2025
14	08-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.6	 10:55:49 08-Jun-2025	 10:56:13 08-Jun-2025	 10:56:42 08-Jun-2025
15	08-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.2 & 3	 10:47:27 08-Jun-2025	 10:47:50 08-Jun-2025	 10:47:39 08-Jun-2025
16	08-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.6 S.D LV.10	 19:59:25 08-Jun-2025	 20:08:21 08-Jun-2025	 20:07:12 08-Jun-2025
17	08-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.6	 10:51:51 08-Jun-2025	 10:52:15 08-Jun-2025	 10:55:24 08-Jun-2025
18	08-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SERVICE LV.1-5	 20:58:16 08-Jun-2025	 21:14:23 08-Jun-2025	 20:59:22 08-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	08-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.3	 10:45:24 08-Jun-2025	 10:45:51 08-Jun-2025	 10:46:25 08-Jun-2025
20	08-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.3	 20:57:44 08-Jun-2025	 21:10:30 08-Jun-2025	 20:57:28 08-Jun-2025
21	08-06-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.3-4-5	 10:48:33 08-Jun-2025	 10:48:58 08-Jun-2025	 10:48:49 08-Jun-2025
22	08-06-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA BAGIAN LUAR LOBBY UTAMA LV.UG	 12:02:48 08-Jun-2025	 12:03:12 08-Jun-2025	 12:03:38 08-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	09-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 14:36:18 09-Jun-2025	 14:36:55 09-Jun-2025	 14:37:16 09-Jun-2025
2	09-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4	 07:08:15 09-Jun-2025	 07:09:50 09-Jun-2025	 07:10:16 09-Jun-2025
3	09-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 07:14:09 09-Jun-2025	 07:14:24 09-Jun-2025	 07:14:41 09-Jun-2025
4	09-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 07:18:40 09-Jun-2025	 07:19:10 09-Jun-2025	 07:19:38 09-Jun-2025
5	09-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.1	 07:21:29 09-Jun-2025	 07:20:30 09-Jun-2025	 07:21:06 09-Jun-2025
6	09-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 07:28:05 09-Jun-2025	 07:22:10 09-Jun-2025	 07:28:17 09-Jun-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	09-06-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.3			
8	09-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B			
9	09-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4			
10	09-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG			
11	09-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4			
12	09-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	09-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:20:32 09-Jun-2025	 20:20:52 09-Jun-2025	 20:21:17 09-Jun-2025
14	09-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 11:55:24 09-Jun-2025	 11:55:13 09-Jun-2025	 11:55:34 09-Jun-2025
15	09-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 11:54:20 09-Jun-2025	 11:54:34 09-Jun-2025	 11:54:49 09-Jun-2025
16	09-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 11:44:42 09-Jun-2025	 11:45:08 09-Jun-2025	 11:46:28 09-Jun-2025
17	09-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 11:27:27 09-Jun-2025	 11:27:49 09-Jun-2025	 11:29:10 09-Jun-2025
18	09-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 11:39:30 09-Jun-2025	 11:40:12 09-Jun-2025	 11:39:46 09-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	09-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 11:24:43 09-Jun-2025	 11:25:20 09-Jun-2025	 11:26:10 09-Jun-2025
20	09-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4	 11:37:00 09-Jun-2025	 11:37:30 09-Jun-2025	 11:38:05 09-Jun-2025
21	09-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 21:11:01 09-Jun-2025	 21:30:46 09-Jun-2025	 21:11:24 09-Jun-2025
22	09-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ORNAMENT PLAFON HPL LV.5	 07:25:47 09-Jun-2025	 07:26:01 09-Jun-2025	 07:26:13 09-Jun-2025
23	09-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 20:22:21 09-Jun-2025	 20:21:53 09-Jun-2025	 20:22:07 09-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	10-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:14:29 10-Jun-2025	 07:15:17 10-Jun-2025	 07:17:29 10-Jun-2025
2	10-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 07:50:16 10-Jun-2025	 07:50:28 10-Jun-2025	 07:50:42 10-Jun-2025
3	10-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA CONCIERGE LV.UG	 07:42:48 10-Jun-2025	 07:43:03 10-Jun-2025	 07:43:17 10-Jun-2025
4	10-06-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.4	 07:40:28 10-Jun-2025	 07:40:06 10-Jun-2025	 07:40:46 10-Jun-2025
5	10-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 07:43:43 10-Jun-2025	 07:43:54 10-Jun-2025	 07:44:09 10-Jun-2025
6	10-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:47:57 10-Jun-2025	 21:48:33 10-Jun-2025	 21:48:55 10-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	10-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 11:36:48 10-Jun-2025	 11:37:08 10-Jun-2025	 11:37:25 10-Jun-2025
8	10-06-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LT.6-4	 07:51:16 10-Jun-2025	 07:51:29 10-Jun-2025	 07:51:46 10-Jun-2025
9	10-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 00:51:00 10-Jun-2025	 00:54:13 10-Jun-2025	 01:19:38 10-Jun-2025
10	10-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:49:10 10-Jun-2025	 20:50:06 10-Jun-2025	 20:48:22 10-Jun-2025
11	10-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 11:42:25 10-Jun-2025	 11:42:34 10-Jun-2025	 11:42:46 10-Jun-2025
12	10-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 11:41:31 10-Jun-2025	 11:41:47 10-Jun-2025	 11:41:59 10-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	10-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 11:40:46 10-Jun-2025	 11:40:58 10-Jun-2025	 11:41:09 10-Jun-2025
14	10-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 11:40:02 10-Jun-2025	 11:40:13 10-Jun-2025	 11:40:24 10-Jun-2025
15	10-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 11:38:57 10-Jun-2025	 11:39:21 10-Jun-2025	 11:39:34 10-Jun-2025
16	10-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 11:37:59 10-Jun-2025	 11:38:15 10-Jun-2025	 11:38:29 10-Jun-2025
17	10-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:50:27 10-Jun-2025	 21:50:42 10-Jun-2025	 21:50:56 10-Jun-2025
18	10-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 12:29:29 10-Jun-2025	 12:30:22 10-Jun-2025	 12:29:48 10-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	10-06-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT PASSENGER LV.UG S.D LV.5			
20	10-06-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT SERVICE LV.UG S.D LV.5			
21	10-06-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG			
22	10-06-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	11-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE	 07:07:32 11-Jun-2025	 07:09:43 11-Jun-2025	 07:13:55 11-Jun-2025
2	11-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 06:56:26 11-Jun-2025	 06:56:44 11-Jun-2025	 06:57:02 11-Jun-2025
3	11-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG	 06:57:58 11-Jun-2025	 06:57:41 11-Jun-2025	 06:58:13 11-Jun-2025
4	11-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 06:58:32 11-Jun-2025	 06:58:59 11-Jun-2025	 06:58:44 11-Jun-2025
5	11-06-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.5	 07:08:48 11-Jun-2025	 07:09:04 11-Jun-2025	 07:09:19 11-Jun-2025
6	11-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B	 06:59:39 11-Jun-2025	 07:00:05 11-Jun-2025	 06:59:52 11-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	11-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7	 22:31:58 11-Jun-2025	 22:32:12 11-Jun-2025	 22:32:21 11-Jun-2025
8	11-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 09:07:20 11-Jun-2025	 09:08:19 11-Jun-2025	 09:07:32 11-Jun-2025
9	11-06-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LT.4-2	 07:00:37 11-Jun-2025	 07:01:09 11-Jun-2025	 07:00:50 11-Jun-2025
10	11-06-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 07:01:32 11-Jun-2025	 07:01:46 11-Jun-2025	 07:02:20 11-Jun-2025
11	11-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 07:02:47 11-Jun-2025	 07:03:09 11-Jun-2025	 07:03:23 11-Jun-2025
12	11-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 07:04:28 11-Jun-2025	 07:04:55 11-Jun-2025	 07:04:41 11-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	11-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 07:05:15 11-Jun-2025	 07:05:41 11-Jun-2025	 07:05:27 11-Jun-2025
14	11-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 22:26:15 11-Jun-2025	 22:27:32 11-Jun-2025	 22:27:44 11-Jun-2025
15	11-06-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10	 22:28:03 11-Jun-2025	 22:28:13 11-Jun-2025	 22:28:22 11-Jun-2025
16	11-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5	 13:31:55 11-Jun-2025	 13:34:02 11-Jun-2025	 13:32:47 11-Jun-2025
17	11-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5	 13:36:48 11-Jun-2025	 13:38:21 11-Jun-2025	 13:37:44 11-Jun-2025
18	11-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3	 22:28:46 11-Jun-2025	 22:28:55 11-Jun-2025	 22:29:14 11-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	11-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10	 09:05:24 11-Jun-2025	 09:06:16 11-Jun-2025	 09:05:37 11-Jun-2025
20	11-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10	 09:03:08 11-Jun-2025	 09:04:38 11-Jun-2025	 09:03:31 11-Jun-2025
21	11-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5	 22:31:18 11-Jun-2025	 22:31:31 11-Jun-2025	 22:31:42 11-Jun-2025
22	11-06-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT PASSENGER LV.6 S.D 10	 07:15:52 11-Jun-2025	 07:14:32 11-Jun-2025	 07:16:07 11-Jun-2025
23	11-06-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT SERVICE LV.6 S.D 10	 07:15:20 11-Jun-2025	 07:14:55 11-Jun-2025	 07:15:32 11-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	13-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)	 03:42:13 13-Jun-2025	 03:42:29 13-Jun-2025	 03:43:18 13-Jun-2025
2	13-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI LANDING ESCALATOR DEPAN TENANT M&S - ARAH KE TENANT COAST / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.1	 03:43:39 13-Jun-2025	 03:45:55 13-Jun-2025	 03:43:54 13-Jun-2025
3	13-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 03:44:10 13-Jun-2025	 03:47:22 13-Jun-2025	 03:44:24 13-Jun-2025
4	13-06-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE 9 & 10	 03:47:52 13-Jun-2025	 03:48:06 13-Jun-2025	 03:48:19 13-Jun-2025
5	13-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B	 02:09:45 13-Jun-2025	 02:09:06 13-Jun-2025	 02:11:32 13-Jun-2025
6	13-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2	 19:52:14 13-Jun-2025	 19:53:09 13-Jun-2025	 19:51:35 13-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	13-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2	 11:04:04 13-Jun-2025	 11:05:10 13-Jun-2025	 11:05:41 13-Jun-2025
8	13-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7A	 02:03:35 13-Jun-2025	 02:04:33 13-Jun-2025	 02:03:56 13-Jun-2025
9	13-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 11:07:40 13-Jun-2025	 11:08:09 13-Jun-2025	 11:07:53 13-Jun-2025
10	13-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG	 10:58:24 13-Jun-2025	 10:59:13 13-Jun-2025	 11:00:39 13-Jun-2025
11	13-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.3	 20:01:29 13-Jun-2025	 20:01:47 13-Jun-2025	 20:02:27 13-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	14-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI OUT MOBIL	 20:18:25 14-Jun-2025	 20:18:35 14-Jun-2025	 20:18:46 14-Jun-2025
2	14-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 04:15:56 14-Jun-2025	 04:16:13 14-Jun-2025	 04:16:29 14-Jun-2025
3	14-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)	 04:01:24 14-Jun-2025	 04:01:38 14-Jun-2025	 04:01:51 14-Jun-2025
4	14-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI DEPAN TENANT BRAUN N BUFFEL - LANDING ESCALATOR DEPAN M&S LV.1	 04:12:26 14-Jun-2025	 03:58:11 14-Jun-2025	 04:12:39 14-Jun-2025
5	14-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 04:17:57 14-Jun-2025	 04:17:18 14-Jun-2025	 04:18:16 14-Jun-2025
6	14-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI KURSI BENCH MARMER LV.1	 04:10:52 14-Jun-2025	 04:11:04 14-Jun-2025	 04:11:13 14-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	14-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A	 03:59:56 14-Jun-2025	 04:00:11 14-Jun-2025	 04:00:25 14-Jun-2025
8	14-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG	 20:56:21 14-Jun-2025	 21:07:31 14-Jun-2025	 20:56:37 14-Jun-2025
9	14-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG	 10:39:45 14-Jun-2025	 10:40:17 14-Jun-2025	 10:40:40 14-Jun-2025
10	14-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.LG	 09:09:48 14-Jun-2025	 09:16:08 14-Jun-2025	 09:34:57 14-Jun-2025
11	14-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7B	 04:02:19 14-Jun-2025	 04:02:36 14-Jun-2025	 04:02:51 14-Jun-2025
12	14-06-2025	KORIDOR SHOPPING	CELLING	CELLING AREA KORIDOR SHOPPING LV.1-5	 11:03:54 14-Jun-2025	 11:07:16 14-Jun-2025	 11:07:48 14-Jun-2025







No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	14-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5			
14	14-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.UG-1			
15	14-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.10			
16	14-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5			
17	14-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LED PROMO LV.1 S.D LV.4			
18	14-06-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN PLANTER BOX LV.UG			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	14-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1	 10:47:29 14-Jun-2025	 10:48:09 14-Jun-2025	 10:47:54 14-Jun-2025
20	14-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.UG S.D LV.5	 19:29:44 14-Jun-2025	 19:32:24 14-Jun-2025	 19:37:09 14-Jun-2025
21	14-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.5	 10:32:18 14-Jun-2025	 10:32:39 14-Jun-2025	 10:34:02 14-Jun-2025
22	14-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR SERVICE LV.LG-10	 21:17:54 14-Jun-2025	 21:18:35 14-Jun-2025	 21:18:25 14-Jun-2025
23	14-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 24 SISI UNION,LC WAIKIKI,KID STATION,SUSHI TEI LV.LG-10	 10:52:07 14-Jun-2025	 10:51:46 14-Jun-2025	 10:52:20 14-Jun-2025
24	14-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.UG	 10:42:51 14-Jun-2025	 10:43:10 14-Jun-2025	 10:44:44 14-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	14-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.UG	 21:02:09 14-Jun-2025	 21:07:57 14-Jun-2025	 21:02:33 14-Jun-2025
26	14-06-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2	 11:11:30 14-Jun-2025	 11:11:57 14-Jun-2025	 11:11:45 14-Jun-2025
27	14-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SELA SELA PINTU LIFT SERVICE LV.LG-10	 11:17:09 14-Jun-2025	 11:18:01 14-Jun-2025	 11:17:44 14-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	16-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 12:12:28 16-Jun-2025	 12:12:37 16-Jun-2025	 12:12:48 16-Jun-2025
2	16-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONNECTION TP4	 05:52:19 16-Jun-2025	 05:52:34 16-Jun-2025	 05:52:49 16-Jun-2025
3	16-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 05:51:21 16-Jun-2025	 05:51:36 16-Jun-2025	 05:51:50 16-Jun-2025
4	16-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 03:36:06 16-Jun-2025	 03:36:18 16-Jun-2025	 03:36:30 16-Jun-2025
5	16-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.3	 03:42:45 16-Jun-2025	 03:43:01 16-Jun-2025	 03:43:26 16-Jun-2025
6	16-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 03:37:59 16-Jun-2025	 03:38:35 16-Jun-2025	 03:38:14 16-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	16-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A	 03:38:56 16-Jun-2025	 03:39:07 16-Jun-2025	 03:39:19 16-Jun-2025
8	16-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 21:09:11 16-Jun-2025	 21:09:35 16-Jun-2025	 21:11:32 16-Jun-2025
9	16-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 03:13:08 16-Jun-2025	 03:15:43 16-Jun-2025	 03:40:50 16-Jun-2025
10	16-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 12:13:29 16-Jun-2025	 12:13:39 16-Jun-2025	 12:13:49 16-Jun-2025
11	16-06-2025	KORIDOR SHOPPING	CELLING	CELLING AREA LOBBY LV.UG	 12:14:27 16-Jun-2025	 12:14:37 16-Jun-2025	 12:14:48 16-Jun-2025
12	16-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 12:10:52 16-Jun-2025	 12:11:03 16-Jun-2025	 12:11:12 16-Jun-2025






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	16-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:27:33 16-Jun-2025	 20:29:10 16-Jun-2025	 20:29:26 16-Jun-2025
14	16-06-2025	KORIDOR SHOPPING	SWEEPING	SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10	 12:15:12 16-Jun-2025	 12:15:25 16-Jun-2025	 12:15:37 16-Jun-2025
15	16-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 12:20:45 16-Jun-2025	 12:20:54 16-Jun-2025	 12:21:05 16-Jun-2025
16	16-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5	 12:21:25 16-Jun-2025	 12:21:40 16-Jun-2025	 12:21:51 16-Jun-2025
17	16-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 12:22:44 16-Jun-2025	 12:22:54 16-Jun-2025	 12:23:03 16-Jun-2025
18	16-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 20:54:53 16-Jun-2025	 21:13:23 16-Jun-2025	 20:55:29 16-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	16-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 12:25:04 16-Jun-2025	 12:25:13 16-Jun-2025	 12:25:23 16-Jun-2025
20	16-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 12:11:30 16-Jun-2025	 12:11:39 16-Jun-2025	 12:11:50 16-Jun-2025
21	16-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 12:24:33 16-Jun-2025	 12:24:42 16-Jun-2025	 12:24:51 16-Jun-2025
22	16-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10	 12:18:41 16-Jun-2025	 12:19:02 16-Jun-2025	 12:19:21 16-Jun-2025
23	16-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10	 12:19:40 16-Jun-2025	 12:19:52 16-Jun-2025	 12:20:04 16-Jun-2025
24	16-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR EXIT LV.LG-10	 12:17:51 16-Jun-2025	 12:18:02 16-Jun-2025	 12:18:14 16-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	16-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4			
26	16-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4			
27	16-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.5			
28	16-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	17-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:11:32 17-Jun-2025	 07:12:10 17-Jun-2025	 07:16:13 17-Jun-2025
2	17-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 04:34:41 17-Jun-2025	 04:34:53 17-Jun-2025	 04:35:08 17-Jun-2025
3	17-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA VALET LV.UG	 04:36:40 17-Jun-2025	 04:30:03 17-Jun-2025	 04:37:00 17-Jun-2025
4	17-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 04:31:02 17-Jun-2025	 04:31:28 17-Jun-2025	 04:31:40 17-Jun-2025
5	17-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:44:12 17-Jun-2025	 21:45:15 17-Jun-2025	 21:45:51 17-Jun-2025
6	17-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 11:10:14 17-Jun-2025	 11:13:28 17-Jun-2025	 11:12:54 17-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	17-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 01:09:36 17-Jun-2025	 01:14:44 17-Jun-2025	 01:26:46 17-Jun-2025
8	17-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:15:32 17-Jun-2025	 20:15:59 17-Jun-2025	 20:16:11 17-Jun-2025
9	17-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 11:42:18 17-Jun-2025	 11:42:35 17-Jun-2025	 11:42:48 17-Jun-2025
10	17-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7	 11:43:22 17-Jun-2025	 11:44:16 17-Jun-2025	 11:43:57 17-Jun-2025
11	17-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 11:46:33 17-Jun-2025	 11:47:07 17-Jun-2025	 11:46:46 17-Jun-2025
12	17-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 11:24:32 17-Jun-2025	 11:25:42 17-Jun-2025	 11:27:37 17-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	17-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 11:24:51 17-Jun-2025	 11:25:11 17-Jun-2025	 11:27:53 17-Jun-2025
14	17-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 11:39:09 17-Jun-2025	 11:39:33 17-Jun-2025	 11:40:11 17-Jun-2025
15	17-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 11:16:49 17-Jun-2025	 11:17:31 17-Jun-2025	 11:18:01 17-Jun-2025
16	17-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:46:13 17-Jun-2025	 21:46:28 17-Jun-2025	 21:47:16 17-Jun-2025
17	17-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:10:08 17-Jun-2025	 10:09:53 17-Jun-2025	 10:10:33 17-Jun-2025
18	17-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.6	 04:32:43 17-Jun-2025	 04:33:26 17-Jun-2025	 04:33:38 17-Jun-2025





No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	17-06-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG			
20	17-06-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	18-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE	 07:07:08 18-Jun-2025	 07:07:31 18-Jun-2025	 07:13:11 18-Jun-2025
2	18-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 03:40:16 18-Jun-2025	 03:40:27 18-Jun-2025	 03:40:40 18-Jun-2025
3	18-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG	 03:49:39 18-Jun-2025	 03:42:06 18-Jun-2025	 03:49:54 18-Jun-2025
4	18-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:50:19 18-Jun-2025	 03:43:17 18-Jun-2025	 03:50:32 18-Jun-2025
5	18-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 03:44:00 18-Jun-2025	 03:44:13 18-Jun-2025	 03:44:27 18-Jun-2025
6	18-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7	 23:03:46 18-Jun-2025	 23:03:55 18-Jun-2025	 23:04:04 18-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	18-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 09:23:04 18-Jun-2025	 09:49:30 18-Jun-2025	 09:22:45 18-Jun-2025
8	18-06-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 03:44:59 18-Jun-2025	 03:45:12 18-Jun-2025	 03:45:23 18-Jun-2025
9	18-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 03:51:28 18-Jun-2025	 03:51:47 18-Jun-2025	 03:52:02 18-Jun-2025
10	18-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 03:46:07 18-Jun-2025	 03:46:20 18-Jun-2025	 03:46:59 18-Jun-2025
11	18-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 03:47:16 18-Jun-2025	 03:47:32 18-Jun-2025	 03:47:44 18-Jun-2025
12	18-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 23:04:50 18-Jun-2025	 23:04:58 18-Jun-2025	 23:05:21 18-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	18-06-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10			
14	18-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5			
15	18-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9			
16	18-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5			
17	18-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3			
18	18-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	18-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10	 09:21:11 18-Jun-2025	 09:48:18 18-Jun-2025	 09:21:46 18-Jun-2025
20	18-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5	 23:06:21 18-Jun-2025	 23:06:29 18-Jun-2025	 23:06:40 18-Jun-2025
21	18-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.7	 03:48:28 18-Jun-2025	 03:48:42 18-Jun-2025	 03:48:53 18-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	19-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI BAWAH UNION	 07:12:08 19-Jun-2025	 07:12:50 19-Jun-2025	 07:15:11 19-Jun-2025
2	19-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 03:16:12 19-Jun-2025	 03:16:27 19-Jun-2025	 03:16:42 19-Jun-2025
3	19-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:24:00 19-Jun-2025	 03:17:29 19-Jun-2025	 03:24:14 19-Jun-2025
4	19-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI LANDING ESCALATOR DEPAN TENANT LC WAIKIKI - ARAH KE TENANT JUSTICE / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.2	 03:24:37 19-Jun-2025	 03:18:06 19-Jun-2025	 03:24:50 19-Jun-2025
5	19-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 03:18:41 19-Jun-2025	 03:18:57 19-Jun-2025	 03:19:12 19-Jun-2025
6	19-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10	 07:45:09 19-Jun-2025	 07:46:05 19-Jun-2025	 07:45:35 19-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	19-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10	 11:13:25 19-Jun-2025	 11:14:01 19-Jun-2025	 11:14:48 19-Jun-2025
8	19-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P6A	 03:22:00 19-Jun-2025	 03:22:14 19-Jun-2025	 03:22:26 19-Jun-2025
9	19-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 22:45:12 19-Jun-2025	 22:45:22 19-Jun-2025	 22:45:34 19-Jun-2025
10	19-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 03:19:44 19-Jun-2025	 03:19:58 19-Jun-2025	 03:20:13 19-Jun-2025
11	19-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:47:14 19-Jun-2025	 22:47:21 19-Jun-2025	 22:47:29 19-Jun-2025
12	19-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 11:24:31 19-Jun-2025	 11:25:41 19-Jun-2025	 11:25:10 19-Jun-2025



No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
13	19-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10	 11:19:50 19-Jun-2025	 11:21:26 19-Jun-2025	 11:20:33 19-Jun-2025
14	19-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 11:22:06 19-Jun-2025	 11:22:34 19-Jun-2025	 11:22:18 19-Jun-2025
15	19-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4	 22:46:40 19-Jun-2025	 22:46:52 19-Jun-2025	 22:47:00 19-Jun-2025
16	19-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.4	 22:46:04 19-Jun-2025	 22:46:13 19-Jun-2025	 22:46:21 19-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	20-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)			
2	20-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2			
3	20-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI DEPAN TENANT MELISSA - LANDING ESCALATOR DEPAN EX TENANT LC WAIKIKI LV.2			
4	20-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2			
5	20-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2			
6	20-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7A			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	20-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9			
8	20-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG			
9	20-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.3			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	21-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI OUT MOBIL	 15:10:46 21-Jun-2025	 15:11:38 21-Jun-2025	 15:12:01 21-Jun-2025
2	21-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 04:52:34 21-Jun-2025	 04:52:45 21-Jun-2025	 04:52:55 21-Jun-2025
3	21-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)	 06:54:40 21-Jun-2025	 06:54:53 21-Jun-2025	 06:55:08 21-Jun-2025
4	21-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 04:58:25 21-Jun-2025	 04:54:29 21-Jun-2025	 04:58:39 21-Jun-2025
5	21-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI LANDING ESCALATOR TENANT COTTON ON - ARAH KE CONNECTION TP4 LV.2	 04:59:02 21-Jun-2025	 04:55:17 21-Jun-2025	 04:59:15 21-Jun-2025
6	21-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI KURSI BENCH MARMER LV.3	 05:03:42 21-Jun-2025	 05:03:57 21-Jun-2025	 05:04:17 21-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	21-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG	 20:43:43 21-Jun-2025	 21:57:37 21-Jun-2025	 20:43:12 21-Jun-2025
8	21-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG	 10:49:19 21-Jun-2025	 10:49:41 21-Jun-2025	 10:50:00 21-Jun-2025
9	21-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.LG	 08:50:21 21-Jun-2025	 08:54:28 21-Jun-2025	 09:15:15 21-Jun-2025
10	21-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7B	 04:56:29 21-Jun-2025	 04:56:40 21-Jun-2025	 04:56:50 21-Jun-2025
11	21-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN,SELA SELA HAND RALLING LV.1-5	 10:53:15 21-Jun-2025	 10:53:38 21-Jun-2025	 10:54:00 21-Jun-2025
12	21-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.10	 10:54:48 21-Jun-2025	 10:55:12 21-Jun-2025	 10:54:58 21-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	21-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5			
14	21-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LED PROMO LV.1 S.D LV.4			
15	21-06-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN PLANTER BOX LV.UG			
16	21-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1			
17	21-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.UG S.D LV.5			
18	21-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.5			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	21-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.UG	 10:40:57 21-Jun-2025	 10:41:39 21-Jun-2025	 10:42:19 21-Jun-2025
20	21-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.UG	 21:04:10 21-Jun-2025	 21:58:10 21-Jun-2025	 21:15:45 21-Jun-2025
21	21-06-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2	 10:52:16 21-Jun-2025	 10:52:38 21-Jun-2025	 10:52:27 21-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	22-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.7-9 (UP&DOWN)			
2	22-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.9-10 (UP&DOWN)			
3	22-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.4			
4	22-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1			
5	22-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B			
6	22-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.3			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	22-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.3			
8	22-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.8			
9	22-06-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P8A			
10	22-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.6-10			
11	22-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.6			
12	22-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA / KOLOM PILAR LV.2 & 3			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	22-06-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.6 S.D LV.10	 19:52:10 22-Jun-2025	 20:00:53 22-Jun-2025	 20:00:36 22-Jun-2025
14	22-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.6	 11:27:19 22-Jun-2025	 11:27:37 22-Jun-2025	 11:28:03 22-Jun-2025
15	22-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.3	 11:18:32 22-Jun-2025	 11:19:07 22-Jun-2025	 11:20:14 22-Jun-2025
16	22-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.3	 20:05:51 22-Jun-2025	 20:06:08 22-Jun-2025	 20:06:28 22-Jun-2025
17	22-06-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.3-4-5	 11:21:51 22-Jun-2025	 11:22:12 22-Jun-2025	 11:22:01 22-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	23-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 07:16:37 23-Jun-2025	 07:17:34 23-Jun-2025	 07:19:35 23-Jun-2025
2	23-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4	 06:53:45 23-Jun-2025	 06:53:57 23-Jun-2025	 06:54:09 23-Jun-2025
3	23-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 06:54:28 23-Jun-2025	 06:56:07 23-Jun-2025	 06:55:03 23-Jun-2025
4	23-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 06:45:56 23-Jun-2025	 06:46:14 23-Jun-2025	 06:46:37 23-Jun-2025
5	23-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.5	 06:58:04 23-Jun-2025	 06:58:53 23-Jun-2025	 06:58:41 23-Jun-2025
6	23-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 07:00:59 23-Jun-2025	 07:01:13 23-Jun-2025	 07:01:32 23-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	23-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 07:02:19 23-Jun-2025	 07:02:33 23-Jun-2025	 07:02:44 23-Jun-2025
8	23-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 22:15:28 23-Jun-2025	 22:15:51 23-Jun-2025	 22:16:23 23-Jun-2025
9	23-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 02:52:13 23-Jun-2025	 02:58:20 23-Jun-2025	 03:58:29 23-Jun-2025
10	23-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 11:27:03 23-Jun-2025	 11:28:14 23-Jun-2025	 11:27:41 23-Jun-2025
11	23-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 11:40:12 23-Jun-2025	 11:40:40 23-Jun-2025	 11:41:13 23-Jun-2025
12	23-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 22:13:12 23-Jun-2025	 22:13:35 23-Jun-2025	 22:14:16 23-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	23-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 11:34:58 23-Jun-2025	 11:35:09 23-Jun-2025	 11:35:21 23-Jun-2025
14	23-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 11:42:56 23-Jun-2025	 11:43:38 23-Jun-2025	 11:44:25 23-Jun-2025
15	23-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 22:20:37 23-Jun-2025	 22:20:56 23-Jun-2025	 22:21:57 23-Jun-2025
16	23-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 11:32:23 23-Jun-2025	 11:32:56 23-Jun-2025	 11:33:42 23-Jun-2025
17	23-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 11:25:05 23-Jun-2025	 11:24:51 23-Jun-2025	 11:25:17 23-Jun-2025
18	23-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 11:29:50 23-Jun-2025	 11:30:23 23-Jun-2025	 11:30:45 23-Jun-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	23-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4	 11:19:28 23-Jun-2025	 11:24:26 23-Jun-2025	 11:20:19 23-Jun-2025
20	23-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 22:10:48 23-Jun-2025	 22:11:13 23-Jun-2025	 22:12:08 23-Jun-2025
21	23-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 22:17:23 23-Jun-2025	 22:18:09 23-Jun-2025	 22:18:55 23-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	24-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:29:55 24-Jun-2025	 07:30:17 24-Jun-2025	 07:30:55 24-Jun-2025
2	24-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 07:09:06 24-Jun-2025	 07:09:26 24-Jun-2025	 07:09:41 24-Jun-2025
3	24-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA CONCIERGE LV.UG	 07:10:40 24-Jun-2025	 07:10:54 24-Jun-2025	 07:11:07 24-Jun-2025
4	24-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 07:11:52 24-Jun-2025	 07:13:23 24-Jun-2025	 07:13:51 24-Jun-2025
5	24-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:55:39 24-Jun-2025	 21:54:33 24-Jun-2025	 21:56:13 24-Jun-2025
6	24-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 13:37:14 24-Jun-2025	 13:37:42 24-Jun-2025	 13:38:02 24-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	24-06-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LT.6-4	 07:14:27 24-Jun-2025	 07:14:41 24-Jun-2025	 07:14:55 24-Jun-2025
8	24-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 07:15:45 24-Jun-2025	 07:15:58 24-Jun-2025	 07:16:10 24-Jun-2025
9	24-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:24:58 24-Jun-2025	 20:25:48 24-Jun-2025	 20:26:04 24-Jun-2025
10	24-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 13:41:38 24-Jun-2025	 13:41:50 24-Jun-2025	 13:42:03 24-Jun-2025
11	24-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 13:48:37 24-Jun-2025	 13:49:49 24-Jun-2025	 13:49:22 24-Jun-2025
12	24-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 13:45:38 24-Jun-2025	 13:46:37 24-Jun-2025	 13:46:56 24-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	24-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 13:45:55 24-Jun-2025	 13:46:25 24-Jun-2025	 13:47:10 24-Jun-2025
14	24-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 13:40:14 24-Jun-2025	 13:40:35 24-Jun-2025	 13:41:12 24-Jun-2025
15	24-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 13:34:14 24-Jun-2025	 13:35:36 24-Jun-2025	 13:35:14 24-Jun-2025
16	24-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:56:37 24-Jun-2025	 21:57:18 24-Jun-2025	 21:57:36 24-Jun-2025
17	24-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:16:22 24-Jun-2025	 10:17:01 24-Jun-2025	 10:16:35 24-Jun-2025
18	24-06-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG	 07:45:43 24-Jun-2025	 07:47:34 24-Jun-2025	 07:53:41 24-Jun-2025

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	24-06-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	30-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM			
2	30-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4			
3	30-06-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO			
4	30-06-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)			
5	30-06-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2			
6	30-06-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	30-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 21:17:40 30-Jun-2025	 21:18:14 30-Jun-2025	 21:18:50 30-Jun-2025
8	30-06-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 02:09:52 30-Jun-2025	 02:17:55 30-Jun-2025	 03:41:21 30-Jun-2025
9	30-06-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 13:12:46 30-Jun-2025	 13:12:32 30-Jun-2025	 13:13:00 30-Jun-2025
10	30-06-2025	KORIDOR SHOPPING	CELLING	CELLING AREA LOBBY LV.UG	 20:43:04 30-Jun-2025	 20:44:06 30-Jun-2025	 20:43:24 30-Jun-2025
11	30-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 11:37:47 30-Jun-2025	 11:38:28 30-Jun-2025	 11:39:01 30-Jun-2025
12	30-06-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:39:57 30-Jun-2025	 20:40:39 30-Jun-2025	 20:35:10 30-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	30-06-2025	KORIDOR SHOPPING	SWEEPING	SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10	 20:48:33 30-Jun-2025	 20:49:22 30-Jun-2025	 20:48:47 30-Jun-2025
14	30-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 13:22:38 30-Jun-2025	 13:22:52 30-Jun-2025	 13:23:03 30-Jun-2025
15	30-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5	 13:08:57 30-Jun-2025	 13:09:20 30-Jun-2025	 13:09:10 30-Jun-2025
16	30-06-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 13:23:31 30-Jun-2025	 13:23:50 30-Jun-2025	 13:24:16 30-Jun-2025
17	30-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 13:18:47 30-Jun-2025	 13:21:14 30-Jun-2025	 13:21:43 30-Jun-2025
18	30-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 11:52:05 30-Jun-2025	 11:52:29 30-Jun-2025	 11:53:06 30-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	30-06-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 20:50:23 30-Jun-2025	 20:49:54 30-Jun-2025	 20:50:33 30-Jun-2025
20	30-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 11:47:17 30-Jun-2025	 11:49:22 30-Jun-2025	 11:48:44 30-Jun-2025
21	30-06-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10	 20:51:57 30-Jun-2025	 20:52:52 30-Jun-2025	 20:52:17 30-Jun-2025
22	30-06-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10	 20:44:48 30-Jun-2025	 20:45:26 30-Jun-2025	 20:45:09 30-Jun-2025
23	30-06-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR EXIT LV.LG-10	 20:46:31 30-Jun-2025	 20:46:47 30-Jun-2025	 20:47:01 30-Jun-2025
24	30-06-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4	 11:57:17 30-Jun-2025	 12:00:42 30-Jun-2025	 12:01:18 30-Jun-2025

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
25	30-06-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 21:14:47 30-Jun-2025	 21:16:08 30-Jun-2025	 21:16:51 30-Jun-2025