











No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	02-06-2025	LANTAI 3	POLISHING	URINOIR			
2	02-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH			
3	02-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS			
4	02-06-2025	LANTAI 3	POLISHING	TRAY			
5	02-06-2025	LANTAI 3	POLISHING	CLOSET			
6	02-06-2025	LANTAI 2	SPOTTING	SOFA			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	02-06-2025	LANTAI 2	WALL CLEANING	PINTU LIFT			
8	02-06-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR			
9	02-06-2025	LANTAI 2	POLISHING	CLOSET			
10	02-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH			
11	02-06-2025	LANTAI 1	HIGH DUSTING	NEON LED			
12	02-06-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	02-06-2025	LANTAI 1	POLISHING	KUBIKAL			
14	02-06-2025	LANTAI 1	GLASS CLEANING	KACA			
15	02-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN			
16	02-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN			
17	02-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			
18	02-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	02-06-2025	BASEMENT	WASHING	LANTAI EPOXY			
20	02-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			
21	02-06-2025	BASEMENT	WALL CLEANING	PILAR BETON			
22	02-06-2025	BASEMENT	PLAFON CLEANING	CEILING			
23	02-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX			
24	02-06-2025	EXTERNAL	POLISHING	PIPA HYDRANT			






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	02-06-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR	 19:26:05 02-Jun-2025	 19:26:22 02-Jun-2025	 19:26:38 02-Jun-2025
26	02-06-2025	EXTERNAL	WALL CLEANING	PIPA HYDRANT	 19:25:14 02-Jun-2025	 19:25:31 02-Jun-2025	 19:25:47 02-Jun-2025
27	02-06-2025	EXTERNAL	BRUSHING	ALCUBON	 20:02:27 02-Jun-2025	 20:02:45 02-Jun-2025	 20:03:00 02-Jun-2025
28	02-06-2025	EXTERNAL	BRUSHING	PIPA HYDRANT	 19:22:23 02-Jun-2025	 19:22:37 02-Jun-2025	 19:22:52 02-Jun-2025
29	02-06-2025	EXTERNAL	HIGH DUSTING	SIGN RAMBU JALAN	 20:03:42 02-Jun-2025	 20:03:58 02-Jun-2025	 20:04:15 02-Jun-2025
30	02-06-2025	EXTERNAL	BRUSHING	LOGO JKTPD	 14:02:33 02-Jun-2025	 14:02:50 02-Jun-2025	 14:03:13 02-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	02-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 13:03:42 02-Jun-2025	 13:04:18 02-Jun-2025	 13:04:40 02-Jun-2025
32	02-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 20:05:15 02-Jun-2025	 20:05:32 02-Jun-2025	 20:05:47 02-Jun-2025
33	02-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 14:05:07 02-Jun-2025	 14:05:28 02-Jun-2025	 14:05:53 02-Jun-2025
34	02-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 19:21:35 02-Jun-2025	 19:21:48 02-Jun-2025	 19:22:04 02-Jun-2025
35	02-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 14:14:38 02-Jun-2025	 14:14:54 02-Jun-2025	 14:15:11 02-Jun-2025
36	02-06-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 20:07:46 02-Jun-2025	 20:08:06 02-Jun-2025	 20:08:25 02-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	02-06-2025	CARPARK P1-P2	POLISHING	STAINLESS BULAT			
38	02-06-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	03-06-2025	LANTAI 3	POLISHING	FLOOR DRAIN			
2	03-06-2025	LANTAI 3	WALL CLEANING	DINDING ACP			
3	03-06-2025	LANTAI 3	GLASS CLEANING	KACA RAILING			
4	03-06-2025	LANTAI 3	GENERAL CLEANING	DISWASHING			
5	03-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH			
6	03-06-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	03-06-2025	LANTAI 2	POLISHING	RAK ACCESORIS	 17:23:05 03-Jun-2025	 17:23:21 03-Jun-2025	 17:23:37 03-Jun-2025
8	03-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 12:07:28 03-Jun-2025	 12:08:03 03-Jun-2025	 12:08:34 03-Jun-2025
9	03-06-2025	LANTAI 2	POLISHING	CLOSET	 17:24:30 03-Jun-2025	 17:24:54 03-Jun-2025	 17:25:13 03-Jun-2025
10	03-06-2025	LANTAI 1	POLISHING	PINTU LIFT	 17:27:30 03-Jun-2025	 17:27:56 03-Jun-2025	 17:28:34 03-Jun-2025
11	03-06-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS	 12:09:23 03-Jun-2025	 12:09:41 03-Jun-2025	 12:10:08 03-Jun-2025
12	03-06-2025	LANTAI 1	POLISHING	WASTAFEL	 17:25:44 03-Jun-2025	 17:25:57 03-Jun-2025	 17:26:14 03-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	03-06-2025	LANTAI 1	POLISHING	PINTU EXIT			
14	03-06-2025	BASEMENT	HIGH DUSTING	JET FAN			
15	03-06-2025	BASEMENT	HIGH DUSTING	JET FAN			
16	03-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR			
17	03-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG			
18	03-06-2025	BASEMENT	WALL CLEANING	PILAR BETON			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	03-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR			
20	03-06-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC			
21	03-06-2025	BASEMENT	POLISHING	BOX HYDRANT			
22	03-06-2025	BASEMENT	BRUSHING	LANTAI KERAMIK			
23	03-06-2025	EXTERNAL	POLISHING	DINDING CAT			
24	03-06-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT			








No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	03-06-2025	EXTERNAL	HIGH DUSTING	DINDING BETON			
26	03-06-2025	EXTERNAL	BRUSHING	SIGN RAMBU JALAN			
27	03-06-2025	EXTERNAL	BRUSHING	BATU ALAM			
28	03-06-2025	EXTERNAL	POLISHING	ALCUBON			
29	03-06-2025	EXTERNAL	BRUSHING	TEMPAT SAMPAH			
30	03-06-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	03-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 12:53:39 03-Jun-2025	 12:55:43 03-Jun-2025	 12:56:25 03-Jun-2025
32	03-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 20:14:04 03-Jun-2025	 20:14:28 03-Jun-2025	 20:15:08 03-Jun-2025
33	03-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 13:06:18 03-Jun-2025	 13:08:40 03-Jun-2025	 13:09:48 03-Jun-2025
34	03-06-2025	CARPARK P1-P2	POLISHING	RAILING	 17:07:47 03-Jun-2025	 17:08:53 03-Jun-2025	 17:09:16 03-Jun-2025
35	03-06-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT	 12:48:47 03-Jun-2025	 12:51:33 03-Jun-2025	 12:52:18 03-Jun-2025
36	03-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 17:06:25 03-Jun-2025	 17:06:53 03-Jun-2025	 17:07:12 03-Jun-2025







No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	03-06-2025	CARPARK P1-P2	HIGH DUSTING	JET FAN			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	04-06-2025	LANTAI 3	POLISHING	KUBIKAL	 14:35:36 04-Jun-2025	 14:35:52 04-Jun-2025	 14:36:15 04-Jun-2025
2	04-06-2025	LANTAI 3	WALL CLEANING	PLANTER BOX	 14:37:42 04-Jun-2025	 14:38:01 04-Jun-2025	 14:38:24 04-Jun-2025
3	04-06-2025	LANTAI 3	WALL CLEANING	PINTU LIFT	 14:39:24 04-Jun-2025	 14:39:44 04-Jun-2025	 14:40:01 04-Jun-2025
4	04-06-2025	LANTAI 3	GLASS CLEANING	MIRROR	 17:27:27 04-Jun-2025	 17:27:47 04-Jun-2025	 17:28:06 04-Jun-2025
5	04-06-2025	LANTAI 2	POLISHING	CLOSET	 14:47:38 04-Jun-2025	 14:47:53 04-Jun-2025	 14:48:15 04-Jun-2025
6	04-06-2025	LANTAI 2	SPOTTING	SOFA	 14:46:02 04-Jun-2025	 14:46:24 04-Jun-2025	 14:46:41 04-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	04-06-2025	LANTAI 2	SPOTTING	FLOOR DRAIN	 17:28:34 04-Jun-2025	 17:28:53 04-Jun-2025	 17:29:10 04-Jun-2025
8	04-06-2025	LANTAI 2	POLISHING	FLOOR DRAIN	 14:44:09 04-Jun-2025	 14:44:33 04-Jun-2025	 14:44:53 04-Jun-2025
9	04-06-2025	LANTAI 1	WALL CLEANING	DINDING LIFT	 14:42:41 04-Jun-2025	 14:43:02 04-Jun-2025	 14:43:28 04-Jun-2025
10	04-06-2025	LANTAI 1	HIGH DUSTING	KIPAS	 17:29:53 04-Jun-2025	 17:31:03 04-Jun-2025	 17:31:28 04-Jun-2025
11	04-06-2025	LANTAI 1	POLISHING	CLOSET	 14:41:23 04-Jun-2025	 14:41:53 04-Jun-2025	 14:42:14 04-Jun-2025
12	04-06-2025	LANTAI 1	SWEEPING	TANGGA	 17:07:30 04-Jun-2025	 17:07:55 04-Jun-2025	 17:08:17 04-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	04-06-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 16:33:51 04-Jun-2025	 16:34:06 04-Jun-2025	 16:37:32 04-Jun-2025
14	04-06-2025	BASEMENT	PLAFON CLEANING	CEILING	 17:09:01 04-Jun-2025	 17:09:21 04-Jun-2025	 17:09:40 04-Jun-2025
15	04-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 17:32:04 04-Jun-2025	 17:32:22 04-Jun-2025	 17:32:45 04-Jun-2025
16	04-06-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR	 17:35:17 04-Jun-2025	 17:35:30 04-Jun-2025	 17:35:41 04-Jun-2025
17	04-06-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC	 17:21:18 04-Jun-2025	 17:21:41 04-Jun-2025	 17:21:59 04-Jun-2025
18	04-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 17:34:27 04-Jun-2025	 17:34:41 04-Jun-2025	 17:34:54 04-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	04-06-2025	BASEMENT	POLISHING	TUTUP SAMPIT	 17:36:12 04-Jun-2025	 17:36:35 04-Jun-2025	 17:36:58 04-Jun-2025
20	04-06-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 17:16:40 04-Jun-2025	 17:17:55 04-Jun-2025	 17:18:19 04-Jun-2025
21	04-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 14:28:49 04-Jun-2025	 14:29:07 04-Jun-2025	 14:29:26 04-Jun-2025
22	04-06-2025	EXTERNAL	BRUSHING	GUTTER	 14:27:11 04-Jun-2025	 14:27:27 04-Jun-2025	 14:27:44 04-Jun-2025
23	04-06-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH	 16:23:52 04-Jun-2025	 16:26:17 04-Jun-2025	 16:26:39 04-Jun-2025
24	04-06-2025	EXTERNAL	WALL CLEANING	GUTTER	 17:38:26 04-Jun-2025	 17:38:36 04-Jun-2025	 17:38:48 04-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	04-06-2025	EXTERNAL	POLISHING	LANTAI ANDESIT	 17:10:26 04-Jun-2025	 17:10:49 04-Jun-2025	 17:11:18 04-Jun-2025
26	04-06-2025	EXTERNAL	WALL CLEANING	DINDING CAT	 17:39:21 04-Jun-2025	 17:39:46 04-Jun-2025	 17:40:05 04-Jun-2025
27	04-06-2025	EXTERNAL	POLISHING	BOX HYDRANT DAN APAR	 16:22:00 04-Jun-2025	 16:22:25 04-Jun-2025	 16:23:26 04-Jun-2025
28	04-06-2025	EXTERNAL	BRUSHING	BATU ALAM	 17:46:54 04-Jun-2025	 17:47:18 04-Jun-2025	 17:47:45 04-Jun-2025
29	04-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 14:30:27 04-Jun-2025	 14:30:45 04-Jun-2025	 14:31:07 04-Jun-2025
30	04-06-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA	 17:40:35 04-Jun-2025	 17:40:54 04-Jun-2025	 17:41:05 04-Jun-2025







No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	04-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 14:49:25 04-Jun-2025	 14:49:43 04-Jun-2025	 14:50:10 04-Jun-2025
32	04-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING	 17:42:00 04-Jun-2025	 17:42:14 04-Jun-2025	 17:42:29 04-Jun-2025
33	04-06-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR	 14:33:51 04-Jun-2025	 14:34:17 04-Jun-2025	 14:34:41 04-Jun-2025
34	04-06-2025	CARPARK P1-P2	BRUSHING	LANTAI KERAMIK	 16:53:06 04-Jun-2025	 16:53:24 04-Jun-2025	 16:53:54 04-Jun-2025
35	04-06-2025	CARPARK P1-P2	GLASS CLEANING	SAFETY MIRROR	 14:32:05 04-Jun-2025	 14:32:26 04-Jun-2025	 14:32:47 04-Jun-2025
36	04-06-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR	 16:44:11 04-Jun-2025	 16:46:06 04-Jun-2025	 16:46:35 04-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	05-06-2025	LANTAI 3	POLISHING	CLOSET	 16:12:28 05-Jun-2025	 16:12:47 05-Jun-2025	 16:13:15 05-Jun-2025
2	05-06-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE	 14:08:13 05-Jun-2025	 14:08:45 05-Jun-2025	 14:09:45 05-Jun-2025
3	05-06-2025	LANTAI 3	POLISHING	MEJA	 14:06:17 05-Jun-2025	 14:06:54 05-Jun-2025	 14:07:14 05-Jun-2025
4	05-06-2025	LANTAI 3	POLISHING	WASTAFEL	 16:13:50 05-Jun-2025	 16:14:06 05-Jun-2025	 16:14:29 05-Jun-2025
5	05-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 16:36:22 05-Jun-2025	 16:36:43 05-Jun-2025	 16:37:01 05-Jun-2025
6	05-06-2025	LANTAI 2	POLISHING	KUBIKAL	 14:03:33 05-Jun-2025	 14:04:15 05-Jun-2025	 14:04:36 05-Jun-2025






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	05-06-2025	LANTAI 2	BRUSHING	GUTTER	 19:10:20 05-Jun-2025	 19:10:39 05-Jun-2025	 19:10:56 05-Jun-2025
8	05-06-2025	LANTAI 1	SPOTTING	KURSI	 20:58:34 05-Jun-2025	 20:59:03 05-Jun-2025	 20:59:53 05-Jun-2025
9	05-06-2025	LANTAI 1	SPOTTING	LIST SKIRTING	 13:59:33 05-Jun-2025	 13:59:55 05-Jun-2025	 14:00:33 05-Jun-2025
10	05-06-2025	LANTAI 1	POLISHING	FLOOR DRAIN	 16:15:20 05-Jun-2025	 16:15:42 05-Jun-2025	 16:16:17 05-Jun-2025
11	05-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 16:26:06 05-Jun-2025	 16:25:44 05-Jun-2025	 16:27:00 05-Jun-2025
12	05-06-2025	BASEMENT	POLISHING	BOX HYDRANT	 16:19:06 05-Jun-2025	 16:19:57 05-Jun-2025	 16:20:19 05-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	05-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX			
14	05-06-2025	BASEMENT	POLISHING	STAINLESS BULAT			
15	05-06-2025	BASEMENT	POLISHING	TUTUP SAMPIT			
16	05-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			
17	05-06-2025	BASEMENT	HIGH DUSTING	JET FAN			
18	05-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	05-06-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR			
20	05-06-2025	BASEMENT	WASHING	LANTAI EPOXY			
21	05-06-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN			
22	05-06-2025	EXTERNAL	BRUSHING	LOGO JKTP0			
23	05-06-2025	EXTERNAL	POLISHING	DINDING CAT			
24	05-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER			








No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	05-06-2025	EXTERNAL	WALL CLEANING	GUTTER			
26	05-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER			
27	05-06-2025	EXTERNAL	BRUSHING	DINDING BETON			
28	05-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU			
29	05-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING			
30	05-06-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	05-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 13:53:56 05-Jun-2025	 13:54:41 05-Jun-2025	 13:55:24 05-Jun-2025
32	05-06-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER	 16:50:55 05-Jun-2025	 17:00:19 05-Jun-2025	 17:00:36 05-Jun-2025
33	05-06-2025	CARPARK P1-P2	POLISHING	TUTUP SAMPIT	 19:24:13 05-Jun-2025	 19:24:35 05-Jun-2025	 19:24:52 05-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	10-06-2025	LANTAI 3	POLISHING	FLOOR DRAIN	 10:32:50 10-Jun-2025	 10:33:08 10-Jun-2025	 10:33:33 10-Jun-2025
2	10-06-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 10:43:14 10-Jun-2025	 10:43:31 10-Jun-2025	 10:43:48 10-Jun-2025
3	10-06-2025	LANTAI 3	GLASS CLEANING	KACA RAILING	 10:44:28 10-Jun-2025	 10:44:45 10-Jun-2025	 10:45:09 10-Jun-2025
4	10-06-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 19:12:14 10-Jun-2025	 19:12:31 10-Jun-2025	 19:12:49 10-Jun-2025
5	10-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 10:40:08 10-Jun-2025	 10:40:55 10-Jun-2025	 10:41:10 10-Jun-2025
6	10-06-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE	 10:35:52 10-Jun-2025	 10:36:17 10-Jun-2025	 10:36:51 10-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	10-06-2025	LANTAI 2	POLISHING	RAK ACCESORIS	 19:13:14 10-Jun-2025	 19:13:28 10-Jun-2025	 19:13:41 10-Jun-2025
8	10-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 10:42:07 10-Jun-2025	 10:42:25 10-Jun-2025	 10:42:40 10-Jun-2025
9	10-06-2025	LANTAI 2	POLISHING	CLOSET	 10:37:35 10-Jun-2025	 10:37:48 10-Jun-2025	 10:38:07 10-Jun-2025
10	10-06-2025	LANTAI 1	POLISHING	PINTU LIFT	 18:52:51 10-Jun-2025	 18:53:11 10-Jun-2025	 18:53:23 10-Jun-2025
11	10-06-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS	 10:34:17 10-Jun-2025	 10:34:34 10-Jun-2025	 10:34:51 10-Jun-2025
12	10-06-2025	LANTAI 1	POLISHING	WASTAFEL	 19:14:16 10-Jun-2025	 19:14:30 10-Jun-2025	 19:14:46 10-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	10-06-2025	LANTAI 1	POLISHING	PINTU EXIT	 10:39:04 10-Jun-2025	 10:39:14 10-Jun-2025	 10:39:33 10-Jun-2025
14	10-06-2025	BASEMENT	HIGH DUSTING	JET FAN	 18:59:11 10-Jun-2025	 18:59:23 10-Jun-2025	 18:59:45 10-Jun-2025
15	10-06-2025	BASEMENT	HIGH DUSTING	JET FAN	 19:00:12 10-Jun-2025	 19:00:23 10-Jun-2025	 19:00:38 10-Jun-2025
16	10-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 18:54:42 10-Jun-2025	 18:54:56 10-Jun-2025	 18:56:24 10-Jun-2025
17	10-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 18:57:06 10-Jun-2025	 18:57:25 10-Jun-2025	 18:57:40 10-Jun-2025
18	10-06-2025	BASEMENT	WALL CLEANING	PILAR BETON	 19:01:07 10-Jun-2025	 19:01:20 10-Jun-2025	 19:01:38 10-Jun-2025






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	10-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR			
20	10-06-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC			
21	10-06-2025	BASEMENT	POLISHING	BOX HYDRANT			
22	10-06-2025	BASEMENT	BRUSHING	LANTAI KERAMIK			
23	10-06-2025	EXTERNAL	POLISHING	DINDING CAT			
24	10-06-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	10-06-2025	EXTERNAL	HIGH DUSTING	DINDING BETON			
26	10-06-2025	EXTERNAL	BRUSHING	SIGN RAMBU JALAN			
27	10-06-2025	EXTERNAL	BRUSHING	BATU ALAM			
28	10-06-2025	EXTERNAL	POLISHING	ALCUBON			
29	10-06-2025	EXTERNAL	BRUSHING	TEMPAT SAMPAH			
30	10-06-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	10-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 10:55:22 10-Jun-2025	 10:55:34 10-Jun-2025	 10:55:52 10-Jun-2025
32	10-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 18:50:33 10-Jun-2025	 18:50:46 10-Jun-2025	 18:51:06 10-Jun-2025
33	10-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 18:49:35 10-Jun-2025	 18:49:50 10-Jun-2025	 18:50:13 10-Jun-2025
34	10-06-2025	CARPARK P1-P2	POLISHING	RAILING	 19:04:06 10-Jun-2025	 19:04:34 10-Jun-2025	 19:04:51 10-Jun-2025
35	10-06-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT	 10:51:25 10-Jun-2025	 10:51:45 10-Jun-2025	 10:52:07 10-Jun-2025
36	10-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 18:45:52 10-Jun-2025	 18:46:04 10-Jun-2025	 18:46:18 10-Jun-2025






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	10-06-2025	CARPARK P1-P2	HIGH DUSTING	JET FAN			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	11-06-2025	LANTAI 3	POLISHING	KUBIKAL			
2	11-06-2025	LANTAI 3	WALL CLEANING	PLANTER BOX			
3	11-06-2025	LANTAI 3	WALL CLEANING	PINTU LIFT			
4	11-06-2025	LANTAI 3	GLASS CLEANING	MIRROR			
5	11-06-2025	LANTAI 2	POLISHING	CLOSET			
6	11-06-2025	LANTAI 2	SPOTTING	SOFA			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	11-06-2025	LANTAI 2	SPOTTING	FLOOR DRAIN	 19:23:58 11-Jun-2025	 19:24:11 11-Jun-2025	 19:24:26 11-Jun-2025
8	11-06-2025	LANTAI 2	POLISHING	FLOOR DRAIN	 13:45:04 11-Jun-2025	 13:45:16 11-Jun-2025	 13:45:30 11-Jun-2025
9	11-06-2025	LANTAI 1	WALL CLEANING	DINDING LIFT	 14:06:33 11-Jun-2025	 14:06:45 11-Jun-2025	 14:06:55 11-Jun-2025
10	11-06-2025	LANTAI 1	HIGH DUSTING	KIPAS	 19:30:34 11-Jun-2025	 19:30:51 11-Jun-2025	 19:31:06 11-Jun-2025
11	11-06-2025	LANTAI 1	POLISHING	CLOSET	 14:00:36 11-Jun-2025	 14:00:51 11-Jun-2025	 14:01:01 11-Jun-2025
12	11-06-2025	LANTAI 1	SWEEPING	TANGGA	 19:25:00 11-Jun-2025	 19:25:13 11-Jun-2025	 19:25:31 11-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	11-06-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 19:26:20 11-Jun-2025	 19:26:34 11-Jun-2025	 19:26:57 11-Jun-2025
14	11-06-2025	BASEMENT	PLAFON CLEANING	CEILING	 19:27:37 11-Jun-2025	 19:27:55 11-Jun-2025	 19:28:08 11-Jun-2025
15	11-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 19:28:34 11-Jun-2025	 19:28:52 11-Jun-2025	 19:29:03 11-Jun-2025
16	11-06-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR	 19:31:48 11-Jun-2025	 19:32:11 11-Jun-2025	 19:32:25 11-Jun-2025
17	11-06-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC	 19:21:40 11-Jun-2025	 19:21:54 11-Jun-2025	 19:22:10 11-Jun-2025
18	11-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 19:18:09 11-Jun-2025	 19:18:24 11-Jun-2025	 19:18:43 11-Jun-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	11-06-2025	BASEMENT	POLISHING	TUTUP SAMPIT	 19:15:58 11-Jun-2025	 19:16:23 11-Jun-2025	 19:16:39 11-Jun-2025
20	11-06-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 19:13:42 11-Jun-2025	 19:14:00 11-Jun-2025	 19:14:16 11-Jun-2025
21	11-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 13:12:41 11-Jun-2025	 13:13:08 11-Jun-2025	 13:13:30 11-Jun-2025
22	11-06-2025	EXTERNAL	BRUSHING	GUTTER	 13:13:58 11-Jun-2025	 13:14:15 11-Jun-2025	 13:14:30 11-Jun-2025
23	11-06-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH	 19:14:48 11-Jun-2025	 19:15:10 11-Jun-2025	 19:15:26 11-Jun-2025
24	11-06-2025	EXTERNAL	WALL CLEANING	GUTTER	 19:17:03 11-Jun-2025	 19:17:18 11-Jun-2025	 19:17:37 11-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	11-06-2025	EXTERNAL	POLISHING	LANTAI ANDESIT	 19:19:16 11-Jun-2025	 19:19:37 11-Jun-2025	 19:19:53 11-Jun-2025
26	11-06-2025	EXTERNAL	WALL CLEANING	DINDING CAT	 19:33:49 11-Jun-2025	 19:34:01 11-Jun-2025	 19:34:15 11-Jun-2025
27	11-06-2025	EXTERNAL	POLISHING	BOX HYDRANT DAN APAR	 19:34:39 11-Jun-2025	 19:34:52 11-Jun-2025	 19:35:06 11-Jun-2025
28	11-06-2025	EXTERNAL	BRUSHING	BATU ALAM	 19:35:42 11-Jun-2025	 19:35:57 11-Jun-2025	 19:36:11 11-Jun-2025
29	11-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 15:06:37 11-Jun-2025	 15:07:00 11-Jun-2025	 15:07:33 11-Jun-2025
30	11-06-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA	 19:37:04 11-Jun-2025	 19:37:23 11-Jun-2025	 19:37:42 11-Jun-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	11-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING			
32	11-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING			
33	11-06-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR			
34	11-06-2025	CARPARK P1-P2	BRUSHING	LANTAI KERAMIK			
35	11-06-2025	CARPARK P1-P2	GLASS CLEANING	SAFETY MIRROR			
36	11-06-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	12-06-2025	LANTAI 3	POLISHING	CLOSET	 19:02:55 12-Jun-2025	 19:03:14 12-Jun-2025	 19:03:29 12-Jun-2025
2	12-06-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE	 13:36:41 12-Jun-2025	 13:36:57 12-Jun-2025	 13:37:15 12-Jun-2025
3	12-06-2025	LANTAI 3	POLISHING	MEJA	 13:38:28 12-Jun-2025	 13:38:45 12-Jun-2025	 13:39:07 12-Jun-2025
4	12-06-2025	LANTAI 3	POLISHING	WASTAFEL	 19:01:34 12-Jun-2025	 19:01:47 12-Jun-2025	 19:02:01 12-Jun-2025
5	12-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 18:57:56 12-Jun-2025	 18:58:07 12-Jun-2025	 19:00:19 12-Jun-2025
6	12-06-2025	LANTAI 2	POLISHING	KUBIKAL	 13:35:15 12-Jun-2025	 13:35:33 12-Jun-2025	 13:35:57 12-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	12-06-2025	LANTAI 2	BRUSHING	GUTTER	 18:58:42 12-Jun-2025	 18:58:54 12-Jun-2025	 18:59:06 12-Jun-2025
8	12-06-2025	LANTAI 1	SPOTTING	KURSI	 19:00:44 12-Jun-2025	 19:00:55 12-Jun-2025	 19:01:11 12-Jun-2025
9	12-06-2025	LANTAI 1	SPOTTING	LIST SKIRTING	 13:34:09 12-Jun-2025	 13:34:25 12-Jun-2025	 13:34:44 12-Jun-2025
10	12-06-2025	LANTAI 1	POLISHING	FLOOR DRAIN	 18:57:13 12-Jun-2025	 18:57:25 12-Jun-2025	 18:57:36 12-Jun-2025
11	12-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 18:56:16 12-Jun-2025	 18:56:29 12-Jun-2025	 18:56:42 12-Jun-2025
12	12-06-2025	BASEMENT	POLISHING	BOX HYDRANT	 18:54:23 12-Jun-2025	 18:54:34 12-Jun-2025	 18:54:50 12-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	12-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX			
14	12-06-2025	BASEMENT	POLISHING	STAINLESS BULAT			
15	12-06-2025	BASEMENT	POLISHING	TUTUP SAMPIT			
16	12-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			
17	12-06-2025	BASEMENT	HIGH DUSTING	JET FAN			
18	12-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	12-06-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR	 13:32:33 12-Jun-2025	 13:32:47 12-Jun-2025	 13:33:09 12-Jun-2025
20	12-06-2025	BASEMENT	WASHING	LANTAI EPOXY	 13:31:36 12-Jun-2025	 13:31:51 12-Jun-2025	 13:32:09 12-Jun-2025
21	12-06-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN	 13:30:32 12-Jun-2025	 13:30:48 12-Jun-2025	 13:31:09 12-Jun-2025
22	12-06-2025	EXTERNAL	BRUSHING	LOGO JKTP	 18:48:51 12-Jun-2025	 18:49:04 12-Jun-2025	 18:49:19 12-Jun-2025
23	12-06-2025	EXTERNAL	POLISHING	DINDING CAT	 18:48:06 12-Jun-2025	 18:48:18 12-Jun-2025	 18:48:30 12-Jun-2025
24	12-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER	 18:45:51 12-Jun-2025	 18:46:03 12-Jun-2025	 18:46:14 12-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	12-06-2025	EXTERNAL	WALL CLEANING	GUTTER			
26	12-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER			
27	12-06-2025	EXTERNAL	BRUSHING	DINDING BETON			
28	12-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU			
29	12-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING			
30	12-06-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	12-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 13:27:40 12-Jun-2025	 13:28:14 12-Jun-2025	 13:28:35 12-Jun-2025
32	12-06-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER	 18:41:09 12-Jun-2025	 18:41:24 12-Jun-2025	 18:41:42 12-Jun-2025
33	12-06-2025	CARPARK P1-P2	POLISHING	TUTUP SAMPIT	 18:40:21 12-Jun-2025	 18:40:37 12-Jun-2025	 18:40:51 12-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	13-06-2025	LANTAI 3	BRUSHING	LANTAI GRANIT BAKAR	 23:01:37 13-Jun-2025	 23:01:52 13-Jun-2025	 23:02:07 13-Jun-2025
2	13-06-2025	LANTAI 3	WALL CLEANING	HAND RAILING	 13:41:30 13-Jun-2025	 13:41:47 13-Jun-2025	 13:42:06 13-Jun-2025
3	13-06-2025	LANTAI 3	POLISHING	KURSI	 13:39:55 13-Jun-2025	 13:40:28 13-Jun-2025	 13:40:46 13-Jun-2025
4	13-06-2025	LANTAI 3	SPOTTING	SOFA	 13:38:47 13-Jun-2025	 13:39:04 13-Jun-2025	 13:39:22 13-Jun-2025
5	13-06-2025	LANTAI 1	BRUSHING	LANTAI CONCRETE	 13:37:23 13-Jun-2025	 13:37:38 13-Jun-2025	 13:37:54 13-Jun-2025
6	13-06-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH	 13:36:02 13-Jun-2025	 13:36:18 13-Jun-2025	 13:36:39 13-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	13-06-2025	BASEMENT	WASHING	TEMPAT SAMPAH	 13:35:05 13-Jun-2025	 13:35:19 13-Jun-2025	 13:35:34 13-Jun-2025
8	13-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 13:33:46 13-Jun-2025	 13:34:01 13-Jun-2025	 13:34:16 13-Jun-2025
9	13-06-2025	BASEMENT	POLISHING	STAINLESS BULAT	 13:31:53 13-Jun-2025	 13:32:08 13-Jun-2025	 13:32:25 13-Jun-2025
10	13-06-2025	EXTERNAL	BRUSHING	ALCUBON	 13:30:44 13-Jun-2025	 13:31:01 13-Jun-2025	 13:31:23 13-Jun-2025
11	13-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING	 13:28:20 13-Jun-2025	 13:28:35 13-Jun-2025	 13:28:55 13-Jun-2025
12	13-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 13:29:25 13-Jun-2025	 13:29:42 13-Jun-2025	 13:29:58 13-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	13-06-2025	CARPARK P1-P2	HIGH DUSTING	OUTDOOR AC	 13:27:04 13-Jun-2025	 13:27:26 13-Jun-2025	 13:27:45 13-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	16-06-2025	LANTAI 3	POLISHING	URINOIR			
2	16-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH			
3	16-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS			
4	16-06-2025	LANTAI 3	POLISHING	TRAY			
5	16-06-2025	LANTAI 3	POLISHING	CLOSET			
6	16-06-2025	LANTAI 2	SPOTTING	SOFA			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	16-06-2025	LANTAI 2	WALL CLEANING	PINTU LIFT	 19:25:15 16-Jun-2025	 19:25:33 16-Jun-2025	 19:25:48 16-Jun-2025
8	16-06-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR	 19:26:15 16-Jun-2025	 19:26:32 16-Jun-2025	 19:26:46 16-Jun-2025
9	16-06-2025	LANTAI 2	POLISHING	CLOSET	 10:50:57 16-Jun-2025	 10:51:21 16-Jun-2025	 10:51:35 16-Jun-2025
10	16-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 19:27:14 16-Jun-2025	 19:27:28 16-Jun-2025	 19:27:41 16-Jun-2025
11	16-06-2025	LANTAI 1	HIGH DUSTING	NEON LED	 11:00:02 16-Jun-2025	 11:00:14 16-Jun-2025	 11:00:27 16-Jun-2025
12	16-06-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK	 19:28:07 16-Jun-2025	 19:28:22 16-Jun-2025	 19:28:37 16-Jun-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	16-06-2025	LANTAI 1	POLISHING	KUBIKAL	 10:52:18 16-Jun-2025	 10:52:28 16-Jun-2025	 10:52:56 16-Jun-2025
14	16-06-2025	LANTAI 1	GLASS CLEANING	KACA	 19:29:04 16-Jun-2025	 19:29:18 16-Jun-2025	 19:29:32 16-Jun-2025
15	16-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 19:29:52 16-Jun-2025	 19:30:06 16-Jun-2025	 19:30:20 16-Jun-2025
16	16-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 19:21:53 16-Jun-2025	 19:22:08 16-Jun-2025	 19:22:41 16-Jun-2025
17	16-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 19:19:40 16-Jun-2025	 19:19:53 16-Jun-2025	 19:20:21 16-Jun-2025
18	16-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK	 19:17:53 16-Jun-2025	 19:18:06 16-Jun-2025	 19:18:21 16-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	16-06-2025	BASEMENT	WASHING	LANTAI EPOXY			
20	16-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			
21	16-06-2025	BASEMENT	WALL CLEANING	PILAR BETON			
22	16-06-2025	BASEMENT	PLAFON CLEANING	CEILING			
23	16-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX			
24	16-06-2025	EXTERNAL	POLISHING	PIPA HYDRANT			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	16-06-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR			
26	16-06-2025	EXTERNAL	WALL CLEANING	PIPA HYDRANT			
27	16-06-2025	EXTERNAL	BRUSHING	ALCUBON			
28	16-06-2025	EXTERNAL	BRUSHING	PIPA HYDRANT			
29	16-06-2025	EXTERNAL	HIGH DUSTING	SIGN RAMBU JALAN			
30	16-06-2025	EXTERNAL	BRUSHING	LOGO JKPTO			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	16-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 15:09:24 16-Jun-2025	 15:09:56 16-Jun-2025	 15:10:40 16-Jun-2025
32	16-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 19:34:31 16-Jun-2025	 19:34:45 16-Jun-2025	 19:34:59 16-Jun-2025
33	16-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 13:00:09 16-Jun-2025	 13:00:48 16-Jun-2025	 13:01:37 16-Jun-2025
34	16-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 19:35:25 16-Jun-2025	 19:35:48 16-Jun-2025	 19:36:04 16-Jun-2025
35	16-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 11:12:02 16-Jun-2025	 11:12:24 16-Jun-2025	 11:12:58 16-Jun-2025
36	16-06-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 19:36:22 16-Jun-2025	 19:36:36 16-Jun-2025	 19:36:52 16-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	16-06-2025	CARPARK P1-P2	POLISHING	STAINLESS BULAT	 11:08:47 16-Jun-2025	 11:09:08 16-Jun-2025	 11:09:22 16-Jun-2025
38	16-06-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX	 19:37:17 16-Jun-2025	 19:37:30 16-Jun-2025	 19:37:46 16-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	17-06-2025	LANTAI 3	POLISHING	FLOOR DRAIN	 11:13:41 17-Jun-2025	 11:14:03 17-Jun-2025	 11:14:22 17-Jun-2025
2	17-06-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 11:16:51 17-Jun-2025	 11:17:43 17-Jun-2025	 11:18:04 17-Jun-2025
3	17-06-2025	LANTAI 3	GLASS CLEANING	KACA RAILING	 11:21:01 17-Jun-2025	 11:21:16 17-Jun-2025	 11:21:29 17-Jun-2025
4	17-06-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 22:13:13 17-Jun-2025	 22:13:29 17-Jun-2025	 22:13:48 17-Jun-2025
5	17-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 11:19:48 17-Jun-2025	 11:20:05 17-Jun-2025	 11:20:21 17-Jun-2025
6	17-06-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE	 11:38:23 17-Jun-2025	 11:39:19 17-Jun-2025	 11:41:18 17-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	17-06-2025	LANTAI 2	POLISHING	RAK ACCESORIS	 11:54:15 17-Jun-2025	 11:54:34 17-Jun-2025	 11:54:53 17-Jun-2025
8	17-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 11:22:10 17-Jun-2025	 11:22:31 17-Jun-2025	 11:22:46 17-Jun-2025
9	17-06-2025	LANTAI 2	POLISHING	CLOSET	 11:51:13 17-Jun-2025	 11:52:36 17-Jun-2025	 11:53:05 17-Jun-2025
10	17-06-2025	LANTAI 1	POLISHING	PINTU LIFT	 11:55:36 17-Jun-2025	 11:56:15 17-Jun-2025	 11:57:06 17-Jun-2025
11	17-06-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS	 11:14:50 17-Jun-2025	 11:15:03 17-Jun-2025	 11:15:38 17-Jun-2025
12	17-06-2025	LANTAI 1	POLISHING	WASTAFEL	 22:14:16 17-Jun-2025	 22:14:32 17-Jun-2025	 22:14:47 17-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	17-06-2025	LANTAI 1	POLISHING	PINTU EXIT	 11:24:07 17-Jun-2025	 11:24:23 17-Jun-2025	 11:24:40 17-Jun-2025
14	17-06-2025	BASEMENT	HIGH DUSTING	JET FAN	 22:15:12 17-Jun-2025	 22:15:25 17-Jun-2025	 22:15:39 17-Jun-2025
15	17-06-2025	BASEMENT	HIGH DUSTING	JET FAN	 22:16:00 17-Jun-2025	 22:16:15 17-Jun-2025	 22:16:31 17-Jun-2025
16	17-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 22:17:04 17-Jun-2025	 22:17:18 17-Jun-2025	 22:17:33 17-Jun-2025
17	17-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 22:17:57 17-Jun-2025	 22:18:13 17-Jun-2025	 22:18:26 17-Jun-2025
18	17-06-2025	BASEMENT	WALL CLEANING	PILAR BETON	 22:18:48 17-Jun-2025	 22:19:02 17-Jun-2025	 22:19:17 17-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	17-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR			
20	17-06-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC			
21	17-06-2025	BASEMENT	POLISHING	BOX HYDRANT			
22	17-06-2025	BASEMENT	BRUSHING	LANTAI KERAMIK			
23	17-06-2025	EXTERNAL	POLISHING	DINDING CAT			
24	17-06-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	17-06-2025	EXTERNAL	HIGH DUSTING	DINDING BETON			
26	17-06-2025	EXTERNAL	BRUSHING	SIGN RAMBU JALAN			
27	17-06-2025	EXTERNAL	BRUSHING	BATU ALAM			
28	17-06-2025	EXTERNAL	POLISHING	ALCUBON			
29	17-06-2025	EXTERNAL	BRUSHING	TEMPAT SAMPAH			
30	17-06-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	17-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 11:47:47 17-Jun-2025	 11:48:57 17-Jun-2025	 11:49:32 17-Jun-2025
32	17-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 22:27:22 17-Jun-2025	 22:27:36 17-Jun-2025	 22:27:53 17-Jun-2025
33	17-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 12:05:10 17-Jun-2025	 12:05:31 17-Jun-2025	 12:05:50 17-Jun-2025
34	17-06-2025	CARPARK P1-P2	POLISHING	RAILING	 22:28:16 17-Jun-2025	 22:28:35 17-Jun-2025	 22:28:50 17-Jun-2025
35	17-06-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT	 11:31:39 17-Jun-2025	 11:32:16 17-Jun-2025	 11:32:41 17-Jun-2025
36	17-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 22:29:12 17-Jun-2025	 22:29:28 17-Jun-2025	 22:29:42 17-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	17-06-2025	CARPARK P1-P2	HIGH DUSTING	JET FAN			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	18-06-2025	LANTAI 3	POLISHING	KUBIKAL	 11:45:13 18-Jun-2025	 11:45:27 18-Jun-2025	 11:45:45 18-Jun-2025
2	18-06-2025	LANTAI 3	WALL CLEANING	PLANTER BOX	 12:01:05 18-Jun-2025	 12:01:57 18-Jun-2025	 12:02:11 18-Jun-2025
3	18-06-2025	LANTAI 3	WALL CLEANING	PINTU LIFT	 11:53:17 18-Jun-2025	 11:53:44 18-Jun-2025	 11:54:05 18-Jun-2025
4	18-06-2025	LANTAI 3	GLASS CLEANING	MIRROR	 18:08:51 18-Jun-2025	 18:09:09 18-Jun-2025	 18:09:25 18-Jun-2025
5	18-06-2025	LANTAI 2	POLISHING	CLOSET	 11:42:25 18-Jun-2025	 11:43:04 18-Jun-2025	 11:43:44 18-Jun-2025
6	18-06-2025	LANTAI 2	SPOTTING	SOFA	 11:57:39 18-Jun-2025	 11:57:51 18-Jun-2025	 11:58:06 18-Jun-2025








No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	18-06-2025	LANTAI 2	SPOTTING	FLOOR DRAIN	 17:47:04 18-Jun-2025	 17:48:17 18-Jun-2025	 17:50:12 18-Jun-2025
8	18-06-2025	LANTAI 2	POLISHING	FLOOR DRAIN	 11:47:15 18-Jun-2025	 11:47:49 18-Jun-2025	 11:48:16 18-Jun-2025
9	18-06-2025	LANTAI 1	WALL CLEANING	DINDING LIFT	 11:54:48 18-Jun-2025	 11:56:06 18-Jun-2025	 11:56:29 18-Jun-2025
10	18-06-2025	LANTAI 1	HIGH DUSTING	KIPAS	 18:34:11 18-Jun-2025	 18:34:32 18-Jun-2025	 18:34:56 18-Jun-2025
11	18-06-2025	LANTAI 1	POLISHING	CLOSET	 11:49:11 18-Jun-2025	 11:49:23 18-Jun-2025	 11:49:59 18-Jun-2025
12	18-06-2025	LANTAI 1	SWEEPING	TANGGA	 17:54:07 18-Jun-2025	 17:54:30 18-Jun-2025	 17:55:20 18-Jun-2025









No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	18-06-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 18:10:00 18-Jun-2025	 18:10:16 18-Jun-2025	 18:10:36 18-Jun-2025
14	18-06-2025	BASEMENT	PLAFON CLEANING	CEILING	 18:11:07 18-Jun-2025	 18:11:23 18-Jun-2025	 18:11:40 18-Jun-2025
15	18-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 18:35:33 18-Jun-2025	 18:35:50 18-Jun-2025	 18:36:07 18-Jun-2025
16	18-06-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR	 18:36:42 18-Jun-2025	 18:37:23 18-Jun-2025	 18:37:41 18-Jun-2025
17	18-06-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC	 18:12:35 18-Jun-2025	 18:12:52 18-Jun-2025	 18:13:08 18-Jun-2025
18	18-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 18:38:04 18-Jun-2025	 18:38:17 18-Jun-2025	 18:38:32 18-Jun-2025









No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	18-06-2025	BASEMENT	POLISHING	TUTUP SAMPIT			
20	18-06-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR			
21	18-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG			
22	18-06-2025	EXTERNAL	BRUSHING	GUTTER			
23	18-06-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH			
24	18-06-2025	EXTERNAL	WALL CLEANING	GUTTER			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	18-06-2025	EXTERNAL	POLISHING	LANTAI ANDESIT			
26	18-06-2025	EXTERNAL	WALL CLEANING	DINDING CAT			
27	18-06-2025	EXTERNAL	POLISHING	BOX HYDRANT DAN APAR			
28	18-06-2025	EXTERNAL	BRUSHING	BATU ALAM			
29	18-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET			
30	18-06-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	18-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING			
32	18-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING			
33	18-06-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR			
34	18-06-2025	CARPARK P1-P2	BRUSHING	LANTAI KERAMIK			
35	18-06-2025	CARPARK P1-P2	GLASS CLEANING	SAFETY MIRROR			
36	18-06-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	19-06-2025	LANTAI 3	POLISHING	CLOSET			
2	19-06-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE			
3	19-06-2025	LANTAI 3	POLISHING	MEJA			
4	19-06-2025	LANTAI 3	POLISHING	WASTAFEL			
5	19-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA			
6	19-06-2025	LANTAI 2	POLISHING	KUBIKAL			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	19-06-2025	LANTAI 2	BRUSHING	GUTTER	 20:13:00 19-Jun-2025	 20:13:11 19-Jun-2025	 20:13:24 19-Jun-2025
8	19-06-2025	LANTAI 1	SPOTTING	KURSI	 20:13:47 19-Jun-2025	 20:13:59 19-Jun-2025	 20:14:12 19-Jun-2025
9	19-06-2025	LANTAI 1	SPOTTING	LIST SKIRTING	 11:15:27 19-Jun-2025	 11:15:46 19-Jun-2025	 11:16:04 19-Jun-2025
10	19-06-2025	LANTAI 1	POLISHING	FLOOR DRAIN	 20:14:31 19-Jun-2025	 20:14:42 19-Jun-2025	 20:14:56 19-Jun-2025
11	19-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 20:15:28 19-Jun-2025	 20:15:39 19-Jun-2025	 20:17:58 19-Jun-2025
12	19-06-2025	BASEMENT	POLISHING	BOX HYDRANT	 19:52:28 19-Jun-2025	 19:52:40 19-Jun-2025	 19:53:23 19-Jun-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	19-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX			
14	19-06-2025	BASEMENT	POLISHING	STAINLESS BULAT			
15	19-06-2025	BASEMENT	POLISHING	TUTUP SAMPIT			
16	19-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			
17	19-06-2025	BASEMENT	HIGH DUSTING	JET FAN			
18	19-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	19-06-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR			
20	19-06-2025	BASEMENT	WASHING	LANTAI EPOXY			
21	19-06-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN			
22	19-06-2025	EXTERNAL	BRUSHING	LOGO JKTP0			
23	19-06-2025	EXTERNAL	POLISHING	DINDING CAT			
24	19-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	19-06-2025	EXTERNAL	WALL CLEANING	GUTTER	 20:23:12 19-Jun-2025	 20:23:23 19-Jun-2025	 20:23:35 19-Jun-2025
26	19-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER	 20:24:00 19-Jun-2025	 20:24:13 19-Jun-2025	 20:24:24 19-Jun-2025
27	19-06-2025	EXTERNAL	BRUSHING	DINDING BETON	 20:24:45 19-Jun-2025	 20:24:57 19-Jun-2025	 20:25:13 19-Jun-2025
28	19-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 20:25:43 19-Jun-2025	 20:25:55 19-Jun-2025	 20:26:07 19-Jun-2025
29	19-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 11:34:42 19-Jun-2025	 11:35:03 19-Jun-2025	 11:35:28 19-Jun-2025
30	19-06-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA	 20:07:33 19-Jun-2025	 20:08:28 19-Jun-2025	 20:10:11 19-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	19-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 11:36:49 19-Jun-2025	 11:37:09 19-Jun-2025	 11:37:39 19-Jun-2025
32	19-06-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER	 20:03:25 19-Jun-2025	 20:03:38 19-Jun-2025	 20:04:18 19-Jun-2025
33	19-06-2025	CARPARK P1-P2	POLISHING	TUTUP SAMPIT	 20:26:28 19-Jun-2025	 20:26:40 19-Jun-2025	 20:26:52 19-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	20-06-2025	LANTAI 3	BRUSHING	LANTAI GRANIT BAKAR	 19:33:34 20-Jun-2025	 19:34:01 20-Jun-2025	 19:34:20 20-Jun-2025
2	20-06-2025	LANTAI 3	WALL CLEANING	HAND RAILING	 12:58:04 20-Jun-2025	 12:58:23 20-Jun-2025	 12:58:38 20-Jun-2025
3	20-06-2025	LANTAI 3	POLISHING	KURSI	 12:56:48 20-Jun-2025	 12:57:02 20-Jun-2025	 12:57:16 20-Jun-2025
4	20-06-2025	LANTAI 3	SPOTTING	SOFA	 12:55:47 20-Jun-2025	 12:56:08 20-Jun-2025	 12:56:24 20-Jun-2025
5	20-06-2025	LANTAI 2	GLASS CLEANING	TEMPAT SAMPAH	 19:15:53 20-Jun-2025	 19:16:16 20-Jun-2025	 19:16:43 20-Jun-2025
6	20-06-2025	LANTAI 2	POLISHING	FLOOR DRAIN	 21:02:41 20-Jun-2025	 21:03:07 20-Jun-2025	 21:03:37 20-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	20-06-2025	LANTAI 2	WALL CLEANING	PLANTER BOX			
8	20-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH STAINLESS			
9	20-06-2025	LANTAI 1	BRUSHING	LANTAI CONCRETE			
10	20-06-2025	LANTAI 1	SPOTTING	AC GRILL			
11	20-06-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH			
12	20-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	20-06-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 19:26:12 20-Jun-2025	 19:26:35 20-Jun-2025	 19:26:55 20-Jun-2025
14	20-06-2025	BASEMENT	BRUSHING	LANTAI KERAMIK	 19:27:58 20-Jun-2025	 19:28:17 20-Jun-2025	 19:28:46 20-Jun-2025
15	20-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 20:00:51 20-Jun-2025	 20:01:16 20-Jun-2025	 20:01:36 20-Jun-2025
16	20-06-2025	BASEMENT	WASHING	TEMPAT SAMPAH	 19:36:12 20-Jun-2025	 19:36:28 20-Jun-2025	 19:36:54 20-Jun-2025
17	20-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 19:30:06 20-Jun-2025	 19:30:32 20-Jun-2025	 19:31:01 20-Jun-2025
18	20-06-2025	BASEMENT	WASHING	TEMPAT SAMPAH	 12:43:38 20-Jun-2025	 12:44:00 20-Jun-2025	 12:44:32 20-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	20-06-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT			
20	20-06-2025	BASEMENT	POLISHING	STAINLESS BULAT			
21	20-06-2025	EXTERNAL	BRUSHING	LANTAI BETON			
22	20-06-2025	EXTERNAL	WALL CLEANING	BATU ALAM			
23	20-06-2025	EXTERNAL	POLISHING	LANTAI BETON			
24	20-06-2025	EXTERNAL	WALL CLEANING	BOX HYDRANT DAN APAR			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	20-06-2025	EXTERNAL	WALL CLEANING	DINDING BETON	 19:42:38 20-Jun-2025	 19:43:09 20-Jun-2025	 19:43:29 20-Jun-2025
26	20-06-2025	EXTERNAL	POLISHING	LANTAI ANDESIT	 21:06:28 20-Jun-2025	 21:06:55 20-Jun-2025	 21:07:22 20-Jun-2025
27	20-06-2025	EXTERNAL	BRUSHING	ALCUBON	 12:50:56 20-Jun-2025	 12:51:11 20-Jun-2025	 12:51:27 20-Jun-2025
28	20-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING	 12:49:48 20-Jun-2025	 12:50:02 20-Jun-2025	 12:50:17 20-Jun-2025
29	20-06-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI	 19:40:49 20-Jun-2025	 19:41:07 20-Jun-2025	 19:41:30 20-Jun-2025
30	20-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 12:48:43 20-Jun-2025	 12:48:58 20-Jun-2025	 12:49:17 20-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	20-06-2025	CARPARK P1-P2	HIGH DUSTING	OUTDOOR AC	 12:47:32 20-Jun-2025	 12:47:51 20-Jun-2025	 12:48:09 20-Jun-2025
32	20-06-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX	 19:37:36 20-Jun-2025	 19:38:14 20-Jun-2025	 19:38:42 20-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	23-06-2025	LANTAI 3	POLISHING	URINOIR			
2	23-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH			
3	23-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS			
4	23-06-2025	LANTAI 3	POLISHING	TRAY			
5	23-06-2025	LANTAI 3	POLISHING	CLOSET			
6	23-06-2025	LANTAI 2	SPOTTING	SOFA			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	23-06-2025	LANTAI 2	WALL CLEANING	PINTU LIFT	 19:24:23 23-Jun-2025	 19:24:50 23-Jun-2025	 19:25:09 23-Jun-2025
8	23-06-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR	 19:28:20 23-Jun-2025	 19:28:44 23-Jun-2025	 19:29:15 23-Jun-2025
9	23-06-2025	LANTAI 2	POLISHING	CLOSET	 10:47:55 23-Jun-2025	 10:48:29 23-Jun-2025	 10:48:58 23-Jun-2025
10	23-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 19:30:02 23-Jun-2025	 19:30:30 23-Jun-2025	 19:31:03 23-Jun-2025
11	23-06-2025	LANTAI 1	HIGH DUSTING	NEON LED	 10:51:55 23-Jun-2025	 10:52:06 23-Jun-2025	 10:52:18 23-Jun-2025
12	23-06-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK	 19:26:59 23-Jun-2025	 19:27:16 23-Jun-2025	 19:27:42 23-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	23-06-2025	LANTAI 1	POLISHING	KUBIKAL	 10:53:21 23-Jun-2025	 10:54:41 23-Jun-2025	 10:54:53 23-Jun-2025
14	23-06-2025	LANTAI 1	GLASS CLEANING	KACA	 19:31:41 23-Jun-2025	 19:31:58 23-Jun-2025	 19:32:27 23-Jun-2025
15	23-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 19:33:10 23-Jun-2025	 19:33:36 23-Jun-2025	 19:34:01 23-Jun-2025
16	23-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 19:21:58 23-Jun-2025	 19:22:16 23-Jun-2025	 19:22:34 23-Jun-2025
17	23-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 19:19:31 23-Jun-2025	 19:19:49 23-Jun-2025	 19:20:13 23-Jun-2025
18	23-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK	 19:17:02 23-Jun-2025	 19:17:26 23-Jun-2025	 19:17:46 23-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	23-06-2025	BASEMENT	WASHING	LANTAI EPOXY	 19:14:12 23-Jun-2025	 19:14:37 23-Jun-2025	 19:15:05 23-Jun-2025
20	23-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 19:15:35 23-Jun-2025	 19:15:55 23-Jun-2025	 19:16:20 23-Jun-2025
21	23-06-2025	BASEMENT	WALL CLEANING	PILAR BETON	 19:18:14 23-Jun-2025	 19:18:33 23-Jun-2025	 19:18:54 23-Jun-2025
22	23-06-2025	BASEMENT	PLAFON CLEANING	CEILING	 12:47:02 23-Jun-2025	 12:47:29 23-Jun-2025	 12:48:05 23-Jun-2025
23	23-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX	 10:59:53 23-Jun-2025	 11:00:25 23-Jun-2025	 11:00:37 23-Jun-2025
24	23-06-2025	EXTERNAL	POLISHING	PIPA HYDRANT	 11:01:43 23-Jun-2025	 11:02:02 23-Jun-2025	 11:02:19 23-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	23-06-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR			
26	23-06-2025	EXTERNAL	WALL CLEANING	PIPA HYDRANT			
27	23-06-2025	EXTERNAL	BRUSHING	ALCUBON			
28	23-06-2025	EXTERNAL	BRUSHING	PIPA HYDRANT			
29	23-06-2025	EXTERNAL	HIGH DUSTING	SIGN RAMBU JALAN			
30	23-06-2025	EXTERNAL	BRUSHING	LOGO JKTP0			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	23-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 15:04:07 23-Jun-2025	 15:05:15 23-Jun-2025	 15:05:39 23-Jun-2025
32	23-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 19:42:02 23-Jun-2025	 19:42:32 23-Jun-2025	 19:43:00 23-Jun-2025
33	23-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 12:14:47 23-Jun-2025	 12:15:19 23-Jun-2025	 12:15:58 23-Jun-2025
34	23-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 19:43:57 23-Jun-2025	 19:44:23 23-Jun-2025	 19:45:07 23-Jun-2025
35	23-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 11:05:57 23-Jun-2025	 11:06:14 23-Jun-2025	 11:06:34 23-Jun-2025
36	23-06-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 19:46:02 23-Jun-2025	 19:46:31 23-Jun-2025	 19:47:01 23-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	23-06-2025	CARPARK P1-P2	POLISHING	STAINLESS BULAT			
38	23-06-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	24-06-2025	LANTAI 3	POLISHING	FLOOR DRAIN	 10:48:26 24-Jun-2025	 10:50:47 24-Jun-2025	 10:51:29 24-Jun-2025
2	24-06-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 11:00:52 24-Jun-2025	 11:01:32 24-Jun-2025	 11:01:48 24-Jun-2025
3	24-06-2025	LANTAI 3	GLASS CLEANING	KACA RAILING	 11:02:20 24-Jun-2025	 11:02:29 24-Jun-2025	 11:03:07 24-Jun-2025
4	24-06-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 21:14:45 24-Jun-2025	 21:15:03 24-Jun-2025	 21:15:21 24-Jun-2025
5	24-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 10:59:11 24-Jun-2025	 10:59:21 24-Jun-2025	 10:59:36 24-Jun-2025
6	24-06-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE	 10:52:15 24-Jun-2025	 10:52:30 24-Jun-2025	 10:52:41 24-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	24-06-2025	LANTAI 2	POLISHING	RAK ACCESORIS	 21:16:10 24-Jun-2025	 21:16:32 24-Jun-2025	 21:16:50 24-Jun-2025
8	24-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 11:03:41 24-Jun-2025	 11:03:59 24-Jun-2025	 11:04:29 24-Jun-2025
9	24-06-2025	LANTAI 2	POLISHING	CLOSET	 21:18:54 24-Jun-2025	 21:19:18 24-Jun-2025	 21:19:35 24-Jun-2025
10	24-06-2025	LANTAI 1	POLISHING	PINTU LIFT	 21:17:30 24-Jun-2025	 21:17:44 24-Jun-2025	 21:18:13 24-Jun-2025
11	24-06-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS	 10:53:43 24-Jun-2025	 10:53:58 24-Jun-2025	 10:54:38 24-Jun-2025
12	24-06-2025	LANTAI 1	POLISHING	WASTAFEL	 21:20:00 24-Jun-2025	 21:20:19 24-Jun-2025	 21:20:40 24-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	24-06-2025	LANTAI 1	POLISHING	PINTU EXIT	 11:07:32 24-Jun-2025	 11:07:43 24-Jun-2025	 11:07:58 24-Jun-2025
14	24-06-2025	BASEMENT	HIGH DUSTING	JET FAN	 21:21:02 24-Jun-2025	 21:22:14 24-Jun-2025	 21:22:33 24-Jun-2025
15	24-06-2025	BASEMENT	HIGH DUSTING	JET FAN	 21:24:26 24-Jun-2025	 21:24:49 24-Jun-2025	 21:25:08 24-Jun-2025
16	24-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 21:23:27 24-Jun-2025	 21:23:44 24-Jun-2025	 21:24:00 24-Jun-2025
17	24-06-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 21:13:29 24-Jun-2025	 21:13:45 24-Jun-2025	 21:14:12 24-Jun-2025
18	24-06-2025	BASEMENT	WALL CLEANING	PILAR BETON	 21:10:03 24-Jun-2025	 21:10:45 24-Jun-2025	 21:11:03 24-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	24-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR			
20	24-06-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC			
21	24-06-2025	BASEMENT	POLISHING	BOX HYDRANT			
22	24-06-2025	BASEMENT	BRUSHING	LANTAI KERAMIK			
23	24-06-2025	EXTERNAL	POLISHING	DINDING CAT			
24	24-06-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	24-06-2025	EXTERNAL	HIGH DUSTING	DINDING BETON			
26	24-06-2025	EXTERNAL	BRUSHING	SIGN RAMBU JALAN			
27	24-06-2025	EXTERNAL	BRUSHING	BATU ALAM			
28	24-06-2025	EXTERNAL	POLISHING	ALCUBON			
29	24-06-2025	EXTERNAL	BRUSHING	TEMPAT SAMPAH			
30	24-06-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	24-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 11:11:17 24-Jun-2025	 11:11:28 24-Jun-2025	 11:12:00 24-Jun-2025
32	24-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 21:30:54 24-Jun-2025	 21:31:07 24-Jun-2025	 21:31:22 24-Jun-2025
33	24-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 21:32:10 24-Jun-2025	 21:32:29 24-Jun-2025	 21:32:46 24-Jun-2025
34	24-06-2025	CARPARK P1-P2	POLISHING	RAILING	 21:37:11 24-Jun-2025	 21:37:24 24-Jun-2025	 21:37:41 24-Jun-2025
35	24-06-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT	 11:13:47 24-Jun-2025	 11:14:05 24-Jun-2025	 11:14:28 24-Jun-2025
36	24-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 21:33:27 24-Jun-2025	 21:33:53 24-Jun-2025	 21:34:17 24-Jun-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	24-06-2025	CARPARK P1-P2	HIGH DUSTING	JET FAN			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	26-06-2025	LANTAI 3	POLISHING	CLOSET	 17:25:52 26-Jun-2025	 17:26:41 26-Jun-2025	 17:27:09 26-Jun-2025
2	26-06-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE	 17:47:55 26-Jun-2025	 17:48:07 26-Jun-2025	 17:48:23 26-Jun-2025
3	26-06-2025	LANTAI 3	POLISHING	MEJA	 20:31:54 26-Jun-2025	 20:32:10 26-Jun-2025	 20:32:23 26-Jun-2025
4	26-06-2025	LANTAI 3	POLISHING	WASTAFEL	 20:32:43 26-Jun-2025	 20:32:57 26-Jun-2025	 20:33:12 26-Jun-2025
5	26-06-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 20:33:32 26-Jun-2025	 20:33:46 26-Jun-2025	 20:34:03 26-Jun-2025
6	26-06-2025	LANTAI 2	POLISHING	KUBIKAL	 20:34:57 26-Jun-2025	 20:35:11 26-Jun-2025	 20:35:23 26-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	26-06-2025	LANTAI 2	BRUSHING	GUTTER	 20:35:57 26-Jun-2025	 20:36:09 26-Jun-2025	 20:36:22 26-Jun-2025
8	26-06-2025	LANTAI 1	SPOTTING	KURSI	 20:36:49 26-Jun-2025	 20:37:02 26-Jun-2025	 20:37:15 26-Jun-2025
9	26-06-2025	LANTAI 1	SPOTTING	LIST SKIRTING	 20:37:38 26-Jun-2025	 20:37:51 26-Jun-2025	 20:38:09 26-Jun-2025
10	26-06-2025	LANTAI 1	POLISHING	FLOOR DRAIN	 17:47:03 26-Jun-2025	 17:47:22 26-Jun-2025	 17:47:35 26-Jun-2025
11	26-06-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 17:44:10 26-Jun-2025	 17:44:23 26-Jun-2025	 17:44:37 26-Jun-2025
12	26-06-2025	BASEMENT	POLISHING	BOX HYDRANT	 17:42:18 26-Jun-2025	 17:42:44 26-Jun-2025	 17:43:00 26-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	26-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX			
14	26-06-2025	BASEMENT	POLISHING	STAINLESS BULAT			
15	26-06-2025	BASEMENT	POLISHING	TUTUP SAMPIT			
16	26-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			
17	26-06-2025	BASEMENT	HIGH DUSTING	JET FAN			
18	26-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	26-06-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR			
20	26-06-2025	BASEMENT	WASHING	LANTAI EPOXY			
21	26-06-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN			
22	26-06-2025	EXTERNAL	BRUSHING	LOGO JKPTO			
23	26-06-2025	EXTERNAL	POLISHING	DINDING CAT			
24	26-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	26-06-2025	EXTERNAL	WALL CLEANING	GUTTER	 17:32:24 26-Jun-2025	 17:32:50 26-Jun-2025	 17:33:08 26-Jun-2025
26	26-06-2025	EXTERNAL	BRUSHING	DINDING ROASTER	 17:37:21 26-Jun-2025	 17:37:35 26-Jun-2025	 17:37:47 26-Jun-2025
27	26-06-2025	EXTERNAL	BRUSHING	DINDING BETON	 20:42:18 26-Jun-2025	 20:42:31 26-Jun-2025	 20:42:46 26-Jun-2025
28	26-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 20:39:30 26-Jun-2025	 20:39:42 26-Jun-2025	 20:39:57 26-Jun-2025
29	26-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 20:43:12 26-Jun-2025	 20:43:27 26-Jun-2025	 20:43:40 26-Jun-2025
30	26-06-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA	 17:23:13 26-Jun-2025	 17:23:48 26-Jun-2025	 17:24:27 26-Jun-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	26-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 20:43:57 26-Jun-2025	 20:44:09 26-Jun-2025	 20:44:22 26-Jun-2025
32	26-06-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER	 17:21:27 26-Jun-2025	 17:21:49 26-Jun-2025	 17:22:19 26-Jun-2025
33	26-06-2025	CARPARK P1-P2	POLISHING	TUTUP SAMPIT	 20:44:47 26-Jun-2025	 20:45:00 26-Jun-2025	 20:45:14 26-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	30-06-2025	LANTAI 3	POLISHING	URINOIR	 11:16:14 30-Jun-2025	 11:16:31 30-Jun-2025	 11:16:53 30-Jun-2025
2	30-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH	 20:05:45 30-Jun-2025	 20:06:05 30-Jun-2025	 20:06:20 30-Jun-2025
3	30-06-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS	 11:17:42 30-Jun-2025	 11:17:59 30-Jun-2025	 11:18:36 30-Jun-2025
4	30-06-2025	LANTAI 3	POLISHING	TRAY	 11:26:24 30-Jun-2025	 11:27:04 30-Jun-2025	 11:27:22 30-Jun-2025
5	30-06-2025	LANTAI 3	POLISHING	CLOSET	 20:06:47 30-Jun-2025	 20:07:03 30-Jun-2025	 20:07:17 30-Jun-2025
6	30-06-2025	LANTAI 2	SPOTTING	SOFA	 11:33:40 30-Jun-2025	 11:33:52 30-Jun-2025	 11:34:11 30-Jun-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	30-06-2025	LANTAI 2	WALL CLEANING	PINTU LIFT	 20:07:43 30-Jun-2025	 20:07:59 30-Jun-2025	 20:08:14 30-Jun-2025
8	30-06-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR	 20:08:46 30-Jun-2025	 20:09:03 30-Jun-2025	 20:09:20 30-Jun-2025
9	30-06-2025	LANTAI 2	POLISHING	CLOSET	 11:19:18 30-Jun-2025	 11:19:41 30-Jun-2025	 11:19:59 30-Jun-2025
10	30-06-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 20:10:51 30-Jun-2025	 20:11:07 30-Jun-2025	 20:11:23 30-Jun-2025
11	30-06-2025	LANTAI 1	HIGH DUSTING	NEON LED	 11:32:50 30-Jun-2025	 11:33:10 30-Jun-2025	 11:33:22 30-Jun-2025
12	30-06-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK	 20:13:29 30-Jun-2025	 20:13:43 30-Jun-2025	 20:13:59 30-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	30-06-2025	LANTAI 1	POLISHING	KUBIKAL	 11:21:15 30-Jun-2025	 11:21:43 30-Jun-2025	 11:22:05 30-Jun-2025
14	30-06-2025	LANTAI 1	GLASS CLEANING	KACA	 20:14:22 30-Jun-2025	 20:14:40 30-Jun-2025	 20:15:15 30-Jun-2025
15	30-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 20:44:42 30-Jun-2025	 20:44:56 30-Jun-2025	 20:45:09 30-Jun-2025
16	30-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 20:04:40 30-Jun-2025	 20:04:57 30-Jun-2025	 20:05:11 30-Jun-2025
17	30-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 20:02:22 30-Jun-2025	 20:02:40 30-Jun-2025	 20:02:56 30-Jun-2025
18	30-06-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK	 20:00:18 30-Jun-2025	 20:00:36 30-Jun-2025	 20:00:49 30-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	30-06-2025	BASEMENT	WASHING	LANTAI EPOXY			
20	30-06-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING			
21	30-06-2025	BASEMENT	WALL CLEANING	PILAR BETON			
22	30-06-2025	BASEMENT	PLAFON CLEANING	CEILING			
23	30-06-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX			
24	30-06-2025	EXTERNAL	POLISHING	PIPA HYDRANT			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	30-06-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR			
26	30-06-2025	EXTERNAL	WALL CLEANING	PIPA HYDRANT			
27	30-06-2025	EXTERNAL	BRUSHING	ALCUBON			
28	30-06-2025	EXTERNAL	BRUSHING	PIPA HYDRANT			
29	30-06-2025	EXTERNAL	HIGH DUSTING	SIGN RAMBU JALAN			
30	30-06-2025	EXTERNAL	BRUSHING	LOGO JKTP			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	30-06-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 13:10:56 30-Jun-2025	 13:12:16 30-Jun-2025	 13:12:31 30-Jun-2025
32	30-06-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 21:25:29 30-Jun-2025	 21:25:47 30-Jun-2025	 21:26:03 30-Jun-2025
33	30-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 15:02:37 30-Jun-2025	 15:03:02 30-Jun-2025	 15:03:28 30-Jun-2025
34	30-06-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 21:26:40 30-Jun-2025	 21:26:51 30-Jun-2025	 21:27:05 30-Jun-2025
35	30-06-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 11:36:41 30-Jun-2025	 11:36:56 30-Jun-2025	 11:37:13 30-Jun-2025
36	30-06-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 21:27:48 30-Jun-2025	 21:27:59 30-Jun-2025	 21:28:11 30-Jun-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	30-06-2025	CARPARK P1-P2	POLISHING	STAINLESS BULAT	 11:31:33 30-Jun-2025	 11:31:44 30-Jun-2025	 11:31:57 30-Jun-2025
38	30-06-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX	 20:12:34 30-Jun-2025	 20:12:48 30-Jun-2025	 20:13:01 30-Jun-2025