





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	01-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP&DOWN)	 07:15:29 01-Jul-2025	 07:16:27 01-Jul-2025	 07:16:40 01-Jul-2025
2	01-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 07:17:21 01-Jul-2025	 07:17:33 01-Jul-2025	 07:17:45 01-Jul-2025
3	01-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 07:18:32 01-Jul-2025	 07:18:44 01-Jul-2025	 07:18:57 01-Jul-2025
4	01-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:11:48 01-Jul-2025	 07:12:33 01-Jul-2025	 07:13:44 01-Jul-2025
5	01-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:27:59 01-Jul-2025	 21:32:58 01-Jul-2025	 21:23:41 01-Jul-2025
6	01-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 13:18:31 01-Jul-2025	 13:19:12 01-Jul-2025	 13:19:32 01-Jul-2025








No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	01-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:14:27 01-Jul-2025	 20:15:13 01-Jul-2025	 20:15:33 01-Jul-2025
8	01-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 13:27:44 01-Jul-2025	 13:27:54 01-Jul-2025	 13:28:05 01-Jul-2025
9	01-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7	 13:26:24 01-Jul-2025	 13:26:45 01-Jul-2025	 13:26:33 01-Jul-2025
10	01-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 13:25:37 01-Jul-2025	 13:25:48 01-Jul-2025	 13:26:02 01-Jul-2025
11	01-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 13:22:07 01-Jul-2025	 13:22:19 01-Jul-2025	 13:22:34 01-Jul-2025
12	01-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 13:22:57 01-Jul-2025	 13:23:10 01-Jul-2025	 13:23:26 01-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	01-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 13:20:06 01-Jul-2025	 13:20:25 01-Jul-2025	 13:20:38 01-Jul-2025
14	01-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 13:21:05 01-Jul-2025	 13:21:19 01-Jul-2025	 13:21:31 01-Jul-2025
15	01-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:39:28 01-Jul-2025	 21:41:00 01-Jul-2025	 21:39:38 01-Jul-2025
16	01-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:03:45 01-Jul-2025	 10:04:26 01-Jul-2025	 10:04:02 01-Jul-2025
17	01-07-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG	 07:22:29 01-Jul-2025	 07:23:51 01-Jul-2025	 07:22:43 01-Jul-2025
18	01-07-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG	 07:25:37 01-Jul-2025	 07:26:44 01-Jul-2025	 07:26:16 01-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	01-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.3	 20:49:35 01-Jul-2025	 20:50:23 01-Jul-2025	 20:49:47 01-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	02-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE	 07:07:39 02-Jul-2025	 07:08:20 02-Jul-2025	 07:12:54 02-Jul-2025
2	02-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 06:40:48 02-Jul-2025	 06:41:02 02-Jul-2025	 06:41:12 02-Jul-2025
3	02-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG	 06:43:23 02-Jul-2025	 06:41:59 02-Jul-2025	 06:43:40 02-Jul-2025
4	02-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SISI DEPAN TENANT UNION DAN DEPAN TENANT TOBBY'S & AREA DEPAN CONCIERGE LV.UG	 06:42:52 02-Jul-2025	 06:42:22 02-Jul-2025	 06:43:04 02-Jul-2025
5	02-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 06:47:22 02-Jul-2025	 06:47:36 02-Jul-2025	 06:47:54 02-Jul-2025
6	02-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 06:49:23 02-Jul-2025	 06:49:37 02-Jul-2025	 06:49:49 02-Jul-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	02-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7	 22:32:23 02-Jul-2025	 22:32:54 02-Jul-2025	 22:33:05 02-Jul-2025
8	02-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 09:44:05 02-Jul-2025	 09:45:18 02-Jul-2025	 09:44:21 02-Jul-2025
9	02-07-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 06:50:44 02-Jul-2025	 06:50:55 02-Jul-2025	 06:51:09 02-Jul-2025
10	02-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 06:52:23 02-Jul-2025	 06:52:34 02-Jul-2025	 06:52:46 02-Jul-2025
11	02-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 06:53:42 02-Jul-2025	 06:53:58 02-Jul-2025	 06:54:10 02-Jul-2025
12	02-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 06:54:35 02-Jul-2025	 06:54:48 02-Jul-2025	 06:55:00 02-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	02-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 22:29:53 02-Jul-2025	 22:30:06 02-Jul-2025	 22:30:16 02-Jul-2025
14	02-07-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10	 09:33:14 02-Jul-2025	 09:33:35 02-Jul-2025	 09:33:59 02-Jul-2025
15	02-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5	 13:05:17 02-Jul-2025	 13:10:22 02-Jul-2025	 13:05:29 02-Jul-2025
16	02-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9	 13:05:49 02-Jul-2025	 13:12:30 02-Jul-2025	 13:06:08 02-Jul-2025
17	02-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5	 13:03:55 02-Jul-2025	 13:09:49 02-Jul-2025	 13:04:34 02-Jul-2025
18	02-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3	 22:30:35 02-Jul-2025	 22:30:47 02-Jul-2025	 22:31:01 02-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	02-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10	 09:35:54 02-Jul-2025	 09:36:24 02-Jul-2025	 09:37:10 02-Jul-2025
20	02-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5	 21:58:45 02-Jul-2025	 22:03:20 02-Jul-2025	 22:16:55 02-Jul-2025
21	02-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.4	 22:34:57 02-Jul-2025	 22:35:08 02-Jul-2025	 22:35:18 02-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	03-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI BAWAH UNION	 07:23:23 03-Jul-2025	 07:23:39 03-Jul-2025	 07:24:37 03-Jul-2025
2	03-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 02:49:31 03-Jul-2025	 02:49:53 03-Jul-2025	 02:50:09 03-Jul-2025
3	03-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 02:55:45 03-Jul-2025	 02:50:47 03-Jul-2025	 02:56:02 03-Jul-2025
4	03-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 02:48:25 03-Jul-2025	 02:48:41 03-Jul-2025	 02:48:58 03-Jul-2025
5	03-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10	 22:44:48 03-Jul-2025	 22:45:00 03-Jul-2025	 22:45:09 03-Jul-2025
6	03-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10	 11:24:26 03-Jul-2025	 11:24:56 03-Jul-2025	 11:25:29 03-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	03-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P6A	 02:53:06 03-Jul-2025	 02:53:18 03-Jul-2025	 02:53:30 03-Jul-2025
8	03-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 22:42:28 03-Jul-2025	 22:42:47 03-Jul-2025	 22:43:05 03-Jul-2025
9	03-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 02:51:56 03-Jul-2025	 02:52:15 03-Jul-2025	 02:52:32 03-Jul-2025
10	03-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:46:12 03-Jul-2025	 22:46:27 03-Jul-2025	 22:46:37 03-Jul-2025
11	03-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 11:28:16 03-Jul-2025	 11:29:17 03-Jul-2025	 11:28:39 03-Jul-2025
12	03-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10	 14:32:35 03-Jul-2025	 14:33:03 03-Jul-2025	 14:32:49 03-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	03-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 14:33:25 03-Jul-2025	 14:33:52 03-Jul-2025	 14:33:36 03-Jul-2025
14	03-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4	 22:41:37 03-Jul-2025	 22:42:05 03-Jul-2025	 22:42:16 03-Jul-2025
15	03-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.4	 22:15:00 03-Jul-2025	 22:13:48 03-Jul-2025	 22:15:53 03-Jul-2025
16	03-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ORNAMENT PLAFON HPL LV.5	 02:54:28 03-Jul-2025	 02:55:09 03-Jul-2025	 02:54:42 03-Jul-2025
17	03-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.5	 22:43:20 03-Jul-2025	 22:43:30 03-Jul-2025	 22:43:40 03-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	04-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)	 07:20:57 04-Jul-2025	 07:21:12 04-Jul-2025	 07:21:28 04-Jul-2025
2	04-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SISI DALAM CONCIERGE S/D DEPAN SERVICE KORIDOR LV.UG	 07:26:45 04-Jul-2025	 07:22:01 04-Jul-2025	 07:26:59 04-Jul-2025
3	04-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 07:26:05 04-Jul-2025	 07:25:38 04-Jul-2025	 07:26:20 04-Jul-2025
4	04-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2	 20:00:17 04-Jul-2025	 21:17:11 04-Jul-2025	 19:59:27 04-Jul-2025
5	04-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2	 13:24:46 04-Jul-2025	 13:25:02 04-Jul-2025	 13:25:14 04-Jul-2025
6	04-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7A	 07:28:25 04-Jul-2025	 07:28:40 04-Jul-2025	 07:28:59 04-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	04-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 13:29:10 04-Jul-2025	 13:30:10 04-Jul-2025	 13:31:39 04-Jul-2025
8	04-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG	 13:25:39 04-Jul-2025	 13:26:04 04-Jul-2025	 13:26:19 04-Jul-2025
9	04-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.3	 21:18:13 04-Jul-2025	 21:18:31 04-Jul-2025	 21:18:52 04-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	05-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI OUT MOBIL	 07:54:26 05-Jul-2025	 07:55:05 05-Jul-2025	 07:58:02 05-Jul-2025
2	05-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 07:09:14 05-Jul-2025	 07:41:33 05-Jul-2025	 07:41:56 05-Jul-2025
3	05-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)	 07:42:22 05-Jul-2025	 07:42:34 05-Jul-2025	 07:42:49 05-Jul-2025
4	05-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SISI DEPAN TENANT BENEFIT S/D LED PROMO LV.UG	 07:43:17 05-Jul-2025	 07:47:30 05-Jul-2025	 07:43:30 05-Jul-2025
5	05-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 07:44:10 05-Jul-2025	 07:44:50 05-Jul-2025	 07:45:11 05-Jul-2025
6	05-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LT.1 & 2	 07:48:41 05-Jul-2025	 07:48:14 05-Jul-2025	 07:49:21 05-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	05-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI KURSI BENCH MARMER LV.UG			
8	05-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
9	05-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
10	05-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.LG			
11	05-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7B			
12	05-07-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT UNION LV.UG			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	05-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5	 10:40:12 05-Jul-2025	 10:40:39 05-Jul-2025	 10:40:51 05-Jul-2025
14	05-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.10	 10:36:11 05-Jul-2025	 10:36:39 05-Jul-2025	 10:36:24 05-Jul-2025
15	05-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5	 10:15:55 05-Jul-2025	 10:16:36 05-Jul-2025	 10:17:05 05-Jul-2025
16	05-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10	 10:34:19 05-Jul-2025	 10:34:48 05-Jul-2025	 10:35:22 05-Jul-2025
17	05-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LED PROMO LV.1 S.D LV.4	 10:42:05 05-Jul-2025	 10:42:43 05-Jul-2025	 10:42:20 05-Jul-2025
18	05-07-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN PLANTER BOX LV.UG	 10:25:19 05-Jul-2025	 10:25:55 05-Jul-2025	 10:25:31 05-Jul-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	05-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA / KOLOM PILAR LV.UG & 1	 10:26:36 05-Jul-2025	 10:27:00 05-Jul-2025	 10:26:48 05-Jul-2025
20	05-07-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.UG S.D LV.5	 20:26:35 05-Jul-2025	 20:27:13 05-Jul-2025	 20:35:56 05-Jul-2025
21	05-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.5	 10:12:47 05-Jul-2025	 10:13:33 05-Jul-2025	 10:15:21 05-Jul-2025
22	05-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SERVICE LV.6-10	 21:08:24 05-Jul-2025	 21:09:26 05-Jul-2025	 21:09:43 05-Jul-2025
23	05-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.UG	 10:22:00 05-Jul-2025	 10:23:10 05-Jul-2025	 10:23:50 05-Jul-2025
24	05-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.UG	 21:11:16 05-Jul-2025	 21:11:30 05-Jul-2025	 21:11:46 05-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	05-07-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	07-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 14:11:33 07-Jul-2025	 14:11:50 07-Jul-2025	 14:12:08 07-Jul-2025
2	07-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4	 04:02:42 07-Jul-2025	 04:02:58 07-Jul-2025	 04:03:10 07-Jul-2025
3	07-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 06:04:33 07-Jul-2025	 06:04:53 07-Jul-2025	 06:05:23 07-Jul-2025
4	07-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI SPIRAL UP&DOWN	 06:19:31 07-Jul-2025	 06:19:41 07-Jul-2025	 06:19:57 07-Jul-2025
5	07-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 06:07:17 07-Jul-2025	 06:07:31 07-Jul-2025	 06:07:42 07-Jul-2025
6	07-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.1	 06:08:19 07-Jul-2025	 06:08:39 07-Jul-2025	 06:09:02 07-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	07-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 06:11:09 07-Jul-2025	 06:10:50 07-Jul-2025	 06:11:22 07-Jul-2025
8	07-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.3	 06:09:37 07-Jul-2025	 06:09:53 07-Jul-2025	 06:10:17 07-Jul-2025
9	07-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 06:12:36 07-Jul-2025	 06:13:09 07-Jul-2025	 06:13:24 07-Jul-2025
10	07-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 21:10:14 07-Jul-2025	 21:10:33 07-Jul-2025	 21:11:06 07-Jul-2025
11	07-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 02:30:07 07-Jul-2025	 02:33:42 07-Jul-2025	 02:53:29 07-Jul-2025
12	07-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 14:13:46 07-Jul-2025	 14:14:19 07-Jul-2025	 14:14:30 07-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	07-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 14:20:54 07-Jul-2025	 14:21:04 07-Jul-2025	 14:21:13 07-Jul-2025
14	07-07-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT TOBY'S LV.UG	 06:14:00 07-Jul-2025	 06:14:19 07-Jul-2025	 06:14:32 07-Jul-2025
15	07-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:59:42 07-Jul-2025	 21:00:31 07-Jul-2025	 20:59:20 07-Jul-2025
16	07-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 14:15:07 07-Jul-2025	 14:15:16 07-Jul-2025	 14:15:27 07-Jul-2025
17	07-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 14:16:29 07-Jul-2025	 14:16:40 07-Jul-2025	 14:16:55 07-Jul-2025
18	07-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 21:01:20 07-Jul-2025	 21:01:45 07-Jul-2025	 21:00:55 07-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	07-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 14:21:30 07-Jul-2025	 14:21:40 07-Jul-2025	 14:21:48 07-Jul-2025
20	07-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 14:15:48 07-Jul-2025	 14:16:05 07-Jul-2025	 14:16:13 07-Jul-2025
21	07-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 14:22:15 07-Jul-2025	 14:22:24 07-Jul-2025	 14:22:38 07-Jul-2025
22	07-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4	 14:20:11 07-Jul-2025	 14:20:22 07-Jul-2025	 14:20:32 07-Jul-2025
23	07-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 21:06:16 07-Jul-2025	 21:06:35 07-Jul-2025	 21:06:50 07-Jul-2025
24	07-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 21:03:11 07-Jul-2025	 21:03:26 07-Jul-2025	 21:03:42 07-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	08-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:17:07 08-Jul-2025	 07:19:10 08-Jul-2025	 07:19:38 08-Jul-2025
2	08-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 03:47:06 08-Jul-2025	 03:47:21 08-Jul-2025	 03:47:33 08-Jul-2025
3	08-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA CONCIERGE LV.UG	 03:49:52 08-Jul-2025	 03:47:54 08-Jul-2025	 03:50:05 08-Jul-2025
4	08-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.4	 03:51:19 08-Jul-2025	 03:51:31 08-Jul-2025	 03:51:48 08-Jul-2025
5	08-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 03:52:35 08-Jul-2025	 03:52:54 08-Jul-2025	 03:53:05 08-Jul-2025
6	08-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 20:53:08 08-Jul-2025	 20:53:27 08-Jul-2025	 20:53:43 08-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	08-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 13:17:38 08-Jul-2025	 13:18:09 08-Jul-2025	 13:18:31 08-Jul-2025
8	08-07-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LT.6-4	 03:54:16 08-Jul-2025	 03:54:29 08-Jul-2025	 03:54:44 08-Jul-2025
9	08-07-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT TOBY'S LV.UG	 03:55:23 08-Jul-2025	 03:55:36 08-Jul-2025	 03:55:49 08-Jul-2025
10	08-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 00:16:58 08-Jul-2025	 00:34:08 08-Jul-2025	 00:38:53 08-Jul-2025
11	08-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:22:02 08-Jul-2025	 20:21:42 08-Jul-2025	 20:21:09 08-Jul-2025
12	08-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 13:19:14 08-Jul-2025	 13:19:30 08-Jul-2025	 13:19:40 08-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	08-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 13:20:02 08-Jul-2025	 13:20:12 08-Jul-2025	 13:20:24 08-Jul-2025
14	08-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 13:21:03 08-Jul-2025	 13:20:46 08-Jul-2025	 13:21:19 08-Jul-2025
15	08-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 13:21:51 08-Jul-2025	 13:22:07 08-Jul-2025	 13:22:30 08-Jul-2025
16	08-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 13:23:53 08-Jul-2025	 13:23:39 08-Jul-2025	 13:24:05 08-Jul-2025
17	08-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 13:24:46 08-Jul-2025	 13:24:28 08-Jul-2025	 13:25:06 08-Jul-2025
18	08-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 20:54:04 08-Jul-2025	 20:54:21 08-Jul-2025	 20:54:38 08-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	08-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:03:58 08-Jul-2025	 10:05:28 08-Jul-2025	 10:05:07 08-Jul-2025
20	08-07-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT PASSENGER LV.UG S.D LV.5	 03:57:02 08-Jul-2025	 03:57:24 08-Jul-2025	 03:57:46 08-Jul-2025
21	08-07-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT SERVICE LV.UG S.D LV.5	 03:58:55 08-Jul-2025	 03:59:41 08-Jul-2025	 03:59:14 08-Jul-2025
22	08-07-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG	 13:25:24 08-Jul-2025	 13:26:01 08-Jul-2025	 13:25:41 08-Jul-2025
23	08-07-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG	 13:22:53 08-Jul-2025	 13:23:07 08-Jul-2025	 13:23:18 08-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	09-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE	 07:07:32 09-Jul-2025	 07:09:49 09-Jul-2025	 07:17:10 09-Jul-2025
2	09-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 07:02:54 09-Jul-2025	 07:03:07 09-Jul-2025	 07:03:18 09-Jul-2025
3	09-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG	 07:07:15 09-Jul-2025	 07:06:41 09-Jul-2025	 07:07:27 09-Jul-2025
4	09-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 07:08:57 09-Jul-2025	 07:08:38 09-Jul-2025	 07:09:17 09-Jul-2025
5	09-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.5	 07:11:10 09-Jul-2025	 07:11:00 09-Jul-2025	 07:11:32 09-Jul-2025
6	09-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B	 07:12:24 09-Jul-2025	 07:13:04 09-Jul-2025	 07:13:33 09-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	09-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7	 22:28:43 09-Jul-2025	 22:29:09 09-Jul-2025	 22:29:32 09-Jul-2025
8	09-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 09:08:41 09-Jul-2025	 08:56:02 09-Jul-2025	 09:08:58 09-Jul-2025
9	09-07-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LT.4-2	 07:15:02 09-Jul-2025	 07:15:14 09-Jul-2025	 07:15:27 09-Jul-2025
10	09-07-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 07:26:44 09-Jul-2025	 07:26:54 09-Jul-2025	 07:27:05 09-Jul-2025
11	09-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 07:25:38 09-Jul-2025	 07:25:57 09-Jul-2025	 07:26:07 09-Jul-2025
12	09-07-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA ATAS PINTU REVOLVING LOBBY LV.UG	 07:24:14 09-Jul-2025	 07:25:04 09-Jul-2025	 07:25:17 09-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	09-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3			
14	09-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4			
15	09-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3			
16	09-07-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10			
17	09-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5			
18	09-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	09-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3	 08:53:23 09-Jul-2025	 08:54:03 09-Jul-2025	 08:53:45 09-Jul-2025
20	09-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10	 08:54:34 09-Jul-2025	 08:55:24 09-Jul-2025	 08:54:52 09-Jul-2025
21	09-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5	 22:25:17 09-Jul-2025	 22:25:39 09-Jul-2025	 22:26:06 09-Jul-2025
22	09-07-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT PASSENGER LV.6 S.D 10	 07:28:52 09-Jul-2025	 07:28:31 09-Jul-2025	 07:29:05 09-Jul-2025
23	09-07-2025	KORIDOR SHOPPING	VACUMMING	GRILL LIFT SERVICE LV.6 S.D 10	 07:29:22 09-Jul-2025	 07:29:32 09-Jul-2025	 07:29:54 09-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	10-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI BAWAH UNION	 07:12:34 10-Jul-2025	 07:13:15 10-Jul-2025	 07:15:00 10-Jul-2025
2	10-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 06:24:45 10-Jul-2025	 06:24:57 10-Jul-2025	 06:25:09 10-Jul-2025
3	10-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI LIFT PASSENGER A DAN B	 06:35:58 10-Jul-2025	 06:41:19 10-Jul-2025	 06:36:13 10-Jul-2025
4	10-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI LIFT SERVICE A DAN B	 06:37:18 10-Jul-2025	 06:37:02 10-Jul-2025	 06:37:43 10-Jul-2025
5	10-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 06:26:12 10-Jul-2025	 06:25:51 10-Jul-2025	 06:26:26 10-Jul-2025
6	10-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE & KORIDOR CONECTION CARPARK LV.6 & 7	 06:31:50 10-Jul-2025	 06:32:04 10-Jul-2025	 06:32:21 10-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	10-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B	 06:29:43 10-Jul-2025	 06:29:56 10-Jul-2025	 06:30:08 10-Jul-2025
8	10-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10	 22:28:12 10-Jul-2025	 22:28:37 10-Jul-2025	 22:28:57 10-Jul-2025
9	10-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10	 11:37:05 10-Jul-2025	 11:38:16 10-Jul-2025	 11:38:35 10-Jul-2025
10	10-07-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LV.2-LG	 06:33:39 10-Jul-2025	 06:34:31 10-Jul-2025	 06:34:11 10-Jul-2025
11	10-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P6A	 06:32:53 10-Jul-2025	 06:33:07 10-Jul-2025	 06:33:20 10-Jul-2025
12	10-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 22:22:25 10-Jul-2025	 22:23:12 10-Jul-2025	 22:23:55 10-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	10-07-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA CANOPY + GUTTER LV.UG	 06:34:59 10-Jul-2025	 06:35:11 10-Jul-2025	 06:35:22 10-Jul-2025
14	10-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 06:38:24 10-Jul-2025	 06:38:37 10-Jul-2025	 06:38:50 10-Jul-2025
15	10-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:24:41 10-Jul-2025	 22:24:54 10-Jul-2025	 22:25:12 10-Jul-2025
16	10-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 11:42:51 10-Jul-2025	 11:43:37 10-Jul-2025	 11:43:18 10-Jul-2025
17	10-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 11:41:12 10-Jul-2025	 11:42:11 10-Jul-2025	 11:41:40 10-Jul-2025
18	10-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4	 22:26:41 10-Jul-2025	 22:26:56 10-Jul-2025	 22:27:17 10-Jul-2025




No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	10-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.4	 22:30:50 10-Jul-2025	 22:30:02 10-Jul-2025	 22:30:21 10-Jul-2025
20	10-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ORNAMENT PLAFON HPL LV.5	 06:30:44 10-Jul-2025	 06:31:06 10-Jul-2025	 06:31:18 10-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	11-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)			
2	11-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI LANDING ESCALATOR DEPAN TENANT M&S - ARAH KE TENANT COAST / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.1			
3	11-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2			
4	11-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE 9 & 10			
5	11-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B			
6	11-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	11-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2	 11:36:23 11-Jul-2025	 11:36:45 11-Jul-2025	 11:37:15 11-Jul-2025
8	11-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7A	 07:20:39 11-Jul-2025	 07:20:51 11-Jul-2025	 07:21:03 11-Jul-2025
9	11-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 11:37:42 11-Jul-2025	 11:38:47 11-Jul-2025	 11:38:20 11-Jul-2025
10	11-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG	 11:31:44 11-Jul-2025	 11:32:14 11-Jul-2025	 11:32:57 11-Jul-2025
11	11-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.3	 20:09:57 11-Jul-2025	 20:09:38 11-Jul-2025	 20:10:23 11-Jul-2025
12	11-07-2025	KORIDOR SHOPPING	GLASS CLEANING	PEMBERSIHAN KACA BAGIAN LUAR LOBBY UTAMA LV.UG	 07:26:45 11-Jul-2025	 07:27:02 11-Jul-2025	 07:27:13 11-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	12-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI OUT MOBIL	 07:19:07 12-Jul-2025	 07:20:22 12-Jul-2025	 11:39:50 12-Jul-2025
2	12-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 03:32:21 12-Jul-2025	 03:32:43 12-Jul-2025	 03:33:02 12-Jul-2025
3	12-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)	 03:33:25 12-Jul-2025	 03:33:39 12-Jul-2025	 03:33:56 12-Jul-2025
4	12-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI DEPAN TENANT BRAUN N BUFFEL - LANDING ESCALATOR DEPAN M&S LV.1	 03:37:04 12-Jul-2025	 03:35:37 12-Jul-2025	 03:37:18 12-Jul-2025
5	12-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:38:01 12-Jul-2025	 03:36:24 12-Jul-2025	 03:37:42 12-Jul-2025
6	12-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI KURSI BENCH MARMER LV.1	 03:40:29 12-Jul-2025	 03:41:13 12-Jul-2025	 03:40:44 12-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	12-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A			
8	12-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
9	12-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
10	12-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.LG			
11	12-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7B			
12	12-07-2025	KORIDOR SHOPPING	CELLING	CELLING AREA KORIDOR SHOPPING LV.1-5			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	12-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5			
14	12-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.UG-1			
15	12-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.10			
16	12-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5			
17	12-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10			
18	12-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LED PROMO LV.1 S.D LV.4			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	12-07-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN PLANTER BOX LV.UG	 11:26:27 12-Jul-2025	 11:27:17 12-Jul-2025	 11:26:48 12-Jul-2025
20	12-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1	 11:29:20 12-Jul-2025	 11:30:05 12-Jul-2025	 11:29:33 12-Jul-2025
21	12-07-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.UG S.D LV.5	 19:15:21 12-Jul-2025	 19:27:39 12-Jul-2025	 19:23:07 12-Jul-2025
22	12-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.5	 10:44:54 12-Jul-2025	 10:45:24 12-Jul-2025	 10:45:54 12-Jul-2025
23	12-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR SERVICE LV.LG-10	 21:47:44 12-Jul-2025	 21:48:06 12-Jul-2025	 21:48:23 12-Jul-2025
24	12-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 24 SISI UNION,LC WAIKIKI,KID STATION,SUSHI TEI LV.LG-10	 11:34:37 12-Jul-2025	 11:35:48 12-Jul-2025	 11:35:17 12-Jul-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	12-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.UG	 11:23:07 12-Jul-2025	 11:24:10 12-Jul-2025	 11:23:27 12-Jul-2025
26	12-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.UG	 21:46:49 12-Jul-2025	 21:47:07 12-Jul-2025	 21:47:23 12-Jul-2025
27	12-07-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2	 11:50:28 12-Jul-2025	 11:50:51 12-Jul-2025	 11:50:39 12-Jul-2025
28	12-07-2025	KORIDOR SHOPPING	DUSTING	DINDING BAGIAN LUAR LOBBY LV.UG	 08:02:36 12-Jul-2025	 08:02:49 12-Jul-2025	 08:03:05 12-Jul-2025
29	12-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SELA SELA PINTU LIFT SERVICE LV.LG-10	 11:41:47 12-Jul-2025	 11:42:47 12-Jul-2025	 11:42:24 12-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	14-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 10:34:28 14-Jul-2025	 10:35:02 14-Jul-2025	 10:35:14 14-Jul-2025
2	14-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4	 06:39:14 14-Jul-2025	 06:39:26 14-Jul-2025	 06:39:39 14-Jul-2025
3	14-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 01:44:19 14-Jul-2025	 01:44:34 14-Jul-2025	 01:45:03 14-Jul-2025
4	14-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 01:50:52 14-Jul-2025	 01:51:03 14-Jul-2025	 01:51:20 14-Jul-2025
5	14-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.3	 01:45:54 14-Jul-2025	 01:45:23 14-Jul-2025	 01:46:06 14-Jul-2025
6	14-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 01:47:12 14-Jul-2025	 01:50:30 14-Jul-2025	 01:47:22 14-Jul-2025






No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	14-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A	 01:47:45 14-Jul-2025	 01:48:27 14-Jul-2025	 01:48:05 14-Jul-2025
8	14-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 21:44:11 14-Jul-2025	 21:45:29 14-Jul-2025	 21:46:04 14-Jul-2025
9	14-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 01:51:50 14-Jul-2025	 01:52:05 14-Jul-2025	 01:52:17 14-Jul-2025
10	14-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 11:28:00 14-Jul-2025	 11:30:57 14-Jul-2025	 11:29:36 14-Jul-2025
11	14-07-2025	KORIDOR SHOPPING	CELLING	CELLING AREA LOBBY LV.UG	 15:09:17 14-Jul-2025	 15:09:29 14-Jul-2025	 15:09:43 14-Jul-2025
12	14-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 08:35:57 14-Jul-2025	 08:36:42 14-Jul-2025	 08:37:59 14-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	14-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:37:45 14-Jul-2025	 20:39:08 14-Jul-2025	 20:38:13 14-Jul-2025
14	14-07-2025	KORIDOR SHOPPING	SWEEPING	SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10	 15:08:36 14-Jul-2025	 15:08:46 14-Jul-2025	 15:08:59 14-Jul-2025
15	14-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 10:13:59 14-Jul-2025	 10:17:19 14-Jul-2025	 10:21:58 14-Jul-2025
16	14-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5	 10:45:47 14-Jul-2025	 10:45:58 14-Jul-2025	 10:46:09 14-Jul-2025
17	14-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 10:46:30 14-Jul-2025	 10:46:43 14-Jul-2025	 10:46:55 14-Jul-2025
18	14-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 11:34:48 14-Jul-2025	 11:35:09 14-Jul-2025	 11:35:48 14-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	14-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 11:20:10 14-Jul-2025	 11:20:30 14-Jul-2025	 11:21:09 14-Jul-2025
20	14-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 10:39:06 14-Jul-2025	 10:40:17 14-Jul-2025	 10:40:33 14-Jul-2025
21	14-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 11:18:14 14-Jul-2025	 11:18:39 14-Jul-2025	 11:19:10 14-Jul-2025
22	14-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10	 20:35:30 14-Jul-2025	 20:35:45 14-Jul-2025	 20:36:05 14-Jul-2025
23	14-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10	 11:22:47 14-Jul-2025	 11:23:09 14-Jul-2025	 11:23:25 14-Jul-2025
24	14-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR EXIT LV.LG-10	 11:28:22 14-Jul-2025	 11:31:21 14-Jul-2025	 11:29:07 14-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	14-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4	 11:40:13 14-Jul-2025	 11:40:40 14-Jul-2025	 11:41:12 14-Jul-2025
26	14-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 21:46:29 14-Jul-2025	 21:46:43 14-Jul-2025	 21:47:11 14-Jul-2025
27	14-07-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.5	 01:49:37 14-Jul-2025	 01:49:48 14-Jul-2025	 01:50:01 14-Jul-2025
28	14-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 20:36:46 14-Jul-2025	 20:37:21 14-Jul-2025	 20:37:06 14-Jul-2025
29	14-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.2	 21:11:42 14-Jul-2025	 21:11:12 14-Jul-2025	 21:12:00 14-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	15-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:22:06 15-Jul-2025	 07:22:58 15-Jul-2025	 07:23:21 15-Jul-2025
2	15-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 06:43:03 15-Jul-2025	 06:43:14 15-Jul-2025	 06:43:33 15-Jul-2025
3	15-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA VALET LV.UG	 06:46:26 15-Jul-2025	 06:46:41 15-Jul-2025	 06:46:58 15-Jul-2025
4	15-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SELA SELA/SUDUT CLOSET TOILET MALE FEMALE DISABLE	 06:58:09 15-Jul-2025	 06:58:24 15-Jul-2025	 06:58:41 15-Jul-2025
5	15-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 06:59:58 15-Jul-2025	 07:00:11 15-Jul-2025	 07:00:24 15-Jul-2025
6	15-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:35:02 15-Jul-2025	 21:35:19 15-Jul-2025	 21:35:35 15-Jul-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	15-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 13:18:00 15-Jul-2025	 13:19:10 15-Jul-2025	 13:20:13 15-Jul-2025
8	15-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 07:03:26 15-Jul-2025	 07:03:46 15-Jul-2025	 07:03:58 15-Jul-2025
9	15-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 21:37:46 15-Jul-2025	 21:38:09 15-Jul-2025	 21:38:24 15-Jul-2025
10	15-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 13:31:02 15-Jul-2025	 13:31:44 15-Jul-2025	 13:32:03 15-Jul-2025
11	15-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7	 13:38:57 15-Jul-2025	 13:39:45 15-Jul-2025	 13:39:23 15-Jul-2025
12	15-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 13:40:49 15-Jul-2025	 13:41:45 15-Jul-2025	 13:41:06 15-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	15-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 13:34:57 15-Jul-2025	 13:36:06 15-Jul-2025	 13:36:59 15-Jul-2025
14	15-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 13:35:19 15-Jul-2025	 13:35:36 15-Jul-2025	 13:37:18 15-Jul-2025
15	15-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 13:29:08 15-Jul-2025	 13:29:32 15-Jul-2025	 13:29:54 15-Jul-2025
16	15-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 13:24:43 15-Jul-2025	 13:26:05 15-Jul-2025	 13:25:25 15-Jul-2025
17	15-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:36:15 15-Jul-2025	 21:36:40 15-Jul-2025	 21:37:19 15-Jul-2025
18	15-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:05:36 15-Jul-2025	 10:06:40 15-Jul-2025	 10:06:52 15-Jul-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	15-07-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.6	 07:09:35 15-Jul-2025	 07:09:49 15-Jul-2025	 07:10:02 15-Jul-2025
20	15-07-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG	 07:43:34 15-Jul-2025	 07:42:32 15-Jul-2025	 07:44:17 15-Jul-2025
21	15-07-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG	 07:50:03 15-Jul-2025	 07:54:00 15-Jul-2025	 07:52:49 15-Jul-2025
22	15-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.3	 21:29:59 15-Jul-2025	 21:30:42 15-Jul-2025	 21:30:10 15-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	16-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE	 07:08:25 16-Jul-2025	 07:08:42 16-Jul-2025	 07:14:20 16-Jul-2025
2	16-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 06:57:56 16-Jul-2025	 06:59:28 16-Jul-2025	 06:59:43 16-Jul-2025
3	16-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG	 07:00:57 16-Jul-2025	 07:00:22 16-Jul-2025	 07:01:13 16-Jul-2025
4	16-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 07:02:41 16-Jul-2025	 07:01:57 16-Jul-2025	 07:02:52 16-Jul-2025
5	16-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SELA/SUDUT CLOSET TOILET MALE FEMALE	 07:03:45 16-Jul-2025	 07:03:31 16-Jul-2025	 07:03:59 16-Jul-2025
6	16-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 07:04:29 16-Jul-2025	 07:04:42 16-Jul-2025	 07:04:53 16-Jul-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	16-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7	 23:07:19 16-Jul-2025	 23:07:28 16-Jul-2025	 23:07:39 16-Jul-2025
8	16-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 09:29:44 16-Jul-2025	 09:21:12 16-Jul-2025	 09:30:04 16-Jul-2025
9	16-07-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 07:09:00 16-Jul-2025	 07:09:13 16-Jul-2025	 07:09:24 16-Jul-2025
10	16-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 07:10:27 16-Jul-2025	 07:10:40 16-Jul-2025	 07:10:51 16-Jul-2025
11	16-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 07:11:44 16-Jul-2025	 07:12:00 16-Jul-2025	 07:12:16 16-Jul-2025
12	16-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 07:12:48 16-Jul-2025	 07:13:01 16-Jul-2025	 07:13:18 16-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	16-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 22:58:15 16-Jul-2025	 22:58:38 16-Jul-2025	 22:59:12 16-Jul-2025
14	16-07-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10	 23:01:21 16-Jul-2025	 23:01:37 16-Jul-2025	 23:04:20 16-Jul-2025
15	16-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5	 13:38:57 16-Jul-2025	 13:39:13 16-Jul-2025	 13:39:33 16-Jul-2025
16	16-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9	 09:34:14 16-Jul-2025	 09:24:49 16-Jul-2025	 09:34:27 16-Jul-2025
17	16-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5	 13:36:49 16-Jul-2025	 13:37:14 16-Jul-2025	 13:36:59 16-Jul-2025
18	16-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3	 23:05:28 16-Jul-2025	 23:05:37 16-Jul-2025	 23:05:48 16-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	16-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10	 09:28:51 16-Jul-2025	 09:21:43 16-Jul-2025	 09:29:05 16-Jul-2025
20	16-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5	 23:06:44 16-Jul-2025	 23:06:56 16-Jul-2025	 23:07:06 16-Jul-2025
21	16-07-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN NOMADE LV.7	 07:15:10 16-Jul-2025	 07:15:41 16-Jul-2025	 07:16:06 16-Jul-2025
22	16-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.4	 23:06:01 16-Jul-2025	 23:06:10 16-Jul-2025	 23:06:27 16-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	17-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI BAWAH UNION	 07:11:19 17-Jul-2025	 07:11:42 17-Jul-2025	 07:13:18 17-Jul-2025
2	17-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 01:14:20 17-Jul-2025	 01:14:34 17-Jul-2025	 01:14:46 17-Jul-2025
3	17-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 01:23:41 17-Jul-2025	 01:15:10 17-Jul-2025	 01:24:05 17-Jul-2025
4	17-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI LANDING ESCALATOR DEPAN TENANT LC WAIKIKI - ARAH KE TENANT JUSTICE / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.2	 01:24:24 17-Jul-2025	 01:15:29 17-Jul-2025	 01:24:36 17-Jul-2025
5	17-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SELA/SUDUT CLOSET TOILET MALE FEMALE DISABLE	 01:16:12 17-Jul-2025	 01:17:03 17-Jul-2025	 01:16:25 17-Jul-2025
6	17-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 01:17:23 17-Jul-2025	 01:17:33 17-Jul-2025	 01:17:45 17-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	17-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10	 22:46:52 17-Jul-2025	 22:47:06 17-Jul-2025	 22:47:19 17-Jul-2025
8	17-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10	 11:53:04 17-Jul-2025	 11:53:36 17-Jul-2025	 11:54:03 17-Jul-2025
9	17-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P6A	 01:25:24 17-Jul-2025	 01:25:36 17-Jul-2025	 01:25:48 17-Jul-2025
10	17-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 22:44:40 17-Jul-2025	 22:44:51 17-Jul-2025	 22:45:09 17-Jul-2025
11	17-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 01:18:39 17-Jul-2025	 01:18:54 17-Jul-2025	 01:19:17 17-Jul-2025
12	17-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:47:50 17-Jul-2025	 22:48:01 17-Jul-2025	 22:48:16 17-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	17-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10			
14	17-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10			
15	17-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7			
16	17-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4			
17	17-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.4			
18	17-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ORNAMENT PLAFON HPL LV.5			

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	17-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.5	 22:45:19 17-Jul-2025	 22:45:28 17-Jul-2025	 22:45:38 17-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	18-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)	 01:38:44 18-Jul-2025	 01:39:00 18-Jul-2025	 01:39:30 18-Jul-2025
2	18-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 01:41:32 18-Jul-2025	 01:40:23 18-Jul-2025	 01:41:51 18-Jul-2025
3	18-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI DEPAN TENANT MELISSA - LANDING ESCALATOR DEPAN EX TENANT LC WAIKIKI LV.2	 01:43:44 18-Jul-2025	 01:42:45 18-Jul-2025	 01:43:59 18-Jul-2025
4	18-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2	 19:50:12 18-Jul-2025	 19:49:47 18-Jul-2025	 20:59:25 18-Jul-2025
5	18-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2	 11:46:56 18-Jul-2025	 11:47:18 18-Jul-2025	 11:47:37 18-Jul-2025
6	18-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7A	 01:45:38 18-Jul-2025	 01:46:00 18-Jul-2025	 01:46:19 18-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	18-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9			
8	18-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG			
9	18-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.3			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	19-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI OUT MOBIL	 07:19:54 19-Jul-2025	 07:20:13 19-Jul-2025	 07:21:48 19-Jul-2025
2	19-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 03:59:17 19-Jul-2025	 03:59:37 19-Jul-2025	 03:59:55 19-Jul-2025
3	19-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)	 04:01:02 19-Jul-2025	 04:01:19 19-Jul-2025	 04:01:36 19-Jul-2025
4	19-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 04:04:28 19-Jul-2025	 04:03:42 19-Jul-2025	 04:04:45 19-Jul-2025
5	19-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LT.1 & 2	 04:05:54 19-Jul-2025	 04:05:37 19-Jul-2025	 04:06:12 19-Jul-2025
6	19-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI DARI LANDING ESCALATOR TENANT COTTON ON - ARAH KE CONNECTION TP4 LV.2	 04:12:02 19-Jul-2025	 04:11:22 19-Jul-2025	 04:12:19 19-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	19-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI KURSI BENCH MARMER LV.3			
8	19-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
9	19-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG			
10	19-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.LG			
11	19-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7B			
12	19-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	19-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.10	 10:43:22 19-Jul-2025	 10:44:12 19-Jul-2025	 10:43:36 19-Jul-2025
14	19-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5	 10:08:05 19-Jul-2025	 10:08:30 19-Jul-2025	 10:09:10 19-Jul-2025
15	19-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10	 10:11:32 19-Jul-2025	 10:11:52 19-Jul-2025	 10:12:38 19-Jul-2025
16	19-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LED PROMO LV.1 S.D LV.4	 10:42:25 19-Jul-2025	 10:42:52 19-Jul-2025	 10:42:38 19-Jul-2025
17	19-07-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN PLANTER BOX LV.UG	 10:31:17 19-Jul-2025	 10:32:16 19-Jul-2025	 10:31:50 19-Jul-2025
18	19-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1	 10:33:49 19-Jul-2025	 10:34:17 19-Jul-2025	 10:34:04 19-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	19-07-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.UG S.D LV.5	 19:54:04 19-Jul-2025	 20:01:20 19-Jul-2025	 20:01:34 19-Jul-2025
20	19-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.5	 10:15:44 19-Jul-2025	 10:16:06 19-Jul-2025	 10:17:03 19-Jul-2025
21	19-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.UG	 10:27:16 19-Jul-2025	 10:28:28 19-Jul-2025	 10:29:34 19-Jul-2025
22	19-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.UG	 20:40:55 19-Jul-2025	 20:49:35 19-Jul-2025	 20:45:37 19-Jul-2025
23	19-07-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2	 10:38:11 19-Jul-2025	 10:38:39 19-Jul-2025	 10:38:20 19-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	21-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 10:55:03 21-Jul-2025	 10:55:13 21-Jul-2025	 10:55:26 21-Jul-2025
2	21-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4	 02:50:27 21-Jul-2025	 02:50:40 21-Jul-2025	 02:50:55 21-Jul-2025
3	21-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 06:15:27 21-Jul-2025	 06:15:44 21-Jul-2025	 06:16:01 21-Jul-2025
4	21-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 02:55:11 21-Jul-2025	 02:55:26 21-Jul-2025	 02:55:40 21-Jul-2025
5	21-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.5	 02:56:06 21-Jul-2025	 02:56:27 21-Jul-2025	 02:56:54 21-Jul-2025
6	21-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 02:58:13 21-Jul-2025	 02:57:22 21-Jul-2025	 02:58:26 21-Jul-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	21-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.3	 02:59:01 21-Jul-2025	 02:59:13 21-Jul-2025	 02:59:36 21-Jul-2025
8	21-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 03:00:23 21-Jul-2025	 03:00:37 21-Jul-2025	 03:00:48 21-Jul-2025
9	21-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 20:29:34 21-Jul-2025	 20:29:53 21-Jul-2025	 20:30:29 21-Jul-2025
10	21-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 03:01:19 21-Jul-2025	 03:01:44 21-Jul-2025	 03:02:00 21-Jul-2025
11	21-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 11:22:44 21-Jul-2025	 11:23:07 21-Jul-2025	 11:23:40 21-Jul-2025
12	21-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 11:18:39 21-Jul-2025	 11:19:36 21-Jul-2025	 11:19:49 21-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	21-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:24:27 21-Jul-2025	 20:24:45 21-Jul-2025	 20:25:01 21-Jul-2025
14	21-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 10:20:41 21-Jul-2025	 10:24:48 21-Jul-2025	 10:26:23 21-Jul-2025
15	21-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1	 11:40:50 21-Jul-2025	 11:41:39 21-Jul-2025	 11:41:24 21-Jul-2025
16	21-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 11:39:22 21-Jul-2025	 11:39:44 21-Jul-2025	 11:40:09 21-Jul-2025
17	21-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 11:33:32 21-Jul-2025	 11:33:58 21-Jul-2025	 11:34:25 21-Jul-2025
18	21-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5	 10:52:45 21-Jul-2025	 10:52:56 21-Jul-2025	 10:53:47 21-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	21-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7	 11:31:30 21-Jul-2025	 11:32:00 21-Jul-2025	 11:32:37 21-Jul-2025
20	21-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4	 11:25:39 21-Jul-2025	 11:26:17 21-Jul-2025	 11:26:53 21-Jul-2025
21	21-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 20:28:26 21-Jul-2025	 20:28:42 21-Jul-2025	 20:29:14 21-Jul-2025
22	21-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 20:26:02 21-Jul-2025	 20:26:42 21-Jul-2025	 20:26:28 21-Jul-2025
23	21-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 20:27:54 21-Jul-2025	 20:27:34 21-Jul-2025	 20:27:11 21-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	22-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:11:17 22-Jul-2025	 07:12:13 22-Jul-2025	 07:12:43 22-Jul-2025
2	22-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 06:11:18 22-Jul-2025	 06:11:30 22-Jul-2025	 06:11:41 22-Jul-2025
3	22-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA CONCIERGE LV.UG	 06:10:27 22-Jul-2025	 06:10:39 22-Jul-2025	 06:10:51 22-Jul-2025
4	22-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.4	 06:09:31 22-Jul-2025	 06:09:44 22-Jul-2025	 06:09:59 22-Jul-2025
5	22-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P6A & P6B	 06:13:06 22-Jul-2025	 06:13:18 22-Jul-2025	 06:13:28 22-Jul-2025
6	22-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 21:16:31 22-Jul-2025	 21:15:48 22-Jul-2025	 21:18:13 22-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	22-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 11:31:46 22-Jul-2025	 11:32:05 22-Jul-2025	 11:32:26 22-Jul-2025
8	22-07-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LT.6-4	 06:15:35 22-Jul-2025	 06:15:46 22-Jul-2025	 06:15:58 22-Jul-2025
9	22-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 06:14:03 22-Jul-2025	 06:14:25 22-Jul-2025	 06:14:37 22-Jul-2025
10	22-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:14:23 22-Jul-2025	 20:14:35 22-Jul-2025	 20:15:23 22-Jul-2025
11	22-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 11:44:58 22-Jul-2025	 11:45:50 22-Jul-2025	 11:45:26 22-Jul-2025
12	22-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 13:33:12 22-Jul-2025	 13:34:02 22-Jul-2025	 13:33:30 22-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	22-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 13:29:59 22-Jul-2025	 13:30:53 22-Jul-2025	 13:31:51 22-Jul-2025
14	22-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 13:30:20 22-Jul-2025	 13:30:35 22-Jul-2025	 13:32:07 22-Jul-2025
15	22-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 11:42:30 22-Jul-2025	 11:43:33 22-Jul-2025	 11:44:01 22-Jul-2025
16	22-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 11:34:52 22-Jul-2025	 11:35:11 22-Jul-2025	 11:35:37 22-Jul-2025
17	22-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 21:18:38 22-Jul-2025	 21:14:55 22-Jul-2025	 21:13:59 22-Jul-2025
18	22-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:06:11 22-Jul-2025	 10:07:16 22-Jul-2025	 10:07:41 22-Jul-2025




No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	22-07-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG			
20	22-07-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	23-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE	 07:36:36 23-Jul-2025	 07:38:07 23-Jul-2025	 07:43:45 23-Jul-2025
2	23-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 02:25:36 23-Jul-2025	 02:25:54 23-Jul-2025	 02:26:10 23-Jul-2025
3	23-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG	 02:27:30 23-Jul-2025	 02:28:30 23-Jul-2025	 02:27:42 23-Jul-2025
4	23-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 02:30:55 23-Jul-2025	 02:30:10 23-Jul-2025	 02:31:10 23-Jul-2025
5	23-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE LV.5	 02:33:21 23-Jul-2025	 02:33:32 23-Jul-2025	 02:33:43 23-Jul-2025
6	23-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B	 02:34:13 23-Jul-2025	 02:34:24 23-Jul-2025	 02:34:38 23-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	23-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7	 13:20:08 23-Jul-2025	 12:24:40 23-Jul-2025	 13:20:20 23-Jul-2025
8	23-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 13:32:00 23-Jul-2025	 13:31:48 23-Jul-2025	 13:32:08 23-Jul-2025
9	23-07-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LT.4-2	 02:35:51 23-Jul-2025	 02:36:04 23-Jul-2025	 02:36:14 23-Jul-2025
10	23-07-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 02:36:43 23-Jul-2025	 02:36:57 23-Jul-2025	 02:37:11 23-Jul-2025
11	23-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 02:37:43 23-Jul-2025	 02:37:54 23-Jul-2025	 02:38:04 23-Jul-2025
12	23-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 02:39:35 23-Jul-2025	 02:40:22 23-Jul-2025	 02:40:50 23-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	23-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 02:41:12 23-Jul-2025	 02:41:25 23-Jul-2025	 02:41:44 23-Jul-2025
14	23-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 22:32:14 23-Jul-2025	 22:32:24 23-Jul-2025	 22:32:33 23-Jul-2025
15	23-07-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10	 22:32:50 23-Jul-2025	 22:32:58 23-Jul-2025	 22:33:12 23-Jul-2025
16	23-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5	 13:20:53 23-Jul-2025	 13:26:57 23-Jul-2025	 13:21:12 23-Jul-2025
17	23-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5	 13:21:49 23-Jul-2025	 13:26:21 23-Jul-2025	 13:22:09 23-Jul-2025
18	23-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3	 22:31:11 23-Jul-2025	 22:31:32 23-Jul-2025	 22:31:48 23-Jul-2025

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	23-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10			
20	23-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	24-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI BAWAH UNION	 14:11:55 24-Jul-2025	 14:12:11 24-Jul-2025	 14:12:24 24-Jul-2025
2	24-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 03:27:09 24-Jul-2025	 03:28:18 24-Jul-2025	 03:27:45 24-Jul-2025
3	24-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI LIFT PASSENGER A DAN B	 03:29:51 24-Jul-2025	 03:44:28 24-Jul-2025	 03:32:48 24-Jul-2025
4	24-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI LIFT SERVICE A DAN B	 03:34:00 24-Jul-2025	 03:33:21 24-Jul-2025	 03:35:29 24-Jul-2025
5	24-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1	 03:36:07 24-Jul-2025	 03:36:28 24-Jul-2025	 03:37:10 24-Jul-2025
6	24-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE & KORIDOR CONECTION CARPARK LV.6 & 7	 03:43:29 24-Jul-2025	 03:43:42 24-Jul-2025	 03:44:01 24-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	24-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B	 03:44:56 24-Jul-2025	 03:45:06 24-Jul-2025	 03:45:24 24-Jul-2025
8	24-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10	 17:30:59 24-Jul-2025	 17:31:57 24-Jul-2025	 17:36:29 24-Jul-2025
9	24-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10	 11:29:04 24-Jul-2025	 11:29:35 24-Jul-2025	 11:29:58 24-Jul-2025
10	24-07-2025	CARPARK	GENERAL CLEANING	PENCUCIAN SPIRAL CARPARK LV.2-LG	 03:45:42 24-Jul-2025	 03:45:52 24-Jul-2025	 03:46:05 24-Jul-2025
11	24-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P6A	 03:46:22 24-Jul-2025	 03:46:32 24-Jul-2025	 03:46:43 24-Jul-2025
12	24-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 16:27:25 24-Jul-2025	 16:30:35 24-Jul-2025	 16:31:43 24-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	24-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 03:48:51 24-Jul-2025	 03:49:02 24-Jul-2025	 03:49:12 24-Jul-2025
14	24-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 20:13:05 24-Jul-2025	 20:14:35 24-Jul-2025	 20:16:03 24-Jul-2025
15	24-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 11:47:12 24-Jul-2025	 11:48:37 24-Jul-2025	 11:48:07 24-Jul-2025
16	24-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 11:33:02 24-Jul-2025	 11:34:39 24-Jul-2025	 11:33:52 24-Jul-2025
17	24-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4	 16:36:58 24-Jul-2025	 16:37:24 24-Jul-2025	 16:38:30 24-Jul-2025
18	24-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.4	 22:15:05 24-Jul-2025	 22:12:40 24-Jul-2025	 22:25:47 24-Jul-2025


No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	24-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ORNAMENT PLAFON HPL LV.5	 03:47:22 24-Jul-2025	 03:47:35 24-Jul-2025	 03:47:49 24-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	25-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)			
2	25-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2			
3	25-07-2025	KRISTALISASI	KRISTALISASI	REVONTULET KORIDOR LIFT SERVICE 9 & 10			
4	25-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P7A & P7B			
5	25-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2			
6	25-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	25-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7A	 02:25:17 25-Jul-2025	 02:25:30 25-Jul-2025	 02:25:41 25-Jul-2025
8	25-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.8-9	 11:15:00 25-Jul-2025	 11:15:25 25-Jul-2025	 11:15:10 25-Jul-2025
9	25-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG	 11:10:05 25-Jul-2025	 11:10:48 25-Jul-2025	 11:11:05 25-Jul-2025
10	25-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.3	 21:14:37 25-Jul-2025	 21:14:22 25-Jul-2025	 21:14:51 25-Jul-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	26-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI OUT MOBIL	 20:14:24 26-Jul-2025	 20:14:37 26-Jul-2025	 20:14:54 26-Jul-2025
2	26-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)	 06:02:38 26-Jul-2025	 06:03:38 26-Jul-2025	 06:04:03 26-Jul-2025
3	26-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)	 06:04:22 26-Jul-2025	 06:04:41 26-Jul-2025	 06:05:04 26-Jul-2025
4	26-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG	 03:08:08 26-Jul-2025	 03:07:42 26-Jul-2025	 03:08:22 26-Jul-2025
5	26-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A	 03:08:56 26-Jul-2025	 03:09:22 26-Jul-2025	 03:09:40 26-Jul-2025
6	26-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG	 20:16:42 26-Jul-2025	 20:17:04 26-Jul-2025	 20:17:45 26-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	26-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG	 11:09:43 26-Jul-2025	 11:10:49 26-Jul-2025	 11:10:22 26-Jul-2025
8	26-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN TOILET CARPARK LV.LG	 03:10:57 26-Jul-2025	 03:11:21 26-Jul-2025	 03:11:34 26-Jul-2025
9	26-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P7B	 03:12:37 26-Jul-2025	 03:13:03 26-Jul-2025	 03:13:17 26-Jul-2025
10	26-07-2025	KORIDOR SHOPPING	CELLING	CELLING AREA KORIDOR SHOPPING LV.1-5	 11:17:18 26-Jul-2025	 11:18:12 26-Jul-2025	 11:19:13 26-Jul-2025
11	26-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING BADUKAN,SELA SELA HAND RALLING LV.1-5	 11:14:40 26-Jul-2025	 11:15:00 26-Jul-2025	 11:14:49 26-Jul-2025
12	26-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.UG-1	 10:51:35 26-Jul-2025	 10:52:40 26-Jul-2025	 10:52:12 26-Jul-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	26-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.10	 11:15:52 26-Jul-2025	 11:16:37 26-Jul-2025	 11:16:04 26-Jul-2025
14	26-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5	 10:32:03 26-Jul-2025	 10:32:35 26-Jul-2025	 10:32:13 26-Jul-2025
15	26-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10	 11:02:58 26-Jul-2025	 11:03:23 26-Jul-2025	 11:04:04 26-Jul-2025
16	26-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LED PROMO LV.1 S.D LV.4	 11:20:49 26-Jul-2025	 11:21:19 26-Jul-2025	 11:21:09 26-Jul-2025
17	26-07-2025	KORIDOR SHOPPING	SWEEPING	PEMBERSIHAN PLANTER BOX LV.UG	 10:46:12 26-Jul-2025	 10:47:05 26-Jul-2025	 10:46:42 26-Jul-2025
18	26-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1	 10:50:02 26-Jul-2025	 10:50:47 26-Jul-2025	 10:50:25 26-Jul-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	26-07-2025	KORIDOR SHOPPING	WASHING	PENCUCIAN TRASHCAN LV.UG S.D LV.5	 21:16:37 26-Jul-2025	 20:16:06 26-Jul-2025	 20:16:19 26-Jul-2025
20	26-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.5	 10:34:17 26-Jul-2025	 10:34:45 26-Jul-2025	 10:35:21 26-Jul-2025
21	26-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR SERVICE LV.LG-10	 20:19:17 26-Jul-2025	 20:19:01 26-Jul-2025	 20:19:27 26-Jul-2025
22	26-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 24 SISI UNION,LC WAIKIKI,KID STATION,SUSHI TEI LV.LG-10	 10:48:02 26-Jul-2025	 10:48:58 26-Jul-2025	 10:48:31 26-Jul-2025
23	26-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.UG	 10:41:59 26-Jul-2025	 10:42:28 26-Jul-2025	 10:44:43 26-Jul-2025
24	26-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.UG	 20:18:06 26-Jul-2025	 20:18:19 26-Jul-2025	 20:18:31 26-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	26-07-2025	KORIDOR SHOPPING	DUSTING	BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2			
26	26-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SELA SELA PINTU LIFT SERVICE LV.LG-10			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	28-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM	 10:24:34 28-Jul-2025	 10:24:55 28-Jul-2025	 10:25:13 28-Jul-2025
2	28-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI CONECTION TP4	 06:46:22 28-Jul-2025	 06:46:36 28-Jul-2025	 06:46:52 28-Jul-2025
3	28-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI MARGOYOSO	 06:44:56 28-Jul-2025	 06:45:28 28-Jul-2025	 06:45:46 28-Jul-2025
4	28-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)	 02:49:31 28-Jul-2025	 02:49:48 28-Jul-2025	 02:50:16 28-Jul-2025
5	28-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2	 02:50:50 28-Jul-2025	 02:51:28 28-Jul-2025	 02:51:49 28-Jul-2025
6	28-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SELA SELA/SUDUT CLOSET TOILET MALE FEMALE DISABLE	 02:55:26 28-Jul-2025	 02:55:48 28-Jul-2025	 02:56:07 28-Jul-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	28-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.P8A	 02:57:52 28-Jul-2025	 02:58:07 28-Jul-2025	 02:58:22 28-Jul-2025
8	28-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4	 21:42:02 28-Jul-2025	 21:42:17 28-Jul-2025	 21:42:40 28-Jul-2025
9	28-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG	 02:59:30 28-Jul-2025	 02:59:52 28-Jul-2025	 03:00:08 28-Jul-2025
10	28-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.4	 11:31:27 28-Jul-2025	 11:31:45 28-Jul-2025	 11:32:06 28-Jul-2025
11	28-07-2025	KORIDOR SHOPPING	CELLING	CELLING AREA LOBBY LV.UG	 11:45:20 28-Jul-2025	 11:45:33 28-Jul-2025	 11:46:18 28-Jul-2025
12	28-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PILLAR UTAMA LV.UG	 11:41:21 28-Jul-2025	 11:41:40 28-Jul-2025	 11:41:59 28-Jul-2025







No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	28-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.1	 20:38:35 28-Jul-2025	 20:38:50 28-Jul-2025	 20:39:05 28-Jul-2025
14	28-07-2025	KORIDOR SHOPPING	SWEEPING	SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10	 11:42:39 28-Jul-2025	 11:43:13 28-Jul-2025	 11:43:02 28-Jul-2025
15	28-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5	 10:34:28 28-Jul-2025	 10:34:44 28-Jul-2025	 10:35:11 28-Jul-2025
16	28-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5	 10:21:57 28-Jul-2025	 10:22:09 28-Jul-2025	 10:22:21 28-Jul-2025
17	28-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1	 20:40:46 28-Jul-2025	 20:41:00 28-Jul-2025	 20:41:14 28-Jul-2025
18	28-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7	 11:37:38 28-Jul-2025	 11:38:14 28-Jul-2025	 11:38:36 28-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	28-07-2025	KORIDOR SHOPPING	DUSTING	SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5			
20	28-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.7			
21	28-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10			
22	28-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10			
23	28-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR EXIT LV.LG-10			
24	28-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.4			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	28-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.4	 21:40:54 28-Jul-2025	 21:41:19 28-Jul-2025	 21:41:34 28-Jul-2025
26	28-07-2025	KORIDOR SHOPPING	WALL CLEANING	PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5	 20:39:31 28-Jul-2025	 20:39:45 28-Jul-2025	 20:40:18 28-Jul-2025
27	28-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.2	 10:25:59 28-Jul-2025	 10:26:25 28-Jul-2025	 10:26:37 28-Jul-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	29-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER RUMP UP DROP OUT	 07:31:55 29-Jul-2025	 07:32:45 29-Jul-2025	 07:33:27 29-Jul-2025
2	29-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)	 06:22:12 29-Jul-2025	 06:22:29 29-Jul-2025	 06:23:00 29-Jul-2025
3	29-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI MEJA VALET LV.UG	 06:27:16 29-Jul-2025	 06:24:34 29-Jul-2025	 06:27:45 29-Jul-2025
4	29-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 06:30:23 29-Jul-2025	 06:30:40 29-Jul-2025	 06:32:40 29-Jul-2025
5	29-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5	 20:57:03 29-Jul-2025	 20:57:25 29-Jul-2025	 20:57:45 29-Jul-2025
6	29-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE LV.5	 11:19:09 29-Jul-2025	 11:19:33 29-Jul-2025	 11:20:07 29-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	29-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.1	 06:34:27 29-Jul-2025	 06:35:18 29-Jul-2025	 06:34:58 29-Jul-2025
8	29-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.2	 20:55:10 29-Jul-2025	 20:55:47 29-Jul-2025	 20:54:55 29-Jul-2025
9	29-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10	 11:28:58 29-Jul-2025	 11:29:27 29-Jul-2025	 11:29:48 29-Jul-2025
10	29-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7	 11:35:38 29-Jul-2025	 11:36:14 29-Jul-2025	 11:35:57 29-Jul-2025
11	29-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.2-3	 11:36:55 29-Jul-2025	 11:37:16 29-Jul-2025	 11:37:04 29-Jul-2025
12	29-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2	 11:32:21 29-Jul-2025	 11:33:23 29-Jul-2025	 11:33:52 29-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	29-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.9	 11:32:36 29-Jul-2025	 11:33:07 29-Jul-2025	 11:34:08 29-Jul-2025
14	29-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.9	 11:26:46 29-Jul-2025	 11:27:14 29-Jul-2025	 11:27:56 29-Jul-2025
15	29-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING KORIDOR EXIT 24 LV.5	 11:22:14 29-Jul-2025	 11:22:45 29-Jul-2025	 11:23:30 29-Jul-2025
16	29-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR EXIT 24 LV.5	 20:58:07 29-Jul-2025	 20:58:26 29-Jul-2025	 20:58:58 29-Jul-2025
17	29-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	PEMBERSIHAN BASS ROOM LV.7	 10:03:25 29-Jul-2025	 10:04:47 29-Jul-2025	 10:03:47 29-Jul-2025
18	29-07-2025	KORIDOR SHOPPING	DUSTING	LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG	 08:02:07 29-Jul-2025	 08:05:41 29-Jul-2025	 08:03:22 29-Jul-2025





No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	29-07-2025	KORIDOR SHOPPING	DUSTING	LEMARI DISPLAY AREA LOBBY LV.UG			
20	29-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.3			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	30-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER ENTRANCE	 07:13:22 30-Jul-2025	 07:13:54 30-Jul-2025	 07:22:54 30-Jul-2025
2	30-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)	 06:59:27 30-Jul-2025	 06:59:55 30-Jul-2025	 07:00:17 30-Jul-2025
3	30-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SELA SELA/SUDUT CLOSET TOILET MALE FEMALE	 07:01:05 30-Jul-2025	 07:01:32 30-Jul-2025	 07:02:58 30-Jul-2025
4	30-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 07:05:41 30-Jul-2025	 07:06:03 30-Jul-2025	 07:06:20 30-Jul-2025
5	30-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7	 22:43:24 30-Jul-2025	 22:43:50 30-Jul-2025	 22:44:34 30-Jul-2025
6	30-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7	 09:29:41 30-Jul-2025	 09:17:58 30-Jul-2025	 09:29:56 30-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	30-07-2025	CARPARK	GENERAL CLEANING	SUMPIT DAN GREASE ROOM LV.LG	 07:07:23 30-Jul-2025	 07:07:38 30-Jul-2025	 07:07:51 30-Jul-2025
8	30-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.LG	 07:08:42 30-Jul-2025	 07:09:01 30-Jul-2025	 07:09:29 30-Jul-2025
9	30-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.3	 07:14:22 30-Jul-2025	 07:14:42 30-Jul-2025	 07:15:00 30-Jul-2025
10	30-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.4	 07:15:22 30-Jul-2025	 07:15:38 30-Jul-2025	 07:15:54 30-Jul-2025
11	30-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.3	 20:16:42 30-Jul-2025	 20:19:32 30-Jul-2025	 20:17:22 30-Jul-2025
12	30-07-2025	KORIDOR SHOPPING	DUSTING	SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10	 11:43:27 30-Jul-2025	 11:46:47 30-Jul-2025	 11:47:16 30-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	30-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5			
14	30-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9			
15	30-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.4-5			
16	30-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3			
17	30-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING VINYL LV.10			
18	30-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.5			

No	Tanggal	Area	Item Pekerjaan	DetailPekerjaan	Before	Progress	After
19	30-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.4	 20:28:10 30-Jul-2025	 20:28:23 30-Jul-2025	 20:28:36 30-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	31-07-2025	GUTTER	SWEEPING	SWEEPING SALURAN GUTTER SISI BAWAH UNION	 07:08:27 31-Jul-2025	 07:10:19 31-Jul-2025	 07:11:33 31-Jul-2025
2	31-07-2025	ESCALATOR	GENERAL CLEANING	PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)	 03:56:26 31-Jul-2025	 03:56:57 31-Jul-2025	 03:57:50 31-Jul-2025
3	31-07-2025	KRISTALISASI	KRISTALISASI	KRISTALISASI SELA SELA/SUDUT CLOSET TOILET MALE FEMALE DISABLE	 03:45:52 31-Jul-2025	 03:46:26 31-Jul-2025	 03:47:49 31-Jul-2025
4	31-07-2025	CARPARK	GENERAL CLEANING	PEMBERSIHAN AREA CARPARK LV.LG	 03:53:00 31-Jul-2025	 03:53:37 31-Jul-2025	 03:53:58 31-Jul-2025
5	31-07-2025	CARPARK	WASHING	PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10	 22:44:25 31-Jul-2025	 22:44:53 31-Jul-2025	 22:46:39 31-Jul-2025
6	31-07-2025	CARPARK	WALL CLEANING	WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10	 11:17:10 31-Jul-2025	 11:17:51 31-Jul-2025	 11:18:19 31-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	31-07-2025	CARPARK	WASHING	PENCUCIAN TRASHCAN CARPARK LV.P6A	 07:01:47 31-Jul-2025	 07:02:41 31-Jul-2025	 07:03:05 31-Jul-2025
8	31-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG	 22:48:19 31-Jul-2025	 22:48:30 31-Jul-2025	 22:48:49 31-Jul-2025
9	31-07-2025	KORIDOR SHOPPING	WASHING	BRUSHING KORIDOR LANTAI KULIT JERUK LV.5	 03:58:49 31-Jul-2025	 03:59:16 31-Jul-2025	 03:59:39 31-Jul-2025
10	31-07-2025	KORIDOR SHOPPING	GLASS CLEANING	GLASS CLEANING SISI DEPAN TENANT LV.4	 22:49:12 31-Jul-2025	 22:49:25 31-Jul-2025	 22:49:40 31-Jul-2025
11	31-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10	 09:40:27 31-Jul-2025	 09:42:46 31-Jul-2025	 09:43:23 31-Jul-2025
12	31-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10	 11:25:10 31-Jul-2025	 11:25:53 31-Jul-2025	 11:25:26 31-Jul-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	31-07-2025	KORIDOR SHOPPING	DUSTING	DUSTING LIST KACA SISI DEPAN TENANT LV.6-7	 11:20:50 31-Jul-2025	 11:21:51 31-Jul-2025	 11:21:14 31-Jul-2025
14	31-07-2025	KORIDOR SHOPPING	WALL CLEANING	WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4	 22:51:13 31-Jul-2025	 22:51:26 31-Jul-2025	 22:51:38 31-Jul-2025
15	31-07-2025	KORIDOR SHOPPING	GENERAL CLEANING	GENERAL CLEANING TOILET LV.4	 22:03:44 31-Jul-2025	 22:04:01 31-Jul-2025	 22:17:46 31-Jul-2025
16	31-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN ORNAMENT PLAFON HPL LV.5	 07:04:08 31-Jul-2025	 07:04:38 31-Jul-2025	 07:05:03 31-Jul-2025
17	31-07-2025	KORIDOR SHOPPING	DUSTING	PEMBERSIHAN PLAFON/ATAP HPL LV.5	 22:50:07 31-Jul-2025	 22:50:20 31-Jul-2025	 22:50:49 31-Jul-2025