





| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 01-07-2025 | LANTAI 3 | POLISHING        | FLOOR DRAIN      | <br>11:19:23<br>01-Jul-2025   | <br>11:19:58<br>01-Jul-2025   | <br>11:21:16<br>01-Jul-2025   |
| 2  | 01-07-2025 | LANTAI 3 | WALL CLEANING    | DINDING ACP      | <br>11:28:41<br>01-Jul-2025   | <br>11:29:07<br>01-Jul-2025   | <br>11:29:45<br>01-Jul-2025   |
| 3  | 01-07-2025 | LANTAI 3 | GLASS CLEANING   | KACA RAILING     | <br>11:31:39<br>01-Jul-2025  | <br>11:31:59<br>01-Jul-2025  | <br>11:32:15<br>01-Jul-2025  |
| 4  | 01-07-2025 | LANTAI 3 | GENERAL CLEANING | DISWASHING       | <br>19:34:50<br>01-Jul-2025 | <br>19:35:09<br>01-Jul-2025 | <br>19:35:23<br>01-Jul-2025 |
| 5  | 01-07-2025 | LANTAI 2 | POLISHING        | TEMPAT SAMPAH    | <br>11:27:14<br>01-Jul-2025 | <br>11:27:39<br>01-Jul-2025 | <br>11:28:11<br>01-Jul-2025 |
| 6  | 01-07-2025 | LANTAI 2 | BRUSHING         | LANTAI CONCRETE  | <br>11:24:30<br>01-Jul-2025 | <br>11:24:46<br>01-Jul-2025 | <br>11:26:01<br>01-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|-------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 7  | 01-07-2025 | LANTAI 2 | POLISHING      | RAK ACCESORIS           |    |    |    |
| 8  | 01-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA              |    |    |    |
| 9  | 01-07-2025 | LANTAI 2 | POLISHING      | CLOSET                  |   |   |   |
| 10 | 01-07-2025 | LANTAI 1 | POLISHING      | PINTU LIFT              |  |  |  |
| 11 | 01-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH STAINLESS |  |  |  |
| 12 | 01-07-2025 | LANTAI 1 | POLISHING      | WASTAFEL                |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan  | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|-------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 01-07-2025 | LANTAI 1 | POLISHING      | PINTU EXIT        |    |    |    |
| 14 | 01-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |    |    |    |
| 15 | 01-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |   |   |   |
| 16 | 01-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR |  |  |  |
| 17 | 01-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG      |  |  |  |
| 18 | 01-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP TURUN |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 01-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>19:20:49<br>01-Jul-2025   | <br>19:21:13<br>01-Jul-2025   | <br>19:21:32<br>01-Jul-2025   |
| 20 | 01-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>19:15:11<br>01-Jul-2025   | <br>19:15:35<br>01-Jul-2025   | <br>19:15:49<br>01-Jul-2025   |
| 21 | 01-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>11:39:19<br>01-Jul-2025  | <br>11:42:34<br>01-Jul-2025  | <br>11:42:52<br>01-Jul-2025  |
| 22 | 01-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR | <br>19:19:05<br>01-Jul-2025 | <br>19:19:24<br>01-Jul-2025 | <br>19:19:42<br>01-Jul-2025 |
| 23 | 01-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>19:11:31<br>01-Jul-2025 | <br>19:11:44<br>01-Jul-2025 | <br>19:11:59<br>01-Jul-2025 |
| 24 | 01-07-2025 | EXTERNAL | POLISHING      | DINDING CAT              | <br>11:36:11<br>01-Jul-2025 | <br>11:36:25<br>01-Jul-2025 | <br>11:36:40<br>01-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 25 | 01-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       |    |    |    |
| 26 | 01-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        |    |    |    |
| 27 | 01-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     |   |   |   |
| 28 | 01-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR |  |  |  |
| 29 | 01-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        |  |  |  |
| 30 | 01-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       |  |  |  |

| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 01-07-2025 | EXTERNAL          | BRUSHING         | ALCUBON          | <br>11:46:09<br>01-Jul-2025   | <br>11:48:56<br>01-Jul-2025   | <br>11:48:56<br>01-Jul-2025   |
| 32 | 01-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI           | <br>19:10:27<br>01-Jul-2025   | <br>19:10:40<br>01-Jul-2025   | <br>19:10:53<br>01-Jul-2025   |
| 33 | 01-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | PIPA PLUMBING    | <br>11:51:26<br>01-Jul-2025  | <br>11:51:39<br>01-Jul-2025  | <br>11:51:50<br>01-Jul-2025  |
| 34 | 01-07-2025 | MANAGEMENT OFFICE | WALL CLEANING    | DINDING          | <br>11:52:41<br>01-Jul-2025 | <br>11:53:03<br>01-Jul-2025 | <br>11:53:20<br>01-Jul-2025 |
| 35 | 01-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING   | KACA             | <br>19:54:13<br>01-Jul-2025 | <br>19:54:28<br>01-Jul-2025 | <br>19:54:43<br>01-Jul-2025 |
| 36 | 01-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>19:55:30<br>01-Jul-2025 | <br>19:56:01<br>01-Jul-2025 | <br>19:56:25<br>01-Jul-2025 |





| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                                           | After                                                                                                            |
|----|------------|---------------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 01-07-2025 | CARPARK P1-P2 | POLISHING      | RAILING             | <br>20:01:37<br>01-Jul-2025   | <br>01/07/25, 5:02 PM<br>20:01:49<br>01-Jul-2025 | <br>20:02:05<br>01-Jul-2025   |
| 38 | 01-07-2025 | CARPARK P1-P2 | POLISHING      | BOX HYDRANT         | <br>11:54:34<br>01-Jul-2025   | <br>11:54:44<br>01-Jul-2025                      | <br>11:55:00<br>01-Jul-2025   |
| 39 | 01-07-2025 | CARPARK P1-P2 | POLISHING      | TUTUP SAMPIT        | <br>19:32:46<br>01-Jul-2025  | <br>19:33:01<br>01-Jul-2025                     | <br>19:33:20<br>01-Jul-2025  |
| 40 | 01-07-2025 | CARPARK P1-P2 | BRUSHING       | DINDING PLANTER BOX | <br>19:25:48<br>01-Jul-2025 | <br>19:26:08<br>01-Jul-2025                    | <br>19:26:24<br>01-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 02-07-2025 | LANTAI 3 | POLISHING      | KUBIKAL          | <br>13:32:03<br>02-Jul-2025   | <br>13:33:16<br>02-Jul-2025   | <br>13:33:46<br>02-Jul-2025   |
| 2  | 02-07-2025 | LANTAI 3 | WALL CLEANING  | PLANTER BOX      | <br>13:55:14<br>02-Jul-2025   | <br>13:55:31<br>02-Jul-2025   | <br>13:55:47<br>02-Jul-2025   |
| 3  | 02-07-2025 | LANTAI 3 | WALL CLEANING  | PINTU LIFT       | <br>13:58:13<br>02-Jul-2025  | <br>13:58:39<br>02-Jul-2025  | <br>13:58:58<br>02-Jul-2025  |
| 4  | 02-07-2025 | LANTAI 3 | GLASS CLEANING | MIRROR           | <br>17:38:52<br>02-Jul-2025 | <br>17:39:09<br>02-Jul-2025 | <br>17:39:52<br>02-Jul-2025 |
| 5  | 02-07-2025 | LANTAI 2 | POLISHING      | CLOSET           | <br>13:34:18<br>02-Jul-2025 | <br>13:34:38<br>02-Jul-2025 | <br>13:35:04<br>02-Jul-2025 |
| 6  | 02-07-2025 | LANTAI 2 | SPOTTING       | SOFA             | <br>13:24:12<br>02-Jul-2025 | <br>13:25:03<br>02-Jul-2025 | <br>13:25:21<br>02-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 02-07-2025 | LANTAI 2 | SPOTTING       | FLOOR DRAIN      | <br>13:43:21<br>02-Jul-2025   | <br>13:44:07<br>02-Jul-2025   | <br>13:44:28<br>02-Jul-2025   |
| 8  | 02-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN      | <br>13:27:56<br>02-Jul-2025   | <br>13:30:32<br>02-Jul-2025   | <br>13:32:29<br>02-Jul-2025   |
| 9  | 02-07-2025 | LANTAI 1 | WALL CLEANING  | DINDING LIFT     | <br>13:59:47<br>02-Jul-2025  | <br>14:00:11<br>02-Jul-2025  | <br>14:00:34<br>02-Jul-2025  |
| 10 | 02-07-2025 | LANTAI 1 | HIGH DUSTING   | KIPAS            | <br>20:57:36<br>02-Jul-2025 | <br>20:57:50<br>02-Jul-2025 | <br>20:58:08<br>02-Jul-2025 |
| 11 | 02-07-2025 | LANTAI 1 | POLISHING      | CLOSET           | <br>13:35:49<br>02-Jul-2025 | <br>13:36:05<br>02-Jul-2025 | <br>13:36:19<br>02-Jul-2025 |
| 12 | 02-07-2025 | LANTAI 1 | SWEEPING       | TANGGA           | <br>14:07:39<br>02-Jul-2025 | <br>14:07:55<br>02-Jul-2025 | <br>14:08:11<br>02-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 02-07-2025 | BASEMENT | POLISHING       | BODY STAINLESS ESCALATOR    | <br>20:21:28<br>02-Jul-2025   | <br>20:22:00<br>02-Jul-2025   | <br>20:22:34<br>02-Jul-2025   |
| 14 | 02-07-2025 | BASEMENT | PLAFON CLEANING | CEILING                     | <br>20:24:18<br>02-Jul-2025   | <br>20:25:23<br>02-Jul-2025   | <br>20:25:59<br>02-Jul-2025   |
| 15 | 02-07-2025 | BASEMENT | WALL CLEANING   | DINDING CAT PARKIR BASEMENT | <br>20:28:25<br>02-Jul-2025  | <br>20:29:38<br>02-Jul-2025  | <br>20:30:28<br>02-Jul-2025  |
| 16 | 02-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR               | <br>21:01:29<br>02-Jul-2025 | <br>21:01:47<br>02-Jul-2025 | <br>21:02:31<br>02-Jul-2025 |
| 17 | 02-07-2025 | BASEMENT | WASHING         | LANTAI EPOXY                | <br>20:31:44<br>02-Jul-2025 | <br>20:32:25<br>02-Jul-2025 | <br>20:33:11<br>02-Jul-2025 |
| 18 | 02-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING               | <br>20:35:43<br>02-Jul-2025 | <br>20:36:03<br>02-Jul-2025 | <br>20:36:40<br>02-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|-----------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 19 | 02-07-2025 | BASEMENT | WALL CLEANING   | PILAR BETON      |    |    |    |
| 20 | 02-07-2025 | BASEMENT | PLAFON CLEANING | CEILING          |    |    |    |
| 21 | 02-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING    |   |   |   |
| 22 | 02-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR    |  |  |  |
| 23 | 02-07-2025 | EXTERNAL | BRUSHING        | GUTTER           |  |  |  |
| 24 | 02-07-2025 | EXTERNAL | WALL CLEANING   | TEMPAT SAMPAH    |  |  |  |








| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 02-07-2025 | EXTERNAL          | WALL CLEANING    | GUTTER           | <br>20:45:35<br>02-Jul-2025   | <br>20:45:54<br>02-Jul-2025   | <br>20:46:40<br>02-Jul-2025   |
| 26 | 02-07-2025 | EXTERNAL          | POLISHING        | LANTAI ANDESIT   | <br>20:42:29<br>02-Jul-2025   | <br>20:42:58<br>02-Jul-2025   | <br>20:43:21<br>02-Jul-2025   |
| 27 | 02-07-2025 | EXTERNAL          | BRUSHING         | PIPA HYDRANT     | <br>20:38:27<br>02-Jul-2025  | <br>20:38:54<br>02-Jul-2025  | <br>20:39:08<br>02-Jul-2025  |
| 28 | 02-07-2025 | EXTERNAL          | HIGH DUSTING     | SIGN RAMBU JALAN | <br>20:55:39<br>02-Jul-2025 | <br>20:55:54<br>02-Jul-2025 | <br>20:56:13<br>02-Jul-2025 |
| 29 | 02-07-2025 | EXTERNAL          | BRUSHING         | LOGO JKTPO       | <br>14:04:42<br>02-Jul-2025 | <br>14:05:00<br>02-Jul-2025 | <br>14:05:23<br>02-Jul-2025 |
| 30 | 02-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>14:16:24<br>02-Jul-2025 | <br>14:16:50<br>02-Jul-2025 | <br>14:17:17<br>02-Jul-2025 |





| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan    | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|-------------------|------------------|---------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 31 | 02-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI              |    |    |    |
| 32 | 02-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU        |    |    |    |
| 33 | 02-07-2025 | CARPARK P1-P2     | POLISHING        | LANDING ESCALATOR   |   |   |   |
| 34 | 02-07-2025 | CARPARK P1-P2     | BRUSHING         | DINDING PLANTER BOX |  |  |  |
| 35 | 02-07-2025 | CARPARK P1-P2     | HIGH DUSTING     | JET FAN             |  |  |  |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 03-07-2025 | LANTAI 3 | POLISHING      | CLOSET           | <br>17:07:24<br>03-Jul-2025   | <br>17:07:53<br>03-Jul-2025   | <br>17:09:23<br>03-Jul-2025   |
| 2  | 03-07-2025 | LANTAI 3 | BRUSHING       | LANTAI CONCRETE  | <br>12:09:22<br>03-Jul-2025   | <br>12:10:11<br>03-Jul-2025   | <br>12:10:42<br>03-Jul-2025   |
| 3  | 03-07-2025 | LANTAI 3 | POLISHING      | MEJA             | <br>12:12:32<br>03-Jul-2025  | <br>12:13:06<br>03-Jul-2025  | <br>12:13:20<br>03-Jul-2025  |
| 4  | 03-07-2025 | LANTAI 3 | POLISHING      | WASTAFEL         | <br>17:09:48<br>03-Jul-2025 | <br>17:10:07<br>03-Jul-2025 | <br>17:13:09<br>03-Jul-2025 |
| 5  | 03-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA       | <br>17:39:04<br>03-Jul-2025 | <br>17:38:25<br>03-Jul-2025 | <br>17:39:23<br>03-Jul-2025 |
| 6  | 03-07-2025 | LANTAI 2 | POLISHING      | KUBIKAL          | <br>12:15:58<br>03-Jul-2025 | <br>12:16:09<br>03-Jul-2025 | <br>12:16:21<br>03-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 03-07-2025 | LANTAI 2 | BRUSHING       | GUTTER                  | <br>17:47:20<br>03-Jul-2025   | <br>17:47:41<br>03-Jul-2025   | <br>17:48:08<br>03-Jul-2025   |
| 8  | 03-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>17:27:41<br>03-Jul-2025   | <br>17:28:00<br>03-Jul-2025   | <br>17:28:54<br>03-Jul-2025   |
| 9  | 03-07-2025 | LANTAI 1 | SPOTTING       | KURSI                   | <br>17:52:58<br>03-Jul-2025  | <br>17:53:16<br>03-Jul-2025  | <br>17:53:31<br>03-Jul-2025  |
| 10 | 03-07-2025 | LANTAI 1 | SPOTTING       | LIST SKIRTING           | <br>12:14:08<br>03-Jul-2025 | <br>12:14:31<br>03-Jul-2025 | <br>12:14:48<br>03-Jul-2025 |
| 11 | 03-07-2025 | LANTAI 1 | POLISHING      | FLOOR DRAIN             | <br>17:22:53<br>03-Jul-2025 | <br>17:23:09<br>03-Jul-2025 | <br>17:24:48<br>03-Jul-2025 |
| 12 | 03-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR       | <br>17:54:46<br>03-Jul-2025 | <br>17:55:04<br>03-Jul-2025 | <br>17:55:33<br>03-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|-----------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 03-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT                 |    |    |    |
| 14 | 03-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         |    |    |    |
| 15 | 03-07-2025 | BASEMENT | WALL CLEANING  | PILAR BETON                 |   |   |   |
| 16 | 03-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR           |  |  |  |
| 17 | 03-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  |  |  |  |
| 18 | 03-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT |  |  |  |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 19 | 03-07-2025 | BASEMENT | POLISHING      | STAINLESS BULAT  |    |    |    |
| 20 | 03-07-2025 | EXTERNAL | POLISHING      | SIGN RAMBU JALAN |    |    |    |
| 21 | 03-07-2025 | EXTERNAL | BRUSHING       | LOGO JKTP0       |   |   |   |
| 22 | 03-07-2025 | EXTERNAL | POLISHING      | DINDING CAT      |  |  |  |
| 23 | 03-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM        |  |  |  |
| 24 | 03-07-2025 | EXTERNAL | POLISHING      | ALCUBON          |  |  |  |





| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan      | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|-----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 03-07-2025 | EXTERNAL          | BRUSHING         | TEMPAT SAMPAH         | <br>17:20:18<br>03-Jul-2025   | <br>17:21:05<br>03-Jul-2025   | <br>17:21:28<br>03-Jul-2025   |
| 26 | 03-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU          | <br>18:07:27<br>03-Jul-2025   | <br>18:09:36<br>03-Jul-2025   | <br>18:07:59<br>03-Jul-2025   |
| 27 | 03-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET                | <br>12:25:15<br>03-Jul-2025  | <br>12:25:27<br>03-Jul-2025  | <br>12:26:08<br>03-Jul-2025  |
| 28 | 03-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING               | <br>18:12:35<br>03-Jul-2025 | <br>18:10:33<br>03-Jul-2025 | <br>18:13:00<br>03-Jul-2025 |
| 29 | 03-07-2025 | CARPARK P1-P2     | POLISHING        | PINTU DAN DOOR CLOSER | <br>17:18:13<br>03-Jul-2025 | <br>17:18:52<br>03-Jul-2025 | <br>17:19:37<br>03-Jul-2025 |
| 30 | 03-07-2025 | CARPARK P1-P2     | POLISHING        | STAINLESS BULAT       | <br>12:18:45<br>03-Jul-2025 | <br>12:19:03<br>03-Jul-2025 | <br>12:19:29<br>03-Jul-2025 |




| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan  | Before                                                                            | Progress                                                                           | After                                                                               |
|----|------------|---------------|----------------|-------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 31 | 03-07-2025 | CARPARK P1-P2 | POLISHING      | LANDING ESCALATOR |  |  |  |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 04-07-2025 | LANTAI 3 | BRUSHING       | LANTAI GRANIT BAKAR | <br>15:28:04<br>04-Jul-2025   | <br>15:28:25<br>04-Jul-2025   | <br>15:28:46<br>04-Jul-2025   |
| 2  | 04-07-2025 | LANTAI 3 | WALL CLEANING  | HAND RAILING        | <br>11:30:37<br>04-Jul-2025   | <br>11:30:51<br>04-Jul-2025   | <br>11:31:05<br>04-Jul-2025   |
| 3  | 04-07-2025 | LANTAI 3 | POLISHING      | KURSI               | <br>11:31:43<br>04-Jul-2025  | <br>11:32:52<br>04-Jul-2025  | <br>11:33:03<br>04-Jul-2025  |
| 4  | 04-07-2025 | LANTAI 3 | SPOTTING       | SOFA                | <br>11:33:36<br>04-Jul-2025 | <br>11:33:47<br>04-Jul-2025 | <br>11:33:59<br>04-Jul-2025 |
| 5  | 04-07-2025 | LANTAI 2 | GLASS CLEANING | TEMPAT SAMPAH       | <br>15:23:34<br>04-Jul-2025 | <br>15:23:51<br>04-Jul-2025 | <br>15:24:09<br>04-Jul-2025 |
| 6  | 04-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN         | <br>22:23:46<br>04-Jul-2025 | <br>22:24:22<br>04-Jul-2025 | <br>22:24:55<br>04-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 04-07-2025 | LANTAI 2 | WALL CLEANING  | PLANTER BOX      | <br>15:31:35<br>04-Jul-2025   | <br>15:32:03<br>04-Jul-2025   | <br>15:32:27<br>04-Jul-2025   |
| 8  | 04-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH    | <br>15:29:35<br>04-Jul-2025   | <br>15:29:53<br>04-Jul-2025   | <br>15:30:12<br>04-Jul-2025   |
| 9  | 04-07-2025 | LANTAI 1 | BRUSHING       | LANTAI CONCRETE  | <br>11:35:20<br>04-Jul-2025  | <br>11:35:31<br>04-Jul-2025  | <br>11:36:03<br>04-Jul-2025  |
| 10 | 04-07-2025 | LANTAI 1 | SPOTTING       | AC GRILL         | <br>15:33:12<br>04-Jul-2025 | <br>15:33:28<br>04-Jul-2025 | <br>15:33:46<br>04-Jul-2025 |
| 11 | 04-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH    | <br>11:37:27<br>04-Jul-2025 | <br>11:37:52<br>04-Jul-2025 | <br>11:38:26<br>04-Jul-2025 |
| 12 | 04-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK | <br>15:38:12<br>04-Jul-2025 | <br>15:38:27<br>04-Jul-2025 | <br>15:38:45<br>04-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 04-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR    | <br>15:35:30<br>04-Jul-2025   | <br>15:35:46<br>04-Jul-2025   | <br>15:36:02<br>04-Jul-2025   |
| 14 | 04-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK              | <br>15:42:14<br>04-Jul-2025   | <br>15:42:33<br>04-Jul-2025   | <br>15:42:49<br>04-Jul-2025   |
| 15 | 04-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  | <br>22:12:59<br>04-Jul-2025  | <br>22:13:42<br>04-Jul-2025  | <br>22:14:01<br>04-Jul-2025  |
| 16 | 04-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT | <br>15:56:09<br>04-Jul-2025 | <br>15:57:49<br>04-Jul-2025 | <br>15:57:16<br>04-Jul-2025 |
| 17 | 04-07-2025 | BASEMENT | POLISHING      | TUTUP SAMPIT                | <br>15:44:26<br>04-Jul-2025 | <br>15:44:47<br>04-Jul-2025 | <br>15:45:06<br>04-Jul-2025 |
| 18 | 04-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         | <br>11:40:07<br>04-Jul-2025 | <br>11:40:23<br>04-Jul-2025 | <br>11:40:47<br>04-Jul-2025 |







| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 19 | 04-07-2025 | BASEMENT | WASHING        | LANTAI EPOXY         |    |    |    |
| 20 | 04-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         |    |    |    |
| 21 | 04-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            |   |   |   |
| 22 | 04-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         |  |  |  |
| 23 | 04-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          |  |  |  |
| 24 | 04-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR |  |  |  |


| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 04-07-2025 | EXTERNAL          | BRUSHING         | BATU ALAM                | <br>22:09:28<br>04-Jul-2025   | <br>22:09:53<br>04-Jul-2025   | <br>22:10:16<br>04-Jul-2025   |
| 26 | 04-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING                  | <br>11:44:05<br>04-Jul-2025   | <br>11:44:31<br>04-Jul-2025   | <br>11:44:45<br>04-Jul-2025   |
| 27 | 04-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU             | <br>22:05:21<br>04-Jul-2025  | <br>22:05:46<br>04-Jul-2025  | <br>22:06:27<br>04-Jul-2025  |
| 28 | 04-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | COVER LAMP               | <br>11:29:26<br>04-Jul-2025 | <br>11:29:54<br>04-Jul-2025 | <br>11:30:08<br>04-Jul-2025 |
| 29 | 04-07-2025 | CARPARK P1-P2     | HIGH DUSTING     | OUTDOOR AC               | <br>11:49:50<br>04-Jul-2025 | <br>11:50:01<br>04-Jul-2025 | <br>11:50:14<br>04-Jul-2025 |
| 30 | 04-07-2025 | CARPARK P1-P2     | POLISHING        | BODY STAINLESS ESCALATOR | <br>15:16:06<br>04-Jul-2025 | <br>15:17:15<br>04-Jul-2025 | <br>15:17:35<br>04-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 07-07-2025 | LANTAI 3 | POLISHING      | URINOIR                 | <br>10:33:02<br>07-Jul-2025   | <br>10:33:35<br>07-Jul-2025   | <br>10:33:58<br>07-Jul-2025   |
| 2  | 07-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH           | <br>18:46:10<br>07-Jul-2025   | <br>18:46:31<br>07-Jul-2025   | <br>18:47:02<br>07-Jul-2025   |
| 3  | 07-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>10:34:35<br>07-Jul-2025  | <br>10:34:54<br>07-Jul-2025  | <br>10:35:25<br>07-Jul-2025  |
| 4  | 07-07-2025 | LANTAI 3 | POLISHING      | TRAY                    | <br>10:42:21<br>07-Jul-2025 | <br>10:42:32<br>07-Jul-2025 | <br>10:43:18<br>07-Jul-2025 |
| 5  | 07-07-2025 | LANTAI 3 | POLISHING      | CLOSET                  | <br>18:56:48<br>07-Jul-2025 | <br>18:57:05<br>07-Jul-2025 | <br>18:57:26<br>07-Jul-2025 |
| 6  | 07-07-2025 | LANTAI 2 | SPOTTING       | SOFA                    | <br>10:44:35<br>07-Jul-2025 | <br>10:44:47<br>07-Jul-2025 | <br>10:45:02<br>07-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|---------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 7  | 07-07-2025 | LANTAI 2 | WALL CLEANING  | PINTU LIFT          |    |    |    |
| 8  | 07-07-2025 | LANTAI 2 | BRUSHING       | LANTAI GRANIT BAKAR |    |    |    |
| 9  | 07-07-2025 | LANTAI 2 | POLISHING      | CLOSET              |   |   |   |
| 10 | 07-07-2025 | LANTAI 1 | HIGH DUSTING   | NEON LED            |  |  |  |
| 11 | 07-07-2025 | LANTAI 1 | BRUSHING       | LANTAI KERAMIK      |  |  |  |
| 12 | 07-07-2025 | LANTAI 1 | POLISHING      | KUBIKAL             |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan  | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 07-07-2025 | LANTAI 1 | GLASS CLEANING  | KACA              | <br>18:41:23<br>07-Jul-2025   | <br>18:41:40<br>07-Jul-2025   | <br>18:41:59<br>07-Jul-2025   |
| 14 | 07-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>18:22:09<br>07-Jul-2025   | <br>18:22:33<br>07-Jul-2025   | <br>18:22:59<br>07-Jul-2025   |
| 15 | 07-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>18:20:53<br>07-Jul-2025  | <br>18:21:14<br>07-Jul-2025  | <br>18:21:34<br>07-Jul-2025  |
| 16 | 07-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING     | <br>21:05:33<br>07-Jul-2025 | <br>21:06:38<br>07-Jul-2025 | <br>21:07:41<br>07-Jul-2025 |
| 17 | 07-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP NAIK  | <br>18:51:14<br>07-Jul-2025 | <br>18:51:51<br>07-Jul-2025 | <br>18:52:13<br>07-Jul-2025 |
| 18 | 07-07-2025 | BASEMENT | POLISHING       | STAINLESS BULAT   | <br>18:58:39<br>07-Jul-2025 | <br>18:58:56<br>07-Jul-2025 | <br>18:59:21<br>07-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 07-07-2025 | BASEMENT | POLISHING      | TUTUP SAMPIT     | <br>19:08:50<br>07-Jul-2025   | <br>19:09:11<br>07-Jul-2025   | <br>19:09:32<br>07-Jul-2025   |
| 20 | 07-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK | <br>18:25:29<br>07-Jul-2025   | <br>18:25:48<br>07-Jul-2025   | <br>18:26:08<br>07-Jul-2025   |
| 21 | 07-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN          | <br>21:08:37<br>07-Jul-2025  | <br>21:10:28<br>07-Jul-2025  | <br>21:10:52<br>07-Jul-2025  |
| 22 | 07-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT      | <br>17:24:06<br>07-Jul-2025 | <br>17:24:27<br>07-Jul-2025 | <br>17:24:51<br>07-Jul-2025 |
| 23 | 07-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK   | <br>12:09:20<br>07-Jul-2025 | <br>12:09:41<br>07-Jul-2025 | <br>12:10:33<br>07-Jul-2025 |
| 24 | 07-07-2025 | EXTERNAL | POLISHING      | PIPA HYDRANT     | <br>10:40:54<br>07-Jul-2025 | <br>10:41:03<br>07-Jul-2025 | <br>10:41:32<br>07-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 07-07-2025 | EXTERNAL | BRUSHING       | BOX HYDRANT DAN APAR | <br>18:15:24<br>07-Jul-2025   | <br>18:16:18<br>07-Jul-2025   | <br>18:16:39<br>07-Jul-2025   |
| 26 | 07-07-2025 | EXTERNAL | WALL CLEANING  | PIPA HYDRANT         | <br>18:37:51<br>07-Jul-2025   | <br>18:38:16<br>07-Jul-2025   | <br>18:38:41<br>07-Jul-2025   |
| 27 | 07-07-2025 | EXTERNAL | BRUSHING       | ALCUBON              | <br>18:36:09<br>07-Jul-2025  | <br>18:36:32<br>07-Jul-2025  | <br>18:36:56<br>07-Jul-2025  |
| 28 | 07-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER      | <br>21:11:39<br>07-Jul-2025 | <br>21:12:02<br>07-Jul-2025 | <br>21:12:25<br>07-Jul-2025 |
| 29 | 07-07-2025 | EXTERNAL | WALL CLEANING  | GUTTER               | <br>18:26:51<br>07-Jul-2025 | <br>18:27:13<br>07-Jul-2025 | <br>18:27:30<br>07-Jul-2025 |
| 30 | 07-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER      | <br>21:13:02<br>07-Jul-2025 | <br>21:13:27<br>07-Jul-2025 | <br>21:13:52<br>07-Jul-2025 |


| No | Tanggal    | Area              | Item Pekerjaan  | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|-------------------|-----------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 31 | 07-07-2025 | EXTERNAL          | BRUSHING        | DINDING BETON    |    |    |    |
| 32 | 07-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING          |    |    |    |
| 33 | 07-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | COVER LAMP       |   |   |   |
| 34 | 07-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING  | KACA             |  |  |  |
| 35 | 07-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | PIPA PLUMBING    |  |  |  |
| 36 | 07-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING          |  |  |  |




| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|---------------|----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 07-07-2025 | CARPARK P1-P2 | POLISHING      | BODY STAINLESS ESCALATOR | <br>10:49:22<br>07-Jul-2025   | <br>10:49:41<br>07-Jul-2025   | <br>10:50:06<br>07-Jul-2025   |
| 38 | 07-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI CONCRETE          | <br>18:32:57<br>07-Jul-2025   | <br>18:33:15<br>07-Jul-2025   | <br>18:33:55<br>07-Jul-2025   |
| 39 | 07-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI KERAMIK           | <br>18:28:22<br>07-Jul-2025  | <br>18:28:43<br>07-Jul-2025  | <br>18:29:06<br>07-Jul-2025  |
| 40 | 07-07-2025 | CARPARK P1-P2 | GLASS CLEANING | SAFETY MIRROR            | <br>15:39:11<br>07-Jul-2025 | <br>15:39:35<br>07-Jul-2025 | <br>15:40:07<br>07-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 08-07-2025 | LANTAI 3 | POLISHING        | FLOOR DRAIN      | <br>11:24:26<br>08-Jul-2025   | <br>11:23:01<br>08-Jul-2025   | <br>11:24:26<br>08-Jul-2025   |
| 2  | 08-07-2025 | LANTAI 3 | WALL CLEANING    | DINDING ACP      | <br>11:28:06<br>08-Jul-2025   | <br>11:28:42<br>08-Jul-2025   | <br>11:29:34<br>08-Jul-2025   |
| 3  | 08-07-2025 | LANTAI 3 | GLASS CLEANING   | KACA RAILING     | <br>11:31:06<br>08-Jul-2025  | <br>11:31:21<br>08-Jul-2025  | <br>11:31:37<br>08-Jul-2025  |
| 4  | 08-07-2025 | LANTAI 3 | GENERAL CLEANING | DISWASHING       | <br>18:54:08<br>08-Jul-2025 | <br>18:54:31<br>08-Jul-2025 | <br>18:55:05<br>08-Jul-2025 |
| 5  | 08-07-2025 | LANTAI 2 | POLISHING        | TEMPAT SAMPAH    | <br>11:32:17<br>08-Jul-2025 | <br>11:32:28<br>08-Jul-2025 | <br>11:32:45<br>08-Jul-2025 |
| 6  | 08-07-2025 | LANTAI 2 | BRUSHING         | LANTAI CONCRETE  | <br>11:46:47<br>08-Jul-2025 | <br>11:47:15<br>08-Jul-2025 | <br>11:47:45<br>08-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 08-07-2025 | LANTAI 2 | POLISHING      | RAK ACCESORIS           | <br>18:56:20<br>08-Jul-2025   | <br>18:56:37<br>08-Jul-2025   | <br>18:57:06<br>08-Jul-2025   |
| 8  | 08-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA              | <br>11:29:55<br>08-Jul-2025   | <br>11:30:09<br>08-Jul-2025   | <br>11:30:27<br>08-Jul-2025   |
| 9  | 08-07-2025 | LANTAI 2 | POLISHING      | CLOSET                  | <br>18:57:35<br>08-Jul-2025  | <br>18:57:50<br>08-Jul-2025  | <br>18:58:12<br>08-Jul-2025  |
| 10 | 08-07-2025 | LANTAI 1 | POLISHING      | PINTU LIFT              | <br>18:58:49<br>08-Jul-2025 | <br>18:59:06<br>08-Jul-2025 | <br>18:59:30<br>08-Jul-2025 |
| 11 | 08-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>11:26:05<br>08-Jul-2025 | <br>11:26:17<br>08-Jul-2025 | <br>11:26:56<br>08-Jul-2025 |
| 12 | 08-07-2025 | LANTAI 1 | POLISHING      | WASTAFEL                | <br>19:01:30<br>08-Jul-2025 | <br>19:01:58<br>08-Jul-2025 | <br>19:02:28<br>08-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan  | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|-------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 08-07-2025 | LANTAI 1 | POLISHING      | PINTU EXIT        |    |    |    |
| 14 | 08-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |    |    |    |
| 15 | 08-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |   |   |   |
| 16 | 08-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR |  |  |  |
| 17 | 08-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG      |  |  |  |
| 18 | 08-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP TURUN |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 08-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>18:51:08<br>08-Jul-2025   | <br>18:51:23<br>08-Jul-2025   | <br>18:51:43<br>08-Jul-2025   |
| 20 | 08-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>19:26:36<br>08-Jul-2025   | <br>19:27:52<br>08-Jul-2025   | <br>19:28:21<br>08-Jul-2025   |
| 21 | 08-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>14:03:42<br>08-Jul-2025  | <br>14:04:04<br>08-Jul-2025  | <br>14:04:41<br>08-Jul-2025  |
| 22 | 08-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR | <br>18:49:33<br>08-Jul-2025 | <br>18:49:47<br>08-Jul-2025 | <br>18:50:06<br>08-Jul-2025 |
| 23 | 08-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>14:09:14<br>08-Jul-2025 | <br>14:09:31<br>08-Jul-2025 | <br>14:09:51<br>08-Jul-2025 |
| 24 | 08-07-2025 | EXTERNAL | POLISHING      | DINDING CAT              | <br>14:05:29<br>08-Jul-2025 | <br>14:05:48<br>08-Jul-2025 | <br>14:06:12<br>08-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 08-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       | <br>19:03:33<br>08-Jul-2025   | <br>19:03:49<br>08-Jul-2025   | <br>19:04:09<br>08-Jul-2025   |
| 26 | 08-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        | <br>19:10:44<br>08-Jul-2025   | <br>19:11:01<br>08-Jul-2025   | <br>19:11:17<br>08-Jul-2025   |
| 27 | 08-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     | <br>19:09:23<br>08-Jul-2025  | <br>19:09:48<br>08-Jul-2025  | <br>19:10:03<br>08-Jul-2025  |
| 28 | 08-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR | <br>18:47:44<br>08-Jul-2025 | <br>18:48:00<br>08-Jul-2025 | <br>18:48:18<br>08-Jul-2025 |
| 29 | 08-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        | <br>19:08:27<br>08-Jul-2025 | <br>19:08:43<br>08-Jul-2025 | <br>19:08:59<br>08-Jul-2025 |
| 30 | 08-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       | <br>13:57:15<br>08-Jul-2025 | <br>13:57:36<br>08-Jul-2025 | <br>13:57:54<br>08-Jul-2025 |



| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 08-07-2025 | EXTERNAL          | BRUSHING         | ALCUBON          | <br>12:06:20<br>08-Jul-2025   | <br>12:06:41<br>08-Jul-2025   | <br>12:06:54<br>08-Jul-2025   |
| 32 | 08-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI           | <br>18:38:04<br>08-Jul-2025   | <br>18:38:22<br>08-Jul-2025   | <br>18:39:08<br>08-Jul-2025   |
| 33 | 08-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | PIPA PLUMBING    | <br>11:38:40<br>08-Jul-2025  | <br>11:42:20<br>08-Jul-2025  | <br>11:42:40<br>08-Jul-2025  |
| 34 | 08-07-2025 | MANAGEMENT OFFICE | WALL CLEANING    | DINDING          | <br>11:43:03<br>08-Jul-2025 | <br>11:43:43<br>08-Jul-2025 | <br>11:44:00<br>08-Jul-2025 |
| 35 | 08-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING   | KACA             | <br>18:46:08<br>08-Jul-2025 | <br>18:46:33<br>08-Jul-2025 | <br>18:46:50<br>08-Jul-2025 |
| 36 | 08-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>18:43:04<br>08-Jul-2025 | <br>18:43:21<br>08-Jul-2025 | <br>18:43:49<br>08-Jul-2025 |




| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|---------------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 08-07-2025 | CARPARK P1-P2 | POLISHING      | RAILING             | <br>18:41:24<br>08-Jul-2025   | <br>18:41:44<br>08-Jul-2025   | <br>18:42:21<br>08-Jul-2025   |
| 38 | 08-07-2025 | CARPARK P1-P2 | POLISHING      | BOX HYDRANT         | <br>11:36:15<br>08-Jul-2025   | <br>11:36:31<br>08-Jul-2025   | <br>11:37:15<br>08-Jul-2025   |
| 39 | 08-07-2025 | CARPARK P1-P2 | POLISHING      | TUTUP SAMPIT        | <br>19:11:54<br>08-Jul-2025  | <br>19:12:08<br>08-Jul-2025  | <br>19:12:23<br>08-Jul-2025  |
| 40 | 08-07-2025 | CARPARK P1-P2 | BRUSHING       | DINDING PLANTER BOX | <br>18:39:43<br>08-Jul-2025 | <br>18:40:02<br>08-Jul-2025 | <br>18:40:25<br>08-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 09-07-2025 | LANTAI 3 | POLISHING      | KUBIKAL          | <br>11:39:05<br>09-Jul-2025   | <br>11:40:08<br>09-Jul-2025   | <br>11:40:33<br>09-Jul-2025   |
| 2  | 09-07-2025 | LANTAI 3 | WALL CLEANING  | PLANTER BOX      | <br>11:59:53<br>09-Jul-2025   | <br>12:00:09<br>09-Jul-2025   | <br>12:00:23<br>09-Jul-2025   |
| 3  | 09-07-2025 | LANTAI 3 | WALL CLEANING  | PINTU LIFT       | <br>12:10:36<br>09-Jul-2025  | <br>12:10:50<br>09-Jul-2025  | <br>12:11:16<br>09-Jul-2025  |
| 4  | 09-07-2025 | LANTAI 3 | GLASS CLEANING | MIRROR           | <br>17:05:31<br>09-Jul-2025 | <br>17:07:25<br>09-Jul-2025 | <br>17:09:12<br>09-Jul-2025 |
| 5  | 09-07-2025 | LANTAI 2 | POLISHING      | CLOSET           | <br>11:42:47<br>09-Jul-2025 | <br>11:43:41<br>09-Jul-2025 | <br>11:44:28<br>09-Jul-2025 |
| 6  | 09-07-2025 | LANTAI 2 | SPOTTING       | SOFA             | <br>12:00:59<br>09-Jul-2025 | <br>12:01:22<br>09-Jul-2025 | <br>12:01:38<br>09-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before | Progress | After |
|----|------------|----------|----------------|------------------|--------|----------|-------|
| 7  | 09-07-2025 | LANTAI 2 | SPOTTING       | FLOOR DRAIN      |        |          |       |
| 8  | 09-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN      |        |          |       |
| 9  | 09-07-2025 | LANTAI 1 | WALL CLEANING  | DINDING LIFT     |        |          |       |
| 10 | 09-07-2025 | LANTAI 1 | HIGH DUSTING   | KIPAS            |        |          |       |
| 11 | 09-07-2025 | LANTAI 1 | POLISHING      | CLOSET           |        |          |       |
| 12 | 09-07-2025 | LANTAI 1 | SWEEPING       | TANGGA           |        |          |       |



| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 09-07-2025 | BASEMENT | POLISHING       | BODY STAINLESS ESCALATOR    | <br>20:11:43<br>09-Jul-2025   | <br>20:12:09<br>09-Jul-2025   | <br>20:12:46<br>09-Jul-2025   |
| 14 | 09-07-2025 | BASEMENT | PLAFON CLEANING | CEILING                     | <br>20:27:00<br>09-Jul-2025   | <br>20:27:25<br>09-Jul-2025   | <br>20:27:44<br>09-Jul-2025   |
| 15 | 09-07-2025 | BASEMENT | WALL CLEANING   | DINDING CAT PARKIR BASEMENT | <br>20:30:01<br>09-Jul-2025  | <br>20:30:25<br>09-Jul-2025  | <br>20:30:56<br>09-Jul-2025  |
| 16 | 09-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR               | <br>19:22:37<br>09-Jul-2025 | <br>19:23:01<br>09-Jul-2025 | <br>19:23:25<br>09-Jul-2025 |
| 17 | 09-07-2025 | BASEMENT | WASHING         | LANTAI EPOXY                | <br>20:31:46<br>09-Jul-2025 | <br>20:32:11<br>09-Jul-2025 | <br>20:32:37<br>09-Jul-2025 |
| 18 | 09-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING               | <br>20:23:30<br>09-Jul-2025 | <br>20:24:01<br>09-Jul-2025 | <br>20:24:16<br>09-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan | Before | Progress | After |
|----|------------|----------|-----------------|------------------|--------|----------|-------|
| 19 | 09-07-2025 | BASEMENT | WALL CLEANING   | PILAR BETON      |        |          |       |
| 20 | 09-07-2025 | BASEMENT | PLAFON CLEANING | CEILING          |        |          |       |
| 21 | 09-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING    |        |          |       |
| 22 | 09-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR    |        |          |       |
| 23 | 09-07-2025 | EXTERNAL | BRUSHING        | GUTTER           |        |          |       |
| 24 | 09-07-2025 | EXTERNAL | WALL CLEANING   | TEMPAT SAMPAH    |        |          |       |




| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|-------------------|------------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 25 | 09-07-2025 | EXTERNAL          | WALL CLEANING    | GUTTER           |    |    |    |
| 26 | 09-07-2025 | EXTERNAL          | POLISHING        | LANTAI ANDESIT   |    |    |    |
| 27 | 09-07-2025 | EXTERNAL          | BRUSHING         | PIPA HYDRANT     |   |   |   |
| 28 | 09-07-2025 | EXTERNAL          | HIGH DUSTING     | SIGN RAMBU JALAN |  |  |  |
| 29 | 09-07-2025 | EXTERNAL          | BRUSHING         | LOGO JKTP0       |  |  |  |
| 30 | 09-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           |  |  |  |


| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 09-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI              | <br>17:18:24<br>09-Jul-2025   | <br>17:20:00<br>09-Jul-2025   | <br>17:22:26<br>09-Jul-2025   |
| 32 | 09-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU        | <br>12:26:55<br>09-Jul-2025   | <br>12:27:12<br>09-Jul-2025   | <br>12:27:33<br>09-Jul-2025   |
| 33 | 09-07-2025 | CARPARK P1-P2     | POLISHING        | LANDING ESCALATOR   | <br>12:03:23<br>09-Jul-2025  | <br>12:03:42<br>09-Jul-2025  | <br>12:04:30<br>09-Jul-2025  |
| 34 | 09-07-2025 | CARPARK P1-P2     | BRUSHING         | DINDING PLANTER BOX | <br>20:19:21<br>09-Jul-2025 | <br>20:19:38<br>09-Jul-2025 | <br>20:19:59<br>09-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 10-07-2025 | LANTAI 3 | POLISHING      | CLOSET           | <br>18:14:19<br>10-Jul-2025   | <br>18:14:36<br>10-Jul-2025   | <br>18:14:52<br>10-Jul-2025   |
| 2  | 10-07-2025 | LANTAI 3 | BRUSHING       | LANTAI CONCRETE  | <br>11:14:30<br>10-Jul-2025   | <br>11:15:09<br>10-Jul-2025   | <br>11:15:42<br>10-Jul-2025   |
| 3  | 10-07-2025 | LANTAI 3 | POLISHING      | MEJA             | <br>11:18:04<br>10-Jul-2025  | <br>11:18:37<br>10-Jul-2025  | <br>11:18:52<br>10-Jul-2025  |
| 4  | 10-07-2025 | LANTAI 3 | POLISHING      | WASTAFEL         | <br>18:26:35<br>10-Jul-2025 | <br>18:27:00<br>10-Jul-2025 | <br>18:27:19<br>10-Jul-2025 |
| 5  | 10-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA       | <br>18:42:59<br>10-Jul-2025 | <br>18:44:28<br>10-Jul-2025 | <br>18:43:48<br>10-Jul-2025 |
| 6  | 10-07-2025 | LANTAI 2 | POLISHING      | KUBIKAL          | <br>11:12:19<br>10-Jul-2025 | <br>11:12:47<br>10-Jul-2025 | <br>11:13:06<br>10-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 10-07-2025 | LANTAI 2 | BRUSHING       | GUTTER                  | <br>18:27:53<br>10-Jul-2025   | <br>18:28:12<br>10-Jul-2025   | <br>18:28:36<br>10-Jul-2025   |
| 8  | 10-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>18:24:29<br>10-Jul-2025   | <br>18:24:49<br>10-Jul-2025   | <br>18:25:11<br>10-Jul-2025   |
| 9  | 10-07-2025 | LANTAI 1 | SPOTTING       | KURSI                   | <br>18:37:03<br>10-Jul-2025  | <br>18:36:57<br>10-Jul-2025  | <br>18:37:19<br>10-Jul-2025  |
| 10 | 10-07-2025 | LANTAI 1 | SPOTTING       | LIST SKIRTING           | <br>11:16:58<br>10-Jul-2025 | <br>11:17:09<br>10-Jul-2025 | <br>11:17:34<br>10-Jul-2025 |
| 11 | 10-07-2025 | LANTAI 1 | POLISHING      | FLOOR DRAIN             | <br>18:29:10<br>10-Jul-2025 | <br>18:29:26<br>10-Jul-2025 | <br>18:29:45<br>10-Jul-2025 |
| 12 | 10-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR       | <br>18:17:02<br>10-Jul-2025 | <br>18:17:27<br>10-Jul-2025 | <br>18:17:43<br>10-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 10-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT                 | <br>18:38:09<br>10-Jul-2025   | <br>18:38:41<br>10-Jul-2025   | <br>18:39:08<br>10-Jul-2025   |
| 14 | 10-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         | <br>18:12:53<br>10-Jul-2025   | <br>18:13:14<br>10-Jul-2025   | <br>18:13:34<br>10-Jul-2025   |
| 15 | 10-07-2025 | BASEMENT | WALL CLEANING  | PILAR BETON                 | <br>18:18:32<br>10-Jul-2025  | <br>18:18:49<br>10-Jul-2025  | <br>18:19:15<br>10-Jul-2025  |
| 16 | 10-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR           | <br>17:58:03<br>10-Jul-2025 | <br>17:58:23<br>10-Jul-2025 | <br>17:58:43<br>10-Jul-2025 |
| 17 | 10-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  | <br>18:20:49<br>10-Jul-2025 | <br>18:21:06<br>10-Jul-2025 | <br>18:21:31<br>10-Jul-2025 |
| 18 | 10-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT | <br>11:21:11<br>10-Jul-2025 | <br>11:21:52<br>10-Jul-2025 | <br>11:22:07<br>10-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 10-07-2025 | BASEMENT | POLISHING      | STAINLESS BULAT  | <br>11:23:45<br>10-Jul-2025   | <br>11:24:03<br>10-Jul-2025   | <br>11:24:16<br>10-Jul-2025   |
| 20 | 10-07-2025 | EXTERNAL | POLISHING      | SIGN RAMBU JALAN | <br>11:25:25<br>10-Jul-2025   | <br>11:25:37<br>10-Jul-2025   | <br>11:25:49<br>10-Jul-2025   |
| 21 | 10-07-2025 | EXTERNAL | BRUSHING       | LOGO JKTP0       | <br>18:23:29<br>10-Jul-2025  | <br>18:23:52<br>10-Jul-2025  | <br>18:23:13<br>10-Jul-2025  |
| 22 | 10-07-2025 | EXTERNAL | POLISHING      | DINDING CAT      | <br>18:47:24<br>10-Jul-2025 | <br>18:47:40<br>10-Jul-2025 | <br>18:48:25<br>10-Jul-2025 |
| 23 | 10-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM        | <br>19:56:13<br>10-Jul-2025 | <br>19:56:53<br>10-Jul-2025 | <br>19:58:20<br>10-Jul-2025 |
| 24 | 10-07-2025 | EXTERNAL | POLISHING      | ALCUBON          | <br>18:31:27<br>10-Jul-2025 | <br>18:32:05<br>10-Jul-2025 | <br>18:32:22<br>10-Jul-2025 |




| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan      | Before | Progress | After |
|----|------------|-------------------|------------------|-----------------------|--------|----------|-------|
| 25 | 10-07-2025 | EXTERNAL          | BRUSHING         | TEMPAT SAMPAH         |        |          |       |
| 26 | 10-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU          |        |          |       |
| 27 | 10-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET                |        |          |       |
| 28 | 10-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING               |        |          |       |
| 29 | 10-07-2025 | CARPARK P1-P2     | POLISHING        | PINTU DAN DOOR CLOSER |        |          |       |
| 30 | 10-07-2025 | CARPARK P1-P2     | POLISHING        | STAINLESS BULAT       |        |          |       |



| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan  | Before                                                                                                                | Progress                                                                                                               | After                                                                                                                   |
|----|------------|---------------|----------------|-------------------|-----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| 31 | 10-07-2025 | CARPARK P1-P2 | POLISHING      | LANDING ESCALATOR |  <div>18:02:09<br/>10-Jul-2025</div> |  <div>18:01:42<br/>10-Jul-2025</div> |  <div>18:02:51<br/>10-Jul-2025</div> |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 11-07-2025 | LANTAI 3 | BRUSHING       | LANTAI GRANIT BAKAR | <br>18:49:32<br>11-Jul-2025   | <br>18:49:50<br>11-Jul-2025   | <br>18:50:16<br>11-Jul-2025   |
| 2  | 11-07-2025 | LANTAI 3 | WALL CLEANING  | HAND RAILING        | <br>13:52:24<br>11-Jul-2025   | <br>13:53:17<br>11-Jul-2025   | <br>13:53:53<br>11-Jul-2025   |
| 3  | 11-07-2025 | LANTAI 3 | POLISHING      | KURSI               | <br>14:22:49<br>11-Jul-2025  | <br>14:24:01<br>11-Jul-2025  | <br>14:24:48<br>11-Jul-2025  |
| 4  | 11-07-2025 | LANTAI 3 | SPOTTING       | SOFA                | <br>13:31:14<br>11-Jul-2025 | <br>13:31:29<br>11-Jul-2025 | <br>13:31:50<br>11-Jul-2025 |
| 5  | 11-07-2025 | LANTAI 2 | GLASS CLEANING | TEMPAT SAMPAH       | <br>18:55:53<br>11-Jul-2025 | <br>18:56:09<br>11-Jul-2025 | <br>18:56:25<br>11-Jul-2025 |
| 6  | 11-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN         | <br>19:09:02<br>11-Jul-2025 | <br>19:09:20<br>11-Jul-2025 | <br>19:09:40<br>11-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 11-07-2025 | LANTAI 2 | WALL CLEANING  | PLANTER BOX      | <br>19:15:39<br>11-Jul-2025   | <br>19:15:55<br>11-Jul-2025   | <br>19:16:13<br>11-Jul-2025   |
| 8  | 11-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH    | <br>18:57:37<br>11-Jul-2025   | <br>18:57:52<br>11-Jul-2025   | <br>18:58:08<br>11-Jul-2025   |
| 9  | 11-07-2025 | LANTAI 1 | BRUSHING       | LANTAI CONCRETE  | <br>14:28:02<br>11-Jul-2025  | <br>14:28:19<br>11-Jul-2025  | <br>14:29:28<br>11-Jul-2025  |
| 10 | 11-07-2025 | LANTAI 1 | SPOTTING       | AC GRILL         | <br>19:00:21<br>11-Jul-2025 | <br>19:00:36<br>11-Jul-2025 | <br>19:00:52<br>11-Jul-2025 |
| 11 | 11-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH    | <br>13:29:19<br>11-Jul-2025 | <br>13:29:45<br>11-Jul-2025 | <br>13:30:07<br>11-Jul-2025 |
| 12 | 11-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK | <br>19:05:04<br>11-Jul-2025 | <br>19:05:18<br>11-Jul-2025 | <br>19:05:36<br>11-Jul-2025 |







| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 11-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR    | <br>18:53:27<br>11-Jul-2025   | <br>18:53:47<br>11-Jul-2025   | <br>18:54:08<br>11-Jul-2025   |
| 14 | 11-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK              | <br>18:51:13<br>11-Jul-2025   | <br>18:51:53<br>11-Jul-2025   | <br>18:52:17<br>11-Jul-2025   |
| 15 | 11-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  | <br>20:18:05<br>11-Jul-2025  | <br>20:18:35<br>11-Jul-2025  | <br>20:19:03<br>11-Jul-2025  |
| 16 | 11-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT | <br>20:20:53<br>11-Jul-2025 | <br>20:21:42<br>11-Jul-2025 | <br>20:22:15<br>11-Jul-2025 |
| 17 | 11-07-2025 | BASEMENT | POLISHING      | TUTUP SAMPIT                | <br>20:35:30<br>11-Jul-2025 | <br>20:35:56<br>11-Jul-2025 | <br>20:36:17<br>11-Jul-2025 |
| 18 | 11-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         | <br>13:13:46<br>11-Jul-2025 | <br>13:14:07<br>11-Jul-2025 | <br>13:15:16<br>11-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before | Progress | After |
|----|------------|----------|----------------|----------------------|--------|----------|-------|
| 19 | 11-07-2025 | BASEMENT | WASHING        | LANTAI EPOXY         |        |          |       |
| 20 | 11-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         |        |          |       |
| 21 | 11-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            |        |          |       |
| 22 | 11-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         |        |          |       |
| 23 | 11-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          |        |          |       |
| 24 | 11-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR |        |          |       |





| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan         | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|-------------------|------------------|--------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 25 | 11-07-2025 | EXTERNAL          | BRUSHING         | BATU ALAM                |    |    |    |
| 26 | 11-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING                  |    |    |    |
| 27 | 11-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU             |   |   |   |
| 28 | 11-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | COVER LAMP               |  |  |  |
| 29 | 11-07-2025 | CARPARK P1-P2     | HIGH DUSTING     | OUTDOOR AC               |  |  |  |
| 30 | 11-07-2025 | CARPARK P1-P2     | POLISHING        | BODY STAINLESS ESCALATOR |  |  |  |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 11-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         | <br>18:45:07<br>11-Jul-2025   | <br>18:45:24<br>11-Jul-2025   | <br>18:45:45<br>11-Jul-2025   |
| 32 | 11-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            | <br>20:40:09<br>11-Jul-2025   | <br>20:40:36<br>11-Jul-2025   | <br>20:41:10<br>11-Jul-2025   |
| 33 | 11-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         | <br>18:47:35<br>11-Jul-2025  | <br>18:47:51<br>11-Jul-2025  | <br>18:48:13<br>11-Jul-2025  |
| 34 | 11-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          | <br>20:27:38<br>11-Jul-2025 | <br>20:27:57<br>11-Jul-2025 | <br>20:28:14<br>11-Jul-2025 |
| 35 | 11-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR | <br>18:37:52<br>11-Jul-2025 | <br>18:38:08<br>11-Jul-2025 | <br>18:38:26<br>11-Jul-2025 |
| 36 | 11-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM            | <br>20:37:01<br>11-Jul-2025 | <br>20:37:38<br>11-Jul-2025 | <br>20:38:54<br>11-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 11-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         | <br>19:22:48<br>11-Jul-2025   | <br>19:23:03<br>11-Jul-2025   | <br>19:23:24<br>11-Jul-2025   |
| 38 | 11-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            | <br>20:26:15<br>11-Jul-2025   | <br>20:26:35<br>11-Jul-2025   | <br>20:27:09<br>11-Jul-2025   |
| 39 | 11-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         | <br>19:06:20<br>11-Jul-2025  | <br>19:06:34<br>11-Jul-2025  | <br>19:06:49<br>11-Jul-2025  |
| 40 | 11-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          | <br>20:23:59<br>11-Jul-2025 | <br>20:24:23<br>11-Jul-2025 | <br>20:24:52<br>11-Jul-2025 |
| 41 | 11-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR | <br>18:43:43<br>11-Jul-2025 | <br>18:43:58<br>11-Jul-2025 | <br>18:44:23<br>11-Jul-2025 |
| 42 | 11-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM            | <br>20:33:36<br>11-Jul-2025 | <br>20:34:02<br>11-Jul-2025 | <br>20:34:21<br>11-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 14-07-2025 | LANTAI 3 | POLISHING      | URINOIR                 | <br>11:17:43<br>14-Jul-2025   | <br>11:20:46<br>14-Jul-2025   | <br>11:20:58<br>14-Jul-2025   |
| 2  | 14-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH           | <br>19:57:42<br>14-Jul-2025   | <br>19:58:00<br>14-Jul-2025   | <br>19:58:25<br>14-Jul-2025   |
| 3  | 14-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>11:25:25<br>14-Jul-2025  | <br>11:25:49<br>14-Jul-2025  | <br>11:26:25<br>14-Jul-2025  |
| 4  | 14-07-2025 | LANTAI 3 | POLISHING      | TRAY                    | <br>11:27:26<br>14-Jul-2025 | <br>11:27:55<br>14-Jul-2025 | <br>11:28:20<br>14-Jul-2025 |
| 5  | 14-07-2025 | LANTAI 3 | POLISHING      | CLOSET                  | <br>19:59:16<br>14-Jul-2025 | <br>19:59:35<br>14-Jul-2025 | <br>19:59:56<br>14-Jul-2025 |
| 6  | 14-07-2025 | LANTAI 2 | SPOTTING       | SOFA                    | <br>11:29:50<br>14-Jul-2025 | <br>11:30:02<br>14-Jul-2025 | <br>11:30:14<br>14-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 14-07-2025 | LANTAI 2 | WALL CLEANING  | PINTU LIFT          | <br>20:16:18<br>14-Jul-2025   | <br>20:16:37<br>14-Jul-2025   | <br>20:16:59<br>14-Jul-2025   |
| 8  | 14-07-2025 | LANTAI 2 | BRUSHING       | LANTAI GRANIT BAKAR | <br>20:30:02<br>14-Jul-2025   | <br>20:30:19<br>14-Jul-2025   | <br>20:30:43<br>14-Jul-2025   |
| 9  | 14-07-2025 | LANTAI 2 | POLISHING      | CLOSET              | <br>11:21:25<br>14-Jul-2025  | <br>11:21:41<br>14-Jul-2025  | <br>11:21:58<br>14-Jul-2025  |
| 10 | 14-07-2025 | LANTAI 1 | HIGH DUSTING   | NEON LED            | <br>11:31:01<br>14-Jul-2025 | <br>11:31:29<br>14-Jul-2025 | <br>11:31:41<br>14-Jul-2025 |
| 11 | 14-07-2025 | LANTAI 1 | BRUSHING       | LANTAI KERAMIK      | <br>20:31:28<br>14-Jul-2025 | <br>20:31:56<br>14-Jul-2025 | <br>20:32:31<br>14-Jul-2025 |
| 12 | 14-07-2025 | LANTAI 1 | POLISHING      | KUBIKAL             | <br>11:22:48<br>14-Jul-2025 | <br>11:23:14<br>14-Jul-2025 | <br>11:23:48<br>14-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan  | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 14-07-2025 | LANTAI 1 | GLASS CLEANING  | KACA              | <br>21:18:59<br>14-Jul-2025   | <br>21:19:22<br>14-Jul-2025   | <br>21:19:50<br>14-Jul-2025   |
| 14 | 14-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>21:07:39<br>14-Jul-2025   | <br>21:07:53<br>14-Jul-2025   | <br>21:08:18<br>14-Jul-2025   |
| 15 | 14-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>21:03:03<br>14-Jul-2025  | <br>21:03:26<br>14-Jul-2025  | <br>21:03:47<br>14-Jul-2025  |
| 16 | 14-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING     | <br>21:14:47<br>14-Jul-2025 | <br>21:15:13<br>14-Jul-2025 | <br>21:15:58<br>14-Jul-2025 |
| 17 | 14-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP NAIK  | <br>21:09:02<br>14-Jul-2025 | <br>21:09:38<br>14-Jul-2025 | <br>21:10:01<br>14-Jul-2025 |
| 18 | 14-07-2025 | BASEMENT | POLISHING       | STAINLESS BULAT   | <br>20:12:05<br>14-Jul-2025 | <br>20:12:25<br>14-Jul-2025 | <br>20:12:54<br>14-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 14-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK     | <br>21:10:25<br>14-Jul-2025   | <br>21:12:11<br>14-Jul-2025   | <br>21:12:40<br>14-Jul-2025   |
| 20 | 14-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN              | <br>21:31:27<br>14-Jul-2025   | <br>21:31:43<br>14-Jul-2025   | <br>21:32:40<br>14-Jul-2025   |
| 21 | 14-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT          | <br>20:06:57<br>14-Jul-2025  | <br>20:07:15<br>14-Jul-2025  | <br>20:07:33<br>14-Jul-2025  |
| 22 | 14-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK       | <br>11:43:11<br>14-Jul-2025 | <br>11:43:32<br>14-Jul-2025 | <br>11:43:47<br>14-Jul-2025 |
| 23 | 14-07-2025 | EXTERNAL | POLISHING      | PIPA HYDRANT         | <br>11:41:12<br>14-Jul-2025 | <br>11:41:28<br>14-Jul-2025 | <br>11:41:40<br>14-Jul-2025 |
| 24 | 14-07-2025 | EXTERNAL | BRUSHING       | BOX HYDRANT DAN APAR | <br>20:05:08<br>14-Jul-2025 | <br>20:05:30<br>14-Jul-2025 | <br>20:05:54<br>14-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 14-07-2025 | EXTERNAL | WALL CLEANING  | PIPA HYDRANT     | <br>20:02:25<br>14-Jul-2025   | <br>20:02:42<br>14-Jul-2025   | <br>20:03:04<br>14-Jul-2025   |
| 26 | 14-07-2025 | EXTERNAL | BRUSHING       | ALCUBON          | <br>20:14:11<br>14-Jul-2025   | <br>20:15:15<br>14-Jul-2025   | <br>20:14:35<br>14-Jul-2025   |
| 27 | 14-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER  | <br>20:18:34<br>14-Jul-2025  | <br>20:19:07<br>14-Jul-2025  | <br>20:19:26<br>14-Jul-2025  |
| 28 | 14-07-2025 | EXTERNAL | WALL CLEANING  | GUTTER           | <br>19:47:03<br>14-Jul-2025 | <br>19:47:20<br>14-Jul-2025 | <br>19:47:35<br>14-Jul-2025 |
| 29 | 14-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER  | <br>20:41:20<br>14-Jul-2025 | <br>20:41:56<br>14-Jul-2025 | <br>20:42:16<br>14-Jul-2025 |
| 30 | 14-07-2025 | EXTERNAL | BRUSHING       | DINDING BETON    | <br>19:39:30<br>14-Jul-2025 | <br>19:39:45<br>14-Jul-2025 | <br>19:40:03<br>14-Jul-2025 |




| No | Tanggal    | Area              | Item Pekerjaan  | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|-----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 14-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING                  | <br>11:39:29<br>14-Jul-2025   | <br>11:39:47<br>14-Jul-2025   | <br>11:40:03<br>14-Jul-2025   |
| 32 | 14-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | COVER LAMP               | <br>21:26:07<br>14-Jul-2025   | <br>21:26:29<br>14-Jul-2025   | <br>21:26:58<br>14-Jul-2025   |
| 33 | 14-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING  | KACA                     | <br>19:41:07<br>14-Jul-2025  | <br>19:41:23<br>14-Jul-2025  | <br>19:41:47<br>14-Jul-2025  |
| 34 | 14-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | PIPA PLUMBING            | <br>11:38:33<br>14-Jul-2025 | <br>11:38:52<br>14-Jul-2025 | <br>11:39:02<br>14-Jul-2025 |
| 35 | 14-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING                  | <br>11:37:46<br>14-Jul-2025 | <br>11:37:58<br>14-Jul-2025 | <br>11:38:13<br>14-Jul-2025 |
| 36 | 14-07-2025 | CARPARK P1-P2     | POLISHING       | BODY STAINLESS ESCALATOR | <br>11:45:19<br>14-Jul-2025 | <br>11:45:21<br>14-Jul-2025 | <br>11:45:42<br>14-Jul-2025 |



| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|---------------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 37 | 14-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI CONCRETE      |    |    |    |
| 38 | 14-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI KERAMIK       |    |    |    |
| 39 | 14-07-2025 | CARPARK P1-P2 | GLASS CLEANING | SAFETY MIRROR        |   |   |   |
| 40 | 14-07-2025 | EXTERNAL      | POLISHING      | PIPA HYDRANT         |  |  |  |
| 41 | 14-07-2025 | EXTERNAL      | BRUSHING       | BOX HYDRANT DAN APAR |  |  |  |
| 42 | 14-07-2025 | EXTERNAL      | WALL CLEANING  | PIPA HYDRANT         |  |  |  |








| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 43 | 14-07-2025 | EXTERNAL | BRUSHING         | ALCUBON          | <br>20:44:16<br>14-Jul-2025   | <br>20:44:34<br>14-Jul-2025   | <br>20:44:59<br>14-Jul-2025   |
| 44 | 14-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER  | <br>19:37:03<br>14-Jul-2025   | <br>19:37:49<br>14-Jul-2025   | <br>19:38:08<br>14-Jul-2025   |
| 45 | 14-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>19:34:47<br>14-Jul-2025  | <br>19:35:03<br>14-Jul-2025  | <br>19:35:29<br>14-Jul-2025  |
| 46 | 14-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER  | <br>21:22:23<br>14-Jul-2025 | <br>21:22:41<br>14-Jul-2025 | <br>21:23:01<br>14-Jul-2025 |
| 47 | 14-07-2025 | EXTERNAL | BRUSHING         | DINDING BETON    | <br>19:55:26<br>14-Jul-2025 | <br>19:55:58<br>14-Jul-2025 | <br>19:56:19<br>14-Jul-2025 |
| 48 | 14-07-2025 | EXTERNAL | POLISHING        | PIPA HYDRANT     | <br>11:34:04<br>14-Jul-2025 | <br>11:34:37<br>14-Jul-2025 | <br>11:34:56<br>14-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|------------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 49 | 14-07-2025 | EXTERNAL | BRUSHING         | BOX HYDRANT DAN APAR |    |    |    |
| 50 | 14-07-2025 | EXTERNAL | WALL CLEANING    | PIPA HYDRANT         |    |    |    |
| 51 | 14-07-2025 | EXTERNAL | BRUSHING         | ALCUBON              |   |   |   |
| 52 | 14-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER      |  |  |  |
| 53 | 14-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER               |  |  |  |
| 54 | 14-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER      |  |  |  |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                            | Progress                                                                           | After                                                                               |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 55 | 14-07-2025 | EXTERNAL | BRUSHING       | DINDING BETON    |  |  |  |

| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 15-07-2025 | LANTAI 3 | POLISHING        | FLOOR DRAIN      | <br>11:14:14<br>15-Jul-2025   | <br>11:16:39<br>15-Jul-2025   | <br>11:17:22<br>15-Jul-2025   |
| 2  | 15-07-2025 | LANTAI 3 | WALL CLEANING    | DINDING ACP      | <br>11:35:13<br>15-Jul-2025   | <br>11:35:33<br>15-Jul-2025   | <br>11:35:49<br>15-Jul-2025   |
| 3  | 15-07-2025 | LANTAI 3 | GLASS CLEANING   | KACA RAILING     | <br>14:12:58<br>15-Jul-2025  | <br>14:13:14<br>15-Jul-2025  | <br>14:13:32<br>15-Jul-2025  |
| 4  | 15-07-2025 | LANTAI 3 | GENERAL CLEANING | DISWASHING       | <br>18:52:47<br>15-Jul-2025 | <br>18:53:09<br>15-Jul-2025 | <br>18:53:32<br>15-Jul-2025 |
| 5  | 15-07-2025 | LANTAI 2 | POLISHING        | TEMPAT SAMPAH    | <br>11:21:07<br>15-Jul-2025 | <br>11:21:36<br>15-Jul-2025 | <br>11:21:48<br>15-Jul-2025 |
| 6  | 15-07-2025 | LANTAI 2 | BRUSHING         | LANTAI CONCRETE  | <br>11:48:15<br>15-Jul-2025 | <br>11:48:32<br>15-Jul-2025 | <br>11:49:06<br>15-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 15-07-2025 | LANTAI 2 | POLISHING      | RAK ACCESORIS           | <br>19:40:51<br>15-Jul-2025   | <br>19:41:10<br>15-Jul-2025   | <br>19:41:27<br>15-Jul-2025   |
| 8  | 15-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA              | <br>11:36:44<br>15-Jul-2025   | <br>11:36:55<br>15-Jul-2025   | <br>11:37:11<br>15-Jul-2025   |
| 9  | 15-07-2025 | LANTAI 2 | POLISHING      | CLOSET                  | <br>19:20:02<br>15-Jul-2025  | <br>19:20:16<br>15-Jul-2025  | <br>19:20:30<br>15-Jul-2025  |
| 10 | 15-07-2025 | LANTAI 1 | POLISHING      | PINTU LIFT              | <br>19:21:28<br>15-Jul-2025 | <br>19:21:43<br>15-Jul-2025 | <br>19:22:05<br>15-Jul-2025 |
| 11 | 15-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>11:18:40<br>15-Jul-2025 | <br>11:18:40<br>15-Jul-2025 | <br>11:19:10<br>15-Jul-2025 |
| 12 | 15-07-2025 | LANTAI 1 | POLISHING      | WASTAFEL                | <br>19:03:04<br>15-Jul-2025 | <br>19:03:18<br>15-Jul-2025 | <br>19:03:32<br>15-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan  | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|-------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 15-07-2025 | LANTAI 1 | POLISHING      | PINTU EXIT        |    |    |    |
| 14 | 15-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |    |    |    |
| 15 | 15-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |   |   |   |
| 16 | 15-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR |  |  |  |
| 17 | 15-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG      |  |  |  |
| 18 | 15-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP TURUN |  |  |  |








| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 15-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>18:56:43<br>15-Jul-2025   | <br>18:57:04<br>15-Jul-2025   | <br>18:57:26<br>15-Jul-2025   |
| 20 | 15-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>20:59:11<br>15-Jul-2025   | <br>21:01:40<br>15-Jul-2025   | <br>21:02:16<br>15-Jul-2025   |
| 21 | 15-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>11:23:14<br>15-Jul-2025  | <br>11:23:27<br>15-Jul-2025  | <br>11:23:47<br>15-Jul-2025  |
| 22 | 15-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR | <br>18:54:43<br>15-Jul-2025 | <br>18:55:22<br>15-Jul-2025 | <br>18:55:42<br>15-Jul-2025 |
| 23 | 15-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>11:34:06<br>15-Jul-2025 | <br>11:34:16<br>15-Jul-2025 | <br>11:34:30<br>15-Jul-2025 |
| 24 | 15-07-2025 | EXTERNAL | POLISHING      | DINDING CAT              | <br>11:26:53<br>15-Jul-2025 | <br>11:27:06<br>15-Jul-2025 | <br>11:27:16<br>15-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 25 | 15-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       |    |    |    |
| 26 | 15-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        |    |    |    |
| 27 | 15-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     |   |   |   |
| 28 | 15-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR |  |  |  |
| 29 | 15-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        |  |  |  |
| 30 | 15-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       |  |  |  |






| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 15-07-2025 | EXTERNAL          | BRUSHING         | ALCUBON          | <br>11:31:48<br>15-Jul-2025   | <br>11:31:59<br>15-Jul-2025   | <br>11:32:11<br>15-Jul-2025   |
| 32 | 15-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI           | <br>18:31:05<br>15-Jul-2025   | <br>18:31:45<br>15-Jul-2025   | <br>18:32:39<br>15-Jul-2025   |
| 33 | 15-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | PIPA PLUMBING    | <br>11:24:52<br>15-Jul-2025  | <br>11:25:01<br>15-Jul-2025  | <br>11:25:12<br>15-Jul-2025  |
| 34 | 15-07-2025 | MANAGEMENT OFFICE | WALL CLEANING    | DINDING          | <br>11:25:51<br>15-Jul-2025 | <br>11:26:04<br>15-Jul-2025 | <br>11:26:16<br>15-Jul-2025 |
| 35 | 15-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING   | KACA             | <br>18:34:00<br>15-Jul-2025 | <br>18:34:24<br>15-Jul-2025 | <br>18:34:55<br>15-Jul-2025 |
| 36 | 15-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>18:38:47<br>15-Jul-2025 | <br>18:39:09<br>15-Jul-2025 | <br>18:39:33<br>15-Jul-2025 |

| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|---------------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 15-07-2025 | CARPARK P1-P2 | POLISHING      | RAILING             | <br>18:40:36<br>15-Jul-2025   | <br>18:41:02<br>15-Jul-2025   | <br>18:41:39<br>15-Jul-2025   |
| 38 | 15-07-2025 | CARPARK P1-P2 | POLISHING      | BOX HYDRANT         | <br>11:28:35<br>15-Jul-2025   | <br>11:29:43<br>15-Jul-2025   | <br>11:29:54<br>15-Jul-2025   |
| 39 | 15-07-2025 | CARPARK P1-P2 | POLISHING      | TUTUP SAMPIT        | <br>18:49:09<br>15-Jul-2025  | <br>18:49:30<br>15-Jul-2025  | <br>18:49:53<br>15-Jul-2025  |
| 40 | 15-07-2025 | CARPARK P1-P2 | BRUSHING       | DINDING PLANTER BOX | <br>18:50:46<br>15-Jul-2025 | <br>18:51:11<br>15-Jul-2025 | <br>18:51:31<br>15-Jul-2025 |
| 41 | 15-07-2025 | EXTERNAL      | POLISHING      | DINDING CAT         | <br>11:45:23<br>15-Jul-2025 | <br>11:45:45<br>15-Jul-2025 | <br>11:45:56<br>15-Jul-2025 |
| 42 | 15-07-2025 | EXTERNAL      | BRUSHING       | LANTAI ANDESIT      | <br>18:47:56<br>15-Jul-2025 | <br>18:48:16<br>15-Jul-2025 | <br>18:48:35<br>15-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 43 | 15-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        |    |    |    |
| 44 | 15-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     |    |    |    |
| 45 | 15-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR |   |   |   |
| 46 | 15-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        |  |  |  |
| 47 | 15-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       |  |  |  |
| 48 | 15-07-2025 | EXTERNAL | BRUSHING       | ALCUBON              |  |  |  |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 49 | 15-07-2025 | EXTERNAL | POLISHING      | DINDING CAT          | <br>11:39:58<br>15-Jul-2025   | <br>11:40:20<br>15-Jul-2025   | <br>11:40:34<br>15-Jul-2025   |
| 50 | 15-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       | <br>19:00:16<br>15-Jul-2025   | <br>19:00:33<br>15-Jul-2025   | <br>19:00:50<br>15-Jul-2025   |
| 51 | 15-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        | <br>19:31:24<br>15-Jul-2025  | <br>19:31:42<br>15-Jul-2025  | <br>19:32:02<br>15-Jul-2025  |
| 52 | 15-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     | <br>20:40:27<br>15-Jul-2025 | <br>20:40:52<br>15-Jul-2025 | <br>20:42:14<br>15-Jul-2025 |
| 53 | 15-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR | <br>18:46:11<br>15-Jul-2025 | <br>18:46:35<br>15-Jul-2025 | <br>18:46:56<br>15-Jul-2025 |
| 54 | 15-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        | <br>19:15:38<br>15-Jul-2025 | <br>19:16:44<br>15-Jul-2025 | <br>19:17:08<br>15-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                       | Progress                                                                                                      | After                                                                                                          |
|----|------------|----------|----------------|------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|
| 55 | 15-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT   | <br>18:59:03<br>15-Jul-2025 | <br>18:59:23<br>15-Jul-2025 | <br>18:59:43<br>15-Jul-2025 |
| 56 | 15-07-2025 | EXTERNAL | BRUSHING       | ALCUBON          | <br>14:05:41<br>15-Jul-2025 | <br>14:06:07<br>15-Jul-2025 | <br>14:06:26<br>15-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 1  | 16-07-2025 | LANTAI 3 | POLISHING      | KUBIKAL          |    |    |    |
| 2  | 16-07-2025 | LANTAI 3 | WALL CLEANING  | PLANTER BOX      |    |    |    |
| 3  | 16-07-2025 | LANTAI 3 | WALL CLEANING  | PINTU LIFT       |   |   |   |
| 4  | 16-07-2025 | LANTAI 3 | GLASS CLEANING | MIRROR           |  |  |  |
| 5  | 16-07-2025 | LANTAI 2 | POLISHING      | CLOSET           |  |  |  |
| 6  | 16-07-2025 | LANTAI 2 | SPOTTING       | SOFA             |  |  |  |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 16-07-2025 | LANTAI 2 | SPOTTING       | FLOOR DRAIN      | <br>16:55:38<br>16-Jul-2025   | <br>16:56:04<br>16-Jul-2025   | <br>16:56:32<br>16-Jul-2025   |
| 8  | 16-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN      | <br>15:37:03<br>16-Jul-2025   | <br>15:37:10<br>16-Jul-2025   | <br>15:37:24<br>16-Jul-2025   |
| 9  | 16-07-2025 | LANTAI 1 | WALL CLEANING  | DINDING LIFT     | <br>15:31:03<br>16-Jul-2025  | <br>15:31:21<br>16-Jul-2025  | <br>15:33:35<br>16-Jul-2025  |
| 10 | 16-07-2025 | LANTAI 1 | HIGH DUSTING   | KIPAS            | <br>21:31:44<br>16-Jul-2025 | <br>21:32:07<br>16-Jul-2025 | <br>21:32:32<br>16-Jul-2025 |
| 11 | 16-07-2025 | LANTAI 1 | POLISHING      | CLOSET           | <br>15:34:04<br>16-Jul-2025 | <br>15:35:04<br>16-Jul-2025 | <br>15:35:18<br>16-Jul-2025 |
| 12 | 16-07-2025 | LANTAI 1 | SWEEPING       | TANGGA           | <br>16:51:10<br>16-Jul-2025 | <br>16:53:37<br>16-Jul-2025 | <br>16:54:03<br>16-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 16-07-2025 | BASEMENT | POLISHING       | BODY STAINLESS ESCALATOR    | <br>20:35:30<br>16-Jul-2025   | <br>20:35:50<br>16-Jul-2025   | <br>20:36:11<br>16-Jul-2025   |
| 14 | 16-07-2025 | BASEMENT | PLAFON CLEANING | CEILING                     | <br>21:19:03<br>16-Jul-2025   | <br>21:19:21<br>16-Jul-2025   | <br>21:19:43<br>16-Jul-2025   |
| 15 | 16-07-2025 | BASEMENT | WALL CLEANING   | DINDING CAT PARKIR BASEMENT | <br>21:01:52<br>16-Jul-2025  | <br>21:02:15<br>16-Jul-2025  | <br>21:02:45<br>16-Jul-2025  |
| 16 | 16-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR               | <br>20:34:08<br>16-Jul-2025 | <br>20:34:28<br>16-Jul-2025 | <br>20:34:53<br>16-Jul-2025 |
| 17 | 16-07-2025 | BASEMENT | WASHING         | LANTAI EPOXY                | <br>21:15:20<br>16-Jul-2025 | <br>21:15:45<br>16-Jul-2025 | <br>21:16:14<br>16-Jul-2025 |
| 18 | 16-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING               | <br>20:46:31<br>16-Jul-2025 | <br>20:47:01<br>16-Jul-2025 | <br>20:47:24<br>16-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 16-07-2025 | BASEMENT | WALL CLEANING   | PILAR BETON      | <br>20:48:15<br>16-Jul-2025   | <br>20:48:54<br>16-Jul-2025   | <br>20:49:15<br>16-Jul-2025   |
| 20 | 16-07-2025 | BASEMENT | PLAFON CLEANING | CEILING          | <br>15:39:11<br>16-Jul-2025   | <br>15:39:25<br>16-Jul-2025   | <br>15:39:35<br>16-Jul-2025   |
| 21 | 16-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING    | <br>20:57:30<br>16-Jul-2025  | <br>20:58:07<br>16-Jul-2025  | <br>20:58:32<br>16-Jul-2025  |
| 22 | 16-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR    | <br>15:39:13<br>16-Jul-2025 | <br>15:39:46<br>16-Jul-2025 | <br>15:40:13<br>16-Jul-2025 |
| 23 | 16-07-2025 | EXTERNAL | BRUSHING        | GUTTER           | <br>14:35:41<br>16-Jul-2025 | <br>14:36:03<br>16-Jul-2025 | <br>15:22:55<br>16-Jul-2025 |
| 24 | 16-07-2025 | EXTERNAL | WALL CLEANING   | TEMPAT SAMPAH    | <br>16:57:47<br>16-Jul-2025 | <br>16:58:08<br>16-Jul-2025 | <br>16:58:31<br>16-Jul-2025 |



| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 16-07-2025 | EXTERNAL          | WALL CLEANING    | GUTTER           | <br>21:04:06<br>16-Jul-2025   | <br>21:04:30<br>16-Jul-2025   | <br>21:04:47<br>16-Jul-2025   |
| 26 | 16-07-2025 | EXTERNAL          | POLISHING        | LANTAI ANDESIT   | <br>20:19:48<br>16-Jul-2025   | <br>20:20:09<br>16-Jul-2025   | <br>20:20:45<br>16-Jul-2025   |
| 27 | 16-07-2025 | EXTERNAL          | BRUSHING         | PIPA HYDRANT     | <br>16:48:28<br>16-Jul-2025  | <br>16:48:52<br>16-Jul-2025  | <br>16:49:11<br>16-Jul-2025  |
| 28 | 16-07-2025 | EXTERNAL          | HIGH DUSTING     | SIGN RAMBU JALAN | <br>20:59:15<br>16-Jul-2025 | <br>20:59:32<br>16-Jul-2025 | <br>20:59:48<br>16-Jul-2025 |
| 29 | 16-07-2025 | EXTERNAL          | BRUSHING         | LOGO JKTP0       | <br>15:17:49<br>16-Jul-2025 | <br>15:18:12<br>16-Jul-2025 | <br>15:18:29<br>16-Jul-2025 |
| 30 | 16-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>14:39:20<br>16-Jul-2025 | <br>14:40:39<br>16-Jul-2025 | <br>14:41:04<br>16-Jul-2025 |





| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 16-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI              | <br>20:32:42<br>16-Jul-2025   | <br>20:33:06<br>16-Jul-2025   | <br>20:33:28<br>16-Jul-2025   |
| 32 | 16-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU        | <br>14:41:37<br>16-Jul-2025   | <br>14:42:08<br>16-Jul-2025   | <br>14:42:50<br>16-Jul-2025   |
| 33 | 16-07-2025 | CARPARK P1-P2     | POLISHING        | LANDING ESCALATOR   | <br>15:04:50<br>16-Jul-2025  | <br>15:03:49<br>16-Jul-2025  | <br>15:04:32<br>16-Jul-2025  |
| 34 | 16-07-2025 | CARPARK P1-P2     | BRUSHING         | DINDING PLANTER BOX | <br>20:31:16<br>16-Jul-2025 | <br>20:31:36<br>16-Jul-2025 | <br>20:31:57<br>16-Jul-2025 |
| 35 | 16-07-2025 | EXTERNAL          | GENERAL CLEANING | GUTTER              | <br>14:43:45<br>16-Jul-2025 | <br>14:44:04<br>16-Jul-2025 | <br>14:44:27<br>16-Jul-2025 |
| 36 | 16-07-2025 | EXTERNAL          | WALL CLEANING    | TEMPAT SAMPAH       | <br>16:46:32<br>16-Jul-2025 | <br>16:47:08<br>16-Jul-2025 | <br>16:47:38<br>16-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 16-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>20:50:29<br>16-Jul-2025   | <br>20:50:55<br>16-Jul-2025   | <br>20:51:22<br>16-Jul-2025   |
| 38 | 16-07-2025 | EXTERNAL | POLISHING        | LANTAI ANDESIT   | <br>20:26:51<br>16-Jul-2025   | <br>20:27:13<br>16-Jul-2025   | <br>20:27:51<br>16-Jul-2025   |
| 39 | 16-07-2025 | EXTERNAL | BRUSHING         | PIPA HYDRANT     | <br>16:44:53<br>16-Jul-2025  | <br>16:45:21<br>16-Jul-2025  | <br>16:45:48<br>16-Jul-2025  |
| 40 | 16-07-2025 | EXTERNAL | HIGH DUSTING     | SIGN RAMBU JALAN | <br>20:52:15<br>16-Jul-2025 | <br>20:52:51<br>16-Jul-2025 | <br>20:53:12<br>16-Jul-2025 |
| 41 | 16-07-2025 | EXTERNAL | BRUSHING         | LOGO JKTP        | <br>15:21:10<br>16-Jul-2025 | <br>15:21:26<br>16-Jul-2025 | <br>15:21:45<br>16-Jul-2025 |
| 42 | 16-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>15:19:19<br>16-Jul-2025 | <br>15:19:50<br>16-Jul-2025 | <br>15:20:11<br>16-Jul-2025 |







| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 43 | 16-07-2025 | EXTERNAL | WALL CLEANING    | TEMPAT SAMPAH    | <br>20:24:58<br>16-Jul-2025   | <br>20:25:39<br>16-Jul-2025   | <br>20:26:09<br>16-Jul-2025   |
| 44 | 16-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>21:09:14<br>16-Jul-2025   | <br>21:09:37<br>16-Jul-2025   | <br>21:10:00<br>16-Jul-2025   |
| 45 | 16-07-2025 | EXTERNAL | POLISHING        | LANTAI ANDESIT   | <br>20:23:16<br>16-Jul-2025  | <br>20:23:42<br>16-Jul-2025  | <br>20:24:07<br>16-Jul-2025  |
| 46 | 16-07-2025 | EXTERNAL | BRUSHING         | PIPA HYDRANT     | <br>20:21:35<br>16-Jul-2025 | <br>20:21:58<br>16-Jul-2025 | <br>20:22:29<br>16-Jul-2025 |
| 47 | 16-07-2025 | EXTERNAL | HIGH DUSTING     | SIGN RAMBU JALAN | <br>20:54:49<br>16-Jul-2025 | <br>20:55:15<br>16-Jul-2025 | <br>20:55:41<br>16-Jul-2025 |
| 48 | 16-07-2025 | EXTERNAL | BRUSHING         | LOGO JKTP        | <br>15:44:26<br>16-Jul-2025 | <br>15:44:37<br>16-Jul-2025 | <br>15:44:47<br>16-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 17-07-2025 | LANTAI 3 | POLISHING      | CLOSET           | <br>18:25:34<br>17-Jul-2025   | <br>18:23:13<br>17-Jul-2025   | <br>18:26:21<br>17-Jul-2025   |
| 2  | 17-07-2025 | LANTAI 3 | BRUSHING       | LANTAI CONCRETE  | <br>11:23:51<br>17-Jul-2025   | <br>11:24:05<br>17-Jul-2025   | <br>11:24:46<br>17-Jul-2025   |
| 3  | 17-07-2025 | LANTAI 3 | POLISHING      | MEJA             | <br>11:25:51<br>17-Jul-2025  | <br>11:26:08<br>17-Jul-2025  | <br>11:26:23<br>17-Jul-2025  |
| 4  | 17-07-2025 | LANTAI 3 | POLISHING      | WASTAFEL         | <br>18:15:13<br>17-Jul-2025 | <br>18:16:25<br>17-Jul-2025 | <br>18:17:21<br>17-Jul-2025 |
| 5  | 17-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA       | <br>18:12:17<br>17-Jul-2025 | <br>18:10:59<br>17-Jul-2025 | <br>18:11:27<br>17-Jul-2025 |
| 6  | 17-07-2025 | LANTAI 2 | POLISHING      | KUBIKAL          | <br>11:19:52<br>17-Jul-2025 | <br>11:20:21<br>17-Jul-2025 | <br>11:20:36<br>17-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 17-07-2025 | LANTAI 2 | BRUSHING       | GUTTER                  | <br>18:48:14<br>17-Jul-2025   | <br>18:48:32<br>17-Jul-2025   | <br>18:48:50<br>17-Jul-2025   |
| 8  | 17-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>18:37:12<br>17-Jul-2025   | <br>18:37:29<br>17-Jul-2025   | <br>18:37:50<br>17-Jul-2025   |
| 9  | 17-07-2025 | LANTAI 1 | SPOTTING       | KURSI                   | <br>18:38:37<br>17-Jul-2025  | <br>18:38:57<br>17-Jul-2025  | <br>18:39:17<br>17-Jul-2025  |
| 10 | 17-07-2025 | LANTAI 1 | SPOTTING       | LIST SKIRTING           | <br>11:26:56<br>17-Jul-2025 | <br>11:27:19<br>17-Jul-2025 | <br>11:27:34<br>17-Jul-2025 |
| 11 | 17-07-2025 | LANTAI 1 | POLISHING      | FLOOR DRAIN             | <br>18:35:12<br>17-Jul-2025 | <br>18:35:30<br>17-Jul-2025 | <br>18:36:26<br>17-Jul-2025 |
| 12 | 17-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR       | <br>18:31:57<br>17-Jul-2025 | <br>18:33:28<br>17-Jul-2025 | <br>18:32:14<br>17-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 17-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT                 | <br>18:41:53<br>17-Jul-2025   | <br>18:42:10<br>17-Jul-2025   | <br>18:42:32<br>17-Jul-2025   |
| 14 | 17-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         | <br>18:28:24<br>17-Jul-2025   | <br>18:28:41<br>17-Jul-2025   | <br>18:29:01<br>17-Jul-2025   |
| 15 | 17-07-2025 | BASEMENT | WALL CLEANING  | PILAR BETON                 | <br>20:59:56<br>17-Jul-2025  | <br>21:00:20<br>17-Jul-2025  | <br>21:00:40<br>17-Jul-2025  |
| 16 | 17-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR           | <br>18:27:07<br>17-Jul-2025 | <br>18:27:25<br>17-Jul-2025 | <br>18:27:39<br>17-Jul-2025 |
| 17 | 17-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  | <br>20:58:06<br>17-Jul-2025 | <br>20:58:35<br>17-Jul-2025 | <br>20:59:02<br>17-Jul-2025 |
| 18 | 17-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT | <br>11:29:06<br>17-Jul-2025 | <br>11:29:53<br>17-Jul-2025 | <br>11:30:06<br>17-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 17-07-2025 | BASEMENT | POLISHING      | STAINLESS BULAT  | <br>11:31:13<br>17-Jul-2025   | <br>11:31:28<br>17-Jul-2025   | <br>11:31:53<br>17-Jul-2025   |
| 20 | 17-07-2025 | EXTERNAL | POLISHING      | SIGN RAMBU JALAN | <br>11:32:54<br>17-Jul-2025   | <br>11:33:02<br>17-Jul-2025   | <br>11:33:14<br>17-Jul-2025   |
| 21 | 17-07-2025 | EXTERNAL | BRUSHING       | LOGO JKTP0       | <br>21:01:11<br>17-Jul-2025  | <br>21:01:34<br>17-Jul-2025  | <br>21:02:09<br>17-Jul-2025  |
| 22 | 17-07-2025 | EXTERNAL | POLISHING      | DINDING CAT      | <br>18:12:55<br>17-Jul-2025 | <br>18:13:11<br>17-Jul-2025 | <br>18:17:52<br>17-Jul-2025 |
| 23 | 17-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM        | <br>21:04:05<br>17-Jul-2025 | <br>21:04:33<br>17-Jul-2025 | <br>21:04:52<br>17-Jul-2025 |
| 24 | 17-07-2025 | EXTERNAL | POLISHING      | ALCUBON          | <br>18:11:04<br>17-Jul-2025 | <br>18:11:22<br>17-Jul-2025 | <br>18:12:04<br>17-Jul-2025 |

| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan      | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|-----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 17-07-2025 | EXTERNAL          | BRUSHING         | TEMPAT SAMPAH         | <br>18:05:22<br>17-Jul-2025   | <br>18:05:41<br>17-Jul-2025   | <br>18:06:02<br>17-Jul-2025   |
| 26 | 17-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU          | <br>17:59:34<br>17-Jul-2025   | <br>17:59:58<br>17-Jul-2025   | <br>18:00:40<br>17-Jul-2025   |
| 27 | 17-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET                | <br>11:21:34<br>17-Jul-2025  | <br>11:21:58<br>17-Jul-2025  | <br>11:22:09<br>17-Jul-2025  |
| 28 | 17-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING               | <br>18:08:20<br>17-Jul-2025 | <br>18:08:43<br>17-Jul-2025 | <br>18:09:02<br>17-Jul-2025 |
| 29 | 17-07-2025 | CARPARK P1-P2     | POLISHING        | PINTU DAN DOOR CLOSER | <br>18:14:44<br>17-Jul-2025 | <br>18:15:32<br>17-Jul-2025 | <br>18:15:06<br>17-Jul-2025 |
| 30 | 17-07-2025 | CARPARK P1-P2     | POLISHING        | STAINLESS BULAT       | <br>11:35:48<br>17-Jul-2025 | <br>11:36:06<br>17-Jul-2025 | <br>11:36:19<br>17-Jul-2025 |




| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan  | Before | Progress | After |
|----|------------|---------------|----------------|-------------------|--------|----------|-------|
| 31 | 17-07-2025 | CARPARK P1-P2 | POLISHING      | LANDING ESCALATOR |        |          |       |
| 32 | 17-07-2025 | EXTERNAL      | POLISHING      | SIGN RAMBU JALAN  |        |          |       |
| 33 | 17-07-2025 | EXTERNAL      | BRUSHING       | LOGO JKTPD        |        |          |       |
| 34 | 17-07-2025 | EXTERNAL      | POLISHING      | DINDING CAT       |        |          |       |
| 35 | 17-07-2025 | EXTERNAL      | BRUSHING       | BATU ALAM         |        |          |       |
| 36 | 17-07-2025 | EXTERNAL      | POLISHING      | ALCUBON           |        |          |       |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 17-07-2025 | EXTERNAL | BRUSHING       | TEMPAT SAMPAH    | <br>18:16:31<br>17-Jul-2025   | <br>18:16:46<br>17-Jul-2025   | <br>18:17:05<br>17-Jul-2025   |
| 38 | 17-07-2025 | EXTERNAL | POLISHING      | SIGN RAMBU JALAN | <br>11:38:25<br>17-Jul-2025   | <br>11:38:38<br>17-Jul-2025   | <br>11:39:10<br>17-Jul-2025   |
| 39 | 17-07-2025 | EXTERNAL | BRUSHING       | LOGO JKTP0       | <br>21:06:59<br>17-Jul-2025  | <br>21:07:18<br>17-Jul-2025  | <br>21:07:36<br>17-Jul-2025  |
| 40 | 17-07-2025 | EXTERNAL | POLISHING      | DINDING CAT      | <br>18:56:29<br>17-Jul-2025 | <br>18:56:45<br>17-Jul-2025 | <br>18:57:10<br>17-Jul-2025 |
| 41 | 17-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM        | <br>21:08:27<br>17-Jul-2025 | <br>21:08:44<br>17-Jul-2025 | <br>21:09:02<br>17-Jul-2025 |
| 42 | 17-07-2025 | EXTERNAL | POLISHING      | ALCUBON          | <br>18:51:38<br>17-Jul-2025 | <br>18:51:59<br>17-Jul-2025 | <br>18:52:19<br>17-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                                | Progress                                                                                                               | After                                                                                                                   |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| 43 | 17-07-2025 | EXTERNAL | BRUSHING       | TEMPAT SAMPAH    |  <div>18:40:27<br/>17-Jul-2025</div> |  <div>18:41:07<br/>17-Jul-2025</div> |  <div>18:40:51<br/>17-Jul-2025</div> |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|---------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 1  | 18-07-2025 | LANTAI 3 | BRUSHING       | LANTAI GRANIT BAKAR |    |    |    |
| 2  | 18-07-2025 | LANTAI 3 | WALL CLEANING  | HAND RAILING        |    |    |    |
| 3  | 18-07-2025 | LANTAI 3 | POLISHING      | KURSI               |   |   |   |
| 4  | 18-07-2025 | LANTAI 3 | SPOTTING       | SOFA                |  |  |  |
| 5  | 18-07-2025 | LANTAI 2 | GLASS CLEANING | TEMPAT SAMPAH       |  |  |  |
| 6  | 18-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN         |  |  |  |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 18-07-2025 | LANTAI 2 | WALL CLEANING  | PLANTER BOX      | <br>20:23:55<br>18-Jul-2025   | <br>20:25:52<br>18-Jul-2025   | <br>20:27:25<br>18-Jul-2025   |
| 8  | 18-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH    | <br>20:45:54<br>18-Jul-2025   | <br>20:46:10<br>18-Jul-2025   | <br>20:46:28<br>18-Jul-2025   |
| 9  | 18-07-2025 | LANTAI 1 | BRUSHING       | LANTAI CONCRETE  | <br>12:51:50<br>18-Jul-2025  | <br>12:52:06<br>18-Jul-2025  | <br>12:52:28<br>18-Jul-2025  |
| 10 | 18-07-2025 | LANTAI 1 | SPOTTING       | AC GRILL         | <br>21:10:07<br>18-Jul-2025 | <br>21:10:35<br>18-Jul-2025 | <br>21:11:22<br>18-Jul-2025 |
| 11 | 18-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH    | <br>12:54:04<br>18-Jul-2025 | <br>12:54:44<br>18-Jul-2025 | <br>12:55:10<br>18-Jul-2025 |
| 12 | 18-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK | <br>20:51:46<br>18-Jul-2025 | <br>20:51:59<br>18-Jul-2025 | <br>20:52:12<br>18-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 18-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR    | <br>20:42:57<br>18-Jul-2025   | <br>20:43:12<br>18-Jul-2025   | <br>20:43:26<br>18-Jul-2025   |
| 14 | 18-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK              | <br>20:40:12<br>18-Jul-2025   | <br>20:40:32<br>18-Jul-2025   | <br>20:40:46<br>18-Jul-2025   |
| 15 | 18-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  | <br>20:41:09<br>18-Jul-2025  | <br>20:41:22<br>18-Jul-2025  | <br>20:41:38<br>18-Jul-2025  |
| 16 | 18-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT | <br>20:54:13<br>18-Jul-2025 | <br>20:54:27<br>18-Jul-2025 | <br>20:54:58<br>18-Jul-2025 |
| 17 | 18-07-2025 | BASEMENT | POLISHING      | TUTUP SAMPIT                | <br>20:49:35<br>18-Jul-2025 | <br>20:49:56<br>18-Jul-2025 | <br>20:50:16<br>18-Jul-2025 |
| 18 | 18-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         | <br>12:57:53<br>18-Jul-2025 | <br>12:58:47<br>18-Jul-2025 | <br>12:59:29<br>18-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before | Progress | After |
|----|------------|----------|----------------|----------------------|--------|----------|-------|
| 19 | 18-07-2025 | BASEMENT | WASHING        | LANTAI EPOXY         |        |          |       |
| 20 | 18-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         |        |          |       |
| 21 | 18-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            |        |          |       |
| 22 | 18-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         |        |          |       |
| 23 | 18-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          |        |          |       |
| 24 | 18-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR |        |          |       |

| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 18-07-2025 | EXTERNAL          | BRUSHING         | BATU ALAM                | <br>20:28:18<br>18-Jul-2025   | <br>20:29:07<br>18-Jul-2025   | <br>20:29:33<br>18-Jul-2025   |
| 26 | 18-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING                  | <br>12:24:58<br>18-Jul-2025   | <br>12:25:53<br>18-Jul-2025   | <br>12:26:12<br>18-Jul-2025   |
| 27 | 18-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU             | <br>20:35:09<br>18-Jul-2025  | <br>20:35:25<br>18-Jul-2025  | <br>20:35:48<br>18-Jul-2025  |
| 28 | 18-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | COVER LAMP               | <br>12:23:37<br>18-Jul-2025 | <br>12:23:56<br>18-Jul-2025 | <br>12:24:14<br>18-Jul-2025 |
| 29 | 18-07-2025 | CARPARK P1-P2     | HIGH DUSTING     | OUTDOOR AC               | <br>12:49:24<br>18-Jul-2025 | <br>12:50:01<br>18-Jul-2025 | <br>12:50:20<br>18-Jul-2025 |
| 30 | 18-07-2025 | CARPARK P1-P2     | POLISHING        | BODY STAINLESS ESCALATOR | <br>20:30:42<br>18-Jul-2025 | <br>20:33:46<br>18-Jul-2025 | <br>20:34:08<br>18-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 18-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         | <br>21:20:14<br>18-Jul-2025   | <br>21:20:32<br>18-Jul-2025   | <br>21:20:50<br>18-Jul-2025   |
| 32 | 18-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            | <br>21:12:30<br>18-Jul-2025   | <br>21:12:43<br>18-Jul-2025   | <br>21:12:57<br>18-Jul-2025   |
| 33 | 18-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         | <br>21:13:47<br>18-Jul-2025  | <br>21:14:01<br>18-Jul-2025  | <br>21:14:21<br>18-Jul-2025  |
| 34 | 18-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          | <br>20:58:41<br>18-Jul-2025 | <br>20:58:59<br>18-Jul-2025 | <br>20:59:15<br>18-Jul-2025 |
| 35 | 18-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR | <br>20:36:33<br>18-Jul-2025 | <br>20:36:47<br>18-Jul-2025 | <br>20:37:07<br>18-Jul-2025 |
| 36 | 18-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM            | <br>20:38:06<br>18-Jul-2025 | <br>20:38:18<br>18-Jul-2025 | <br>20:38:31<br>18-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 18-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         | <br>21:21:17<br>18-Jul-2025   | <br>21:21:43<br>18-Jul-2025   | <br>21:22:04<br>18-Jul-2025   |
| 38 | 18-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            | <br>20:48:08<br>18-Jul-2025   | <br>20:48:31<br>18-Jul-2025   | <br>20:48:49<br>18-Jul-2025   |
| 39 | 18-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         | <br>22:57:22<br>18-Jul-2025  | <br>22:57:44<br>18-Jul-2025  | <br>22:57:59<br>18-Jul-2025  |
| 40 | 18-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          | <br>20:53:00<br>18-Jul-2025 | <br>20:53:15<br>18-Jul-2025 | <br>20:53:37<br>18-Jul-2025 |
| 41 | 18-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR | <br>21:00:18<br>18-Jul-2025 | <br>21:00:34<br>18-Jul-2025 | <br>21:00:48<br>18-Jul-2025 |
| 42 | 18-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM            | <br>21:01:53<br>18-Jul-2025 | <br>21:02:09<br>18-Jul-2025 | <br>21:02:26<br>18-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|-------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 1  | 21-07-2025 | LANTAI 3 | POLISHING      | URINOIR                 |    |    |    |
| 2  | 21-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH           |    |    |    |
| 3  | 21-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH STAINLESS |   |   |   |
| 4  | 21-07-2025 | LANTAI 3 | POLISHING      | TRAY                    |  |  |  |
| 5  | 21-07-2025 | LANTAI 3 | POLISHING      | CLOSET                  |  |  |  |
| 6  | 21-07-2025 | LANTAI 2 | SPOTTING       | SOFA                    |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 21-07-2025 | LANTAI 2 | WALL CLEANING  | PINTU LIFT          | <br>19:26:17<br>21-Jul-2025   | <br>19:26:35<br>21-Jul-2025   | <br>19:26:59<br>21-Jul-2025   |
| 8  | 21-07-2025 | LANTAI 2 | BRUSHING       | LANTAI GRANIT BAKAR | <br>19:24:27<br>21-Jul-2025   | <br>19:24:55<br>21-Jul-2025   | <br>19:25:14<br>21-Jul-2025   |
| 9  | 21-07-2025 | LANTAI 2 | POLISHING      | CLOSET              | <br>11:52:34<br>21-Jul-2025  | <br>11:52:49<br>21-Jul-2025  | <br>11:53:02<br>21-Jul-2025  |
| 10 | 21-07-2025 | LANTAI 1 | HIGH DUSTING   | NEON LED            | <br>11:54:42<br>21-Jul-2025 | <br>11:55:08<br>21-Jul-2025 | <br>11:55:21<br>21-Jul-2025 |
| 11 | 21-07-2025 | LANTAI 1 | BRUSHING       | LANTAI KERAMIK      | <br>19:22:29<br>21-Jul-2025 | <br>19:22:53<br>21-Jul-2025 | <br>19:23:14<br>21-Jul-2025 |
| 12 | 21-07-2025 | LANTAI 1 | POLISHING      | KUBIKAL             | <br>11:56:41<br>21-Jul-2025 | <br>11:56:55<br>21-Jul-2025 | <br>11:57:15<br>21-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan  | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 21-07-2025 | LANTAI 1 | GLASS CLEANING  | KACA              | <br>19:27:53<br>21-Jul-2025   | <br>19:29:28<br>21-Jul-2025   | <br>19:50:00<br>21-Jul-2025   |
| 14 | 21-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>19:20:38<br>21-Jul-2025   | <br>19:21:03<br>21-Jul-2025   | <br>19:21:40<br>21-Jul-2025   |
| 15 | 21-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>19:18:57<br>21-Jul-2025  | <br>19:19:14<br>21-Jul-2025  | <br>19:19:41<br>21-Jul-2025  |
| 16 | 21-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING     | <br>19:29:56<br>21-Jul-2025 | <br>19:30:14<br>21-Jul-2025 | <br>19:30:28<br>21-Jul-2025 |
| 17 | 21-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP NAIK  | <br>19:17:09<br>21-Jul-2025 | <br>19:17:31<br>21-Jul-2025 | <br>19:17:53<br>21-Jul-2025 |
| 18 | 21-07-2025 | BASEMENT | POLISHING       | STAINLESS BULAT   | <br>19:31:35<br>21-Jul-2025 | <br>19:32:01<br>21-Jul-2025 | <br>19:32:21<br>21-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 19 | 21-07-2025 | BASEMENT | POLISHING      | TUTUP SAMPIT     |    |    |    |
| 20 | 21-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK |    |    |    |
| 21 | 21-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN          |   |   |   |
| 22 | 21-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT      |  |  |  |
| 23 | 21-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK   |  |  |  |
| 24 | 21-07-2025 | EXTERNAL | POLISHING      | PIPA HYDRANT     |  |  |  |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 21-07-2025 | EXTERNAL | BRUSHING       | BOX HYDRANT DAN APAR | <br>19:33:24<br>21-Jul-2025   | <br>19:33:44<br>21-Jul-2025   | <br>19:34:09<br>21-Jul-2025   |
| 26 | 21-07-2025 | EXTERNAL | WALL CLEANING  | PIPA HYDRANT         | <br>19:20:52<br>21-Jul-2025   | <br>19:21:20<br>21-Jul-2025   | <br>19:21:41<br>21-Jul-2025   |
| 27 | 21-07-2025 | EXTERNAL | BRUSHING       | ALCUBON              | <br>18:58:25<br>21-Jul-2025  | <br>18:59:09<br>21-Jul-2025  | <br>18:59:43<br>21-Jul-2025  |
| 28 | 21-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER      | <br>19:36:39<br>21-Jul-2025 | <br>19:37:10<br>21-Jul-2025 | <br>19:37:35<br>21-Jul-2025 |
| 29 | 21-07-2025 | EXTERNAL | WALL CLEANING  | GUTTER               | <br>18:40:22<br>21-Jul-2025 | <br>18:36:04<br>21-Jul-2025 | <br>18:41:56<br>21-Jul-2025 |
| 30 | 21-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER      | <br>19:38:40<br>21-Jul-2025 | <br>19:38:55<br>21-Jul-2025 | <br>19:39:12<br>21-Jul-2025 |

| No | Tanggal    | Area              | Item Pekerjaan  | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|-----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 21-07-2025 | EXTERNAL          | BRUSHING        | DINDING BETON    | <br>19:03:42<br>21-Jul-2025   | <br>19:03:59<br>21-Jul-2025   | <br>19:04:17<br>21-Jul-2025   |
| 32 | 21-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING          | <br>12:08:14<br>21-Jul-2025   | <br>12:08:25<br>21-Jul-2025   | <br>12:08:41<br>21-Jul-2025   |
| 33 | 21-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | COVER LAMP       | <br>19:53:48<br>21-Jul-2025  | <br>19:54:14<br>21-Jul-2025  | <br>19:54:36<br>21-Jul-2025  |
| 34 | 21-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING  | KACA             | <br>18:21:05<br>21-Jul-2025 | <br>18:21:36<br>21-Jul-2025 | <br>18:22:35<br>21-Jul-2025 |
| 35 | 21-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | PIPA PLUMBING    | <br>12:04:41<br>21-Jul-2025 | <br>12:04:56<br>21-Jul-2025 | <br>12:05:10<br>21-Jul-2025 |
| 36 | 21-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING          | <br>12:05:31<br>21-Jul-2025 | <br>12:05:41<br>21-Jul-2025 | <br>12:06:33<br>21-Jul-2025 |



| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan         | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|---------------|----------------|--------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 37 | 21-07-2025 | CARPARK P1-P2 | POLISHING      | BODY STAINLESS ESCALATOR |    |    |    |
| 38 | 21-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI CONCRETE          |    |    |    |
| 39 | 21-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI KERAMIK           |   |   |   |
| 40 | 21-07-2025 | CARPARK P1-P2 | GLASS CLEANING | SAFETY MIRROR            |  |  |  |
| 41 | 21-07-2025 | EXTERNAL      | POLISHING      | PIPA HYDRANT             |  |  |  |
| 42 | 21-07-2025 | EXTERNAL      | BRUSHING       | BOX HYDRANT DAN APAR     |  |  |  |

| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|------------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 43 | 21-07-2025 | EXTERNAL | WALL CLEANING    | PIPA HYDRANT     |    |    |    |
| 44 | 21-07-2025 | EXTERNAL | BRUSHING         | ALCUBON          |    |    |    |
| 45 | 21-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER  |   |   |   |
| 46 | 21-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           |  |  |  |
| 47 | 21-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER  |  |  |  |
| 48 | 21-07-2025 | EXTERNAL | BRUSHING         | DINDING BETON    |  |  |  |





| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|------------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 49 | 21-07-2025 | EXTERNAL | POLISHING        | PIPA HYDRANT         |    |    |    |
| 50 | 21-07-2025 | EXTERNAL | BRUSHING         | BOX HYDRANT DAN APAR |    |    |    |
| 51 | 21-07-2025 | EXTERNAL | WALL CLEANING    | PIPA HYDRANT         |   |   |   |
| 52 | 21-07-2025 | EXTERNAL | BRUSHING         | ALCUBON              |  |  |  |
| 53 | 21-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER      |  |  |  |
| 54 | 21-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER               |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                            | Progress                                                                           | After                                                                               |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 55 | 21-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER  |  |  |  |
| 56 | 21-07-2025 | EXTERNAL | BRUSHING       | DINDING BETON    |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 22-07-2025 | LANTAI 3 | POLISHING        | FLOOR DRAIN      | <br>11:49:00<br>22-Jul-2025   | <br>11:49:18<br>22-Jul-2025   | <br>11:49:53<br>22-Jul-2025   |
| 2  | 22-07-2025 | LANTAI 3 | WALL CLEANING    | DINDING ACP      | <br>11:58:29<br>22-Jul-2025   | <br>11:58:46<br>22-Jul-2025   | <br>11:59:12<br>22-Jul-2025   |
| 3  | 22-07-2025 | LANTAI 3 | GLASS CLEANING   | KACA RAILING     | <br>11:59:59<br>22-Jul-2025  | <br>12:00:13<br>22-Jul-2025  | <br>12:00:24<br>22-Jul-2025  |
| 4  | 22-07-2025 | LANTAI 3 | GENERAL CLEANING | DISWASHING       | <br>16:50:03<br>22-Jul-2025 | <br>16:50:22<br>22-Jul-2025 | <br>16:50:46<br>22-Jul-2025 |
| 5  | 22-07-2025 | LANTAI 2 | POLISHING        | TEMPAT SAMPAH    | <br>11:41:03<br>22-Jul-2025 | <br>11:41:14<br>22-Jul-2025 | <br>11:41:33<br>22-Jul-2025 |
| 6  | 22-07-2025 | LANTAI 2 | BRUSHING         | LANTAI CONCRETE  | <br>11:52:31<br>22-Jul-2025 | <br>11:52:58<br>22-Jul-2025 | <br>11:53:15<br>22-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 22-07-2025 | LANTAI 2 | POLISHING      | RAK ACCESORIS           | <br>16:33:43<br>22-Jul-2025   | <br>16:33:59<br>22-Jul-2025   | <br>16:34:15<br>22-Jul-2025   |
| 8  | 22-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA              | <br>11:57:09<br>22-Jul-2025   | <br>11:57:56<br>22-Jul-2025   | <br>11:57:33<br>22-Jul-2025   |
| 9  | 22-07-2025 | LANTAI 2 | POLISHING      | CLOSET                  | <br>16:32:15<br>22-Jul-2025  | <br>16:32:36<br>22-Jul-2025  | <br>16:32:52<br>22-Jul-2025  |
| 10 | 22-07-2025 | LANTAI 1 | POLISHING      | PINTU LIFT              | <br>16:46:42<br>22-Jul-2025 | <br>16:47:08<br>22-Jul-2025 | <br>16:47:27<br>22-Jul-2025 |
| 11 | 22-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>11:43:23<br>22-Jul-2025 | <br>11:43:57<br>22-Jul-2025 | <br>11:44:13<br>22-Jul-2025 |
| 12 | 22-07-2025 | LANTAI 1 | POLISHING      | WASTAFEL                | <br>16:34:39<br>22-Jul-2025 | <br>16:34:57<br>22-Jul-2025 | <br>16:35:22<br>22-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan  | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 22-07-2025 | LANTAI 1 | POLISHING      | PINTU EXIT        | <br>11:42:13<br>22-Jul-2025   | <br>11:42:30<br>22-Jul-2025   | <br>11:43:01<br>22-Jul-2025   |
| 14 | 22-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           | <br>21:10:55<br>22-Jul-2025   | <br>21:11:15<br>22-Jul-2025   | <br>21:11:35<br>22-Jul-2025   |
| 15 | 22-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           | <br>21:12:00<br>22-Jul-2025  | <br>21:12:19<br>22-Jul-2025  | <br>21:12:39<br>22-Jul-2025  |
| 16 | 22-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR | <br>17:34:45<br>22-Jul-2025 | <br>17:35:06<br>22-Jul-2025 | <br>17:35:38<br>22-Jul-2025 |
| 17 | 22-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG      | <br>18:22:50<br>22-Jul-2025 | <br>18:21:17<br>22-Jul-2025 | <br>18:23:05<br>22-Jul-2025 |
| 18 | 22-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP TURUN | <br>18:09:19<br>22-Jul-2025 | <br>18:09:37<br>22-Jul-2025 | <br>18:09:54<br>22-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 22-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>17:32:46<br>22-Jul-2025   | <br>17:33:24<br>22-Jul-2025   | <br>17:33:51<br>22-Jul-2025   |
| 20 | 22-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>18:18:35<br>22-Jul-2025   | <br>18:19:13<br>22-Jul-2025   | <br>18:19:52<br>22-Jul-2025   |
| 21 | 22-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>11:44:54<br>22-Jul-2025  | <br>11:45:04<br>22-Jul-2025  | <br>11:45:13<br>22-Jul-2025  |
| 22 | 22-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR | <br>18:16:03<br>22-Jul-2025 | <br>18:15:47<br>22-Jul-2025 | <br>18:16:16<br>22-Jul-2025 |
| 23 | 22-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>11:47:02<br>22-Jul-2025 | <br>11:47:16<br>22-Jul-2025 | <br>11:47:40<br>22-Jul-2025 |
| 24 | 22-07-2025 | EXTERNAL | POLISHING      | DINDING CAT              | <br>11:45:55<br>22-Jul-2025 | <br>11:46:04<br>22-Jul-2025 | <br>11:46:17<br>22-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 22-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       | <br>18:06:17<br>22-Jul-2025   | <br>18:06:55<br>22-Jul-2025   | <br>18:07:24<br>22-Jul-2025   |
| 26 | 22-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        | <br>21:08:45<br>22-Jul-2025   | <br>21:09:03<br>22-Jul-2025   | <br>21:09:18<br>22-Jul-2025   |
| 27 | 22-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     | <br>17:59:52<br>22-Jul-2025  | <br>18:00:17<br>22-Jul-2025  | <br>18:00:35<br>22-Jul-2025  |
| 28 | 22-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR | <br>17:42:23<br>22-Jul-2025 | <br>17:42:47<br>22-Jul-2025 | <br>17:43:07<br>22-Jul-2025 |
| 29 | 22-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        | <br>21:09:41<br>22-Jul-2025 | <br>21:10:15<br>22-Jul-2025 | <br>21:10:33<br>22-Jul-2025 |
| 30 | 22-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       | <br>17:27:54<br>22-Jul-2025 | <br>17:28:19<br>22-Jul-2025 | <br>17:28:46<br>22-Jul-2025 |



| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 22-07-2025 | EXTERNAL          | BRUSHING         | ALCUBON          | <br>11:32:53<br>22-Jul-2025   | <br>11:33:12<br>22-Jul-2025   | <br>11:33:24<br>22-Jul-2025   |
| 32 | 22-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI           | <br>16:22:31<br>22-Jul-2025   | <br>16:23:02<br>22-Jul-2025   | <br>16:23:25<br>22-Jul-2025   |
| 33 | 22-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | PIPA PLUMBING    | <br>11:36:03<br>22-Jul-2025  | <br>11:36:14<br>22-Jul-2025  | <br>11:36:27<br>22-Jul-2025  |
| 34 | 22-07-2025 | MANAGEMENT OFFICE | WALL CLEANING    | DINDING          | <br>11:36:53<br>22-Jul-2025 | <br>11:37:21<br>22-Jul-2025 | <br>11:37:39<br>22-Jul-2025 |
| 35 | 22-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING   | KACA             | <br>16:24:43<br>22-Jul-2025 | <br>16:25:15<br>22-Jul-2025 | <br>16:25:42<br>22-Jul-2025 |
| 36 | 22-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>16:20:05<br>22-Jul-2025 | <br>16:20:57<br>22-Jul-2025 | <br>16:21:33<br>22-Jul-2025 |




| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|---------------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 22-07-2025 | CARPARK P1-P2 | POLISHING      | RAILING             | <br>16:53:16<br>22-Jul-2025   | <br>16:53:43<br>22-Jul-2025   | <br>16:54:06<br>22-Jul-2025   |
| 38 | 22-07-2025 | CARPARK P1-P2 | POLISHING      | BOX HYDRANT         | <br>11:35:08<br>22-Jul-2025   | <br>11:35:22<br>22-Jul-2025   | <br>11:35:38<br>22-Jul-2025   |
| 39 | 22-07-2025 | CARPARK P1-P2 | POLISHING      | TUTUP SAMPIT        | <br>18:29:38<br>22-Jul-2025  | <br>18:29:54<br>22-Jul-2025  | <br>18:30:07<br>22-Jul-2025  |
| 40 | 22-07-2025 | CARPARK P1-P2 | BRUSHING       | DINDING PLANTER BOX | <br>16:39:29<br>22-Jul-2025 | <br>16:41:32<br>22-Jul-2025 | <br>16:41:55<br>22-Jul-2025 |
| 41 | 22-07-2025 | EXTERNAL      | POLISHING      | DINDING CAT         | <br>11:30:12<br>22-Jul-2025 | <br>11:30:22<br>22-Jul-2025 | <br>11:30:38<br>22-Jul-2025 |
| 42 | 22-07-2025 | EXTERNAL      | BRUSHING       | LANTAI ANDESIT      | <br>17:30:35<br>22-Jul-2025 | <br>17:31:05<br>22-Jul-2025 | <br>17:31:30<br>22-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 43 | 22-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        | <br>21:07:29<br>22-Jul-2025   | <br>21:07:55<br>22-Jul-2025   | <br>21:08:16<br>22-Jul-2025   |
| 44 | 22-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     | <br>18:26:40<br>22-Jul-2025   | <br>18:27:02<br>22-Jul-2025   | <br>18:27:21<br>22-Jul-2025   |
| 45 | 22-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR | <br>16:36:12<br>22-Jul-2025  | <br>16:36:31<br>22-Jul-2025  | <br>16:36:58<br>22-Jul-2025  |
| 46 | 22-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        | <br>18:28:14<br>22-Jul-2025 | <br>18:28:33<br>22-Jul-2025 | <br>18:28:57<br>22-Jul-2025 |
| 47 | 22-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       | <br>17:43:47<br>22-Jul-2025 | <br>17:44:11<br>22-Jul-2025 | <br>17:44:40<br>22-Jul-2025 |
| 48 | 22-07-2025 | EXTERNAL | BRUSHING       | ALCUBON              | <br>11:54:26<br>22-Jul-2025 | <br>11:54:56<br>22-Jul-2025 | <br>11:55:08<br>22-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 49 | 22-07-2025 | EXTERNAL | POLISHING      | DINDING CAT          |    |    |    |
| 50 | 22-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       |    |    |    |
| 51 | 22-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        |   |   |   |
| 52 | 22-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     |  |  |  |
| 53 | 22-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR |  |  |  |
| 54 | 22-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        |  |  |  |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                                | Progress                                                                                                               | After                                                                                                                   |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| 55 | 22-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT   |  <div>17:37:10<br/>22-Jul-2025</div> |  <div>17:37:36<br/>22-Jul-2025</div> |  <div>17:38:00<br/>22-Jul-2025</div> |
| 56 | 22-07-2025 | EXTERNAL | BRUSHING       | ALCUBON          |  <div>11:39:33<br/>22-Jul-2025</div> |  <div>11:39:55<br/>22-Jul-2025</div> |  <div>11:40:12<br/>22-Jul-2025</div> |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 23-07-2025 | LANTAI 3 | POLISHING      | KUBIKAL          | <br>11:36:19<br>23-Jul-2025   | <br>11:36:39<br>23-Jul-2025   | <br>11:37:21<br>23-Jul-2025   |
| 2  | 23-07-2025 | LANTAI 3 | WALL CLEANING  | PLANTER BOX      | <br>11:21:35<br>23-Jul-2025   | <br>11:21:47<br>23-Jul-2025   | <br>11:22:00<br>23-Jul-2025   |
| 3  | 23-07-2025 | LANTAI 3 | WALL CLEANING  | PINTU LIFT       | <br>11:41:14<br>23-Jul-2025  | <br>11:41:49<br>23-Jul-2025  | <br>11:42:08<br>23-Jul-2025  |
| 4  | 23-07-2025 | LANTAI 3 | GLASS CLEANING | MIRROR           | <br>19:21:47<br>23-Jul-2025 | <br>19:22:04<br>23-Jul-2025 | <br>19:22:20<br>23-Jul-2025 |
| 5  | 23-07-2025 | LANTAI 2 | POLISHING      | CLOSET           | <br>11:32:12<br>23-Jul-2025 | <br>11:32:32<br>23-Jul-2025 | <br>11:32:46<br>23-Jul-2025 |
| 6  | 23-07-2025 | LANTAI 2 | SPOTTING       | SOFA             | <br>11:18:30<br>23-Jul-2025 | <br>11:19:21<br>23-Jul-2025 | <br>11:19:37<br>23-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 23-07-2025 | LANTAI 2 | SPOTTING       | FLOOR DRAIN      | <br>19:27:45<br>23-Jul-2025   | <br>19:28:05<br>23-Jul-2025   | <br>19:28:19<br>23-Jul-2025   |
| 8  | 23-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN      | <br>11:33:25<br>23-Jul-2025   | <br>11:33:42<br>23-Jul-2025   | <br>11:33:55<br>23-Jul-2025   |
| 9  | 23-07-2025 | LANTAI 1 | WALL CLEANING  | DINDING LIFT     | <br>11:39:06<br>23-Jul-2025  | <br>11:39:23<br>23-Jul-2025  | <br>11:39:37<br>23-Jul-2025  |
| 10 | 23-07-2025 | LANTAI 1 | HIGH DUSTING   | KIPAS            | <br>16:58:20<br>23-Jul-2025 | <br>16:58:53<br>23-Jul-2025 | <br>16:59:26<br>23-Jul-2025 |
| 11 | 23-07-2025 | LANTAI 1 | POLISHING      | CLOSET           | <br>11:35:21<br>23-Jul-2025 | <br>11:35:37<br>23-Jul-2025 | <br>11:35:50<br>23-Jul-2025 |
| 12 | 23-07-2025 | LANTAI 1 | SWEEPING       | TANGGA           | <br>19:26:29<br>23-Jul-2025 | <br>19:26:48<br>23-Jul-2025 | <br>19:27:08<br>23-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 23-07-2025 | BASEMENT | POLISHING       | BODY STAINLESS ESCALATOR    | <br>19:25:15<br>23-Jul-2025   | <br>19:25:38<br>23-Jul-2025   | <br>19:25:57<br>23-Jul-2025   |
| 14 | 23-07-2025 | BASEMENT | PLAFON CLEANING | CEILING                     | <br>21:05:24<br>23-Jul-2025   | <br>21:05:56<br>23-Jul-2025   | <br>21:06:19<br>23-Jul-2025   |
| 15 | 23-07-2025 | BASEMENT | WALL CLEANING   | DINDING CAT PARKIR BASEMENT | <br>19:23:56<br>23-Jul-2025  | <br>19:24:13<br>23-Jul-2025  | <br>19:24:34<br>23-Jul-2025  |
| 16 | 23-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR               | <br>19:31:52<br>23-Jul-2025 | <br>19:32:12<br>23-Jul-2025 | <br>19:32:29<br>23-Jul-2025 |
| 17 | 23-07-2025 | BASEMENT | WASHING         | LANTAI EPOXY                | <br>19:22:46<br>23-Jul-2025 | <br>19:23:02<br>23-Jul-2025 | <br>19:23:16<br>23-Jul-2025 |
| 18 | 23-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING               | <br>19:30:39<br>23-Jul-2025 | <br>19:30:56<br>23-Jul-2025 | <br>19:31:10<br>23-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|-----------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 19 | 23-07-2025 | BASEMENT | WALL CLEANING   | PILAR BETON      |    |    |    |
| 20 | 23-07-2025 | BASEMENT | PLAFON CLEANING | CEILING          |    |    |    |
| 21 | 23-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING    |   |   |   |
| 22 | 23-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR    |  |  |  |
| 23 | 23-07-2025 | EXTERNAL | BRUSHING        | GUTTER           |  |  |  |
| 24 | 23-07-2025 | EXTERNAL | WALL CLEANING   | TEMPAT SAMPAH    |  |  |  |



| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 23-07-2025 | EXTERNAL          | WALL CLEANING    | GUTTER           | <br>21:04:01<br>23-Jul-2025   | <br>21:04:28<br>23-Jul-2025   | <br>21:04:47<br>23-Jul-2025   |
| 26 | 23-07-2025 | EXTERNAL          | POLISHING        | LANTAI ANDESIT   | <br>21:07:43<br>23-Jul-2025   | <br>21:08:20<br>23-Jul-2025   | <br>21:08:40<br>23-Jul-2025   |
| 27 | 23-07-2025 | EXTERNAL          | BRUSHING         | PIPA HYDRANT     | <br>16:46:01<br>23-Jul-2025  | <br>16:46:51<br>23-Jul-2025  | <br>16:47:19<br>23-Jul-2025  |
| 28 | 23-07-2025 | EXTERNAL          | HIGH DUSTING     | SIGN RAMBU JALAN | <br>21:20:48<br>23-Jul-2025 | <br>21:21:35<br>23-Jul-2025 | <br>21:21:59<br>23-Jul-2025 |
| 29 | 23-07-2025 | EXTERNAL          | BRUSHING         | LOGO JKTP0       | <br>11:46:12<br>23-Jul-2025 | <br>11:46:36<br>23-Jul-2025 | <br>11:46:53<br>23-Jul-2025 |
| 30 | 23-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>11:34:19<br>23-Jul-2025 | <br>11:34:32<br>23-Jul-2025 | <br>11:34:43<br>23-Jul-2025 |

| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 23-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI              | <br>21:12:21<br>23-Jul-2025   | <br>21:13:31<br>23-Jul-2025   | <br>21:13:59<br>23-Jul-2025   |
| 32 | 23-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU        | <br>11:44:31<br>23-Jul-2025   | <br>11:45:17<br>23-Jul-2025   | <br>11:45:32<br>23-Jul-2025   |
| 33 | 23-07-2025 | CARPARK P1-P2     | POLISHING        | LANDING ESCALATOR   | <br>11:13:19<br>23-Jul-2025  | <br>11:13:38<br>23-Jul-2025  | <br>11:13:57<br>23-Jul-2025  |
| 34 | 23-07-2025 | CARPARK P1-P2     | BRUSHING         | DINDING PLANTER BOX | <br>19:16:03<br>23-Jul-2025 | <br>19:16:18<br>23-Jul-2025 | <br>19:16:50<br>23-Jul-2025 |
| 35 | 23-07-2025 | CARPARK P1-P2     | HIGH DUSTING     | JET FAN             | <br>11:42:35<br>23-Jul-2025 | <br>11:42:59<br>23-Jul-2025 | <br>11:43:12<br>23-Jul-2025 |
| 36 | 23-07-2025 | EXTERNAL          | GENERAL CLEANING | GUTTER              | <br>11:14:38<br>23-Jul-2025 | <br>11:15:01<br>23-Jul-2025 | <br>11:15:25<br>23-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 23-07-2025 | EXTERNAL | WALL CLEANING    | TEMPAT SAMPAH    | <br>16:42:22<br>23-Jul-2025   | <br>16:42:59<br>23-Jul-2025   | <br>16:43:31<br>23-Jul-2025   |
| 38 | 23-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>19:12:38<br>23-Jul-2025   | <br>19:13:04<br>23-Jul-2025   | <br>19:13:21<br>23-Jul-2025   |
| 39 | 23-07-2025 | EXTERNAL | POLISHING        | LANTAI ANDESIT   | <br>21:14:47<br>23-Jul-2025  | <br>21:15:11<br>23-Jul-2025  | <br>21:15:32<br>23-Jul-2025  |
| 40 | 23-07-2025 | EXTERNAL | BRUSHING         | PIPA HYDRANT     | <br>17:10:42<br>23-Jul-2025 | <br>17:11:07<br>23-Jul-2025 | <br>17:11:40<br>23-Jul-2025 |
| 41 | 23-07-2025 | EXTERNAL | HIGH DUSTING     | SIGN RAMBU JALAN | <br>19:29:15<br>23-Jul-2025 | <br>19:29:35<br>23-Jul-2025 | <br>19:29:53<br>23-Jul-2025 |
| 42 | 23-07-2025 | EXTERNAL | BRUSHING         | LOGO JKTPO       | <br>15:16:45<br>23-Jul-2025 | <br>15:17:03<br>23-Jul-2025 | <br>15:17:32<br>23-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                      | Progress                                                                                                     | After                                                                                                         |
|----|------------|----------|------------------|------------------|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| 43 | 23-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           |  11:29:54<br>23-Jul-2025   |  11:31:00<br>23-Jul-2025   |  11:31:33<br>23-Jul-2025   |
| 44 | 23-07-2025 | EXTERNAL | WALL CLEANING    | TEMPAT SAMPAH    |  17:13:42<br>23-Jul-2025   |  17:14:01<br>23-Jul-2025   |  17:14:29<br>23-Jul-2025   |
| 45 | 23-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           |  21:17:15<br>23-Jul-2025  |  21:17:51<br>23-Jul-2025  |  21:18:28<br>23-Jul-2025  |
| 46 | 23-07-2025 | EXTERNAL | POLISHING        | LANTAI ANDESIT   |  19:34:34<br>23-Jul-2025 |  19:34:49<br>23-Jul-2025 |  19:35:03<br>23-Jul-2025 |
| 47 | 23-07-2025 | EXTERNAL | BRUSHING         | PIPA HYDRANT     |  16:50:21<br>23-Jul-2025 |  16:50:52<br>23-Jul-2025 |  16:51:14<br>23-Jul-2025 |
| 48 | 23-07-2025 | EXTERNAL | HIGH DUSTING     | SIGN RAMBU JALAN |  19:14:30<br>23-Jul-2025 |  19:14:59<br>23-Jul-2025 |  19:15:19<br>23-Jul-2025 |








| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                            | Progress                                                                           | After                                                                               |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 49 | 23-07-2025 | EXTERNAL | BRUSHING       | LOGO JKTPO       |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 24-07-2025 | LANTAI 3 | POLISHING      | CLOSET           | <br>18:14:11<br>24-Jul-2025   | <br>18:14:30<br>24-Jul-2025   | <br>18:14:52<br>24-Jul-2025   |
| 2  | 24-07-2025 | LANTAI 3 | BRUSHING       | LANTAI CONCRETE  | <br>11:36:31<br>24-Jul-2025   | <br>11:36:53<br>24-Jul-2025   | <br>11:37:37<br>24-Jul-2025   |
| 3  | 24-07-2025 | LANTAI 3 | POLISHING      | MEJA             | <br>11:30:49<br>24-Jul-2025  | <br>11:31:16<br>24-Jul-2025  | <br>11:31:29<br>24-Jul-2025  |
| 4  | 24-07-2025 | LANTAI 3 | POLISHING      | WASTAFEL         | <br>18:31:01<br>24-Jul-2025 | <br>18:31:23<br>24-Jul-2025 | <br>18:31:51<br>24-Jul-2025 |
| 5  | 24-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA       | <br>18:55:19<br>24-Jul-2025 | <br>18:56:10<br>24-Jul-2025 | <br>18:56:29<br>24-Jul-2025 |
| 6  | 24-07-2025 | LANTAI 2 | POLISHING      | KUBIKAL          | <br>11:39:10<br>24-Jul-2025 | <br>11:39:38<br>24-Jul-2025 | <br>11:40:03<br>24-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 24-07-2025 | LANTAI 2 | BRUSHING       | GUTTER                  | <br>18:58:51<br>24-Jul-2025   | <br>18:59:13<br>24-Jul-2025   | <br>18:59:40<br>24-Jul-2025   |
| 8  | 24-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>19:02:39<br>24-Jul-2025   | <br>19:03:07<br>24-Jul-2025   | <br>19:03:32<br>24-Jul-2025   |
| 9  | 24-07-2025 | LANTAI 1 | SPOTTING       | KURSI                   | <br>18:57:15<br>24-Jul-2025  | <br>18:57:34<br>24-Jul-2025  | <br>18:57:56<br>24-Jul-2025  |
| 10 | 24-07-2025 | LANTAI 1 | SPOTTING       | LIST SKIRTING           | <br>11:29:48<br>24-Jul-2025 | <br>11:30:05<br>24-Jul-2025 | <br>11:30:21<br>24-Jul-2025 |
| 11 | 24-07-2025 | LANTAI 1 | POLISHING      | FLOOR DRAIN             | <br>18:34:58<br>24-Jul-2025 | <br>18:35:25<br>24-Jul-2025 | <br>18:35:57<br>24-Jul-2025 |
| 12 | 24-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR       | <br>19:07:05<br>24-Jul-2025 | <br>19:07:23<br>24-Jul-2025 | <br>19:07:41<br>24-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 24-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT                 | <br>18:21:32<br>24-Jul-2025   | <br>18:21:49<br>24-Jul-2025   | <br>18:22:18<br>24-Jul-2025   |
| 14 | 24-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         | <br>18:18:43<br>24-Jul-2025   | <br>18:20:06<br>24-Jul-2025   | <br>18:20:24<br>24-Jul-2025   |
| 15 | 24-07-2025 | BASEMENT | WALL CLEANING  | PILAR BETON                 | <br>19:14:33<br>24-Jul-2025  | <br>19:15:01<br>24-Jul-2025  | <br>19:15:21<br>24-Jul-2025  |
| 16 | 24-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR           | <br>18:16:05<br>24-Jul-2025 | <br>18:17:08<br>24-Jul-2025 | <br>18:17:38<br>24-Jul-2025 |
| 17 | 24-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  | <br>19:11:58<br>24-Jul-2025 | <br>19:12:20<br>24-Jul-2025 | <br>19:12:37<br>24-Jul-2025 |
| 18 | 24-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT | <br>11:52:49<br>24-Jul-2025 | <br>11:53:37<br>24-Jul-2025 | <br>11:53:48<br>24-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 24-07-2025 | BASEMENT | POLISHING      | STAINLESS BULAT  | <br>11:55:06<br>24-Jul-2025   | <br>11:55:22<br>24-Jul-2025   | <br>11:55:49<br>24-Jul-2025   |
| 20 | 24-07-2025 | EXTERNAL | POLISHING      | SIGN RAMBU JALAN | <br>11:48:46<br>24-Jul-2025   | <br>11:49:01<br>24-Jul-2025   | <br>11:49:22<br>24-Jul-2025   |
| 21 | 24-07-2025 | EXTERNAL | BRUSHING       | LOGO JKPTO       | <br>19:13:10<br>24-Jul-2025  | <br>19:13:29<br>24-Jul-2025  | <br>19:13:50<br>24-Jul-2025  |
| 22 | 24-07-2025 | EXTERNAL | POLISHING      | DINDING CAT      | <br>19:09:42<br>24-Jul-2025 | <br>19:09:57<br>24-Jul-2025 | <br>19:10:18<br>24-Jul-2025 |
| 23 | 24-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM        | <br>19:18:25<br>24-Jul-2025 | <br>19:18:44<br>24-Jul-2025 | <br>19:19:01<br>24-Jul-2025 |
| 24 | 24-07-2025 | EXTERNAL | POLISHING      | ALCUBON          | <br>18:02:11<br>24-Jul-2025 | <br>18:02:41<br>24-Jul-2025 | <br>18:03:10<br>24-Jul-2025 |

| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan      | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|-----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 24-07-2025 | EXTERNAL          | BRUSHING         | TEMPAT SAMPAH         | <br>17:56:09<br>24-Jul-2025   | <br>17:56:33<br>24-Jul-2025   | <br>17:56:54<br>24-Jul-2025   |
| 26 | 24-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU          | <br>17:58:35<br>24-Jul-2025   | <br>17:58:56<br>24-Jul-2025   | <br>17:59:17<br>24-Jul-2025   |
| 27 | 24-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET                | <br>11:38:10<br>24-Jul-2025  | <br>11:38:27<br>24-Jul-2025  | <br>11:38:40<br>24-Jul-2025  |
| 28 | 24-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING               | <br>18:00:08<br>24-Jul-2025 | <br>18:00:46<br>24-Jul-2025 | <br>18:01:15<br>24-Jul-2025 |
| 29 | 24-07-2025 | CARPARK P1-P2     | POLISHING        | PINTU DAN DOOR CLOSER | <br>18:05:51<br>24-Jul-2025 | <br>18:06:51<br>24-Jul-2025 | <br>18:06:14<br>24-Jul-2025 |
| 30 | 24-07-2025 | CARPARK P1-P2     | POLISHING        | STAINLESS BULAT       | <br>11:50:55<br>24-Jul-2025 | <br>11:51:09<br>24-Jul-2025 | <br>11:51:26<br>24-Jul-2025 |



| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan  | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|---------------|----------------|-------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 24-07-2025 | CARPARK P1-P2 | POLISHING      | LANDING ESCALATOR | <br>18:10:22<br>24-Jul-2025   | <br>18:10:49<br>24-Jul-2025   | <br>18:11:08<br>24-Jul-2025   |
| 32 | 24-07-2025 | EXTERNAL      | POLISHING      | SIGN RAMBU JALAN  | <br>11:33:22<br>24-Jul-2025   | <br>11:33:41<br>24-Jul-2025   | <br>11:34:00<br>24-Jul-2025   |
| 33 | 24-07-2025 | EXTERNAL      | BRUSHING       | LOGO JKTPO        | <br>19:10:45<br>24-Jul-2025  | <br>19:11:00<br>24-Jul-2025  | <br>19:11:28<br>24-Jul-2025  |
| 34 | 24-07-2025 | EXTERNAL      | POLISHING      | DINDING CAT       | <br>19:19:51<br>24-Jul-2025 | <br>19:20:11<br>24-Jul-2025 | <br>19:20:30<br>24-Jul-2025 |
| 35 | 24-07-2025 | EXTERNAL      | BRUSHING       | BATU ALAM         | <br>19:21:43<br>24-Jul-2025 | <br>19:22:01<br>24-Jul-2025 | <br>19:22:21<br>24-Jul-2025 |
| 36 | 24-07-2025 | EXTERNAL      | POLISHING      | ALCUBON           | <br>18:27:22<br>24-Jul-2025 | <br>18:27:46<br>24-Jul-2025 | <br>18:28:10<br>24-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 24-07-2025 | EXTERNAL | BRUSHING       | TEMPAT SAMPAH    | <br>18:23:31<br>24-Jul-2025   | <br>18:23:57<br>24-Jul-2025   | <br>18:24:19<br>24-Jul-2025   |
| 38 | 24-07-2025 | EXTERNAL | POLISHING      | SIGN RAMBU JALAN | <br>11:34:36<br>24-Jul-2025   | <br>11:34:56<br>24-Jul-2025   | <br>11:35:24<br>24-Jul-2025   |
| 39 | 24-07-2025 | EXTERNAL | BRUSHING       | LOGO JKTP0       | <br>19:15:46<br>24-Jul-2025  | <br>19:16:02<br>24-Jul-2025  | <br>19:16:26<br>24-Jul-2025  |
| 40 | 24-07-2025 | EXTERNAL | POLISHING      | DINDING CAT      | <br>19:16:59<br>24-Jul-2025 | <br>19:17:15<br>24-Jul-2025 | <br>19:17:30<br>24-Jul-2025 |
| 41 | 24-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM        | <br>19:23:13<br>24-Jul-2025 | <br>19:23:27<br>24-Jul-2025 | <br>19:23:41<br>24-Jul-2025 |
| 42 | 24-07-2025 | EXTERNAL | POLISHING      | ALCUBON          | <br>18:26:26<br>24-Jul-2025 | <br>18:25:17<br>24-Jul-2025 | <br>18:26:52<br>24-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                                | Progress                                                                                                               | After                                                                                                                   |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| 43 | 24-07-2025 | EXTERNAL | BRUSHING       | TEMPAT SAMPAH    |  <div>18:11:55<br/>24-Jul-2025</div> |  <div>18:12:15<br/>24-Jul-2025</div> |  <div>18:12:41<br/>24-Jul-2025</div> |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 25-07-2025 | LANTAI 3 | BRUSHING       | LANTAI GRANIT BAKAR | <br>19:24:37<br>25-Jul-2025   | <br>19:24:52<br>25-Jul-2025   | <br>19:25:09<br>25-Jul-2025   |
| 2  | 25-07-2025 | LANTAI 3 | WALL CLEANING  | HAND RAILING        | <br>13:49:21<br>25-Jul-2025   | <br>13:49:39<br>25-Jul-2025   | <br>13:49:50<br>25-Jul-2025   |
| 3  | 25-07-2025 | LANTAI 3 | POLISHING      | KURSI               | <br>13:16:45<br>25-Jul-2025  | <br>13:18:08<br>25-Jul-2025  | <br>13:19:15<br>25-Jul-2025  |
| 4  | 25-07-2025 | LANTAI 3 | SPOTTING       | SOFA                | <br>13:50:12<br>25-Jul-2025 | <br>13:50:32<br>25-Jul-2025 | <br>13:50:44<br>25-Jul-2025 |
| 5  | 25-07-2025 | LANTAI 2 | GLASS CLEANING | TEMPAT SAMPAH       | <br>19:34:26<br>25-Jul-2025 | <br>19:34:55<br>25-Jul-2025 | <br>19:35:22<br>25-Jul-2025 |
| 6  | 25-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN         | <br>19:18:00<br>25-Jul-2025 | <br>19:18:16<br>25-Jul-2025 | <br>19:18:37<br>25-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 25-07-2025 | LANTAI 2 | WALL CLEANING  | PLANTER BOX      | <br>19:16:55<br>25-Jul-2025   | <br>19:17:16<br>25-Jul-2025   | <br>19:17:32<br>25-Jul-2025   |
| 8  | 25-07-2025 | LANTAI 2 | POLISHING      | TEMPAT SAMPAH    | <br>19:37:21<br>25-Jul-2025   | <br>19:37:45<br>25-Jul-2025   | <br>19:38:11<br>25-Jul-2025   |
| 9  | 25-07-2025 | LANTAI 1 | BRUSHING       | LANTAI CONCRETE  | <br>13:51:18<br>25-Jul-2025  | <br>13:52:33<br>25-Jul-2025  | <br>13:52:47<br>25-Jul-2025  |
| 10 | 25-07-2025 | LANTAI 1 | SPOTTING       | AC GRILL         | <br>19:39:59<br>25-Jul-2025 | <br>19:40:30<br>25-Jul-2025 | <br>19:40:52<br>25-Jul-2025 |
| 11 | 25-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH    | <br>13:53:15<br>25-Jul-2025 | <br>13:53:55<br>25-Jul-2025 | <br>13:54:07<br>25-Jul-2025 |
| 12 | 25-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK | <br>19:32:22<br>25-Jul-2025 | <br>19:32:44<br>25-Jul-2025 | <br>19:33:00<br>25-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-----------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 25-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR    | <br>19:14:43<br>25-Jul-2025   | <br>19:15:03<br>25-Jul-2025   | <br>19:15:33<br>25-Jul-2025   |
| 14 | 25-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK              | <br>19:29:18<br>25-Jul-2025   | <br>19:29:32<br>25-Jul-2025   | <br>19:29:49<br>25-Jul-2025   |
| 15 | 25-07-2025 | BASEMENT | HIGH DUSTING   | OUTDOOR AC                  | <br>19:12:46<br>25-Jul-2025  | <br>19:13:09<br>25-Jul-2025  | <br>19:13:32<br>25-Jul-2025  |
| 16 | 25-07-2025 | BASEMENT | WALL CLEANING  | DINDING CAT PARKIR BASEMENT | <br>19:33:41<br>25-Jul-2025 | <br>19:34:06<br>25-Jul-2025 | <br>19:34:25<br>25-Jul-2025 |
| 17 | 25-07-2025 | BASEMENT | POLISHING      | TUTUP SAMPIT                | <br>21:25:39<br>25-Jul-2025 | <br>21:25:03<br>25-Jul-2025 | <br>21:25:58<br>25-Jul-2025 |
| 18 | 25-07-2025 | BASEMENT | BRUSHING       | DINDING PLANTER BOX         | <br>13:56:46<br>25-Jul-2025 | <br>13:56:56<br>25-Jul-2025 | <br>13:57:06<br>25-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 19 | 25-07-2025 | BASEMENT | WASHING        | LANTAI EPOXY         |    |    |    |
| 20 | 25-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         |    |    |    |
| 21 | 25-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            |   |   |   |
| 22 | 25-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         |  |  |  |
| 23 | 25-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          |  |  |  |
| 24 | 25-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR |  |  |  |

| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 25-07-2025 | EXTERNAL          | BRUSHING         | BATU ALAM                | <br>21:23:06<br>25-Jul-2025   | <br>21:23:25<br>25-Jul-2025   | <br>21:23:39<br>25-Jul-2025   |
| 26 | 25-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | CEILING                  | <br>13:54:48<br>25-Jul-2025   | <br>13:55:07<br>25-Jul-2025   | <br>13:55:17<br>25-Jul-2025   |
| 27 | 25-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU             | <br>19:16:55<br>25-Jul-2025  | <br>19:17:18<br>25-Jul-2025  | <br>19:17:41<br>25-Jul-2025  |
| 28 | 25-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | COVER LAMP               | <br>13:01:09<br>25-Jul-2025 | <br>13:01:52<br>25-Jul-2025 | <br>13:02:13<br>25-Jul-2025 |
| 29 | 25-07-2025 | CARPARK P1-P2     | HIGH DUSTING     | OUTDOOR AC               | <br>13:55:49<br>25-Jul-2025 | <br>13:56:00<br>25-Jul-2025 | <br>13:56:09<br>25-Jul-2025 |
| 30 | 25-07-2025 | CARPARK P1-P2     | POLISHING        | BODY STAINLESS ESCALATOR | <br>19:18:23<br>25-Jul-2025 | <br>19:18:37<br>25-Jul-2025 | <br>19:18:54<br>25-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 25-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         | <br>19:27:13<br>25-Jul-2025   | <br>19:27:45<br>25-Jul-2025   | <br>19:28:06<br>25-Jul-2025   |
| 32 | 25-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            | <br>21:26:39<br>25-Jul-2025   | <br>21:26:55<br>25-Jul-2025   | <br>21:27:13<br>25-Jul-2025   |
| 33 | 25-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         | <br>19:22:31<br>25-Jul-2025  | <br>19:22:55<br>25-Jul-2025  | <br>19:23:41<br>25-Jul-2025  |
| 34 | 25-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          | <br>19:44:51<br>25-Jul-2025 | <br>19:45:19<br>25-Jul-2025 | <br>19:45:49<br>25-Jul-2025 |
| 35 | 25-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR | <br>18:37:11<br>25-Jul-2025 | <br>18:37:50<br>25-Jul-2025 | <br>18:38:18<br>25-Jul-2025 |
| 36 | 25-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM            | <br>21:27:38<br>25-Jul-2025 | <br>21:27:52<br>25-Jul-2025 | <br>21:28:10<br>25-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 25-07-2025 | EXTERNAL | BRUSHING       | LANTAI BETON         | <br>19:25:46<br>25-Jul-2025   | <br>19:26:03<br>25-Jul-2025   | <br>19:26:20<br>25-Jul-2025   |
| 38 | 25-07-2025 | EXTERNAL | WALL CLEANING  | BATU ALAM            | <br>21:28:33<br>25-Jul-2025   | <br>21:28:47<br>25-Jul-2025   | <br>21:29:04<br>25-Jul-2025   |
| 39 | 25-07-2025 | EXTERNAL | POLISHING      | LANTAI BETON         | <br>19:20:12<br>25-Jul-2025  | <br>19:20:34<br>25-Jul-2025  | <br>19:21:07<br>25-Jul-2025  |
| 40 | 25-07-2025 | EXTERNAL | WALL CLEANING  | DINDING CAT          | <br>19:40:40<br>25-Jul-2025 | <br>19:41:02<br>25-Jul-2025 | <br>19:41:28<br>25-Jul-2025 |
| 41 | 25-07-2025 | EXTERNAL | POLISHING      | BOX HYDRANT DAN APAR | <br>18:39:58<br>25-Jul-2025 | <br>18:40:19<br>25-Jul-2025 | <br>18:40:49<br>25-Jul-2025 |
| 42 | 25-07-2025 | EXTERNAL | BRUSHING       | BATU ALAM            | <br>21:30:07<br>25-Jul-2025 | <br>21:30:26<br>25-Jul-2025 | <br>21:30:46<br>25-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 28-07-2025 | LANTAI 3 | POLISHING      | URINOIR                 | <br>11:28:34<br>28-Jul-2025   | <br>11:28:55<br>28-Jul-2025   | <br>11:29:14<br>28-Jul-2025   |
| 2  | 28-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH           | <br>18:33:36<br>28-Jul-2025   | <br>18:34:29<br>28-Jul-2025   | <br>18:35:47<br>28-Jul-2025   |
| 3  | 28-07-2025 | LANTAI 3 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>11:21:33<br>28-Jul-2025  | <br>11:21:49<br>28-Jul-2025  | <br>11:22:14<br>28-Jul-2025  |
| 4  | 28-07-2025 | LANTAI 3 | POLISHING      | TRAY                    | <br>11:29:43<br>28-Jul-2025 | <br>11:29:54<br>28-Jul-2025 | <br>11:30:10<br>28-Jul-2025 |
| 5  | 28-07-2025 | LANTAI 3 | POLISHING      | CLOSET                  | <br>18:38:32<br>28-Jul-2025 | <br>18:37:42<br>28-Jul-2025 | <br>18:39:21<br>28-Jul-2025 |
| 6  | 28-07-2025 | LANTAI 2 | SPOTTING       | SOFA                    | <br>11:41:34<br>28-Jul-2025 | <br>11:41:48<br>28-Jul-2025 | <br>11:41:58<br>28-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 28-07-2025 | LANTAI 2 | WALL CLEANING  | PINTU LIFT          | <br>18:54:08<br>28-Jul-2025   | <br>18:54:31<br>28-Jul-2025   | <br>18:54:53<br>28-Jul-2025   |
| 8  | 28-07-2025 | LANTAI 2 | BRUSHING       | LANTAI GRANIT BAKAR | <br>19:10:30<br>28-Jul-2025   | <br>19:10:51<br>28-Jul-2025   | <br>19:11:17<br>28-Jul-2025   |
| 9  | 28-07-2025 | LANTAI 2 | POLISHING      | CLOSET              | <br>11:27:04<br>28-Jul-2025  | <br>11:27:14<br>28-Jul-2025  | <br>11:27:33<br>28-Jul-2025  |
| 10 | 28-07-2025 | LANTAI 1 | HIGH DUSTING   | NEON LED            | <br>11:40:46<br>28-Jul-2025 | <br>11:41:03<br>28-Jul-2025 | <br>11:41:19<br>28-Jul-2025 |
| 11 | 28-07-2025 | LANTAI 1 | BRUSHING       | LANTAI KERAMIK      | <br>18:59:07<br>28-Jul-2025 | <br>18:59:28<br>28-Jul-2025 | <br>18:59:56<br>28-Jul-2025 |
| 12 | 28-07-2025 | LANTAI 1 | POLISHING      | KUBIKAL             | <br>11:30:52<br>28-Jul-2025 | <br>11:31:05<br>28-Jul-2025 | <br>11:31:15<br>28-Jul-2025 |







| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan  | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|-----------------|-------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 28-07-2025 | LANTAI 1 | GLASS CLEANING  | KACA              | <br>18:57:22<br>28-Jul-2025   | <br>18:57:47<br>28-Jul-2025   | <br>18:58:14<br>28-Jul-2025   |
| 14 | 28-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>18:47:39<br>28-Jul-2025   | <br>18:48:02<br>28-Jul-2025   | <br>18:48:23<br>28-Jul-2025   |
| 15 | 28-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP TURUN | <br>18:46:22<br>28-Jul-2025  | <br>18:46:50<br>28-Jul-2025  | <br>18:47:07<br>28-Jul-2025  |
| 16 | 28-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING     | <br>19:15:07<br>28-Jul-2025 | <br>19:15:29<br>28-Jul-2025 | <br>19:15:51<br>28-Jul-2025 |
| 17 | 28-07-2025 | BASEMENT | JET SPRAYING    | LANTAI RAMP NAIK  | <br>18:43:09<br>28-Jul-2025 | <br>18:43:47<br>28-Jul-2025 | <br>18:45:10<br>28-Jul-2025 |
| 18 | 28-07-2025 | BASEMENT | POLISHING       | STAINLESS BULAT   | <br>18:55:51<br>28-Jul-2025 | <br>18:56:12<br>28-Jul-2025 | <br>18:56:29<br>28-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 28-07-2025 | BASEMENT | POLISHING      | TUTUP SAMPIT     | <br>23:04:07<br>28-Jul-2025   | <br>23:04:31<br>28-Jul-2025   | <br>23:05:27<br>28-Jul-2025   |
| 20 | 28-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP NAIK | <br>18:41:17<br>28-Jul-2025   | <br>18:41:44<br>28-Jul-2025   | <br>18:42:11<br>28-Jul-2025   |
| 21 | 28-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN          | <br>19:13:54<br>28-Jul-2025  | <br>19:14:15<br>28-Jul-2025  | <br>19:14:37<br>28-Jul-2025  |
| 22 | 28-07-2025 | BASEMENT | POLISHING      | BOX HYDRANT      | <br>18:26:21<br>28-Jul-2025 | <br>18:27:06<br>28-Jul-2025 | <br>18:27:31<br>28-Jul-2025 |
| 23 | 28-07-2025 | BASEMENT | BRUSHING       | LANTAI KERAMIK   | <br>11:39:43<br>28-Jul-2025 | <br>11:40:04<br>28-Jul-2025 | <br>11:40:22<br>28-Jul-2025 |
| 24 | 28-07-2025 | EXTERNAL | POLISHING      | PIPA HYDRANT     | <br>11:35:53<br>28-Jul-2025 | <br>11:36:03<br>28-Jul-2025 | <br>11:36:19<br>28-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 28-07-2025 | EXTERNAL | BRUSHING       | BOX HYDRANT DAN APAR | <br>17:27:14<br>28-Jul-2025   | <br>17:27:33<br>28-Jul-2025   | <br>17:27:49<br>28-Jul-2025   |
| 26 | 28-07-2025 | EXTERNAL | WALL CLEANING  | PIPA HYDRANT         | <br>18:22:31<br>28-Jul-2025   | <br>18:23:50<br>28-Jul-2025   | <br>18:24:21<br>28-Jul-2025   |
| 27 | 28-07-2025 | EXTERNAL | BRUSHING       | ALCUBON              | <br>17:22:37<br>28-Jul-2025  | <br>17:22:56<br>28-Jul-2025  | <br>17:23:13<br>28-Jul-2025  |
| 28 | 28-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER      | <br>19:02:18<br>28-Jul-2025 | <br>19:02:37<br>28-Jul-2025 | <br>19:02:54<br>28-Jul-2025 |
| 29 | 28-07-2025 | EXTERNAL | WALL CLEANING  | GUTTER               | <br>17:14:27<br>28-Jul-2025 | <br>17:14:45<br>28-Jul-2025 | <br>17:15:02<br>28-Jul-2025 |
| 30 | 28-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER      | <br>19:03:54<br>28-Jul-2025 | <br>19:04:14<br>28-Jul-2025 | <br>19:04:46<br>28-Jul-2025 |

| No | Tanggal    | Area              | Item Pekerjaan  | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|-----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 28-07-2025 | EXTERNAL          | BRUSHING        | DINDING BETON    | <br>19:12:34<br>28-Jul-2025   | <br>19:12:53<br>28-Jul-2025   | <br>19:13:14<br>28-Jul-2025   |
| 32 | 28-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING          | <br>11:23:13<br>28-Jul-2025   | <br>11:23:25<br>28-Jul-2025   | <br>11:23:46<br>28-Jul-2025   |
| 33 | 28-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | COVER LAMP       | <br>17:13:13<br>28-Jul-2025  | <br>17:13:28<br>28-Jul-2025  | <br>17:13:51<br>28-Jul-2025  |
| 34 | 28-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING  | KACA             | <br>17:11:49<br>28-Jul-2025 | <br>17:12:22<br>28-Jul-2025 | <br>17:12:42<br>28-Jul-2025 |
| 35 | 28-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING | PIPA PLUMBING    | <br>11:36:56<br>28-Jul-2025 | <br>11:37:09<br>28-Jul-2025 | <br>11:37:40<br>28-Jul-2025 |
| 36 | 28-07-2025 | MANAGEMENT OFFICE | WALL CLEANING   | DINDING          | <br>11:32:04<br>28-Jul-2025 | <br>11:32:21<br>28-Jul-2025 | <br>11:32:37<br>28-Jul-2025 |



| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|---------------|----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 28-07-2025 | CARPARK P1-P2 | POLISHING      | BODY STAINLESS ESCALATOR | <br>11:44:22<br>28-Jul-2025   | <br>11:44:50<br>28-Jul-2025   | <br>11:45:07<br>28-Jul-2025   |
| 38 | 28-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI CONCRETE          | <br>17:15:55<br>28-Jul-2025   | <br>17:17:22<br>28-Jul-2025   | <br>17:17:38<br>28-Jul-2025   |
| 39 | 28-07-2025 | CARPARK P1-P2 | BRUSHING       | LANTAI KERAMIK           | <br>17:18:12<br>28-Jul-2025  | <br>17:18:30<br>28-Jul-2025  | <br>17:18:46<br>28-Jul-2025  |
| 40 | 28-07-2025 | CARPARK P1-P2 | GLASS CLEANING | SAFETY MIRROR            | <br>11:24:27<br>28-Jul-2025 | <br>11:25:03<br>28-Jul-2025 | <br>11:25:28<br>28-Jul-2025 |
| 41 | 28-07-2025 | EXTERNAL      | POLISHING      | PIPA HYDRANT             | <br>11:34:24<br>28-Jul-2025 | <br>11:34:48<br>28-Jul-2025 | <br>11:35:09<br>28-Jul-2025 |
| 42 | 28-07-2025 | EXTERNAL      | BRUSHING       | BOX HYDRANT DAN APAR     | <br>17:19:30<br>28-Jul-2025 | <br>17:19:47<br>28-Jul-2025 | <br>17:20:03<br>28-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 43 | 28-07-2025 | EXTERNAL | WALL CLEANING    | PIPA HYDRANT     | <br>17:21:07<br>28-Jul-2025   | <br>17:21:26<br>28-Jul-2025   | <br>17:21:50<br>28-Jul-2025   |
| 44 | 28-07-2025 | EXTERNAL | BRUSHING         | ALCUBON          | <br>17:23:57<br>28-Jul-2025   | <br>17:24:13<br>28-Jul-2025   | <br>17:24:31<br>28-Jul-2025   |
| 45 | 28-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER  | <br>19:05:12<br>28-Jul-2025  | <br>19:05:30<br>28-Jul-2025  | <br>19:05:46<br>28-Jul-2025  |
| 46 | 28-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>17:09:37<br>28-Jul-2025 | <br>17:09:54<br>28-Jul-2025 | <br>17:10:13<br>28-Jul-2025 |
| 47 | 28-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER  | <br>19:07:01<br>28-Jul-2025 | <br>19:07:23<br>28-Jul-2025 | <br>19:07:40<br>28-Jul-2025 |
| 48 | 28-07-2025 | EXTERNAL | BRUSHING         | DINDING BETON    | <br>19:17:31<br>28-Jul-2025 | <br>19:18:01<br>28-Jul-2025 | <br>19:18:41<br>28-Jul-2025 |





| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 49 | 28-07-2025 | EXTERNAL | POLISHING        | PIPA HYDRANT         | <br>11:48:00<br>28-Jul-2025   | <br>11:48:11<br>28-Jul-2025   | <br>11:48:30<br>28-Jul-2025   |
| 50 | 28-07-2025 | EXTERNAL | BRUSHING         | BOX HYDRANT DAN APAR | <br>18:57:11<br>28-Jul-2025   | <br>18:57:27<br>28-Jul-2025   | <br>18:57:50<br>28-Jul-2025   |
| 51 | 28-07-2025 | EXTERNAL | WALL CLEANING    | PIPA HYDRANT         | <br>18:52:40<br>28-Jul-2025  | <br>18:53:01<br>28-Jul-2025  | <br>18:53:21<br>28-Jul-2025  |
| 52 | 28-07-2025 | EXTERNAL | BRUSHING         | ALCUBON              | <br>18:50:53<br>28-Jul-2025 | <br>18:51:12<br>28-Jul-2025 | <br>18:51:33<br>28-Jul-2025 |
| 53 | 28-07-2025 | EXTERNAL | BRUSHING         | DINDING ROASTER      | <br>19:00:46<br>28-Jul-2025 | <br>19:01:19<br>28-Jul-2025 | <br>19:01:43<br>28-Jul-2025 |
| 54 | 28-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER               | <br>17:26:06<br>28-Jul-2025 | <br>17:26:26<br>28-Jul-2025 | <br>17:26:42<br>28-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                            | Progress                                                                           | After                                                                               |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 55 | 28-07-2025 | EXTERNAL | BRUSHING       | DINDING ROASTER  |  |  |  |
| 56 | 28-07-2025 | EXTERNAL | BRUSHING       | DINDING BETON    |  |  |  |



| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 29-07-2025 | LANTAI 3 | POLISHING        | FLOOR DRAIN      | <br>11:52:08<br>29-Jul-2025   | <br>11:53:07<br>29-Jul-2025   | <br>11:53:22<br>29-Jul-2025   |
| 2  | 29-07-2025 | LANTAI 3 | WALL CLEANING    | DINDING ACP      | <br>11:47:42<br>29-Jul-2025   | <br>11:47:53<br>29-Jul-2025   | <br>11:48:12<br>29-Jul-2025   |
| 3  | 29-07-2025 | LANTAI 3 | GLASS CLEANING   | KACA RAILING     | <br>11:42:20<br>29-Jul-2025  | <br>11:42:30<br>29-Jul-2025  | <br>11:42:44<br>29-Jul-2025  |
| 4  | 29-07-2025 | LANTAI 3 | GENERAL CLEANING | DISWASHING       | <br>18:32:52<br>29-Jul-2025 | <br>18:33:28<br>29-Jul-2025 | <br>18:34:04<br>29-Jul-2025 |
| 5  | 29-07-2025 | LANTAI 2 | POLISHING        | TEMPAT SAMPAH    | <br>11:35:36<br>29-Jul-2025 | <br>11:35:52<br>29-Jul-2025 | <br>11:36:03<br>29-Jul-2025 |
| 6  | 29-07-2025 | LANTAI 2 | BRUSHING         | LANTAI CONCRETE  | <br>11:50:48<br>29-Jul-2025 | <br>11:50:59<br>29-Jul-2025 | <br>11:51:20<br>29-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|-------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 29-07-2025 | LANTAI 2 | POLISHING      | RAK ACCESORIS           | <br>18:24:29<br>29-Jul-2025   | <br>18:24:49<br>29-Jul-2025   | <br>18:25:07<br>29-Jul-2025   |
| 8  | 29-07-2025 | LANTAI 2 | GLASS CLEANING | PINTU KACA              | <br>11:41:07<br>29-Jul-2025   | <br>11:41:21<br>29-Jul-2025   | <br>11:41:41<br>29-Jul-2025   |
| 9  | 29-07-2025 | LANTAI 2 | POLISHING      | CLOSET                  | <br>18:39:33<br>29-Jul-2025  | <br>18:40:01<br>29-Jul-2025  | <br>18:40:24<br>29-Jul-2025  |
| 10 | 29-07-2025 | LANTAI 1 | POLISHING      | PINTU LIFT              | <br>18:21:00<br>29-Jul-2025 | <br>18:21:21<br>29-Jul-2025 | <br>18:21:41<br>29-Jul-2025 |
| 11 | 29-07-2025 | LANTAI 1 | POLISHING      | TEMPAT SAMPAH STAINLESS | <br>11:36:43<br>29-Jul-2025 | <br>11:37:17<br>29-Jul-2025 | <br>11:37:33<br>29-Jul-2025 |
| 12 | 29-07-2025 | LANTAI 1 | POLISHING      | WASTAFEL                | <br>18:41:56<br>29-Jul-2025 | <br>18:42:36<br>29-Jul-2025 | <br>18:43:09<br>29-Jul-2025 |







| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan  | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|-------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 29-07-2025 | LANTAI 1 | POLISHING      | PINTU EXIT        |    |    |    |
| 14 | 29-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |    |    |    |
| 15 | 29-07-2025 | BASEMENT | HIGH DUSTING   | JET FAN           |   |   |   |
| 16 | 29-07-2025 | BASEMENT | POLISHING      | LANDING ESCALATOR |  |  |  |
| 17 | 29-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG      |  |  |  |
| 18 | 29-07-2025 | BASEMENT | JET SPRAYING   | LANTAI RAMP TURUN |  |  |  |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|--------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 29-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>18:37:12<br>29-Jul-2025   | <br>18:37:39<br>29-Jul-2025   | <br>18:38:01<br>29-Jul-2025   |
| 20 | 29-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>20:11:35<br>29-Jul-2025   | <br>20:11:58<br>29-Jul-2025   | <br>20:12:21<br>29-Jul-2025   |
| 21 | 29-07-2025 | BASEMENT | WASHING        | TEMPAT SAMPAH            | <br>11:38:34<br>29-Jul-2025  | <br>11:38:44<br>29-Jul-2025  | <br>11:38:59<br>29-Jul-2025  |
| 22 | 29-07-2025 | BASEMENT | POLISHING      | BODY STAINLESS ESCALATOR | <br>18:35:46<br>29-Jul-2025 | <br>18:36:18<br>29-Jul-2025 | <br>18:36:38<br>29-Jul-2025 |
| 23 | 29-07-2025 | BASEMENT | HIGH DUSTING   | SIGN GANTUNG             | <br>11:49:06<br>29-Jul-2025 | <br>11:49:17<br>29-Jul-2025 | <br>11:49:26<br>29-Jul-2025 |
| 24 | 29-07-2025 | EXTERNAL | POLISHING      | DINDING CAT              | <br>11:44:02<br>29-Jul-2025 | <br>11:44:15<br>29-Jul-2025 | <br>11:44:24<br>29-Jul-2025 |






| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|----------------|----------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 25 | 29-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       |    |    |    |
| 26 | 29-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        |    |    |    |
| 27 | 29-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     |   |   |   |
| 28 | 29-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR |  |  |  |
| 29 | 29-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        |  |  |  |
| 30 | 29-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       |  |  |  |



| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 31 | 29-07-2025 | EXTERNAL          | BRUSHING         | ALCUBON          | <br>11:29:44<br>29-Jul-2025   | <br>11:31:11<br>29-Jul-2025   | <br>11:31:34<br>29-Jul-2025   |
| 32 | 29-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI           | <br>18:13:31<br>29-Jul-2025   | <br>18:13:49<br>29-Jul-2025   | <br>18:14:16<br>29-Jul-2025   |
| 33 | 29-07-2025 | MANAGEMENT OFFICE | PLAFON CLEANING  | PIPA PLUMBING    | <br>11:32:28<br>29-Jul-2025  | <br>11:32:48<br>29-Jul-2025  | <br>11:32:59<br>29-Jul-2025  |
| 34 | 29-07-2025 | MANAGEMENT OFFICE | WALL CLEANING    | DINDING          | <br>11:28:32<br>29-Jul-2025 | <br>11:28:49<br>29-Jul-2025 | <br>11:29:00<br>29-Jul-2025 |
| 35 | 29-07-2025 | MANAGEMENT OFFICE | GLASS CLEANING   | KACA             | <br>18:16:07<br>29-Jul-2025 | <br>18:16:28<br>29-Jul-2025 | <br>18:16:51<br>29-Jul-2025 |
| 36 | 29-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>18:14:55<br>29-Jul-2025 | <br>18:15:12<br>29-Jul-2025 | <br>18:15:29<br>29-Jul-2025 |




| No | Tanggal    | Area          | Item Pekerjaan | Detail Pekerjaan    | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|---------------|----------------|---------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 29-07-2025 | CARPARK P1-P2 | POLISHING      | RAILING             | <br>18:05:30<br>29-Jul-2025   | <br>18:06:09<br>29-Jul-2025   | <br>18:06:29<br>29-Jul-2025   |
| 38 | 29-07-2025 | CARPARK P1-P2 | POLISHING      | BOX HYDRANT         | <br>11:26:17<br>29-Jul-2025   | <br>11:27:09<br>29-Jul-2025   | <br>11:27:23<br>29-Jul-2025   |
| 39 | 29-07-2025 | CARPARK P1-P2 | POLISHING      | TUTUP SAMPIT        | <br>20:26:32<br>29-Jul-2025  | <br>20:26:52<br>29-Jul-2025  | <br>20:27:15<br>29-Jul-2025  |
| 40 | 29-07-2025 | CARPARK P1-P2 | BRUSHING       | DINDING PLANTER BOX | <br>18:10:38<br>29-Jul-2025 | <br>18:11:00<br>29-Jul-2025 | <br>18:11:21<br>29-Jul-2025 |
| 41 | 29-07-2025 | EXTERNAL      | POLISHING      | DINDING CAT         | <br>11:24:30<br>29-Jul-2025 | <br>11:25:27<br>29-Jul-2025 | <br>11:25:41<br>29-Jul-2025 |
| 42 | 29-07-2025 | EXTERNAL      | BRUSHING       | LANTAI ANDESIT      | <br>18:29:05<br>29-Jul-2025 | <br>18:29:28<br>29-Jul-2025 | <br>18:29:55<br>29-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 43 | 29-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        | <br>20:27:40<br>29-Jul-2025   | <br>20:27:56<br>29-Jul-2025   | <br>20:28:13<br>29-Jul-2025   |
| 44 | 29-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     | <br>20:25:08<br>29-Jul-2025   | <br>20:25:28<br>29-Jul-2025   | <br>20:25:54<br>29-Jul-2025   |
| 45 | 29-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR | <br>18:03:51<br>29-Jul-2025  | <br>18:04:17<br>29-Jul-2025  | <br>18:04:33<br>29-Jul-2025  |
| 46 | 29-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        | <br>20:28:36<br>29-Jul-2025 | <br>20:28:55<br>29-Jul-2025 | <br>20:29:15<br>29-Jul-2025 |
| 47 | 29-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT       | <br>18:17:51<br>29-Jul-2025 | <br>18:18:10<br>29-Jul-2025 | <br>18:18:32<br>29-Jul-2025 |
| 48 | 29-07-2025 | EXTERNAL | BRUSHING       | ALCUBON              | <br>11:46:32<br>29-Jul-2025 | <br>11:47:01<br>29-Jul-2025 | <br>11:47:14<br>29-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|----------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 49 | 29-07-2025 | EXTERNAL | POLISHING      | DINDING CAT          | <br>11:44:47<br>29-Jul-2025   | <br>11:44:58<br>29-Jul-2025   | <br>11:45:07<br>29-Jul-2025   |
| 50 | 29-07-2025 | EXTERNAL | BRUSHING       | LANTAI ANDESIT       | <br>18:27:37<br>29-Jul-2025   | <br>18:28:00<br>29-Jul-2025   | <br>18:28:20<br>29-Jul-2025   |
| 51 | 29-07-2025 | EXTERNAL | HIGH DUSTING   | DINDING BETON        | <br>20:29:56<br>29-Jul-2025  | <br>20:30:19<br>29-Jul-2025  | <br>20:30:46<br>29-Jul-2025  |
| 52 | 29-07-2025 | EXTERNAL | BRUSHING       | SIGN RAMBU JALAN     | <br>20:31:16<br>29-Jul-2025 | <br>20:31:36<br>29-Jul-2025 | <br>20:31:53<br>29-Jul-2025 |
| 53 | 29-07-2025 | EXTERNAL | WALL CLEANING  | BOX HYDRANT DAN APAR | <br>18:31:51<br>29-Jul-2025 | <br>18:32:08<br>29-Jul-2025 | <br>18:32:32<br>29-Jul-2025 |
| 54 | 29-07-2025 | EXTERNAL | WALL CLEANING  | DINDING BETON        | <br>20:32:57<br>29-Jul-2025 | <br>20:33:22<br>29-Jul-2025 | <br>20:33:41<br>29-Jul-2025 |


| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                       | Progress                                                                                                      | After                                                                                                          |
|----|------------|----------|----------------|------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|
| 55 | 29-07-2025 | EXTERNAL | POLISHING      | LANTAI ANDESIT   | <br>18:30:37<br>29-Jul-2025 | <br>18:31:00<br>29-Jul-2025 | <br>18:31:16<br>29-Jul-2025 |
| 56 | 29-07-2025 | EXTERNAL | BRUSHING       | ALCUBON          | <br>11:33:52<br>29-Jul-2025 | <br>11:34:14<br>29-Jul-2025 | <br>11:34:29<br>29-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 30-07-2025 | LANTAI 3 | POLISHING      | KUBIKAL          | <br>11:41:41<br>30-Jul-2025   | <br>11:41:52<br>30-Jul-2025   | <br>11:42:01<br>30-Jul-2025   |
| 2  | 30-07-2025 | LANTAI 3 | WALL CLEANING  | PLANTER BOX      | <br>11:58:02<br>30-Jul-2025   | <br>11:58:21<br>30-Jul-2025   | <br>11:58:30<br>30-Jul-2025   |
| 3  | 30-07-2025 | LANTAI 3 | WALL CLEANING  | PINTU LIFT       | <br>11:45:17<br>30-Jul-2025  | <br>11:45:31<br>30-Jul-2025  | <br>11:46:16<br>30-Jul-2025  |
| 4  | 30-07-2025 | LANTAI 3 | GLASS CLEANING | MIRROR           | <br>18:31:08<br>30-Jul-2025 | <br>18:31:31<br>30-Jul-2025 | <br>18:32:12<br>30-Jul-2025 |
| 5  | 30-07-2025 | LANTAI 2 | POLISHING      | CLOSET           | <br>11:29:33<br>30-Jul-2025 | <br>11:30:19<br>30-Jul-2025 | <br>11:30:30<br>30-Jul-2025 |
| 6  | 30-07-2025 | LANTAI 2 | SPOTTING       | SOFA             | <br>12:00:56<br>30-Jul-2025 | <br>12:01:12<br>30-Jul-2025 | <br>12:01:23<br>30-Jul-2025 |




| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|----------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 30-07-2025 | LANTAI 2 | SPOTTING       | FLOOR DRAIN      | <br>18:33:57<br>30-Jul-2025   | <br>18:34:41<br>30-Jul-2025   | <br>18:35:23<br>30-Jul-2025   |
| 8  | 30-07-2025 | LANTAI 2 | POLISHING      | FLOOR DRAIN      | <br>11:38:00<br>30-Jul-2025   | <br>11:38:32<br>30-Jul-2025   | <br>11:38:51<br>30-Jul-2025   |
| 9  | 30-07-2025 | LANTAI 1 | WALL CLEANING  | DINDING LIFT     | <br>11:46:51<br>30-Jul-2025  | <br>11:47:05<br>30-Jul-2025  | <br>11:47:20<br>30-Jul-2025  |
| 10 | 30-07-2025 | LANTAI 1 | HIGH DUSTING   | KIPAS            | <br>19:41:01<br>30-Jul-2025 | <br>19:41:24<br>30-Jul-2025 | <br>19:41:46<br>30-Jul-2025 |
| 11 | 30-07-2025 | LANTAI 1 | POLISHING      | CLOSET           | <br>11:40:29<br>30-Jul-2025 | <br>11:40:50<br>30-Jul-2025 | <br>11:41:04<br>30-Jul-2025 |
| 12 | 30-07-2025 | LANTAI 1 | SWEEPING       | TANGGA           | <br>18:26:11<br>30-Jul-2025 | <br>18:26:36<br>30-Jul-2025 | <br>18:27:07<br>30-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan            | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 30-07-2025 | BASEMENT | POLISHING       | BODY STAINLESS ESCALATOR    |    |    |    |
| 14 | 30-07-2025 | BASEMENT | PLAFON CLEANING | CEILING                     |    |    |    |
| 15 | 30-07-2025 | BASEMENT | WALL CLEANING   | DINDING CAT PARKIR BASEMENT |   |   |   |
| 16 | 30-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR               |  |  |  |
| 17 | 30-07-2025 | BASEMENT | WASHING         | LANTAI EPOXY                |  |  |  |
| 18 | 30-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING               |  |  |  |

| No | Tanggal    | Area     | Item Pekerjaan  | Detail Pekerjaan | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|----------|-----------------|------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 19 | 30-07-2025 | BASEMENT | WALL CLEANING   | PILAR BETON      |    |    |    |
| 20 | 30-07-2025 | BASEMENT | PLAFON CLEANING | CEILING          |    |    |    |
| 21 | 30-07-2025 | BASEMENT | PLAFON CLEANING | PIPA PLUMBING    |   |   |   |
| 22 | 30-07-2025 | BASEMENT | GLASS CLEANING  | SAFETY MIRROR    |  |  |  |
| 23 | 30-07-2025 | EXTERNAL | BRUSHING        | GUTTER           |  |  |  |
| 24 | 30-07-2025 | EXTERNAL | WALL CLEANING   | TEMPAT SAMPAH    |  |  |  |



| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|-------------------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 30-07-2025 | EXTERNAL          | WALL CLEANING    | GUTTER           | <br>19:28:58<br>30-Jul-2025   | <br>19:29:22<br>30-Jul-2025   | <br>19:29:50<br>30-Jul-2025   |
| 26 | 30-07-2025 | EXTERNAL          | POLISHING        | LANTAI ANDESIT   | <br>19:24:28<br>30-Jul-2025   | <br>19:24:51<br>30-Jul-2025   | <br>19:25:12<br>30-Jul-2025   |
| 27 | 30-07-2025 | EXTERNAL          | BRUSHING         | PIPA HYDRANT     | <br>19:27:06<br>30-Jul-2025  | <br>19:27:27<br>30-Jul-2025  | <br>19:27:47<br>30-Jul-2025  |
| 28 | 30-07-2025 | EXTERNAL          | HIGH DUSTING     | SIGN RAMBU JALAN | <br>20:03:57<br>30-Jul-2025 | <br>20:04:12<br>30-Jul-2025 | <br>20:04:29<br>30-Jul-2025 |
| 29 | 30-07-2025 | EXTERNAL          | BRUSHING         | LOGO JKTP0       | <br>12:01:55<br>30-Jul-2025 | <br>12:02:08<br>30-Jul-2025 | <br>12:02:19<br>30-Jul-2025 |
| 30 | 30-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TOILET           | <br>11:28:17<br>30-Jul-2025 | <br>11:28:43<br>30-Jul-2025 | <br>11:28:58<br>30-Jul-2025 |


| No | Tanggal    | Area              | Item Pekerjaan   | Detail Pekerjaan    | Before | Progress | After |
|----|------------|-------------------|------------------|---------------------|--------|----------|-------|
| 31 | 30-07-2025 | MANAGEMENT OFFICE | BRUSHING         | LANTAI              |        |          |       |
| 32 | 30-07-2025 | MANAGEMENT OFFICE | GENERAL CLEANING | TEMPAT WUDHU        |        |          |       |
| 33 | 30-07-2025 | CARPARK P1-P2     | POLISHING        | LANDING ESCALATOR   |        |          |       |
| 34 | 30-07-2025 | CARPARK P1-P2     | BRUSHING         | DINDING PLANTER BOX |        |          |       |
| 35 | 30-07-2025 | CARPARK P1-P2     | HIGH DUSTING     | JET FAN             |        |          |       |
| 36 | 30-07-2025 | EXTERNAL          | GENERAL CLEANING | GUTTER              |        |          |       |



| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 37 | 30-07-2025 | EXTERNAL | WALL CLEANING    | TEMPAT SAMPAH    | <br>18:39:54<br>30-Jul-2025   | <br>18:40:15<br>30-Jul-2025   | <br>18:40:59<br>30-Jul-2025   |
| 38 | 30-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>18:45:01<br>30-Jul-2025   | <br>18:45:22<br>30-Jul-2025   | <br>18:46:53<br>30-Jul-2025   |
| 39 | 30-07-2025 | EXTERNAL | POLISHING        | LANTAI ANDESIT   | <br>19:45:09<br>30-Jul-2025  | <br>19:45:28<br>30-Jul-2025  | <br>19:45:48<br>30-Jul-2025  |
| 40 | 30-07-2025 | EXTERNAL | BRUSHING         | PIPA HYDRANT     | <br>19:35:14<br>30-Jul-2025 | <br>19:35:32<br>30-Jul-2025 | <br>19:53:22<br>30-Jul-2025 |
| 41 | 30-07-2025 | EXTERNAL | HIGH DUSTING     | SIGN RAMBU JALAN | <br>20:07:56<br>30-Jul-2025 | <br>20:08:11<br>30-Jul-2025 | <br>20:08:32<br>30-Jul-2025 |
| 42 | 30-07-2025 | EXTERNAL | BRUSHING         | LOGO JKTP0       | <br>12:07:53<br>30-Jul-2025 | <br>12:08:09<br>30-Jul-2025 | <br>12:08:31<br>30-Jul-2025 |

| No | Tanggal    | Area     | Item Pekerjaan   | Detail Pekerjaan | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|----------|------------------|------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 43 | 30-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>11:55:54<br>30-Jul-2025   | <br>11:56:05<br>30-Jul-2025   | <br>11:56:59<br>30-Jul-2025   |
| 44 | 30-07-2025 | EXTERNAL | WALL CLEANING    | TEMPAT SAMPAH    | <br>19:33:30<br>30-Jul-2025   | <br>19:33:57<br>30-Jul-2025   | <br>19:34:26<br>30-Jul-2025   |
| 45 | 30-07-2025 | EXTERNAL | GENERAL CLEANING | GUTTER           | <br>19:47:39<br>30-Jul-2025  | <br>19:48:01<br>30-Jul-2025  | <br>19:48:31<br>30-Jul-2025  |
| 46 | 30-07-2025 | EXTERNAL | POLISHING        | LANTAI ANDESIT   | <br>19:32:09<br>30-Jul-2025 | <br>19:32:30<br>30-Jul-2025 | <br>19:32:57<br>30-Jul-2025 |
| 47 | 30-07-2025 | EXTERNAL | BRUSHING         | PIPA HYDRANT     | <br>19:30:41<br>30-Jul-2025 | <br>19:31:06<br>30-Jul-2025 | <br>19:31:33<br>30-Jul-2025 |
| 48 | 30-07-2025 | EXTERNAL | HIGH DUSTING     | SIGN RAMBU JALAN | <br>20:10:18<br>30-Jul-2025 | <br>20:10:34<br>30-Jul-2025 | <br>20:10:56<br>30-Jul-2025 |



| No | Tanggal    | Area     | Item Pekerjaan | Detail Pekerjaan | Before                                                                                                                | Progress                                                                                                               | After                                                                                                                   |
|----|------------|----------|----------------|------------------|-----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| 49 | 30-07-2025 | EXTERNAL | BRUSHING       | LOGO JKTPO       |  <div>12:06:13<br/>30-Jul-2025</div> |  <div>12:06:26<br/>30-Jul-2025</div> |  <div>12:06:36<br/>30-Jul-2025</div> |