






| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                                | Before | Progress | After |
|----|------------|------------------|------------------|---------------------------------------------------------------------------------|--------|----------|-------|
| 1  | 01-08-2025 | ESCALATOR        | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)                                          |        |          |       |
| 2  | 01-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2                                    |        |          |       |
| 3  | 01-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2                                  |        |          |       |
| 4  | 01-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.8-9                                      |        |          |       |
| 5  | 01-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG |        |          |       |

| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 02-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI OUT MOBIL                          | <br>07:31:12<br>02-Agu-2025   | <br>07:31:53<br>02-Agu-2025   | <br>07:35:05<br>02-Agu-2025   |
| 2  | 02-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)                          | <br>06:37:43<br>02-Agu-2025   | <br>06:39:08<br>02-Agu-2025   | <br>06:39:29<br>02-Agu-2025   |
| 3  | 02-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)                          | <br>06:40:09<br>02-Agu-2025  | <br>06:40:28<br>02-Agu-2025  | <br>06:40:48<br>02-Agu-2025  |
| 4  | 02-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG | <br>06:44:18<br>02-Agu-2025 | <br>06:43:27<br>02-Agu-2025 | <br>06:44:36<br>02-Agu-2025 |
| 5  | 02-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LT.1 & 2                        | <br>06:45:57<br>02-Agu-2025 | <br>06:46:14<br>02-Agu-2025 | <br>06:46:31<br>02-Agu-2025 |
| 6  | 02-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI KURSI BENCH MARMER LV.UG                           | <br>06:59:07<br>02-Agu-2025 | <br>06:59:29<br>02-Agu-2025 | <br>06:59:45<br>02-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                              | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 02-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG   | <br>20:31:40<br>02-Agu-2025   | <br>21:01:52<br>02-Agu-2025   | <br>20:31:59<br>02-Agu-2025   |
| 8  | 02-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG | <br>10:42:02<br>02-Agu-2025   | <br>10:43:07<br>02-Agu-2025   | <br>10:43:18<br>02-Agu-2025   |
| 9  | 02-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.LG                              | <br>08:52:24<br>02-Agu-2025  | <br>08:54:28<br>02-Agu-2025  | <br>09:15:22<br>02-Agu-2025  |
| 10 | 02-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7B                             | <br>06:53:08<br>02-Agu-2025 | <br>06:53:24<br>02-Agu-2025 | <br>06:53:44<br>02-Agu-2025 |
| 11 | 02-08-2025 | KORIDOR SHOPPING | SWEEPING         | PEMBERSIHAN SELA SELA PINTU LIFT PASSENGER LV.UG-10           | <br>21:03:11<br>02-Agu-2025 | <br>21:03:29<br>02-Agu-2025 | <br>21:04:21<br>02-Agu-2025 |
| 12 | 02-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5                | <br>10:26:53<br>02-Agu-2025 | <br>10:27:34<br>02-Agu-2025 | <br>10:27:09<br>02-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                     | Before                                                                              | Progress                                                                              | After                                                                                 |
|----|------------|------------------|----------------|------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 02-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.10            |    |    |    |
| 14 | 02-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5 |    |    |    |
| 15 | 02-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LED PROMO LV.1 S.D LV.4                      |   |   |   |
| 16 | 02-08-2025 | KORIDOR SHOPPING | SWEEPING       | PEMBERSIHAN PLANTER BOX LV.UG                        |  |  |  |
| 17 | 02-08-2025 | KORIDOR SHOPPING | DUSTING        | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1        |  |  |  |
| 18 | 02-08-2025 | KORIDOR SHOPPING | WASHING        | PENCUCIAN TRASHCAN LV.UG S.D LV.5                    |  |  |  |





| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                      | Before                                                                                                      | Progress                                                                                                      | After                                                                                                         |
|----|------------|------------------|----------------|-----------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| 19 | 02-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING VINYL LV.5                                              |  10:21:06<br>02-Agu-2025   |  10:23:07<br>02-Agu-2025   |  10:21:30<br>02-Agu-2025   |
| 20 | 02-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.UG                                   |  10:31:15<br>02-Agu-2025   |  10:31:37<br>02-Agu-2025   |  10:32:36<br>02-Agu-2025   |
| 21 | 02-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.UG                                        |  20:47:12<br>02-Agu-2025  |  21:02:17<br>02-Agu-2025  |  20:59:04<br>02-Agu-2025  |
| 22 | 02-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2 |  10:39:18<br>02-Agu-2025 |  10:40:04<br>02-Agu-2025 |  10:39:42<br>02-Agu-2025 |





| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                              | Progress                                                                              | After                                                                                 |
|----|------------|--------------|------------------|----------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 1  | 03-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.7-9 (UP&DOWN)                         |    |    |    |
| 2  | 03-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.9-10 (UP&DOWN)                        |    |    |    |
| 3  | 03-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1 |   |   |   |
| 4  | 03-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR TOILET LV.UG                                |  |  |  |
| 5  | 03-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LV.UG                          |  |  |  |
| 6  | 03-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P6A & P6B                          |  |  |  |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                     | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 03-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.3             | <br>20:17:49<br>03-Agu-2025   | <br>21:16:35<br>03-Agu-2025   | <br>20:31:59<br>03-Agu-2025   |
| 8  | 03-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.3           | <br>10:35:00<br>03-Agu-2025   | <br>10:35:18<br>03-Agu-2025   | <br>10:35:32<br>03-Agu-2025   |
| 9  | 03-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.8                      | <br>08:35:08<br>03-Agu-2025  | <br>08:34:54<br>03-Agu-2025  | <br>08:48:22<br>03-Agu-2025  |
| 10 | 03-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P8A                    | <br>03:22:18<br>03-Agu-2025 | <br>03:22:36<br>03-Agu-2025 | <br>03:22:53<br>03-Agu-2025 |
| 11 | 03-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING BADUKAN, SELA SELA HAND RALLING LV.6-10      | <br>10:23:56<br>03-Agu-2025 | <br>10:24:29<br>03-Agu-2025 | <br>10:24:08<br>03-Agu-2025 |
| 12 | 03-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.6 | <br>10:19:44<br>03-Agu-2025 | <br>10:22:40<br>03-Agu-2025 | <br>10:20:33<br>03-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                     | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 03-08-2025 | KORIDOR SHOPPING | DUSTING        | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.2 & 3                         | <br>10:30:45<br>03-Agu-2025   | <br>10:31:08<br>03-Agu-2025   | <br>10:30:57<br>03-Agu-2025   |
| 14 | 03-08-2025 | KORIDOR SHOPPING | WASHING        | PENCUCIAN TRASHCAN LV.6 S.D LV.10                                    | <br>20:54:23<br>03-Agu-2025   | <br>21:00:32<br>03-Agu-2025   | <br>20:59:45<br>03-Agu-2025   |
| 15 | 03-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING VINYL LV.6                                             | <br>10:13:13<br>03-Agu-2025  | <br>10:18:01<br>03-Agu-2025  | <br>10:13:54<br>03-Agu-2025  |
| 16 | 03-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.3                                   | <br>10:27:45<br>03-Agu-2025 | <br>10:28:56<br>03-Agu-2025 | <br>10:29:46<br>03-Agu-2025 |
| 17 | 03-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.3                                        | <br>20:21:03<br>03-Agu-2025 | <br>21:17:03<br>03-Agu-2025 | <br>20:31:20<br>03-Agu-2025 |
| 18 | 03-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.3-4-5 | <br>10:31:53<br>03-Agu-2025 | <br>10:32:17<br>03-Agu-2025 | <br>10:32:05<br>03-Agu-2025 |




| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 04-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM               | <br>07:14:37<br>04-Agu-2025   | <br>07:15:09<br>04-Agu-2025   | <br>07:17:21<br>04-Agu-2025   |
| 2  | 04-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI CONECTION TP4                     | <br>06:53:53<br>04-Agu-2025   | <br>06:55:12<br>04-Agu-2025   | <br>06:54:32<br>04-Agu-2025   |
| 3  | 04-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI MARGOYOSO                         | <br>06:55:39<br>04-Agu-2025  | <br>06:55:56<br>04-Agu-2025  | <br>06:56:19<br>04-Agu-2025  |
| 4  | 04-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI SPIRAL UP&DOWN                    | <br>06:57:56<br>04-Agu-2025 | <br>06:58:12<br>04-Agu-2025 | <br>06:58:42<br>04-Agu-2025 |
| 5  | 04-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)                        | <br>07:00:12<br>04-Agu-2025 | <br>07:00:35<br>04-Agu-2025 | <br>07:01:25<br>04-Agu-2025 |
| 6  | 04-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2 | <br>07:02:49<br>04-Agu-2025 | <br>07:02:09<br>04-Agu-2025 | <br>07:03:15<br>04-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                             | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 04-08-2025 | KRISTALISASI     | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LV.3                         | <br>07:03:43<br>04-Agu-2025   | <br>07:04:07<br>04-Agu-2025   | <br>07:04:30<br>04-Agu-2025   |
| 8  | 04-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P6A & P6B                        | <br>07:05:14<br>04-Agu-2025   | <br>07:05:30<br>04-Agu-2025   | <br>07:06:00<br>04-Agu-2025   |
| 9  | 04-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4                     | <br>21:21:53<br>04-Agu-2025  | <br>21:22:14<br>04-Agu-2025  | <br>21:22:34<br>04-Agu-2025  |
| 10 | 04-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG | <br>07:06:47<br>04-Agu-2025 | <br>07:07:03<br>04-Agu-2025 | <br>07:07:19<br>04-Agu-2025 |
| 11 | 04-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.4                   | <br>11:29:31<br>04-Agu-2025 | <br>11:29:53<br>04-Agu-2025 | <br>11:30:15<br>04-Agu-2025 |
| 12 | 04-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN PILLAR UTAMA LV.UG                               | <br>11:37:56<br>04-Agu-2025 | <br>11:38:16<br>04-Agu-2025 | <br>11:38:35<br>04-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 04-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.1                    | <br>21:24:10<br>04-Agu-2025   | <br>21:24:26<br>04-Agu-2025   | <br>21:25:02<br>04-Agu-2025   |
| 14 | 04-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5 | <br>11:39:28<br>04-Agu-2025   | <br>11:39:56<br>04-Agu-2025   | <br>11:39:45<br>04-Agu-2025   |
| 15 | 04-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1              | <br>11:35:16<br>04-Agu-2025  | <br>11:35:36<br>04-Agu-2025  | <br>11:35:26<br>04-Agu-2025  |
| 16 | 04-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1     | <br>11:33:06<br>04-Agu-2025 | <br>11:33:27<br>04-Agu-2025 | <br>11:34:08<br>04-Agu-2025 |
| 17 | 04-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7     | <br>11:20:02<br>04-Agu-2025 | <br>11:20:19<br>04-Agu-2025 | <br>11:20:45<br>04-Agu-2025 |
| 18 | 04-08-2025 | KORIDOR SHOPPING | DUSTING        | SELA SELA PILLAR UTAMA /KOLOM PILLAR LV.4 & 5            | <br>11:27:43<br>04-Agu-2025 | <br>11:28:16<br>04-Agu-2025 | <br>11:27:59<br>04-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                           | Before                                                                                                      | Progress                                                                                                     | After                                                                                                         |
|----|------------|------------------|----------------|--------------------------------------------|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| 19 | 04-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING VINYL LV.7                   |  11:17:29<br>04-Agu-2025   |  11:17:39<br>04-Agu-2025   |  11:18:10<br>04-Agu-2025   |
| 20 | 04-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.4         |  11:25:24<br>04-Agu-2025   |  11:25:45<br>04-Agu-2025   |  11:26:15<br>04-Agu-2025   |
| 21 | 04-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.4              |  21:23:05<br>04-Agu-2025  |  21:23:35<br>04-Agu-2025  |  21:23:50<br>04-Agu-2025  |
| 22 | 04-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5 |  21:28:06<br>04-Agu-2025 |  21:25:26<br>04-Agu-2025 |  21:28:25<br>04-Agu-2025 |





| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 06-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER ENTRANCE                                | <br>11:08:26<br>06-Agu-2025   | <br>11:09:07<br>06-Agu-2025   | <br>11:10:16<br>06-Agu-2025   |
| 2  | 06-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)                          | <br>06:24:16<br>06-Agu-2025   | <br>06:24:33<br>06-Agu-2025   | <br>06:25:34<br>06-Agu-2025   |
| 3  | 06-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG   | <br>06:27:50<br>06-Agu-2025  | <br>06:26:07<br>06-Agu-2025  | <br>06:28:09<br>06-Agu-2025  |
| 4  | 06-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG | <br>06:29:53<br>06-Agu-2025 | <br>06:29:26<br>06-Agu-2025 | <br>06:30:22<br>06-Agu-2025 |
| 5  | 06-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LV.5                            | <br>06:34:23<br>06-Agu-2025 | <br>06:33:55<br>06-Agu-2025 | <br>06:34:36<br>06-Agu-2025 |
| 6  | 06-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P7A & P7B                           | <br>06:43:35<br>06-Agu-2025 | <br>06:43:52<br>06-Agu-2025 | <br>06:44:13<br>06-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 06-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7   | <br>20:00:35<br>06-Agu-2025   | <br>20:00:16<br>06-Agu-2025   | <br>20:01:03<br>06-Agu-2025   |
| 8  | 06-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7 | <br>11:10:47<br>06-Agu-2025   | <br>11:10:58<br>06-Agu-2025   | <br>11:11:19<br>06-Agu-2025   |
| 9  | 06-08-2025 | CARPARK          | GENERAL CLEANING | PENCUCIAN SPIRAL CARPARK LT.4-2             | <br>06:46:09<br>06-Agu-2025  | <br>06:45:58<br>06-Agu-2025  | <br>06:45:46<br>06-Agu-2025  |
| 10 | 06-08-2025 | CARPARK          | GENERAL CLEANING | SUMPIT DAN GREASE ROOM LV.LG                | <br>06:48:09<br>06-Agu-2025 | <br>06:48:22<br>06-Agu-2025 | <br>06:48:38<br>06-Agu-2025 |
| 11 | 06-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.LG            | <br>06:50:04<br>06-Agu-2025 | <br>06:50:18<br>06-Agu-2025 | <br>06:50:31<br>06-Agu-2025 |
| 12 | 06-08-2025 | KORIDOR SHOPPING | WASHING          | BRUSHING KORIDOR LANTAI KULIT JERUK LV.3    | <br>06:51:08<br>06-Agu-2025 | <br>07:06:34<br>06-Agu-2025 | <br>07:07:17<br>06-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 06-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.4                   | <br>07:07:47<br>06-Agu-2025   | <br>07:08:10<br>06-Agu-2025   | <br>07:08:34<br>06-Agu-2025   |
| 14 | 06-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.3                      | <br>20:02:00<br>06-Agu-2025   | <br>20:02:18<br>06-Agu-2025   | <br>20:02:39<br>06-Agu-2025   |
| 15 | 06-08-2025 | KORIDOR SHOPPING | DUSTING        | SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10 | <br>20:06:50<br>06-Agu-2025  | <br>20:07:06<br>06-Agu-2025  | <br>20:07:22<br>06-Agu-2025  |
| 16 | 06-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5           | <br>11:11:50<br>06-Agu-2025 | <br>11:12:06<br>06-Agu-2025 | <br>11:12:20<br>06-Agu-2025 |
| 17 | 06-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.4-5                 | <br>15:16:25<br>06-Agu-2025 | <br>15:16:38<br>06-Agu-2025 | <br>15:16:47<br>06-Agu-2025 |
| 18 | 06-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3       | <br>20:04:47<br>06-Agu-2025 | <br>20:05:24<br>06-Agu-2025 | <br>20:06:09<br>06-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                 | Before                                                                                                      | Progress                                                                                                     | After                                                                                                         |
|----|------------|------------------|------------------|----------------------------------|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| 19 | 06-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.10        |  11:12:47<br>06-Agu-2025   |  11:12:59<br>06-Agu-2025   |  11:13:21<br>06-Agu-2025   |
| 20 | 06-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.5     |  22:49:26<br>06-Agu-2025   |  22:49:04<br>06-Agu-2025   |  22:49:59<br>06-Agu-2025   |
| 21 | 06-08-2025 | KORIDOR SHOPPING | VACUMMING        | GRILL LIFT PASSENGER LV.6 S.D 10 |  07:11:51<br>06-Agu-2025  |  07:12:10<br>06-Agu-2025  |  07:12:29<br>06-Agu-2025  |
| 22 | 06-08-2025 | KORIDOR SHOPPING | VACUMMING        | GRILL LIFT SERVICE LV.6 S.D 10   |  07:12:55<br>06-Agu-2025 |  07:13:10<br>06-Agu-2025 |  07:13:25<br>06-Agu-2025 |



| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|--------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 07-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI BAWAH UNION                                                   | <br>14:25:59<br>07-Agu-2025   | <br>14:26:30<br>07-Agu-2025   | <br>14:26:48<br>07-Agu-2025   |
| 2  | 07-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)                                                     | <br>06:22:10<br>07-Agu-2025   | <br>06:22:25<br>07-Agu-2025   | <br>07:15:14<br>07-Agu-2025   |
| 3  | 07-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SISI DEPAN TENANT UNION DAN DEPAN TENANT TOBBY'S & AREA DEPAN CONCIERGE LV.UG | <br>14:37:08<br>07-Agu-2025  | <br>07:18:27<br>07-Agu-2025  | <br>14:37:24<br>07-Agu-2025  |
| 4  | 07-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI LIFT PASSENGER A DAN B                                                        | <br>14:38:45<br>07-Agu-2025 | <br>14:39:04<br>07-Agu-2025 | <br>14:39:19<br>07-Agu-2025 |
| 5  | 07-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI LIFT SERVICE A DAN B                                                          | <br>14:50:35<br>07-Agu-2025 | <br>14:50:51<br>07-Agu-2025 | <br>14:51:08<br>07-Agu-2025 |
| 6  | 07-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1                             | <br>14:40:56<br>07-Agu-2025 | <br>14:41:18<br>07-Agu-2025 | <br>14:41:36<br>07-Agu-2025 |

| No | Tanggal    | Area         | Item Pekerjaan   | DetailPekerjaan                                                      | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 07-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE & KORIDOR CONECTION CARPARK LV.6 & 7 | <br>14:46:19<br>07-Agu-2025   | <br>14:46:37<br>07-Agu-2025   | <br>14:46:55<br>07-Agu-2025   |
| 8  | 07-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P7A & P7B                                | <br>14:42:20<br>07-Agu-2025   | <br>14:42:41<br>07-Agu-2025   | <br>14:43:07<br>07-Agu-2025   |
| 9  | 07-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10                           | <br>14:44:43<br>07-Agu-2025  | <br>14:45:00<br>07-Agu-2025  | <br>14:45:23<br>07-Agu-2025  |
| 10 | 07-08-2025 | CARPARK      | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10                         | <br>14:48:02<br>07-Agu-2025 | <br>14:48:22<br>07-Agu-2025 | <br>14:48:40<br>07-Agu-2025 |
| 11 | 07-08-2025 | CARPARK      | GENERAL CLEANING | PENCUCIAN SPIRAL CARPARK LV.2-LG                                     | <br>14:56:43<br>07-Agu-2025 | <br>14:57:01<br>07-Agu-2025 | <br>14:57:16<br>07-Agu-2025 |
| 12 | 07-08-2025 | CARPARK      | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P6A                                    | <br>14:57:47<br>07-Agu-2025 | <br>14:58:01<br>07-Agu-2025 | <br>14:58:53<br>07-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|---------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 07-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG | <br>22:37:29<br>07-Agu-2025   | <br>22:37:47<br>07-Agu-2025   | <br>22:38:10<br>07-Agu-2025   |
| 14 | 07-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.5                | <br>14:34:16<br>07-Agu-2025   | <br>14:34:43<br>07-Agu-2025   | <br>14:36:24<br>07-Agu-2025   |
| 15 | 07-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.4                   | <br>22:41:05<br>07-Agu-2025  | <br>22:40:51<br>07-Agu-2025  | <br>22:40:34<br>07-Agu-2025  |
| 16 | 07-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10       | <br>14:59:57<br>07-Agu-2025 | <br>15:00:23<br>07-Agu-2025 | <br>15:00:43<br>07-Agu-2025 |
| 17 | 07-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.6-7              | <br>15:03:31<br>07-Agu-2025 | <br>15:03:48<br>07-Agu-2025 | <br>15:04:05<br>07-Agu-2025 |
| 18 | 07-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4    | <br>22:39:17<br>07-Agu-2025 | <br>22:39:53<br>07-Agu-2025 | <br>22:40:09<br>07-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan   | DetailPekerjaan              | Before                                                                                                                | Progress                                                                                                               | After                                                                                                                   |
|----|------------|------------------|------------------|------------------------------|-----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| 19 | 07-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.4 |  <div>22:34:30<br/>07-Agu-2025</div> |  <div>22:34:06<br/>07-Agu-2025</div> |  <div>22:33:43<br/>07-Agu-2025</div> |



| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                  | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|--------------|------------------|-------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 1  | 08-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)                            |    |    |    |
| 2  | 08-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SISI DALAM CONCIERGE S/D DEPAN SERVICE KORIDOR LV.UG |    |    |    |
| 3  | 08-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2    |   |   |   |
| 4  | 08-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE 9 & 10                            |  |  |  |
| 5  | 08-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P7A & P7B                             |  |  |  |
| 6  | 08-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2                      |  |  |  |





| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                                | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 08-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2                                  | <br>13:15:36<br>08-Agu-2025   | <br>13:16:00<br>08-Agu-2025   | <br>13:16:16<br>08-Agu-2025   |
| 8  | 08-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7A                                               | <br>02:45:15<br>08-Agu-2025   | <br>02:45:54<br>08-Agu-2025   | <br>02:46:16<br>08-Agu-2025   |
| 9  | 08-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.8-9                                      | <br>13:17:01<br>08-Agu-2025  | <br>13:17:31<br>08-Agu-2025  | <br>13:17:18<br>08-Agu-2025  |
| 10 | 08-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG | <br>13:11:00<br>08-Agu-2025 | <br>13:13:12<br>08-Agu-2025 | <br>13:11:43<br>08-Agu-2025 |
| 11 | 08-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.3                                                    | <br>21:02:06<br>08-Agu-2025 | <br>21:02:32<br>08-Agu-2025 | <br>21:02:49<br>08-Agu-2025 |
| 12 | 08-08-2025 | KORIDOR SHOPPING | GLASS CLEANING   | PEMBERSIHAN KACA BAGIAN LUAR LOBBY UTAMA LV.UG                                  | <br>05:56:22<br>08-Agu-2025 | <br>05:56:38<br>08-Agu-2025 | <br>05:56:56<br>08-Agu-2025 |




| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 09-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI OUT MOBIL                          | <br>21:21:56<br>09-Agu-2025   | <br>21:22:16<br>09-Agu-2025   | <br>21:23:13<br>09-Agu-2025   |
| 2  | 09-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)                          | <br>04:14:27<br>09-Agu-2025   | <br>04:14:52<br>09-Agu-2025   | <br>04:15:16<br>09-Agu-2025   |
| 3  | 09-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)                          | <br>04:15:57<br>09-Agu-2025  | <br>04:16:12<br>09-Agu-2025  | <br>04:16:30<br>09-Agu-2025  |
| 4  | 09-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SISI DEPAN TENANT BENEFIT S/D LED PROMO LV.UG      | <br>04:22:11<br>09-Agu-2025 | <br>04:17:17<br>09-Agu-2025 | <br>04:22:29<br>09-Agu-2025 |
| 5  | 09-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG | <br>04:23:05<br>09-Agu-2025 | <br>04:18:50<br>09-Agu-2025 | <br>04:23:30<br>09-Agu-2025 |
| 6  | 09-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI KURSI BENCH MARMER LV.1                            | <br>04:21:17<br>09-Agu-2025 | <br>04:20:02<br>09-Agu-2025 | <br>04:21:30<br>09-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                              | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 09-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P8A                               | <br>04:24:16<br>09-Agu-2025   | <br>04:24:32<br>09-Agu-2025   | <br>04:24:47<br>09-Agu-2025   |
| 8  | 09-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG   | <br>20:52:34<br>09-Agu-2025   | <br>20:53:18<br>09-Agu-2025   | <br>20:52:51<br>09-Agu-2025   |
| 9  | 09-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG | <br>10:35:24<br>09-Agu-2025  | <br>10:35:38<br>09-Agu-2025  | <br>10:35:51<br>09-Agu-2025  |
| 10 | 09-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.LG                              | <br>09:09:11<br>09-Agu-2025 | <br>09:22:05<br>09-Agu-2025 | <br>09:26:30<br>09-Agu-2025 |
| 11 | 09-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7B                             | <br>04:26:43<br>09-Agu-2025 | <br>04:27:02<br>09-Agu-2025 | <br>04:27:19<br>09-Agu-2025 |
| 12 | 09-08-2025 | KORIDOR SHOPPING | CELLING          | CELLING AREA KORIDOR SHOPPING LV.1-5                          | <br>10:43:44<br>09-Agu-2025 | <br>10:44:03<br>09-Agu-2025 | <br>10:44:56<br>09-Agu-2025 |






| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                     | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 09-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5       | <br>10:39:31<br>09-Agu-2025   | <br>10:40:07<br>09-Agu-2025   | <br>10:39:50<br>09-Agu-2025   |
| 14 | 09-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.UG-1    | <br>10:33:30<br>09-Agu-2025   | <br>10:34:04<br>09-Agu-2025   | <br>10:33:44<br>09-Agu-2025   |
| 15 | 09-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.10            | <br>10:38:18<br>09-Agu-2025  | <br>10:39:05<br>09-Agu-2025  | <br>10:38:49<br>09-Agu-2025  |
| 16 | 09-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5 | <br>10:17:37<br>09-Agu-2025 | <br>10:17:55<br>09-Agu-2025 | <br>10:18:47<br>09-Agu-2025 |
| 17 | 09-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LED PROMO LV.1 S.D LV.4                      | <br>10:42:02<br>09-Agu-2025 | <br>10:42:27<br>09-Agu-2025 | <br>10:42:12<br>09-Agu-2025 |
| 18 | 09-08-2025 | KORIDOR SHOPPING | SWEEPING       | PEMBERSIHAN PLANTER BOX LV.UG                        | <br>10:28:00<br>09-Agu-2025 | <br>10:28:34<br>09-Agu-2025 | <br>10:28:20<br>09-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                                | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 09-08-2025 | KORIDOR SHOPPING | DUSTING          | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1                                   | <br>10:32:31<br>09-Agu-2025   | <br>10:32:59<br>09-Agu-2025   | <br>10:32:43<br>09-Agu-2025   |
| 20 | 09-08-2025 | KORIDOR SHOPPING | WASHING          | PENCUCIAN TRASHCAN LV.UG S.D LV.5                                               | <br>19:34:48<br>09-Agu-2025   | <br>20:53:42<br>09-Agu-2025   | <br>19:41:43<br>09-Agu-2025   |
| 21 | 09-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.5                                                        | <br>10:20:00<br>09-Agu-2025  | <br>10:20:23<br>09-Agu-2025  | <br>10:21:21<br>09-Agu-2025  |
| 22 | 09-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN DINDING KORIDOR SERVICE LV.LG-10                                    | <br>21:00:19<br>09-Agu-2025 | <br>20:59:48<br>09-Agu-2025 | <br>21:00:33<br>09-Agu-2025 |
| 23 | 09-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN SUDUT LANTAI KORIDOR SERVICE LV.6-10                                | <br>20:58:14<br>09-Agu-2025 | <br>20:59:14<br>09-Agu-2025 | <br>20:58:30<br>09-Agu-2025 |
| 24 | 09-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | PEMBERSIHAN TANGGA EXIT 24 SISI UNION,LC WAIKIKI,KID STATION,SUSHI TEI LV.LG-10 | <br>10:30:08<br>09-Agu-2025 | <br>10:30:29<br>09-Agu-2025 | <br>10:30:52<br>09-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                      | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|-----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 09-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.UG                                   | <br>10:25:19<br>09-Agu-2025   | <br>10:25:42<br>09-Agu-2025   | <br>10:26:24<br>09-Agu-2025   |
| 26 | 09-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.UG                                        | <br>20:54:54<br>09-Agu-2025   | <br>20:54:23<br>09-Agu-2025   | <br>20:55:20<br>09-Agu-2025   |
| 27 | 09-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2 | <br>10:40:54<br>09-Agu-2025  | <br>10:41:16<br>09-Agu-2025  | <br>10:41:04<br>09-Agu-2025  |
| 28 | 09-08-2025 | KORIDOR SHOPPING | DUSTING        | DINDING BAGIAN LUAR LOBBY LV.UG                                       | <br>04:28:27<br>09-Agu-2025 | <br>04:28:46<br>09-Agu-2025 | <br>04:29:02<br>09-Agu-2025 |
| 29 | 09-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SELA SELA PINTU LIFT SERVICE LV.LG-10                     | <br>10:46:11<br>09-Agu-2025 | <br>10:46:24<br>09-Agu-2025 | <br>10:46:47<br>09-Agu-2025 |



| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 11-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM               | <br>14:17:57<br>11-Agu-2025   | <br>14:18:10<br>11-Agu-2025   | <br>14:18:27<br>11-Agu-2025   |
| 2  | 11-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI CONECTION TP4                     | <br>03:21:13<br>11-Agu-2025   | <br>03:21:28<br>11-Agu-2025   | <br>03:21:53<br>11-Agu-2025   |
| 3  | 11-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI MARGOYOSO                         | <br>06:06:35<br>11-Agu-2025  | <br>06:06:56<br>11-Agu-2025  | <br>06:07:15<br>11-Agu-2025  |
| 4  | 11-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)                        | <br>03:25:46<br>11-Agu-2025 | <br>03:26:04<br>11-Agu-2025 | <br>03:26:19<br>11-Agu-2025 |
| 5  | 11-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.1           | <br>03:33:24<br>11-Agu-2025 | <br>03:29:19<br>11-Agu-2025 | <br>03:33:36<br>11-Agu-2025 |
| 6  | 11-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2 | <br>03:33:55<br>11-Agu-2025 | <br>03:27:10<br>11-Agu-2025 | <br>03:34:06<br>11-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                             | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 11-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P8A                              | <br>03:27:54<br>11-Agu-2025   | <br>03:28:25<br>11-Agu-2025   | <br>03:28:52<br>11-Agu-2025   |
| 8  | 11-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4                     | <br>21:28:34<br>11-Agu-2025   | <br>20:46:04<br>11-Agu-2025   | <br>21:28:48<br>11-Agu-2025   |
| 9  | 11-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG | <br>03:35:03<br>11-Agu-2025  | <br>03:35:17<br>11-Agu-2025  | <br>03:35:34<br>11-Agu-2025  |
| 10 | 11-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.4                   | <br>11:11:23<br>11-Agu-2025 | <br>11:12:00<br>11-Agu-2025 | <br>11:12:37<br>11-Agu-2025 |
| 11 | 11-08-2025 | KORIDOR SHOPPING | CELLING          | CELLING AREA LOBBY LV.UG                                     | <br>11:36:02<br>11-Agu-2025 | <br>11:36:25<br>11-Agu-2025 | <br>11:36:15<br>11-Agu-2025 |
| 12 | 11-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN PILLAR UTAMA LV.UG                               | <br>11:33:50<br>11-Agu-2025 | <br>11:34:10<br>11-Agu-2025 | <br>11:34:24<br>11-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 11-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT UNION LV.UG        | <br>03:29:56<br>11-Agu-2025   | <br>06:19:10<br>11-Agu-2025   | <br>06:19:29<br>11-Agu-2025   |
| 14 | 11-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.1                          | <br>20:42:37<br>11-Agu-2025   | <br>20:43:12<br>11-Agu-2025   | <br>20:43:30<br>11-Agu-2025   |
| 15 | 11-08-2025 | KORIDOR SHOPPING | SWEEPING       | SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10 | <br>11:26:04<br>11-Agu-2025  | <br>11:26:37<br>11-Agu-2025  | <br>11:26:28<br>11-Agu-2025  |
| 16 | 11-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5       | <br>11:28:00<br>11-Agu-2025 | <br>11:29:12<br>11-Agu-2025 | <br>11:28:54<br>11-Agu-2025 |
| 17 | 11-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5               | <br>11:15:59<br>11-Agu-2025 | <br>11:16:19<br>11-Agu-2025 | <br>11:16:11<br>11-Agu-2025 |
| 18 | 11-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1                    | <br>11:35:03<br>11-Agu-2025 | <br>11:35:28<br>11-Agu-2025 | <br>11:35:16<br>11-Agu-2025 |






| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                 | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 11-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1             | <br>20:44:28<br>11-Agu-2025   | <br>20:45:18<br>11-Agu-2025   | <br>20:44:55<br>11-Agu-2025   |
| 20 | 11-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7             | <br>11:24:08<br>11-Agu-2025   | <br>11:24:40<br>11-Agu-2025   | <br>11:24:57<br>11-Agu-2025   |
| 21 | 11-08-2025 | KORIDOR SHOPPING | DUSTING          | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5                     | <br>11:17:41<br>11-Agu-2025  | <br>11:17:59<br>11-Agu-2025  | <br>11:17:50<br>11-Agu-2025  |
| 22 | 11-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.7                                         | <br>11:21:33<br>11-Agu-2025 | <br>11:22:15<br>11-Agu-2025 | <br>11:22:29<br>11-Agu-2025 |
| 23 | 11-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10                 | <br>20:51:48<br>11-Agu-2025 | <br>20:51:26<br>11-Agu-2025 | <br>20:52:13<br>11-Agu-2025 |
| 24 | 11-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10 | <br>14:17:04<br>11-Agu-2025 | <br>14:17:24<br>11-Agu-2025 | <br>14:17:35<br>11-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|--------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 11-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN DINDING KORIDOR EXIT LV.LG-10  | <br>14:19:46<br>11-Agu-2025   | <br>14:20:30<br>11-Agu-2025   | <br>14:20:53<br>11-Agu-2025   |
| 26 | 11-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.4         | <br>11:14:21<br>11-Agu-2025   | <br>11:15:12<br>11-Agu-2025   | <br>11:15:23<br>11-Agu-2025   |
| 27 | 11-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.4              | <br>21:29:41<br>11-Agu-2025  | <br>20:53:49<br>11-Agu-2025  | <br>21:29:53<br>11-Agu-2025  |
| 28 | 11-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN PLAFON/ATAP HPL LV.2           | <br>20:47:16<br>11-Agu-2025 | <br>20:47:57<br>11-Agu-2025 | <br>20:47:32<br>11-Agu-2025 |
| 29 | 11-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5 | <br>20:52:57<br>11-Agu-2025 | <br>20:52:37<br>11-Agu-2025 | <br>20:53:20<br>11-Agu-2025 |



| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                          | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 12-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER RUMP UP DROP OUT                  | <br>07:14:52<br>12-Agu-2025   | <br>07:15:35<br>12-Agu-2025   | <br>07:17:12<br>12-Agu-2025   |
| 2  | 12-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)                   | <br>06:37:18<br>12-Agu-2025   | <br>06:37:32<br>12-Agu-2025   | <br>06:37:49<br>12-Agu-2025   |
| 3  | 12-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MEJA VALET LV.UG                             | <br>06:47:31<br>12-Agu-2025  | <br>06:39:58<br>12-Agu-2025  | <br>06:47:47<br>12-Agu-2025  |
| 4  | 12-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SELA/SUDUT CLOSET TOILET MALE FEMALE DISABLE | <br>06:40:44<br>12-Agu-2025 | <br>06:41:00<br>12-Agu-2025 | <br>06:41:16<br>12-Agu-2025 |
| 5  | 12-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.LG                            | <br>06:42:00<br>12-Agu-2025 | <br>06:42:25<br>12-Agu-2025 | <br>06:42:59<br>12-Agu-2025 |
| 6  | 12-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5                  | <br>20:56:20<br>12-Agu-2025 | <br>20:56:02<br>12-Agu-2025 | <br>20:58:51<br>12-Agu-2025 |






| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                          | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 12-08-2025 | CARPARK          | WALL CLEANING  | WALL CLEANING AREA DEPAN LIFT SERVICE LV.5                | <br>11:21:37<br>12-Agu-2025   | <br>11:21:59<br>12-Agu-2025   | <br>11:22:25<br>12-Agu-2025   |
| 8  | 12-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT TOBY'S LV.UG  | <br>06:44:40<br>12-Agu-2025   | <br>06:44:55<br>12-Agu-2025   | <br>06:45:34<br>12-Agu-2025   |
| 9  | 12-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.1                  | <br>06:46:05<br>12-Agu-2025  | <br>06:46:17<br>12-Agu-2025  | <br>06:46:32<br>12-Agu-2025  |
| 10 | 12-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.2                     | <br>20:54:57<br>12-Agu-2025 | <br>20:55:13<br>12-Agu-2025 | <br>20:55:28<br>12-Agu-2025 |
| 11 | 12-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10 | <br>11:47:09<br>12-Agu-2025 | <br>11:48:33<br>12-Agu-2025 | <br>11:49:51<br>12-Agu-2025 |
| 12 | 12-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.6-7          | <br>11:40:30<br>12-Agu-2025 | <br>11:41:09<br>12-Agu-2025 | <br>11:40:44<br>12-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                      | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|-------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 12-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.2-3            | <br>12:20:57<br>12-Agu-2025   | <br>12:21:20<br>12-Agu-2025   | <br>12:21:09<br>12-Agu-2025   |
| 14 | 12-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2  | <br>11:36:36<br>12-Agu-2025   | <br>11:36:50<br>12-Agu-2025   | <br>11:37:29<br>12-Agu-2025   |
| 15 | 12-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10 | <br>11:29:41<br>12-Agu-2025  | <br>11:30:02<br>12-Agu-2025  | <br>11:30:31<br>12-Agu-2025  |
| 16 | 12-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING VINYL LV.9                              | <br>11:32:05<br>12-Agu-2025 | <br>11:32:42<br>12-Agu-2025 | <br>11:33:05<br>12-Agu-2025 |
| 17 | 12-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.5                    | <br>11:24:19<br>12-Agu-2025 | <br>11:24:51<br>12-Agu-2025 | <br>11:25:33<br>12-Agu-2025 |
| 18 | 12-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.5                         | <br>20:56:52<br>12-Agu-2025 | <br>20:57:11<br>12-Agu-2025 | <br>20:57:28<br>12-Agu-2025 |






| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|--------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 12-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | PEMBERSIHAN BASS ROOM LV.7                 | <br>10:21:01<br>12-Agu-2025   | <br>10:21:57<br>12-Agu-2025   | <br>10:21:18<br>12-Agu-2025   |
| 20 | 12-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN PLAFON/ATAP HPL LV.3           | <br>20:54:15<br>12-Agu-2025   | <br>20:53:57<br>12-Agu-2025   | <br>20:54:31<br>12-Agu-2025   |
| 21 | 12-08-2025 | KORIDOR SHOPPING | DUSTING          | LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG | <br>09:09:23<br>12-Agu-2025  | <br>09:11:19<br>12-Agu-2025  | <br>09:10:17<br>12-Agu-2025  |
| 22 | 12-08-2025 | KORIDOR SHOPPING | DUSTING          | LEMARI DISPLAY AREA LOBBY LV.UG            | <br>09:15:45<br>12-Agu-2025 | <br>09:15:01<br>12-Agu-2025 | <br>09:16:16<br>12-Agu-2025 |




| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 13-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER ENTRANCE                                | <br>07:12:27<br>13-Agu-2025   | <br>07:13:22<br>13-Agu-2025   | <br>07:23:31<br>13-Agu-2025   |
| 2  | 13-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)                          | <br>06:45:45<br>13-Agu-2025   | <br>06:45:58<br>13-Agu-2025   | <br>06:46:10<br>13-Agu-2025   |
| 3  | 13-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG   | <br>07:02:31<br>13-Agu-2025  | <br>06:46:31<br>13-Agu-2025  | <br>07:02:47<br>13-Agu-2025  |
| 4  | 13-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG | <br>07:03:26<br>13-Agu-2025 | <br>06:47:12<br>13-Agu-2025 | <br>07:03:39<br>13-Agu-2025 |
| 5  | 13-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SELA SELA/SUDUT CLOSET TOILET MALE FEMALE          | <br>06:47:43<br>13-Agu-2025 | <br>06:47:55<br>13-Agu-2025 | <br>06:48:07<br>13-Agu-2025 |
| 6  | 13-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.LG                                  | <br>06:48:43<br>13-Agu-2025 | <br>06:48:57<br>13-Agu-2025 | <br>06:49:10<br>13-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 13-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7                | <br>22:52:14<br>13-Agu-2025   | <br>22:52:24<br>13-Agu-2025   | <br>22:52:34<br>13-Agu-2025   |
| 8  | 13-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7              | <br>09:09:20<br>13-Agu-2025   | <br>10:48:48<br>13-Agu-2025   | <br>09:08:37<br>13-Agu-2025   |
| 9  | 13-08-2025 | CARPARK          | GENERAL CLEANING | SUMPIT DAN GREASE ROOM LV.LG                             | <br>06:52:09<br>13-Agu-2025  | <br>06:52:22<br>13-Agu-2025  | <br>06:52:36<br>13-Agu-2025  |
| 10 | 13-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.LG                         | <br>06:53:33<br>13-Agu-2025 | <br>06:53:48<br>13-Agu-2025 | <br>06:54:00<br>13-Agu-2025 |
| 11 | 13-08-2025 | KORIDOR SHOPPING | GLASS CLEANING   | PEMBERSIHAN KACA SHOFRONT SISI DEPAN TENANT TOBY'S LV.UG | <br>07:01:12<br>13-Agu-2025 | <br>07:01:36<br>13-Agu-2025 | <br>07:01:50<br>13-Agu-2025 |
| 12 | 13-08-2025 | KORIDOR SHOPPING | WASHING          | BRUSHING KORIDOR LANTAI KULIT JERUK LV.3                 | <br>06:54:59<br>13-Agu-2025 | <br>06:55:11<br>13-Agu-2025 | <br>06:55:23<br>13-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                           | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|------------------|----------------|------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 13-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.4                   |    |    |    |
| 14 | 13-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.3                      |    |    |    |
| 15 | 13-08-2025 | KORIDOR SHOPPING | DUSTING        | SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10 |   |   |   |
| 16 | 13-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5           |  |  |  |
| 17 | 13-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9           |  |  |  |
| 18 | 13-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.4-5                 |  |  |  |

| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 13-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3 | <br>22:52:59<br>13-Agu-2025   | <br>22:53:07<br>13-Agu-2025   | <br>22:53:18<br>13-Agu-2025   |
| 20 | 13-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.10                            | <br>09:02:12<br>13-Agu-2025   | <br>10:46:36<br>13-Agu-2025   | <br>09:01:47<br>13-Agu-2025   |
| 21 | 13-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.5                         | <br>22:51:01<br>13-Agu-2025  | <br>22:51:09<br>13-Agu-2025  | <br>22:51:18<br>13-Agu-2025  |
| 22 | 13-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN PLAFON/ATAP HPL LV.4                     | <br>22:53:39<br>13-Agu-2025 | <br>22:53:47<br>13-Agu-2025 | <br>22:53:56<br>13-Agu-2025 |




| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 14-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI BAWAH UNION                       | <br>07:04:29<br>14-Agu-2025   | <br>07:06:02<br>14-Agu-2025   | <br>07:06:47<br>14-Agu-2025   |
| 2  | 14-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)                         | <br>06:34:29<br>14-Agu-2025   | <br>06:34:43<br>14-Agu-2025   | <br>06:34:59<br>14-Agu-2025   |
| 3  | 14-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1 | <br>06:48:54<br>14-Agu-2025  | <br>06:36:58<br>14-Agu-2025  | <br>06:49:11<br>14-Agu-2025  |
| 4  | 14-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SELA/SUDUT CLOSET TOILET MALE FEMALE DISABLE      | <br>06:37:39<br>14-Agu-2025 | <br>06:38:01<br>14-Agu-2025 | <br>06:38:18<br>14-Agu-2025 |
| 5  | 14-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.LG                                 | <br>06:39:03<br>14-Agu-2025 | <br>06:39:17<br>14-Agu-2025 | <br>06:39:29<br>14-Agu-2025 |
| 6  | 14-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10                     | <br>22:51:27<br>14-Agu-2025 | <br>22:51:42<br>14-Agu-2025 | <br>22:51:57<br>14-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|---------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 14-08-2025 | CARPARK          | WALL CLEANING  | WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10            | <br>11:13:27<br>14-Agu-2025   | <br>11:14:00<br>14-Agu-2025   | <br>11:14:34<br>14-Agu-2025   |
| 8  | 14-08-2025 | CARPARK          | WASHING        | PENCUCIAN TRASHCAN CARPARK LV.P6A                       | <br>06:40:27<br>14-Agu-2025   | <br>06:40:40<br>14-Agu-2025   | <br>06:40:52<br>14-Agu-2025   |
| 9  | 14-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG | <br>22:48:49<br>14-Agu-2025  | <br>22:48:59<br>14-Agu-2025  | <br>22:49:11<br>14-Agu-2025  |
| 10 | 14-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | PEMBERSIHAN KACA ATAS PINTU REVOLVING LOBBY LV.UG       | <br>06:44:36<br>14-Agu-2025 | <br>06:45:00<br>14-Agu-2025 | <br>06:45:18<br>14-Agu-2025 |
| 11 | 14-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.5                | <br>06:46:56<br>14-Agu-2025 | <br>06:47:12<br>14-Agu-2025 | <br>06:47:27<br>14-Agu-2025 |
| 12 | 14-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.4                   | <br>22:50:49<br>14-Agu-2025 | <br>22:50:56<br>14-Agu-2025 | <br>22:51:04<br>14-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                     | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|------------------|------------------|------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 13 | 14-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10    |    |    |    |
| 14 | 14-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10      |    |    |    |
| 15 | 14-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.6-7           |   |   |   |
| 16 | 14-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4 |  |  |  |
| 17 | 14-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.4                         |  |  |  |
| 18 | 14-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN PLAFON/ATAP HPL LV.5                     |  |  |  |




| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                                                                             | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|--------------|------------------|------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 1  | 15-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)                                                                                       |    |    |    |
| 2  | 15-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI DARI LANDING ESCALATOR DEPAN TENANT M&S - ARAH KE TENANT COAST / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.1 |    |    |    |
| 3  | 15-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2                                                               |   |   |   |
| 4  | 15-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2                                                                                 |  |  |  |
| 5  | 15-08-2025 | CARPARK      | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2                                                                               |  |  |  |
| 6  | 15-08-2025 | CARPARK      | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7A                                                                                            |  |  |  |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                                | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 15-08-2025 | KORIDOR SHOPPING | GLASS CLEANING   | PEMBERSIHAN KACA CANOPY + GUTTER LV.UG                                          | <br>07:05:57<br>15-Agu-2025   | <br>07:06:11<br>15-Agu-2025   | <br>07:06:25<br>15-Agu-2025   |
| 8  | 15-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.8-9                                      | <br>11:23:11<br>15-Agu-2025   | <br>11:23:40<br>15-Agu-2025   | <br>11:23:23<br>15-Agu-2025   |
| 9  | 15-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG | <br>11:17:05<br>15-Agu-2025  | <br>11:17:38<br>15-Agu-2025  | <br>11:18:42<br>15-Agu-2025  |
| 10 | 15-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.3                                                    | <br>21:34:34<br>15-Agu-2025 | <br>21:34:52<br>15-Agu-2025 | <br>21:35:12<br>15-Agu-2025 |


| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                                 | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 16-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI OUT MOBIL                                           | <br>21:45:43<br>16-Agu-2025   | <br>21:46:02<br>16-Agu-2025   | <br>21:46:26<br>16-Agu-2025   |
| 2  | 16-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)                                           | <br>03:57:32<br>16-Agu-2025   | <br>03:57:54<br>16-Agu-2025   | <br>03:58:13<br>16-Agu-2025   |
| 3  | 16-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)                                           | <br>03:59:34<br>16-Agu-2025  | <br>03:59:48<br>16-Agu-2025  | <br>04:00:03<br>16-Agu-2025  |
| 4  | 16-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI DARI DEPAN TENANT BRAUN N BUFFEL - LANDING ESCALATOR DEPAN M&S LV.1 | <br>04:09:33<br>16-Agu-2025 | <br>04:01:24<br>16-Agu-2025 | <br>04:09:46<br>16-Agu-2025 |
| 5  | 16-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG                  | <br>04:10:11<br>16-Agu-2025 | <br>04:01:58<br>16-Agu-2025 | <br>04:10:32<br>16-Agu-2025 |
| 6  | 16-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LT.1 & 2                                         | <br>04:03:06<br>16-Agu-2025 | <br>04:03:20<br>16-Agu-2025 | <br>04:03:36<br>16-Agu-2025 |








| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                              | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 16-08-2025 | KRISTALISASI     | KRISTALISASI     | KRISTALISASI KURSI BENCH MARMER LV.3                          | <br>04:06:08<br>16-Agu-2025   | <br>04:05:27<br>16-Agu-2025   | <br>04:06:27<br>16-Agu-2025   |
| 8  | 16-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG   | <br>21:47:22<br>16-Agu-2025   | <br>21:47:45<br>16-Agu-2025   | <br>21:48:31<br>16-Agu-2025   |
| 9  | 16-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG | <br>11:10:26<br>16-Agu-2025  | <br>11:21:10<br>16-Agu-2025  | <br>11:11:16<br>16-Agu-2025  |
| 10 | 16-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.LG                              | <br>08:54:37<br>16-Agu-2025 | <br>09:17:02<br>16-Agu-2025 | <br>09:18:09<br>16-Agu-2025 |
| 11 | 16-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7B                             | <br>04:07:48<br>16-Agu-2025 | <br>04:08:01<br>16-Agu-2025 | <br>04:08:15<br>16-Agu-2025 |
| 12 | 16-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING BADUKAN,SELA SELA HAND RALLING LV.1-5                 | <br>11:24:20<br>16-Agu-2025 | <br>11:24:49<br>16-Agu-2025 | <br>11:25:11<br>16-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                     | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 16-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.10            | <br>11:26:55<br>16-Agu-2025   | <br>11:27:21<br>16-Agu-2025   | <br>11:27:09<br>16-Agu-2025   |
| 14 | 16-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5 | <br>10:17:07<br>16-Agu-2025   | <br>10:17:58<br>16-Agu-2025   | <br>10:18:31<br>16-Agu-2025   |
| 15 | 16-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LED PROMO LV.1 S.D LV.4                      | <br>11:29:17<br>16-Agu-2025  | <br>11:29:01<br>16-Agu-2025  | <br>11:29:28<br>16-Agu-2025  |
| 16 | 16-08-2025 | KORIDOR SHOPPING | SWEEPING       | PEMBERSIHAN PLANTER BOX LV.UG                        | <br>11:06:21<br>16-Agu-2025 | <br>11:06:45<br>16-Agu-2025 | <br>11:06:32<br>16-Agu-2025 |
| 17 | 16-08-2025 | KORIDOR SHOPPING | DUSTING        | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1        | <br>11:08:28<br>16-Agu-2025 | <br>11:07:56<br>16-Agu-2025 | <br>11:08:42<br>16-Agu-2025 |
| 18 | 16-08-2025 | KORIDOR SHOPPING | WASHING        | PENCUCIAN TRASHCAN LV.UG S.D LV.5                    | <br>19:15:31<br>16-Agu-2025 | <br>21:46:46<br>16-Agu-2025 | <br>19:23:19<br>16-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                      | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|-----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 16-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING VINYL LV.5                                              | <br>10:19:47<br>16-Agu-2025   | <br>10:20:26<br>16-Agu-2025   | <br>10:20:46<br>16-Agu-2025   |
| 20 | 16-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.UG                                   | <br>10:59:00<br>16-Agu-2025   | <br>11:04:22<br>16-Agu-2025   | <br>11:03:14<br>16-Agu-2025   |
| 21 | 16-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.UG                                        | <br>21:49:12<br>16-Agu-2025  | <br>21:49:34<br>16-Agu-2025  | <br>21:50:05<br>16-Agu-2025  |
| 22 | 16-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2 | <br>11:25:39<br>16-Agu-2025 | <br>11:26:09<br>16-Agu-2025 | <br>11:25:51<br>16-Agu-2025 |

| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                              | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|-------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 17-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.7-9 (UP&DOWN)                                        | <br>06:20:59<br>17-Agu-2025   | <br>06:21:26<br>17-Agu-2025   | <br>06:22:01<br>17-Agu-2025   |
| 2  | 17-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.9-10 (UP&DOWN)                                       | <br>06:22:41<br>17-Agu-2025   | <br>06:23:00<br>17-Agu-2025   | <br>06:23:16<br>17-Agu-2025   |
| 3  | 17-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.2                          | <br>06:35:16<br>17-Agu-2025  | <br>06:23:44<br>17-Agu-2025  | <br>06:35:25<br>17-Agu-2025  |
| 4  | 17-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI DARI LANDING ESCALATOR TENANT GEOX - ARAH KE CONNECTION TP4 LV.1 | <br>06:35:57<br>17-Agu-2025 | <br>06:27:29<br>17-Agu-2025 | <br>06:36:15<br>17-Agu-2025 |
| 5  | 17-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1                | <br>06:36:48<br>17-Agu-2025 | <br>06:28:48<br>17-Agu-2025 | <br>06:37:02<br>17-Agu-2025 |
| 6  | 17-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR TOILET LV.UG                                               | <br>06:29:58<br>17-Agu-2025 | <br>06:30:13<br>17-Agu-2025 | <br>06:30:33<br>17-Agu-2025 |




| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                           | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|--------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 17-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LV.UG      | <br>06:31:20<br>17-Agu-2025   | <br>06:31:33<br>17-Agu-2025   | <br>06:32:09<br>17-Agu-2025   |
| 8  | 17-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P6A & P6B      | <br>06:32:43<br>17-Agu-2025   | <br>06:33:02<br>17-Agu-2025   | <br>06:33:12<br>17-Agu-2025   |
| 9  | 17-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.3   | <br>21:42:35<br>17-Agu-2025  | <br>21:42:57<br>17-Agu-2025  | <br>21:44:49<br>17-Agu-2025  |
| 10 | 17-08-2025 | CARPARK      | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.3 | <br>10:01:46<br>17-Agu-2025 | <br>10:02:15<br>17-Agu-2025 | <br>10:02:50<br>17-Agu-2025 |
| 11 | 17-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.8            | <br>08:44:52<br>17-Agu-2025 | <br>08:48:47<br>17-Agu-2025 | <br>09:00:13<br>17-Agu-2025 |
| 12 | 17-08-2025 | CARPARK      | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P8A          | <br>06:33:51<br>17-Agu-2025 | <br>06:34:03<br>17-Agu-2025 | <br>06:34:27<br>17-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                    | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 17-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING<br>BADUKAN, SELA<br>SELA HAND<br>RALLING LV.6-<br>10        | <br>10:07:29<br>17-Agu-2025   | <br>10:08:00<br>17-Agu-2025   | <br>10:07:43<br>17-Agu-2025   |
| 14 | 17-08-2025 | KORIDOR SHOPPING | WALL<br>CLEANING | WALL<br>CLEANING<br>DINDING SISI<br>DEPAN LIFT<br>PASSENGER<br>LV.6 | <br>10:06:02<br>17-Agu-2025   | <br>10:06:25<br>17-Agu-2025   | <br>10:06:54<br>17-Agu-2025   |
| 15 | 17-08-2025 | KORIDOR SHOPPING | DUSTING          | SELA SELA<br>PILLAR UTAMA<br>/KOLOM PILAR<br>LV.2 & 3               | <br>09:59:24<br>17-Agu-2025  | <br>09:59:47<br>17-Agu-2025  | <br>09:59:36<br>17-Agu-2025  |
| 16 | 17-08-2025 | KORIDOR SHOPPING | WASHING          | PENCUCIAN<br>TRASHCAN LV.6<br>S.D LV.10                             | <br>19:41:49<br>17-Agu-2025 | <br>21:42:04<br>17-Agu-2025 | <br>19:47:24<br>17-Agu-2025 |
| 17 | 17-08-2025 | KORIDOR SHOPPING | WALL<br>CLEANING | WALL<br>CLEANING<br>VINYL LV.6                                      | <br>10:04:20<br>17-Agu-2025 | <br>10:04:44<br>17-Agu-2025 | <br>10:05:08<br>17-Agu-2025 |
| 18 | 17-08-2025 | KORIDOR SHOPPING | WALL<br>CLEANING | WALL<br>CLEANING<br>KORIDOR EXIT<br>24 LV.3                         | <br>09:57:14<br>17-Agu-2025 | <br>09:58:19<br>17-Agu-2025 | <br>09:58:41<br>17-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                       | Before                                                                                                        | Progress                                                                                                        | After                                                                                                           |
|----|------------|------------------|----------------|------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| 19 | 17-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.3                                          | <br>21:44:20<br>17-Agu-2025  | <br>21:43:17<br>17-Agu-2025  | <br>21:43:57<br>17-Agu-2025  |
| 20 | 17-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY, SISI PILLAR, SISI DEPAN LIFT PASSENGER LV.3-4-5 | <br>10:00:21<br>17-Agu-2025  | <br>10:00:43<br>17-Agu-2025  | <br>10:01:07<br>17-Agu-2025  |
| 21 | 17-08-2025 | KORIDOR SHOPPING | WASHING        | PENCUCIAN NOMADE LV.UG                                                 | <br>04:34:18<br>17-Agu-2025 | <br>04:34:28<br>17-Agu-2025 | <br>04:34:47<br>17-Agu-2025 |


| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 18-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM               | <br>13:29:37<br>18-Agu-2025   | <br>13:29:54<br>18-Agu-2025   | <br>13:30:12<br>18-Agu-2025   |
| 2  | 18-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI CONECTION TP4                     | <br>04:06:48<br>18-Agu-2025   | <br>04:07:12<br>18-Agu-2025   | <br>04:07:27<br>18-Agu-2025   |
| 3  | 18-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI MARGOYOSO                         | <br>04:07:52<br>18-Agu-2025  | <br>04:08:12<br>18-Agu-2025  | <br>04:08:50<br>18-Agu-2025  |
| 4  | 18-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)                        | <br>04:09:34<br>18-Agu-2025 | <br>04:09:56<br>18-Agu-2025 | <br>04:10:10<br>18-Agu-2025 |
| 5  | 18-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.3           | <br>04:31:10<br>18-Agu-2025 | <br>04:13:38<br>18-Agu-2025 | <br>04:31:30<br>18-Agu-2025 |
| 6  | 18-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2 | <br>04:32:13<br>18-Agu-2025 | <br>04:14:10<br>18-Agu-2025 | <br>04:32:30<br>18-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                             | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 18-08-2025 | KRISTALISASI     | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LV.3                         | <br>04:15:13<br>18-Agu-2025   | <br>04:14:46<br>18-Agu-2025   | <br>04:15:38<br>18-Agu-2025   |
| 8  | 18-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P6A & P6B                        | <br>04:16:20<br>18-Agu-2025   | <br>04:16:41<br>18-Agu-2025   | <br>04:16:56<br>18-Agu-2025   |
| 9  | 18-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4                     | <br>21:13:49<br>18-Agu-2025  | <br>21:14:17<br>18-Agu-2025  | <br>21:14:36<br>18-Agu-2025  |
| 10 | 18-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG | <br>04:18:01<br>18-Agu-2025 | <br>04:18:18<br>18-Agu-2025 | <br>04:18:37<br>18-Agu-2025 |
| 11 | 18-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.4                   | <br>11:24:18<br>18-Agu-2025 | <br>11:24:41<br>18-Agu-2025 | <br>11:24:55<br>18-Agu-2025 |
| 12 | 18-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN PILLAR UTAMA LV.UG                               | <br>11:14:01<br>18-Agu-2025 | <br>11:15:10<br>18-Agu-2025 | <br>11:15:39<br>18-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 18-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.1                    | <br>20:28:27<br>18-Agu-2025   | <br>20:28:40<br>18-Agu-2025   | <br>20:28:54<br>18-Agu-2025   |
| 14 | 18-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5 | <br>13:16:19<br>18-Agu-2025   | <br>13:17:26<br>18-Agu-2025   | <br>13:17:42<br>18-Agu-2025   |
| 15 | 18-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1              | <br>13:14:53<br>18-Agu-2025  | <br>13:15:39<br>18-Agu-2025  | <br>13:15:08<br>18-Agu-2025  |
| 16 | 18-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1     | <br>20:30:57<br>18-Agu-2025 | <br>20:31:10<br>18-Agu-2025 | <br>20:31:25<br>18-Agu-2025 |
| 17 | 18-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7     | <br>11:28:36<br>18-Agu-2025 | <br>11:28:58<br>18-Agu-2025 | <br>11:29:29<br>18-Agu-2025 |
| 18 | 18-08-2025 | KORIDOR SHOPPING | DUSTING        | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5             | <br>11:22:37<br>18-Agu-2025 | <br>11:23:00<br>18-Agu-2025 | <br>11:22:51<br>18-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|--------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 18-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING VINYL LV.7                   | <br>11:26:52<br>18-Agu-2025   | <br>11:27:23<br>18-Agu-2025   | <br>11:27:43<br>18-Agu-2025   |
| 20 | 18-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.4         | <br>11:19:55<br>18-Agu-2025   | <br>11:20:18<br>18-Agu-2025   | <br>11:21:17<br>18-Agu-2025   |
| 21 | 18-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.4              | <br>21:15:08<br>18-Agu-2025  | <br>21:15:26<br>18-Agu-2025  | <br>21:15:43<br>18-Agu-2025  |
| 22 | 18-08-2025 | KORIDOR SHOPPING | WASHING        | PENCUCIAN NOMADE LV.5                      | <br>04:27:35<br>18-Agu-2025 | <br>04:33:27<br>18-Agu-2025 | <br>04:30:06<br>18-Agu-2025 |
| 23 | 18-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5 | <br>20:29:19<br>18-Agu-2025 | <br>20:30:21<br>18-Agu-2025 | <br>20:30:36<br>18-Agu-2025 |


| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                         | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 19-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER RUMP UP DROP OUT | <br>07:08:38<br>19-Agu-2025   | <br>07:09:39<br>19-Agu-2025   | <br>07:10:47<br>19-Agu-2025   |
| 2  | 19-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.1-2 (UP& DOWN)  | <br>04:17:50<br>19-Agu-2025   | <br>04:18:07<br>19-Agu-2025   | <br>04:18:34<br>19-Agu-2025   |
| 3  | 19-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MEJA CONCIERGE LV.UG        | <br>04:28:00<br>19-Agu-2025  | <br>04:19:52<br>19-Agu-2025  | <br>04:28:13<br>19-Agu-2025  |
| 4  | 19-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LV.4     | <br>04:21:06<br>19-Agu-2025 | <br>04:21:25<br>19-Agu-2025 | <br>04:21:42<br>19-Agu-2025 |
| 5  | 19-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P6A & P6B    | <br>04:22:27<br>19-Agu-2025 | <br>04:22:45<br>19-Agu-2025 | <br>04:23:07<br>19-Agu-2025 |
| 6  | 19-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.5 | <br>21:04:22<br>19-Agu-2025 | <br>21:03:50<br>19-Agu-2025 | <br>21:04:04<br>19-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                          | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 19-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.5                | <br>11:32:32<br>19-Agu-2025   | <br>11:32:59<br>19-Agu-2025   | <br>11:33:12<br>19-Agu-2025   |
| 8  | 19-08-2025 | CARPARK          | GENERAL CLEANING | PENCUCIAN SPIRAL CARPARK LT.6-4                           | <br>04:23:51<br>19-Agu-2025   | <br>04:24:03<br>19-Agu-2025   | <br>04:24:19<br>19-Agu-2025   |
| 9  | 19-08-2025 | KORIDOR SHOPPING | WASHING          | BRUSHING KORIDOR LANTAI KULIT JERUK LV.1                  | <br>04:24:59<br>19-Agu-2025  | <br>04:25:13<br>19-Agu-2025  | <br>04:25:25<br>19-Agu-2025  |
| 10 | 19-08-2025 | KORIDOR SHOPPING | GLASS CLEANING   | GLASS CLEANING SISI DEPAN TENANT LV.2                     | <br>21:00:54<br>19-Agu-2025 | <br>21:01:37<br>19-Agu-2025 | <br>21:01:56<br>19-Agu-2025 |
| 11 | 19-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.6-10 | <br>11:44:21<br>19-Agu-2025 | <br>11:44:44<br>19-Agu-2025 | <br>11:44:33<br>19-Agu-2025 |
| 12 | 19-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.2-3                | <br>12:08:18<br>19-Agu-2025 | <br>12:13:46<br>19-Agu-2025 | <br>12:08:30<br>19-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                      | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|-------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 19-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.2  | <br>11:47:16<br>19-Agu-2025   | <br>11:47:56<br>19-Agu-2025   | <br>11:48:10<br>19-Agu-2025   |
| 14 | 19-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.10 | <br>11:40:54<br>19-Agu-2025   | <br>11:41:19<br>19-Agu-2025   | <br>11:41:40<br>19-Agu-2025   |
| 15 | 19-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.9                              | <br>11:43:08<br>19-Agu-2025  | <br>11:43:32<br>19-Agu-2025  | <br>11:43:44<br>19-Agu-2025  |
| 16 | 19-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING KORIDOR EXIT 24 LV.5                    | <br>11:35:30<br>19-Agu-2025 | <br>11:35:51<br>19-Agu-2025 | <br>11:36:18<br>19-Agu-2025 |
| 17 | 19-08-2025 | KORIDOR SHOPPING | WASHING          | BRUSHING KORIDOR EXIT 24 LV.5                         | <br>21:02:27<br>19-Agu-2025 | <br>21:02:52<br>19-Agu-2025 | <br>21:03:24<br>19-Agu-2025 |
| 18 | 19-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | PEMBERSIHAN BASS ROOM LV.7                            | <br>10:03:36<br>19-Agu-2025 | <br>10:04:48<br>19-Agu-2025 | <br>10:03:50<br>19-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                           | Before                                                                                                        | Progress                                                                                                       | After                                                                                                           |
|----|------------|------------------|----------------|--------------------------------------------|---------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| 19 | 19-08-2025 | KORIDOR SHOPPING | WASHING        | PENCUCIAN NOMADE LV.6                      | <br>04:26:49<br>19-Agu-2025  | <br>04:27:01<br>19-Agu-2025  | <br>04:27:17<br>19-Agu-2025  |
| 20 | 19-08-2025 | KORIDOR SHOPPING | DUSTING        | LAMPU HIAS SISI ATAS CONCIERGE LOBBY LV.UG | <br>08:35:59<br>19-Agu-2025  | <br>08:34:34<br>19-Agu-2025  | <br>08:36:35<br>19-Agu-2025  |
| 21 | 19-08-2025 | KORIDOR SHOPPING | DUSTING        | LEMARI DISPLAY AREA LOBBY LV.UG            | <br>08:38:23<br>19-Agu-2025 | <br>08:40:03<br>19-Agu-2025 | <br>08:38:49<br>19-Agu-2025 |



| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 20-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER ENTRANCE                                | <br>07:16:17<br>20-Agu-2025   | <br>07:18:27<br>20-Agu-2025   | <br>07:25:44<br>20-Agu-2025   |
| 2  | 20-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)                          | <br>06:41:40<br>20-Agu-2025   | <br>06:41:54<br>20-Agu-2025   | <br>06:42:06<br>20-Agu-2025   |
| 3  | 20-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG   | <br>06:48:54<br>20-Agu-2025  | <br>06:42:33<br>20-Agu-2025  | <br>06:49:06<br>20-Agu-2025  |
| 4  | 20-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG | <br>06:49:30<br>20-Agu-2025 | <br>06:44:04<br>20-Agu-2025 | <br>06:49:49<br>20-Agu-2025 |
| 5  | 20-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LV.5                            | <br>06:52:51<br>20-Agu-2025 | <br>06:53:07<br>20-Agu-2025 | <br>06:53:21<br>20-Agu-2025 |
| 6  | 20-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P7A & P7B                           | <br>06:53:59<br>20-Agu-2025 | <br>06:54:10<br>20-Agu-2025 | <br>06:54:23<br>20-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 20-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7   | <br>22:38:47<br>20-Agu-2025   | <br>22:39:06<br>20-Agu-2025   | <br>22:39:21<br>20-Agu-2025   |
| 8  | 20-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7 | <br>14:03:59<br>20-Agu-2025   | <br>14:05:36<br>20-Agu-2025   | <br>14:05:52<br>20-Agu-2025   |
| 9  | 20-08-2025 | CARPARK          | GENERAL CLEANING | PENCUCIAN SPIRAL CARPARK LT.4-2             | <br>06:55:03<br>20-Agu-2025  | <br>06:55:15<br>20-Agu-2025  | <br>06:55:29<br>20-Agu-2025  |
| 10 | 20-08-2025 | CARPARK          | GENERAL CLEANING | SUMPIT DAN GREASE ROOM LV.LG                | <br>06:57:17<br>20-Agu-2025 | <br>06:57:29<br>20-Agu-2025 | <br>06:57:47<br>20-Agu-2025 |
| 11 | 20-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.LG            | <br>06:58:26<br>20-Agu-2025 | <br>06:58:38<br>20-Agu-2025 | <br>06:58:49<br>20-Agu-2025 |
| 12 | 20-08-2025 | KORIDOR SHOPPING | WASHING          | BRUSHING KORIDOR LANTAI KULIT JERUK LV.3    | <br>06:59:23<br>20-Agu-2025 | <br>06:59:34<br>20-Agu-2025 | <br>06:59:45<br>20-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 20-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.4                   | <br>07:00:01<br>20-Agu-2025   | <br>07:00:14<br>20-Agu-2025   | <br>07:00:25<br>20-Agu-2025   |
| 14 | 20-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.3                      | <br>22:34:03<br>20-Agu-2025   | <br>22:34:12<br>20-Agu-2025   | <br>22:34:39<br>20-Agu-2025   |
| 15 | 20-08-2025 | KORIDOR SHOPPING | DUSTING        | SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10 | <br>22:36:16<br>20-Agu-2025  | <br>22:36:28<br>20-Agu-2025  | <br>22:36:41<br>20-Agu-2025  |
| 16 | 20-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5           | <br>11:42:48<br>20-Agu-2025 | <br>11:43:20<br>20-Agu-2025 | <br>11:43:06<br>20-Agu-2025 |
| 17 | 20-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.4-5                 | <br>11:43:44<br>20-Agu-2025 | <br>11:44:04<br>20-Agu-2025 | <br>11:43:55<br>20-Agu-2025 |
| 18 | 20-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3       | <br>22:35:28<br>20-Agu-2025 | <br>22:35:39<br>20-Agu-2025 | <br>22:35:49<br>20-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan             | Before                                                                                                        | Progress                                                                                                       | After                                                                                                           |
|----|------------|------------------|------------------|------------------------------|---------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| 19 | 20-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.10    | <br>09:39:21<br>20-Agu-2025  | <br>09:36:59<br>20-Agu-2025  | <br>09:39:36<br>20-Agu-2025  |
| 20 | 20-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.5 | <br>22:37:48<br>20-Agu-2025  | <br>22:38:00<br>20-Agu-2025  | <br>22:38:13<br>20-Agu-2025  |
| 21 | 20-08-2025 | KORIDOR SHOPPING | WASHING          | PENCUCIAN NOMADE LV.7        | <br>07:01:45<br>20-Agu-2025 | <br>07:02:01<br>20-Agu-2025 | <br>07:02:18<br>20-Agu-2025 |

| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 21-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI BAWAH UNION                             | <br>07:10:27<br>21-Agu-2025   | <br>07:12:04<br>21-Agu-2025   | <br>07:14:27<br>21-Agu-2025   |
| 2  | 21-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)                               | <br>06:27:40<br>21-Agu-2025   | <br>06:28:08<br>21-Agu-2025   | <br>06:28:22<br>21-Agu-2025   |
| 3  | 21-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI LIFT PASSENGER A DAN B                                  | <br>06:42:09<br>21-Agu-2025  | <br>06:29:38<br>21-Agu-2025  | <br>06:42:28<br>21-Agu-2025  |
| 4  | 21-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI LIFT SERVICE A DAN B                                    | <br>06:43:21<br>21-Agu-2025 | <br>06:29:54<br>21-Agu-2025 | <br>06:43:38<br>21-Agu-2025 |
| 5  | 21-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1       | <br>06:44:16<br>21-Agu-2025 | <br>06:30:15<br>21-Agu-2025 | <br>06:44:34<br>21-Agu-2025 |
| 6  | 21-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE & KORIDOR CONECTION CARPARK LV.6 & 7 | <br>06:34:57<br>21-Agu-2025 | <br>06:34:40<br>21-Agu-2025 | <br>06:35:54<br>21-Agu-2025 |



| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                                                                                      | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|---------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 21-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI DARI LANDING ESCALATOR DEPAN TENANT LC WAIKIKI - ARAH KE TENANT JUSTICE / BATAS SISI KE LORONG CORIDOR LIFT SERVICE LV.2 | <br>06:44:57<br>21-Agu-2025   | <br>06:36:34<br>21-Agu-2025   | <br>06:45:11<br>21-Agu-2025   |
| 8  | 21-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P7A & P7B                                                                                                 | <br>06:37:12<br>21-Agu-2025   | <br>06:37:27<br>21-Agu-2025   | <br>06:37:38<br>21-Agu-2025   |
| 9  | 21-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10                                                                                            | <br>22:42:47<br>21-Agu-2025  | <br>22:43:02<br>21-Agu-2025  | <br>22:43:12<br>21-Agu-2025  |
| 10 | 21-08-2025 | CARPARK      | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10                                                                                          | <br>11:18:59<br>21-Agu-2025 | <br>11:19:41<br>21-Agu-2025 | <br>11:19:59<br>21-Agu-2025 |
| 11 | 21-08-2025 | CARPARK      | GENERAL CLEANING | PENCUCIAN SPIRAL CARPARK LV.2-LG                                                                                                      | <br>06:38:16<br>21-Agu-2025 | <br>06:38:29<br>21-Agu-2025 | <br>06:38:45<br>21-Agu-2025 |
| 12 | 21-08-2025 | CARPARK      | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P6A                                                                                                     | <br>06:39:34<br>21-Agu-2025 | <br>06:39:47<br>21-Agu-2025 | <br>06:39:59<br>21-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                        | Before | Progress | After |
|----|------------|------------------|----------------|---------------------------------------------------------|--------|----------|-------|
| 13 | 21-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG |        |          |       |
| 14 | 21-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.5                |        |          |       |
| 15 | 21-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.4                   |        |          |       |
| 16 | 21-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10       |        |          |       |
| 17 | 21-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.6-7              |        |          |       |
| 18 | 21-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4    |        |          |       |






| No | Tanggal    | Area             | Item Pekerjaan   | DetailPekerjaan              | Before                                                                            | Progress                                                                           | After                                                                               |
|----|------------|------------------|------------------|------------------------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 19 | 21-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.4 |  |  |  |






| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|--------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 22-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)                                                     | <br>03:51:07<br>22-Agu-2025   | <br>03:51:23<br>22-Agu-2025   | <br>03:51:50<br>22-Agu-2025   |
| 2  | 22-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2                             | <br>03:54:33<br>22-Agu-2025   | <br>03:54:11<br>22-Agu-2025   | <br>03:54:45<br>22-Agu-2025   |
| 3  | 22-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE 9 & 10                                                     | <br>03:57:26<br>22-Agu-2025  | <br>03:57:44<br>22-Agu-2025  | <br>03:58:00<br>22-Agu-2025  |
| 4  | 22-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI DARI DEPAN TENANT MELISSA - LANDING ESCALATOR DEPAN EX TENANT LC WAIKIKI LV.2 | <br>03:53:00<br>22-Agu-2025 | <br>03:56:43<br>22-Agu-2025 | <br>03:53:25<br>22-Agu-2025 |
| 5  | 22-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P7A & P7B                                                      | <br>03:58:35<br>22-Agu-2025 | <br>03:58:56<br>22-Agu-2025 | <br>03:59:18<br>22-Agu-2025 |
| 6  | 22-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2                                               | <br>20:29:06<br>22-Agu-2025 | <br>20:35:04<br>22-Agu-2025 | <br>20:35:17<br>22-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                                | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 22-08-2025 | CARPARK          | WALL CLEANING  | WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2                                  | <br>11:12:35<br>22-Agu-2025   | <br>11:12:59<br>22-Agu-2025   | <br>11:13:25<br>22-Agu-2025   |
| 8  | 22-08-2025 | CARPARK          | WASHING        | PENCUCIAN TRASHCAN CARPARK LV.P7A                                               | <br>04:00:02<br>22-Agu-2025   | <br>04:00:22<br>22-Agu-2025   | <br>04:00:38<br>22-Agu-2025   |
| 9  | 22-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.8-9                                      | <br>11:14:20<br>22-Agu-2025  | <br>11:15:36<br>22-Agu-2025  | <br>11:15:13<br>22-Agu-2025  |
| 10 | 22-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG | <br>11:07:32<br>22-Agu-2025 | <br>11:09:14<br>22-Agu-2025 | <br>11:09:46<br>22-Agu-2025 |


| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                                   | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 23-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI OUT MOBIL                                             | <br>07:13:06<br>23-Agu-2025   | <br>07:14:21<br>23-Agu-2025   | <br>07:16:08<br>23-Agu-2025   |
| 2  | 23-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)                                             | <br>06:38:17<br>23-Agu-2025   | <br>06:38:32<br>23-Agu-2025   | <br>06:38:53<br>23-Agu-2025   |
| 3  | 23-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)                                             | <br>06:39:15<br>23-Agu-2025  | <br>06:39:33<br>23-Agu-2025  | <br>06:39:46<br>23-Agu-2025  |
| 4  | 23-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG                    | <br>06:42:40<br>23-Agu-2025 | <br>06:42:03<br>23-Agu-2025 | <br>06:42:52<br>23-Agu-2025 |
| 5  | 23-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI DARI LANDING ESCALATOR TENANT COTTON ON - ARAH KE CONNECTION TP4 LV.2 | <br>06:40:43<br>23-Agu-2025 | <br>06:40:18<br>23-Agu-2025 | <br>06:40:55<br>23-Agu-2025 |
| 6  | 23-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI KURSI BENCH MARMER LV.4                                               | <br>06:43:36<br>23-Agu-2025 | <br>06:44:06<br>23-Agu-2025 | <br>06:43:50<br>23-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                              | Before                                                                              | Progress                                                                              | After                                                                                 |
|----|------------|------------------|------------------|---------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 7  | 23-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P8A                               |    |    |    |
| 8  | 23-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG   |    |    |    |
| 9  | 23-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG |   |   |   |
| 10 | 23-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.LG                              |  |  |  |
| 11 | 23-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7B                             |  |  |  |
| 12 | 23-08-2025 | KORIDOR SHOPPING | CELLING          | CELLING AREA KORIDOR SHOPPING LV.1-5                          |  |  |  |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                     | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 23-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5       | <br>11:32:47<br>23-Agu-2025   | <br>11:32:59<br>23-Agu-2025   | <br>11:33:12<br>23-Agu-2025   |
| 14 | 23-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.UG-1    | <br>07:53:55<br>23-Agu-2025   | <br>07:55:13<br>23-Agu-2025   | <br>07:52:23<br>23-Agu-2025   |
| 15 | 23-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.10            | <br>11:46:22<br>23-Agu-2025  | <br>11:47:57<br>23-Agu-2025  | <br>11:46:51<br>23-Agu-2025  |
| 16 | 23-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5 | <br>11:30:21<br>23-Agu-2025 | <br>11:31:15<br>23-Agu-2025 | <br>11:31:57<br>23-Agu-2025 |
| 17 | 23-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LED PROMO LV.1 S.D LV.4                      | <br>11:50:30<br>23-Agu-2025 | <br>11:50:53<br>23-Agu-2025 | <br>11:50:40<br>23-Agu-2025 |
| 18 | 23-08-2025 | KORIDOR SHOPPING | SWEEPING       | PEMBERSIHAN PLANTER BOX LV.UG                        | <br>06:49:49<br>23-Agu-2025 | <br>06:50:05<br>23-Agu-2025 | <br>06:50:24<br>23-Agu-2025 |





| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                                | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 23-08-2025 | KORIDOR SHOPPING | DUSTING          | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1                                   | <br>11:45:35<br>23-Agu-2025   | <br>11:45:58<br>23-Agu-2025   | <br>11:45:45<br>23-Agu-2025   |
| 20 | 23-08-2025 | KORIDOR SHOPPING | WASHING          | PENCUCIAN TRASHCAN LV.UG S.D LV.5                                               | <br>22:24:52<br>23-Agu-2025   | <br>22:25:10<br>23-Agu-2025   | <br>22:25:31<br>23-Agu-2025   |
| 21 | 23-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.5                                                        | <br>11:28:24<br>23-Agu-2025  | <br>11:35:36<br>23-Agu-2025  | <br>11:28:50<br>23-Agu-2025  |
| 22 | 23-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN DINDING KORIDOR SERVICE LV.LG-10                                    | <br>22:25:56<br>23-Agu-2025 | <br>22:26:13<br>23-Agu-2025 | <br>22:26:42<br>23-Agu-2025 |
| 23 | 23-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | PEMBERSIHAN TANGGA EXIT 24 SISI UNION,LC WAIKIKI,KID STATION,SUSHI TEI LV.LG-10 | <br>11:44:16<br>23-Agu-2025 | <br>11:44:31<br>23-Agu-2025 | <br>11:44:47<br>23-Agu-2025 |
| 24 | 23-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING KORIDOR EXIT 24 LV.UG                                             | <br>11:39:57<br>23-Agu-2025 | <br>11:40:27<br>23-Agu-2025 | <br>11:41:24<br>23-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                      | Before                                                                                                        | Progress                                                                                                        | After                                                                                                           |
|----|------------|------------------|----------------|-----------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| 25 | 23-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.UG                                        | <br>22:27:54<br>23-Agu-2025  | <br>22:28:19<br>23-Agu-2025  | <br>22:29:00<br>23-Agu-2025  |
| 26 | 23-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2 | <br>11:33:37<br>23-Agu-2025  | <br>11:34:03<br>23-Agu-2025  | <br>11:33:51<br>23-Agu-2025  |
| 27 | 23-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SELA SELA PINTU LIFT SERVICE LV.LG-10                     | <br>11:52:01<br>23-Agu-2025 | <br>11:52:26<br>23-Agu-2025 | <br>11:52:12<br>23-Agu-2025 |







| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 24-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.7-9 (UP&DOWN)                         | <br>06:44:41<br>24-Agu-2025   | <br>06:45:07<br>24-Agu-2025   | <br>06:45:29<br>24-Agu-2025   |
| 2  | 24-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.9-10 (UP&DOWN)                        | <br>06:45:55<br>24-Agu-2025   | <br>06:46:10<br>24-Agu-2025   | <br>06:46:25<br>24-Agu-2025   |
| 3  | 24-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.4           | <br>06:47:03<br>24-Agu-2025  | <br>06:47:27<br>24-Agu-2025  | <br>06:47:53<br>24-Agu-2025  |
| 4  | 24-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1 | <br>06:49:18<br>24-Agu-2025 | <br>06:48:59<br>24-Agu-2025 | <br>06:49:42<br>24-Agu-2025 |
| 5  | 24-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P8A                                | <br>06:50:24<br>24-Agu-2025 | <br>06:50:58<br>24-Agu-2025 | <br>06:51:16<br>24-Agu-2025 |
| 6  | 24-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.3                       | <br>20:42:25<br>24-Agu-2025 | <br>20:43:09<br>24-Agu-2025 | <br>20:42:50<br>24-Agu-2025 |


| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                 | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|--------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 24-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.3       | <br>10:19:22<br>24-Agu-2025   | <br>10:19:47<br>24-Agu-2025   | <br>10:20:21<br>24-Agu-2025   |
| 8  | 24-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.8                  | <br>08:54:49<br>24-Agu-2025   | <br>08:54:27<br>24-Agu-2025   | <br>09:07:30<br>24-Agu-2025   |
| 9  | 24-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P8A                | <br>06:52:24<br>24-Agu-2025  | <br>06:52:40<br>24-Agu-2025  | <br>06:52:55<br>24-Agu-2025  |
| 10 | 24-08-2025 | KORIDOR SHOPPING | CELLING          | CELLING AREA KORIDOR SHOPPING LV.6-10            | <br>10:30:31<br>24-Agu-2025 | <br>10:34:34<br>24-Agu-2025 | <br>10:34:20<br>24-Agu-2025 |
| 11 | 24-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING BADUKAN, SELA SELA HAND RALLING LV.6-10  | <br>10:29:26<br>24-Agu-2025 | <br>10:29:53<br>24-Agu-2025 | <br>10:29:45<br>24-Agu-2025 |
| 12 | 24-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.2-3 | <br>10:46:12<br>24-Agu-2025 | <br>10:46:25<br>24-Agu-2025 | <br>10:46:38<br>24-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                 | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 24-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.6             | <br>10:25:27<br>24-Agu-2025   | <br>10:25:49<br>24-Agu-2025   | <br>10:27:16<br>24-Agu-2025   |
| 14 | 24-08-2025 | KORIDOR SHOPPING | DUSTING          | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.2 & 3                     | <br>10:11:18<br>24-Agu-2025   | <br>10:11:40<br>24-Agu-2025   | <br>10:11:29<br>24-Agu-2025   |
| 15 | 24-08-2025 | KORIDOR SHOPPING | WASHING          | PENCUCIAN TRASHCAN LV.6 S.D LV.10                                | <br>21:50:10<br>24-Agu-2025  | <br>22:02:16<br>24-Agu-2025  | <br>21:56:13<br>24-Agu-2025  |
| 16 | 24-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.6                                         | <br>10:22:48<br>24-Agu-2025 | <br>10:23:09<br>24-Agu-2025 | <br>10:23:39<br>24-Agu-2025 |
| 17 | 24-08-2025 | KORIDOR SHOPPING | CELLING          | CELLING AREA KORIDOR SERVICE LV.LG-10                            | <br>19:23:52<br>24-Agu-2025 | <br>19:27:05<br>24-Agu-2025 | <br>19:29:44<br>24-Agu-2025 |
| 18 | 24-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | PEMBERSIHAN TANGGA EXIT 22 SISI BELAKANG LIFT PASSENGER LV.LG-10 | <br>10:28:04<br>24-Agu-2025 | <br>10:28:21<br>24-Agu-2025 | <br>10:28:36<br>24-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                     | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 24-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.3                                   | <br>10:08:20<br>24-Agu-2025   | <br>10:09:41<br>24-Agu-2025   | <br>10:09:57<br>24-Agu-2025   |
| 20 | 24-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.3                                        | <br>20:45:28<br>24-Agu-2025   | <br>20:43:44<br>24-Agu-2025   | <br>20:48:06<br>24-Agu-2025   |
| 21 | 24-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.3-4-5 | <br>10:12:45<br>24-Agu-2025  | <br>10:13:20<br>24-Agu-2025  | <br>10:12:58<br>24-Agu-2025  |
| 22 | 24-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN PLAFON/ATAP HPL LV.UG                                    | <br>10:48:05<br>24-Agu-2025 | <br>10:48:17<br>24-Agu-2025 | <br>10:48:34<br>24-Agu-2025 |
| 23 | 24-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN PLAFON/ATAP HPL LV.1                                     | <br>19:44:10<br>24-Agu-2025 | <br>19:46:01<br>24-Agu-2025 | <br>19:48:29<br>24-Agu-2025 |







| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 25-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI IN MOBIL SISI TOTEM               | <br>07:12:30<br>25-Agu-2025   | <br>15:24:24<br>25-Agu-2025   | <br>15:24:45<br>25-Agu-2025   |
| 2  | 25-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI CONECTION TP4                     | <br>06:27:09<br>25-Agu-2025   | <br>06:27:37<br>25-Agu-2025   | <br>06:27:56<br>25-Agu-2025   |
| 3  | 25-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI MARGOYOSO                         | <br>06:28:53<br>25-Agu-2025  | <br>06:29:20<br>25-Agu-2025  | <br>06:29:40<br>25-Agu-2025  |
| 4  | 25-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.UG-1 (UP&DOWN)                        | <br>06:31:12<br>25-Agu-2025 | <br>06:31:31<br>25-Agu-2025 | <br>06:31:48<br>25-Agu-2025 |
| 5  | 25-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MEJA WASTAFEL TOILET MALE & FEMALE LV.5           | <br>06:34:29<br>25-Agu-2025 | <br>06:34:06<br>25-Agu-2025 | <br>06:34:47<br>25-Agu-2025 |
| 6  | 25-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2 | <br>06:37:07<br>25-Agu-2025 | <br>06:36:40<br>25-Agu-2025 | <br>06:37:31<br>25-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                             | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 25-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.P8A                              | <br>06:38:09<br>25-Agu-2025   | <br>06:38:25<br>25-Agu-2025   | <br>06:38:39<br>25-Agu-2025   |
| 8  | 25-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LV.4                     | <br>21:42:28<br>25-Agu-2025   | <br>20:02:39<br>25-Agu-2025   | <br>21:42:38<br>25-Agu-2025   |
| 9  | 25-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI GRANIT BAKAR SISI UNION - SISI TOBY'S LV.UG | <br>06:39:22<br>25-Agu-2025  | <br>06:39:41<br>25-Agu-2025  | <br>06:39:58<br>25-Agu-2025  |
| 10 | 25-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LV.4                   | <br>11:16:23<br>25-Agu-2025 | <br>11:16:50<br>25-Agu-2025 | <br>11:17:25<br>25-Agu-2025 |
| 11 | 25-08-2025 | KORIDOR SHOPPING | CELLING          | CELLING AREA LOBBY LV.UG                                     | <br>11:36:04<br>25-Agu-2025 | <br>11:36:47<br>25-Agu-2025 | <br>11:36:22<br>25-Agu-2025 |
| 12 | 25-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN PILLAR UTAMA LV.UG                               | <br>11:01:59<br>25-Agu-2025 | <br>11:02:27<br>25-Agu-2025 | <br>11:03:07<br>25-Agu-2025 |






| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 25-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.1                          | <br>19:57:38<br>25-Agu-2025   | <br>19:57:53<br>25-Agu-2025   | <br>19:58:07<br>25-Agu-2025   |
| 14 | 25-08-2025 | KORIDOR SHOPPING | SWEEPING       | SWEEPING BADUKAN SISI ESCALATOR (SELA SELA ESCALATOR) LV.UG-10 | <br>11:25:34<br>25-Agu-2025   | <br>11:26:05<br>25-Agu-2025   | <br>11:25:51<br>25-Agu-2025   |
| 15 | 25-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.1-5       | <br>11:31:01<br>25-Agu-2025  | <br>11:31:18<br>25-Agu-2025  | <br>11:31:29<br>25-Agu-2025  |
| 16 | 25-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.4-5               | <br>11:11:35<br>25-Agu-2025 | <br>11:11:59<br>25-Agu-2025 | <br>11:11:44<br>25-Agu-2025 |
| 17 | 25-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.UG-1                    | <br>11:13:17<br>25-Agu-2025 | <br>11:13:57<br>25-Agu-2025 | <br>11:13:35<br>25-Agu-2025 |
| 18 | 25-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.1           | <br>19:58:30<br>25-Agu-2025 | <br>19:59:07<br>25-Agu-2025 | <br>19:58:46<br>25-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                                 | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 19 | 25-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.7             | <br>11:21:32<br>25-Agu-2025   | <br>11:21:56<br>25-Agu-2025   | <br>11:22:24<br>25-Agu-2025   |
| 20 | 25-08-2025 | KORIDOR SHOPPING | DUSTING          | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.4 & 5                     | <br>11:09:50<br>25-Agu-2025   | <br>11:10:22<br>25-Agu-2025   | <br>11:10:02<br>25-Agu-2025   |
| 21 | 25-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.7                                         | <br>11:19:53<br>25-Agu-2025  | <br>11:20:12<br>25-Agu-2025  | <br>11:20:33<br>25-Agu-2025  |
| 22 | 25-08-2025 | KORIDOR SHOPPING | DUSTING          | PEMBERSIHAN PINTU MASUK KORIDOR SERVICE LV.LG-10                 | <br>20:00:30<br>25-Agu-2025 | <br>20:01:04<br>25-Agu-2025 | <br>20:00:51<br>25-Agu-2025 |
| 23 | 25-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | PEMBERSIHAN TANGGA EXIT 21 SISI BELAKANG LIFT PASSENGER LV.LG-10 | <br>11:33:32<br>25-Agu-2025 | <br>11:33:52<br>25-Agu-2025 | <br>11:34:03<br>25-Agu-2025 |
| 24 | 25-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN DINDING KORIDOR EXIT LV.LG-10                        | <br>11:24:02<br>25-Agu-2025 | <br>11:24:34<br>25-Agu-2025 | <br>11:25:00<br>25-Agu-2025 |






| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|--------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 25 | 25-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.4         | <br>11:07:26<br>25-Agu-2025   | <br>11:08:01<br>25-Agu-2025   | <br>11:08:30<br>25-Agu-2025   |
| 26 | 25-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.4              | <br>21:43:53<br>25-Agu-2025   | <br>20:02:57<br>25-Agu-2025   | <br>21:44:03<br>25-Agu-2025   |
| 27 | 25-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN PLAFON/ATAP HPL LV.2           | <br>20:01:48<br>25-Agu-2025  | <br>20:01:32<br>25-Agu-2025  | <br>20:02:00<br>25-Agu-2025  |
| 28 | 25-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | PEMBERSIHAN DINDING KORIDOR TOILET LV.UG-5 | <br>19:59:33<br>25-Agu-2025 | <br>20:00:04<br>25-Agu-2025 | <br>19:59:52<br>25-Agu-2025 |


| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 27-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER ENTRANCE                                | <br>15:18:04<br>27-Agu-2025   | <br>15:18:29<br>27-Agu-2025   | <br>15:18:47<br>27-Agu-2025   |
| 2  | 27-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.2-3 (UP&DOWN)                          | <br>23:07:45<br>27-Agu-2025   | <br>23:08:03<br>27-Agu-2025   | <br>23:08:18<br>27-Agu-2025   |
| 3  | 27-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI MAIN ENTRANCE LOBBY DROP OFF DAN REVOLVING LV.UG   | <br>23:19:48<br>27-Agu-2025  | <br>23:08:57<br>27-Agu-2025  | <br>23:20:04<br>27-Agu-2025  |
| 4  | 27-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG | <br>23:19:03<br>27-Agu-2025 | <br>23:10:00<br>27-Agu-2025 | <br>23:19:18<br>27-Agu-2025 |
| 5  | 27-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SELA/SUDUT CLOSET TOILET MALE FEMALE               | <br>23:11:11<br>27-Agu-2025 | <br>23:11:48<br>27-Agu-2025 | <br>23:11:25<br>27-Agu-2025 |
| 6  | 27-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.LG                                  | <br>23:12:57<br>27-Agu-2025 | <br>23:13:12<br>27-Agu-2025 | <br>23:13:24<br>27-Agu-2025 |







| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                            | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 27-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 6 & 7   | <br>22:31:01<br>27-Agu-2025   | <br>22:31:11<br>27-Agu-2025   | <br>22:31:25<br>27-Agu-2025   |
| 8  | 27-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE 6 & 7 | <br>15:20:52<br>27-Agu-2025   | <br>15:21:27<br>27-Agu-2025   | <br>15:21:44<br>27-Agu-2025   |
| 9  | 27-08-2025 | CARPARK          | GENERAL CLEANING | SUMPIT DAN GREASE ROOM LV.LG                | <br>23:14:02<br>27-Agu-2025  | <br>23:14:23<br>27-Agu-2025  | <br>23:14:41<br>27-Agu-2025  |
| 10 | 27-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.LG            | <br>23:20:36<br>27-Agu-2025 | <br>23:21:08<br>27-Agu-2025 | <br>23:21:23<br>27-Agu-2025 |
| 11 | 27-08-2025 | KORIDOR SHOPPING | WASHING          | BRUSHING KORIDOR LANTAI KULIT JERUK LV.3    | <br>23:15:30<br>27-Agu-2025 | <br>23:15:47<br>27-Agu-2025 | <br>23:16:13<br>27-Agu-2025 |
| 12 | 27-08-2025 | KORIDOR SHOPPING | WASHING          | BRUSHING KORIDOR LANTAI KULIT JERUK LV.4    | <br>23:16:44<br>27-Agu-2025 | <br>23:17:04<br>27-Agu-2025 | <br>23:17:20<br>27-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                           | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 27-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.3                      | <br>22:29:15<br>27-Agu-2025   | <br>22:29:26<br>27-Agu-2025   | <br>22:29:38<br>27-Agu-2025   |
| 14 | 27-08-2025 | KORIDOR SHOPPING | DUSTING        | SHINING POLISH ALL TRASHCAN AREA KORIDOR SHOPPING LV.UG-10 | <br>22:33:27<br>27-Agu-2025   | <br>22:33:40<br>27-Agu-2025   | <br>22:33:51<br>27-Agu-2025   |
| 15 | 27-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.1-5           | <br>15:41:02<br>27-Agu-2025  | <br>15:41:22<br>27-Agu-2025  | <br>15:41:37<br>27-Agu-2025  |
| 16 | 27-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.8-9           | <br>15:22:30<br>27-Agu-2025 | <br>15:22:54<br>27-Agu-2025 | <br>15:23:08<br>27-Agu-2025 |
| 17 | 27-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LIST KACA SISI DEPAN TENANT LV.4-5                 | <br>15:38:49<br>27-Agu-2025 | <br>15:39:04<br>27-Agu-2025 | <br>15:39:56<br>27-Agu-2025 |
| 18 | 27-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.3       | <br>22:34:14<br>27-Agu-2025 | <br>22:34:23<br>27-Agu-2025 | <br>22:34:34<br>27-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan   | DetailPekerjaan                  | Before                                                                             | Progress                                                                            | After                                                                                |
|----|------------|------------------|------------------|----------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| 19 | 27-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING VINYL LV.10        |   |   |   |
| 20 | 27-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.5     |   |   |   |
| 21 | 27-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN PLAFON/ATAP HPL LV.4 |  |  |  |

| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|--------------|------------------|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 28-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI BAWAH UNION                       | <br>07:07:03<br>28-Agu-2025   | <br>07:07:39<br>28-Agu-2025   | <br>07:09:46<br>28-Agu-2025   |
| 2  | 28-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.3-4 (UP&DOWN)                         | <br>02:12:47<br>28-Agu-2025   | <br>02:13:01<br>28-Agu-2025   | <br>02:13:21<br>28-Agu-2025   |
| 3  | 28-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.1 | <br>02:24:41<br>28-Agu-2025  | <br>02:14:29<br>28-Agu-2025  | <br>02:24:54<br>28-Agu-2025  |
| 4  | 28-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI SELA/SUDUT CLOSET TOILET MALE FEMALE DISABLE      | <br>02:15:37<br>28-Agu-2025 | <br>02:16:18<br>28-Agu-2025 | <br>02:15:54<br>28-Agu-2025 |
| 5  | 28-08-2025 | CARPARK      | GENERAL CLEANING | PEMBERSIHAN AREA CARPARK LV.LG                                 | <br>02:17:23<br>28-Agu-2025 | <br>02:17:40<br>28-Agu-2025 | <br>02:17:58<br>28-Agu-2025 |
| 6  | 28-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE 9 & 10                     | <br>22:26:44<br>28-Agu-2025 | <br>22:26:56<br>28-Agu-2025 | <br>22:27:08<br>28-Agu-2025 |




| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                        | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|----------------|---------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 28-08-2025 | CARPARK          | WALL CLEANING  | WALL CLEANING AREA DEPAN LIFT SERVICE 9 & 10            | <br>11:19:10<br>28-Agu-2025   | <br>11:19:35<br>28-Agu-2025   | <br>11:20:00<br>28-Agu-2025   |
| 8  | 28-08-2025 | CARPARK          | WASHING        | PENCUCIAN TRASHCAN CARPARK LV.P6A                       | <br>02:23:07<br>28-Agu-2025   | <br>02:23:22<br>28-Agu-2025   | <br>02:23:40<br>28-Agu-2025   |
| 9  | 28-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN GRILL AC, EXHAUST FAN, SMOKE DETECTOR LV.UG | <br>22:29:24<br>28-Agu-2025  | <br>22:29:33<br>28-Agu-2025  | <br>22:29:43<br>28-Agu-2025  |
| 10 | 28-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR LANTAI KULIT JERUK LV.5                | <br>02:21:10<br>28-Agu-2025 | <br>02:21:35<br>28-Agu-2025 | <br>02:21:49<br>28-Agu-2025 |
| 11 | 28-08-2025 | KORIDOR SHOPPING | GLASS CLEANING | GLASS CLEANING SISI DEPAN TENANT LV.4                   | <br>20:10:15<br>28-Agu-2025 | <br>20:13:54<br>28-Agu-2025 | <br>20:12:47<br>28-Agu-2025 |
| 12 | 28-08-2025 | KORIDOR SHOPPING | DUSTING        | PEMBERSIHAN SUDUT LANTAI KORIDOR SHOPPING LV.6-10       | <br>11:26:13<br>28-Agu-2025 | <br>11:28:10<br>28-Agu-2025 | <br>11:27:00<br>28-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                     | Before                                                                                                         | Progress                                                                                                        | After                                                                                                            |
|----|------------|------------------|------------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 28-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LOGO NAMA TENANT & SIGN DIRECTION LV.10      | <br>11:30:14<br>28-Agu-2025   | <br>11:30:36<br>28-Agu-2025   | <br>11:30:24<br>28-Agu-2025   |
| 14 | 28-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.6-7           | <br>11:22:43<br>28-Agu-2025   | <br>11:23:31<br>28-Agu-2025   | <br>11:22:56<br>28-Agu-2025   |
| 15 | 28-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.4 | <br>22:29:59<br>28-Agu-2025  | <br>22:30:08<br>28-Agu-2025  | <br>22:30:17<br>28-Agu-2025  |
| 16 | 28-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.4                         | <br>22:28:03<br>28-Agu-2025 | <br>22:28:14<br>28-Agu-2025 | <br>22:28:28<br>28-Agu-2025 |
| 17 | 28-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | PEMBERSIHAN PLAFON/ATAP HPL LV.5                     | <br>22:27:24<br>28-Agu-2025 | <br>22:27:32<br>28-Agu-2025 | <br>22:27:43<br>28-Agu-2025 |






| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                               | Before                                                                              | Progress                                                                             | After                                                                                 |
|----|------------|------------------|------------------|----------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| 1  | 29-08-2025 | ESCALATOR        | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.4-5 (UP&DOWN)                         |    |    |    |
| 2  | 29-08-2025 | KRISTALISASI     | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.2 |    |    |    |
| 3  | 29-08-2025 | CARPARK          | WASHING          | PENCUCIAN LANTAI DEPAN LIFT SERVICE LT.1 & 2                   |   |   |   |
| 4  | 29-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA DEPAN LIFT SERVICE LT.1 & 2                 |  |  |  |
| 5  | 29-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7A                              |  |  |  |
| 6  | 29-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.8-9                     |  |  |  |


| No | Tanggal    | Area             | Item Pekerjaan   | DetailPekerjaan                                                                 | Before                                                                                                       | Progress                                                                                                      | After                                                                                                          |
|----|------------|------------------|------------------|---------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|
| 7  | 29-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER & SISI ARAH PAKUWON TOWER LV.UG | <br>11:25:45<br>29-Agu-2025 | <br>11:26:14<br>29-Agu-2025 | <br>11:26:38<br>29-Agu-2025 |
| 8  | 29-08-2025 | KORIDOR SHOPPING | GENERAL CLEANING | GENERAL CLEANING TOILET LV.3                                                    | <br>20:53:10<br>29-Agu-2025 | <br>20:53:30<br>29-Agu-2025 | <br>20:53:55<br>29-Agu-2025 |



| No | Tanggal    | Area         | Item Pekerjaan   | Detail Pekerjaan                                                | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|--------------|------------------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 1  | 30-08-2025 | GUTTER       | SWEEPING         | SWEEPING SALURAN GUTTER SISI OUT MOBIL                          | <br>07:18:42<br>30-Agu-2025   | <br>07:19:18<br>30-Agu-2025   | <br>07:22:26<br>30-Agu-2025   |
| 2  | 30-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.5-6 (UP&DOWN)                          | <br>04:59:59<br>30-Agu-2025   | <br>05:00:18<br>30-Agu-2025   | <br>05:00:36<br>30-Agu-2025   |
| 3  | 30-08-2025 | ESCALATOR    | GENERAL CLEANING | PEMBERSIHAN ESCALATOR LV.6-7 (UP&DOWN)                          | <br>05:01:03<br>30-Agu-2025  | <br>05:01:35<br>30-Agu-2025  | <br>05:01:50<br>30-Agu-2025  |
| 4  | 30-08-2025 | KRISTALISASI | KRISTALISASI     | KRISTALISASI TOILET PRIA + TOILET WANITA + KORIDOR TOILET LV.UG | <br>05:06:33<br>30-Agu-2025 | <br>05:02:51<br>30-Agu-2025 | <br>05:06:52<br>30-Agu-2025 |
| 5  | 30-08-2025 | KRISTALISASI | KRISTALISASI     | REVONTULET KORIDOR LIFT SERVICE LT.1 & 2                        | <br>05:03:25<br>30-Agu-2025 | <br>05:03:49<br>30-Agu-2025 | <br>05:04:14<br>30-Agu-2025 |
| 6  | 30-08-2025 | CARPARK      | WASHING          | PENCUCIAN LANTAI LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG     | <br>20:16:38<br>30-Agu-2025 | <br>20:17:11<br>30-Agu-2025 | <br>20:23:01<br>30-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan   | Detail Pekerjaan                                              | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|------------------|---------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 7  | 30-08-2025 | CARPARK          | WALL CLEANING    | WALL CLEANING AREA LOADING DOCK DEPAN LIFT SERVICE LT.LG & UG | <br>09:10:30<br>30-Agu-2025   | <br>09:12:59<br>30-Agu-2025   | <br>09:13:34<br>30-Agu-2025   |
| 8  | 30-08-2025 | CARPARK          | GENERAL CLEANING | PEMBERSIHAN TOILET CARPARK LV.LG                              | <br>08:45:16<br>30-Agu-2025   | <br>08:58:23<br>30-Agu-2025   | <br>09:00:09<br>30-Agu-2025   |
| 9  | 30-08-2025 | CARPARK          | WASHING          | PENCUCIAN TRASHCAN CARPARK LV.P7B                             | <br>05:05:09<br>30-Agu-2025  | <br>05:05:23<br>30-Agu-2025  | <br>05:05:40<br>30-Agu-2025  |
| 10 | 30-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING BADUKAN, SELA SELA HAND RALLING LV.1-5                | <br>13:01:41<br>30-Agu-2025 | <br>13:03:05<br>30-Agu-2025 | <br>13:02:30<br>30-Agu-2025 |
| 11 | 30-08-2025 | KORIDOR SHOPPING | DUSTING          | DUSTING LIST KACA SISI DEPAN TENANT LV.10                     | <br>13:08:15<br>30-Agu-2025 | <br>13:08:36<br>30-Agu-2025 | <br>13:08:26<br>30-Agu-2025 |
| 12 | 30-08-2025 | KORIDOR SHOPPING | WALL CLEANING    | WALL CLEANING DINDING SISI DEPAN LIFT PASSENGER LV.5          | <br>09:21:15<br>30-Agu-2025 | <br>09:21:55<br>30-Agu-2025 | <br>09:22:50<br>30-Agu-2025 |



| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                              | Before                                                                                                         | Progress                                                                                                         | After                                                                                                            |
|----|------------|------------------|----------------|-----------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| 13 | 30-08-2025 | KORIDOR SHOPPING | DUSTING        | DUSTING LED PROMO LV.1 S.D LV.4               | <br>13:05:51<br>30-Agu-2025   | <br>13:07:06<br>30-Agu-2025   | <br>13:06:40<br>30-Agu-2025   |
| 14 | 30-08-2025 | KORIDOR SHOPPING | SWEEPING       | PEMBERSIHAN PLANTER BOX LV.UG                 | <br>10:18:21<br>30-Agu-2025   | <br>10:19:39<br>30-Agu-2025   | <br>10:20:06<br>30-Agu-2025   |
| 15 | 30-08-2025 | KORIDOR SHOPPING | DUSTING        | SELA SELA PILLAR UTAMA /KOLOM PILAR LV.UG & 1 | <br>10:21:44<br>30-Agu-2025  | <br>10:33:34<br>30-Agu-2025  | <br>10:22:33<br>30-Agu-2025  |
| 16 | 30-08-2025 | KORIDOR SHOPPING | WASHING        | PENCUCIAN TRASHCAN LV.UG S.D LV.5             | <br>21:49:52<br>30-Agu-2025 | <br>21:50:17<br>30-Agu-2025 | <br>21:50:54<br>30-Agu-2025 |
| 17 | 30-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING VINYL LV.5                      | <br>09:18:01<br>30-Agu-2025 | <br>09:18:29<br>30-Agu-2025 | <br>09:19:38<br>30-Agu-2025 |
| 18 | 30-08-2025 | KORIDOR SHOPPING | WALL CLEANING  | WALL CLEANING KORIDOR EXIT 24 LV.UG           | <br>09:26:38<br>30-Agu-2025 | <br>09:27:15<br>30-Agu-2025 | <br>09:27:58<br>30-Agu-2025 |

| No | Tanggal    | Area             | Item Pekerjaan | Detail Pekerjaan                                                      | Before                                                                            | Progress                                                                            | After                                                                               |
|----|------------|------------------|----------------|-----------------------------------------------------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 19 | 30-08-2025 | KORIDOR SHOPPING | WASHING        | BRUSHING KORIDOR EXIT 24 LV.UG                                        |  |  |  |
| 20 | 30-08-2025 | KORIDOR SHOPPING | DUSTING        | BUNGA HIAS AREA LOBBY,SISI PILLAR,SISI DEPAN LIFT PASSENGER LV.UG-1-2 |  |  |  |