











No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	01-08-2025	LANTAI 1	POLISHING	PINTU LIFT			
2	01-08-2025	LANTAI 1	HIGH DUSTING	CEILING FAN			
3	01-08-2025	LANTAI 1	POLISHING	CLOSET			
4	01-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH			
5	01-08-2025	LANTAI 2	HIGH DUSTING	CEILING FAN			
6	01-08-2025	LANTAI 3	POLISHING	URINOIR			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	01-08-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 13:54:25 01-Agu-2025	 13:54:40 01-Agu-2025	 13:54:50 01-Agu-2025
8	01-08-2025	LANTAI 3	WALL CLEANING	PINTU LIFT	 13:53:04 01-Agu-2025	 13:53:18 01-Agu-2025	 13:53:27 01-Agu-2025
9	01-08-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 17:02:50 01-Agu-2025	 17:03:16 01-Agu-2025	 17:03:33 01-Agu-2025
10	01-08-2025	EXTERNAL	POLISHING	PIPA HYDRANT	 13:45:59 01-Agu-2025	 13:46:11 01-Agu-2025	 13:46:27 01-Agu-2025
11	01-08-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT	 17:43:46 01-Agu-2025	 17:44:08 01-Agu-2025	 17:44:27 01-Agu-2025
12	01-08-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH	 16:58:32 01-Agu-2025	 16:58:54 01-Agu-2025	 16:59:18 01-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	01-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 17:45:52 01-Agu-2025	 17:46:12 01-Agu-2025	 17:46:33 01-Agu-2025
14	01-08-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 17:49:34 01-Agu-2025	 17:49:55 01-Agu-2025	 17:50:35 01-Agu-2025
15	01-08-2025	BASEMENT	POLISHING	STAINLESS BULAT	 16:54:29 01-Agu-2025	 16:55:02 01-Agu-2025	 16:55:28 01-Agu-2025
16	01-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 13:51:51 01-Agu-2025	 13:52:04 01-Agu-2025	 13:52:17 01-Agu-2025
17	01-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 13:49:08 01-Agu-2025	 13:49:19 01-Agu-2025	 13:49:31 01-Agu-2025
18	01-08-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 13:48:26 01-Agu-2025	 13:48:40 01-Agu-2025	 13:48:51 01-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	01-08-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	04-08-2025	LANTAI 1	WALL CLEANING	DINDING LIFT	 20:41:41 04-Agu-2025	 20:42:11 04-Agu-2025	 20:43:01 04-Agu-2025
2	04-08-2025	LANTAI 1	SPOTTING	LIST SKIRTING	 20:37:46 04-Agu-2025	 20:38:11 04-Agu-2025	 20:38:40 04-Agu-2025
3	04-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH	 20:39:17 04-Agu-2025	 20:39:49 04-Agu-2025	 20:40:28 04-Agu-2025
4	04-08-2025	LANTAI 2	POLISHING	CLOSET	 11:31:36 04-Agu-2025	 11:32:26 04-Agu-2025	 11:32:38 04-Agu-2025
5	04-08-2025	LANTAI 2	POLISHING	KUBIKAL	 11:30:44 04-Agu-2025	 11:30:57 04-Agu-2025	 11:31:19 04-Agu-2025
6	04-08-2025	LANTAI 2	BRUSHING	GUTTER	 20:55:28 04-Agu-2025	 20:55:49 04-Agu-2025	 20:56:09 04-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	04-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH STAINLESS	 11:29:11 04-Agu-2025	 11:29:51 04-Agu-2025	 11:30:27 04-Agu-2025
8	04-08-2025	LANTAI 3	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 11:33:29 04-Agu-2025	 11:33:47 04-Agu-2025	 11:34:03 04-Agu-2025
9	04-08-2025	LANTAI 3	GENERAL CLEANING	PLANTER BOX	 11:38:51 04-Agu-2025	 11:39:07 04-Agu-2025	 11:39:30 04-Agu-2025
10	04-08-2025	LANTAI 3	POLISHING	MEJA	 11:37:30 04-Agu-2025	 11:37:46 04-Agu-2025	 11:38:04 04-Agu-2025
11	04-08-2025	LANTAI 3	GLASS CLEANING	MIRROR	 20:43:36 04-Agu-2025	 20:43:58 04-Agu-2025	 20:44:18 04-Agu-2025
12	04-08-2025	LANTAI 3	SPOTTING	SOFA	 11:36:13 04-Agu-2025	 11:36:50 04-Agu-2025	 11:37:04 04-Agu-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	04-08-2025	EXTERNAL	POLISHING	DINDING CAT	 11:35:16 04-Agu-2025	 11:35:29 04-Agu-2025	 11:35:47 04-Agu-2025
14	04-08-2025	EXTERNAL	BRUSHING	LOGO JKTP	 20:57:24 04-Agu-2025	 20:57:48 04-Agu-2025	 20:58:23 04-Agu-2025
15	04-08-2025	BASEMENT	HIGH DUSTING	CEILING FAN	 21:10:57 04-Agu-2025	 21:12:34 04-Agu-2025	 21:11:12 04-Agu-2025
16	04-08-2025	BASEMENT	PLAFON CLEANING	CEILING	 21:14:26 04-Agu-2025	 21:15:58 04-Agu-2025	 21:14:48 04-Agu-2025
17	04-08-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX	 21:17:38 04-Agu-2025	 21:18:02 04-Agu-2025	 21:19:24 04-Agu-2025
18	04-08-2025	BASEMENT	POLISHING	TUTUP SAMPIT	 21:20:12 04-Agu-2025	 21:20:36 04-Agu-2025	 21:20:53 04-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	04-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI	 20:45:03 04-Agu-2025	 20:45:40 04-Agu-2025	 20:46:10 04-Agu-2025
20	04-08-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA	 20:46:52 04-Agu-2025	 20:47:20 04-Agu-2025	 20:47:50 04-Agu-2025
21	04-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI	 20:48:42 04-Agu-2025	 20:49:12 04-Agu-2025	 20:50:03 04-Agu-2025
22	04-08-2025	CARPARK P1-P2	POLISHING	RAILING	 20:50:54 04-Agu-2025	 20:51:19 04-Agu-2025	 20:51:45 04-Agu-2025
23	04-08-2025	CARPARK P1-P2	BRUSHING	LANTAI KERAMIK	 20:52:24 04-Agu-2025	 20:52:47 04-Agu-2025	 20:53:39 04-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	05-08-2025	LANTAI 1	SPOTTING	KURSI			
2	05-08-2025	LANTAI 1	GENERAL CLEANING	GLASS CANOPY ESCALATOR			
3	05-08-2025	LANTAI 1	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN			
4	05-08-2025	LANTAI 1	GLASS CLEANING	KACA			
5	05-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA			
6	05-08-2025	LANTAI 2	GENERAL CLEANING	GLASS CANOPY ESCALATOR			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	05-08-2025	LANTAI 2	WALL CLEANING	PLANTER BOX			
8	05-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH			
9	05-08-2025	LANTAI 3	POLISHING	KUBIKAL			
10	05-08-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE			
11	05-08-2025	LANTAI 3	WALL CLEANING	HAND RAILING			
12	05-08-2025	LANTAI 3	POLISHING	KURSI			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	05-08-2025	LANTAI 3	POLISHING	WASTAFEL	 18:28:34 05-Agu-2025	 18:29:05 05-Agu-2025	 18:29:27 05-Agu-2025
14	05-08-2025	LANTAI 3	GENERAL CLEANING	TRANSPARENT CANOPY	 20:35:07 05-Agu-2025	 20:35:36 05-Agu-2025	 20:35:54 05-Agu-2025
15	05-08-2025	EXTERNAL	GENERAL CLEANING	GUTTER	 11:57:07 05-Agu-2025	 11:57:22 05-Agu-2025	 11:58:02 05-Agu-2025
16	05-08-2025	EXTERNAL	WALL CLEANING	BATU ALAM	 20:33:35 05-Agu-2025	 20:34:06 05-Agu-2025	 20:34:27 05-Agu-2025
17	05-08-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 18:30:46 05-Agu-2025	 18:31:05 05-Agu-2025	 18:31:32 05-Agu-2025
18	05-08-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 18:41:07 05-Agu-2025	 18:41:30 05-Agu-2025	 18:41:56 05-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	05-08-2025	BASEMENT	GENERAL CLEANING	DINDING PLANTER BOX	 18:37:13 05-Agu-2025	 18:38:19 05-Agu-2025	 18:38:37 05-Agu-2025
20	05-08-2025	BASEMENT	WASHING	LANTAI EPOXY	 18:34:46 05-Agu-2025	 18:35:10 05-Agu-2025	 18:35:33 05-Agu-2025
21	05-08-2025	BASEMENT	WASHING	TEMPAT SAMPAH	 18:32:51 05-Agu-2025	 18:33:08 05-Agu-2025	 18:33:26 05-Agu-2025
22	05-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 11:29:32 05-Agu-2025	 11:29:42 05-Agu-2025	 11:29:54 05-Agu-2025
23	05-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 11:28:39 05-Agu-2025	 11:28:59 05-Agu-2025	 11:29:10 05-Agu-2025
24	05-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 11:26:44 05-Agu-2025	 11:27:24 05-Agu-2025	 11:27:46 05-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	05-08-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR			
26	05-08-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	06-08-2025	LANTAI 1	BRUSHING	LANTAI CONCRETE			
2	06-08-2025	LANTAI 1	POLISHING	KUBIKAL			
3	06-08-2025	LANTAI 1	POLISHING	PINTU EXIT			
4	06-08-2025	LANTAI 2	GENERAL CLEANING	TEMPAT SAMPAH			
5	06-08-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR			
6	06-08-2025	LANTAI 2	POLISHING	CLOSET			





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	06-08-2025	LANTAI 2	POLISHING	CLOSET			
8	06-08-2025	LANTAI 3	POLISHING	CLOSET			
9	06-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS			
10	06-08-2025	LANTAI 3	POLISHING	TRAY			
11	06-08-2025	LANTAI 1	GENERAL CLEANING	PLANTER BOX			
12	06-08-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	06-08-2025	BASEMENT	POLISHING	LANDING ESCALATOR			
14	06-08-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG			
15	06-08-2025	BASEMENT	WALL CLEANING	PILAR BETON			
16	06-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU			
17	06-08-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	07-08-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK	 21:10:18 07-Agu-2025	 21:10:43 07-Agu-2025	 21:11:04 07-Agu-2025
2	07-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS	 21:12:16 07-Agu-2025	 21:13:29 07-Agu-2025	 21:13:59 07-Agu-2025
3	07-08-2025	LANTAI 1	POLISHING	WASTAFEL	 18:39:32 07-Agu-2025	 18:38:56 07-Agu-2025	 18:39:53 07-Agu-2025
4	07-08-2025	LANTAI 1	SWEEPING	TANGGA	 18:44:51 07-Agu-2025	 18:45:10 07-Agu-2025	 18:45:28 07-Agu-2025
5	07-08-2025	LANTAI 2	SPOTTING	SOFA	 21:17:02 07-Agu-2025	 21:17:36 07-Agu-2025	 21:18:44 07-Agu-2025
6	07-08-2025	LANTAI 2	WALL CLEANING	PINTU LIFT	 18:47:46 07-Agu-2025	 18:48:03 07-Agu-2025	 18:48:18 07-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	07-08-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE	 21:20:43 07-Agu-2025	 21:21:25 07-Agu-2025	 21:21:41 07-Agu-2025
8	07-08-2025	LANTAI 2	POLISHING	RAK ACCESORIS	 18:57:58 07-Agu-2025	 18:58:19 07-Agu-2025	 18:58:48 07-Agu-2025
9	07-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 21:29:54 07-Agu-2025	 21:29:14 07-Agu-2025	 21:30:29 07-Agu-2025
10	07-08-2025	LANTAI 2	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 21:24:20 07-Agu-2025	 21:25:01 07-Agu-2025	 21:25:41 07-Agu-2025
11	07-08-2025	LANTAI 3	BRUSHING	LANTAI GRANIT BAKAR	 18:55:48 07-Agu-2025	 18:56:10 07-Agu-2025	 18:56:30 07-Agu-2025
12	07-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH	 18:34:12 07-Agu-2025	 18:34:34 07-Agu-2025	 18:34:59 07-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	07-08-2025	LANTAI 3	GLASS CLEANING	KACA RAILING	 21:23:21 07-Agu-2025	 21:22:59 07-Agu-2025	 21:23:18 07-Agu-2025
14	07-08-2025	EXTERNAL	GENERAL CLEANING	DINDING BETON	 18:15:38 07-Agu-2025	 18:15:56 07-Agu-2025	 18:16:18 07-Agu-2025
15	07-08-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR	 18:30:36 07-Agu-2025	 18:31:06 07-Agu-2025	 18:31:36 07-Agu-2025
16	07-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK	 18:28:30 07-Agu-2025	 18:28:47 07-Agu-2025	 18:29:07 07-Agu-2025
17	07-08-2025	BASEMENT	PLAFON CLEANING	CEILING	 18:35:48 07-Agu-2025	 18:36:20 07-Agu-2025	 18:36:50 07-Agu-2025
18	07-08-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR	 18:25:47 07-Agu-2025	 18:25:23 07-Agu-2025	 18:26:09 07-Agu-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	07-08-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC	 21:15:06 07-Agu-2025	 21:15:22 07-Agu-2025	 21:15:43 07-Agu-2025
20	07-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING	 21:13:46 07-Agu-2025	 21:14:02 07-Agu-2025	 21:14:18 07-Agu-2025
21	07-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 18:20:28 07-Agu-2025	 18:20:50 07-Agu-2025	 18:21:06 07-Agu-2025
22	07-08-2025	CARPARK P1-P2	HIGH DUSTING	OUTDOOR AC	 21:10:31 07-Agu-2025	 21:10:47 07-Agu-2025	 21:11:00 07-Agu-2025
23	07-08-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 18:17:29 07-Agu-2025	 18:17:48 07-Agu-2025	 18:18:13 07-Agu-2025
24	07-08-2025	CARPARK P1-P2	GENERAL CLEANING	DRAIN COVER METAL COVER CEMENT	 21:11:45 07-Agu-2025	 21:12:12 07-Agu-2025	 21:12:29 07-Agu-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	08-08-2025	LANTAI 1	POLISHING	PINTU LIFT			
2	08-08-2025	LANTAI 1	HIGH DUSTING	CEILING FAN			
3	08-08-2025	LANTAI 1	POLISHING	CLOSET			
4	08-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH			
5	08-08-2025	LANTAI 2	HIGH DUSTING	CEILING FAN			
6	08-08-2025	LANTAI 3	POLISHING	URINOIR			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	08-08-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 13:58:48 08-Agu-2025	 13:59:01 08-Agu-2025	 13:59:16 08-Agu-2025
8	08-08-2025	LANTAI 3	WALL CLEANING	PINTU LIFT	 13:59:48 08-Agu-2025	 14:00:01 08-Agu-2025	 14:00:17 08-Agu-2025
9	08-08-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 17:52:46 08-Agu-2025	 17:53:10 08-Agu-2025	 17:53:34 08-Agu-2025
10	08-08-2025	EXTERNAL	POLISHING	PIPA HYDRANT	 14:00:49 08-Agu-2025	 14:01:00 08-Agu-2025	 14:01:13 08-Agu-2025
11	08-08-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT	 17:57:28 08-Agu-2025	 17:57:49 08-Agu-2025	 17:58:15 08-Agu-2025
12	08-08-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH	 17:56:07 08-Agu-2025	 17:56:29 08-Agu-2025	 17:56:52 08-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	08-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 17:59:35 08-Agu-2025	 17:59:59 08-Agu-2025	 18:00:22 08-Agu-2025
14	08-08-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 18:01:53 08-Agu-2025	 18:02:15 08-Agu-2025	 18:02:38 08-Agu-2025
15	08-08-2025	BASEMENT	POLISHING	STAINLESS BULAT	 13:55:18 08-Agu-2025	 13:55:31 08-Agu-2025	 13:55:49 08-Agu-2025
16	08-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 13:54:03 08-Agu-2025	 13:54:21 08-Agu-2025	 13:54:33 08-Agu-2025
17	08-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 14:05:12 08-Agu-2025	 14:05:25 08-Agu-2025	 14:05:37 08-Agu-2025
18	08-08-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 14:06:03 08-Agu-2025	 14:06:22 08-Agu-2025	 14:06:35 08-Agu-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	08-08-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT	 14:07:18 08-Agu-2025	 14:07:32 08-Agu-2025	 14:07:44 08-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	11-08-2025	LANTAI 1	WALL CLEANING	DINDING LIFT			
2	11-08-2025	LANTAI 1	SPOTTING	LIST SKIRTING			
3	11-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH			
4	11-08-2025	LANTAI 2	POLISHING	CLOSET			
5	11-08-2025	LANTAI 2	POLISHING	KUBIKAL			
6	11-08-2025	LANTAI 2	BRUSHING	GUTTER			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	11-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH STAINLESS	 11:23:31 11-Agu-2025	 11:23:41 11-Agu-2025	 11:23:52 11-Agu-2025
8	11-08-2025	LANTAI 3	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 11:21:14 11-Agu-2025	 11:21:38 11-Agu-2025	 11:22:17 11-Agu-2025
9	11-08-2025	LANTAI 3	GENERAL CLEANING	PLANTER BOX	 11:27:15 11-Agu-2025	 11:27:33 11-Agu-2025	 11:27:51 11-Agu-2025
10	11-08-2025	LANTAI 3	POLISHING	MEJA	 11:26:10 11-Agu-2025	 11:26:25 11-Agu-2025	 11:26:35 11-Agu-2025
11	11-08-2025	LANTAI 3	GLASS CLEANING	MIRROR	 19:37:23 11-Agu-2025	 19:37:47 11-Agu-2025	 19:38:19 11-Agu-2025
12	11-08-2025	LANTAI 3	SPOTTING	SOFA	 11:25:42 11-Agu-2025	 11:25:51 11-Agu-2025	 11:26:00 11-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	11-08-2025	EXTERNAL	POLISHING	DINDING CAT	 11:24:33 11-Agu-2025	 11:24:51 11-Agu-2025	 11:25:05 11-Agu-2025
14	11-08-2025	EXTERNAL	BRUSHING	LOGO JKTP	 19:56:31 11-Agu-2025	 19:56:54 11-Agu-2025	 19:57:16 11-Agu-2025
15	11-08-2025	BASEMENT	HIGH DUSTING	CEILING FAN	 19:39:43 11-Agu-2025	 19:40:05 11-Agu-2025	 19:40:27 11-Agu-2025
16	11-08-2025	BASEMENT	PLAFON CLEANING	CEILING	 19:41:20 11-Agu-2025	 19:41:44 11-Agu-2025	 19:42:08 11-Agu-2025
17	11-08-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX	 19:54:37 11-Agu-2025	 19:55:02 11-Agu-2025	 19:55:23 11-Agu-2025
18	11-08-2025	BASEMENT	POLISHING	TUTUP SAMPIT	 19:58:14 11-Agu-2025	 19:58:46 11-Agu-2025	 19:59:11 11-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	11-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI	 19:43:38 11-Agu-2025	 19:44:01 11-Agu-2025	 19:44:25 11-Agu-2025
20	11-08-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA	 19:48:14 11-Agu-2025	 19:48:37 11-Agu-2025	 19:49:35 11-Agu-2025
21	11-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI	 19:45:34 11-Agu-2025	 19:46:00 11-Agu-2025	 19:46:45 11-Agu-2025
22	11-08-2025	CARPARK P1-P2	POLISHING	RAILING	 19:53:10 11-Agu-2025	 19:53:34 11-Agu-2025	 19:54:05 11-Agu-2025
23	11-08-2025	CARPARK P1-P2	BRUSHING	LANTAI KERAMIK	 19:51:20 11-Agu-2025	 19:51:44 11-Agu-2025	 19:52:06 11-Agu-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	12-08-2025	LANTAI 1	SPOTTING	KURSI	 11:37:19 12-Agu-2025	 11:37:31 12-Agu-2025	 11:37:42 12-Agu-2025
2	12-08-2025	LANTAI 1	GENERAL CLEANING	GLASS CANOPY ESCALATOR	 11:33:09 12-Agu-2025	 11:33:51 12-Agu-2025	 11:34:20 12-Agu-2025
3	12-08-2025	LANTAI 1	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 18:31:31 12-Agu-2025	 18:31:51 12-Agu-2025	 18:32:08 12-Agu-2025
4	12-08-2025	LANTAI 1	GLASS CLEANING	KACA	 11:27:39 12-Agu-2025	 11:27:55 12-Agu-2025	 11:28:09 12-Agu-2025
5	12-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 18:38:19 12-Agu-2025	 18:37:40 12-Agu-2025	 18:38:39 12-Agu-2025
6	12-08-2025	LANTAI 2	GENERAL CLEANING	GLASS CANOPY ESCALATOR	 11:35:44 12-Agu-2025	 11:35:54 12-Agu-2025	 11:36:11 12-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	12-08-2025	LANTAI 2	WALL CLEANING	PLANTER BOX			
8	12-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH			
9	12-08-2025	LANTAI 3	POLISHING	KUBIKAL			
10	12-08-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE			
11	12-08-2025	LANTAI 3	WALL CLEANING	HAND RAILING			
12	12-08-2025	LANTAI 3	POLISHING	KURSI			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	12-08-2025	LANTAI 3	POLISHING	WASTAFEL			
14	12-08-2025	LANTAI 3	GENERAL CLEANING	TRANSPARENT CANOPY			
15	12-08-2025	EXTERNAL	GENERAL CLEANING	GUTTER			
16	12-08-2025	EXTERNAL	WALL CLEANING	BATU ALAM			
17	12-08-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR			
18	12-08-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	12-08-2025	BASEMENT	GENERAL CLEANING	DINDING PLANTER BOX	 18:45:14 12-Agu-2025	 18:45:34 12-Agu-2025	 18:45:55 12-Agu-2025
20	12-08-2025	BASEMENT	WASHING	LANTAI EPOXY	 18:46:50 12-Agu-2025	 18:47:07 12-Agu-2025	 18:47:29 12-Agu-2025
21	12-08-2025	BASEMENT	WASHING	TEMPAT SAMPAH	 18:36:00 12-Agu-2025	 18:36:17 12-Agu-2025	 18:36:33 12-Agu-2025
22	12-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 11:25:39 12-Agu-2025	 11:25:46 12-Agu-2025	 11:25:59 12-Agu-2025
23	12-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 11:23:13 12-Agu-2025	 11:24:34 12-Agu-2025	 11:24:44 12-Agu-2025
24	12-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 11:22:08 12-Agu-2025	 11:22:38 12-Agu-2025	 11:22:49 12-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	12-08-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR	 11:30:11 12-Agu-2025	 11:30:29 12-Agu-2025	 11:30:51 12-Agu-2025
26	12-08-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX	 18:50:05 12-Agu-2025	 18:50:22 12-Agu-2025	 18:50:35 12-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	13-08-2025	LANTAI 1	BRUSHING	LANTAI CONCRETE			
2	13-08-2025	LANTAI 1	POLISHING	KUBIKAL			
3	13-08-2025	LANTAI 1	POLISHING	PINTU EXIT			
4	13-08-2025	LANTAI 2	GENERAL CLEANING	TEMPAT SAMPAH			
5	13-08-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR			
6	13-08-2025	LANTAI 2	POLISHING	CLOSET			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	13-08-2025	LANTAI 2	POLISHING	CLOSET			
8	13-08-2025	LANTAI 3	POLISHING	CLOSET			
9	13-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS			
10	13-08-2025	LANTAI 3	POLISHING	TRAY			
11	13-08-2025	LANTAI 1	GENERAL CLEANING	PLANTER BOX			
12	13-08-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	13-08-2025	BASEMENT	POLISHING	LANDING ESCALATOR			
14	13-08-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG			
15	13-08-2025	BASEMENT	WALL CLEANING	PILAR BETON			
16	13-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU			
17	13-08-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	14-08-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK			
2	14-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS			
3	14-08-2025	LANTAI 1	POLISHING	WASTAFEL			
4	14-08-2025	LANTAI 1	SWEEPING	TANGGA			
5	14-08-2025	LANTAI 2	SPOTTING	SOFA			
6	14-08-2025	LANTAI 2	WALL CLEANING	PINTU LIFT			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	14-08-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE	 11:29:18 14-Agu-2025	 11:29:28 14-Agu-2025	 11:29:44 14-Agu-2025
8	14-08-2025	LANTAI 2	POLISHING	RAK ACCESORIS	 19:37:52 14-Agu-2025	 19:38:16 14-Agu-2025	 19:39:19 14-Agu-2025
9	14-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 11:42:05 14-Agu-2025	 11:42:32 14-Agu-2025	 11:42:45 14-Agu-2025
10	14-08-2025	LANTAI 2	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 11:22:23 14-Agu-2025	 11:22:54 14-Agu-2025	 11:23:13 14-Agu-2025
11	14-08-2025	LANTAI 3	BRUSHING	LANTAI GRANIT BAKAR	 19:18:32 14-Agu-2025	 19:19:02 14-Agu-2025	 19:19:25 14-Agu-2025
12	14-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH	 19:22:06 14-Agu-2025	 19:22:29 14-Agu-2025	 19:23:05 14-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	14-08-2025	LANTAI 3	GLASS CLEANING	KACA RAILING			
14	14-08-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR			
15	14-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			
16	14-08-2025	BASEMENT	PLAFON CLEANING	CEILING			
17	14-08-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR			
18	14-08-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	14-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING	 11:36:51 14-Agu-2025	 11:37:21 14-Agu-2025	 11:37:46 14-Agu-2025
20	14-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 19:33:00 14-Agu-2025	 19:33:32 14-Agu-2025	 19:33:58 14-Agu-2025
21	14-08-2025	CARPARK P1-P2	HIGH DUSTING	OUTDOOR AC	 11:44:55 14-Agu-2025	 11:45:32 14-Agu-2025	 11:46:10 14-Agu-2025
22	14-08-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 19:36:11 14-Agu-2025	 19:36:46 14-Agu-2025	 19:37:07 14-Agu-2025
23	14-08-2025	CARPARK P1-P2	GENERAL CLEANING	DRAIN COVER METAL COVER CEMENT	 11:26:04 14-Agu-2025	 11:26:36 14-Agu-2025	 11:26:53 14-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	15-08-2025	LANTAI 1	POLISHING	PINTU LIFT	 14:20:16 15-Agu-2025	 14:20:33 15-Agu-2025	 14:20:48 15-Agu-2025
2	15-08-2025	LANTAI 1	HIGH DUSTING	CEILING FAN	 14:24:19 15-Agu-2025	 14:24:37 15-Agu-2025	 14:24:50 15-Agu-2025
3	15-08-2025	LANTAI 1	POLISHING	CLOSET	 14:26:44 15-Agu-2025	 14:26:55 15-Agu-2025	 14:27:08 15-Agu-2025
4	15-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 14:27:53 15-Agu-2025	 14:28:09 15-Agu-2025	 14:28:23 15-Agu-2025
5	15-08-2025	LANTAI 2	HIGH DUSTING	CEILING FAN	 18:54:59 15-Agu-2025	 18:55:17 15-Agu-2025	 18:55:37 15-Agu-2025
6	15-08-2025	LANTAI 3	POLISHING	URINOIR	 14:28:47 15-Agu-2025	 14:29:02 15-Agu-2025	 14:29:19 15-Agu-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	15-08-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 14:18:01 15-Agu-2025	 14:18:20 15-Agu-2025	 14:18:34 15-Agu-2025
8	15-08-2025	LANTAI 3	WALL CLEANING	PINTU LIFT	 14:19:00 15-Agu-2025	 14:19:15 15-Agu-2025	 14:19:41 15-Agu-2025
9	15-08-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 18:53:34 15-Agu-2025	 18:53:58 15-Agu-2025	 18:54:18 15-Agu-2025
10	15-08-2025	EXTERNAL	POLISHING	PIPA HYDRANT	 14:23:24 15-Agu-2025	 14:23:37 15-Agu-2025	 14:23:50 15-Agu-2025
11	15-08-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT	 18:56:41 15-Agu-2025	 18:57:00 15-Agu-2025	 18:57:23 15-Agu-2025
12	15-08-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH	 18:59:30 15-Agu-2025	 19:00:12 15-Agu-2025	 19:01:56 15-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	15-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 18:58:01 15-Agu-2025	 18:58:22 15-Agu-2025	 18:58:44 15-Agu-2025
14	15-08-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 19:07:43 15-Agu-2025	 19:08:04 15-Agu-2025	 19:08:37 15-Agu-2025
15	15-08-2025	BASEMENT	POLISHING	STAINLESS BULAT	 19:04:54 15-Agu-2025	 19:05:13 15-Agu-2025	 19:06:17 15-Agu-2025
16	15-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 14:16:44 15-Agu-2025	 14:16:57 15-Agu-2025	 14:17:11 15-Agu-2025
17	15-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 14:22:20 15-Agu-2025	 14:22:42 15-Agu-2025	 14:22:55 15-Agu-2025
18	15-08-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 14:21:21 15-Agu-2025	 14:21:42 15-Agu-2025	 14:21:56 15-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	15-08-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	18-08-2025	LANTAI 1	WALL CLEANING	DINDING LIFT	 18:33:03 18-Agu-2025	 18:33:33 18-Agu-2025	 18:34:06 18-Agu-2025
2	18-08-2025	LANTAI 1	SPOTTING	KURSI	 11:17:23 18-Agu-2025	 11:17:33 18-Agu-2025	 11:17:53 18-Agu-2025
3	18-08-2025	LANTAI 1	SPOTTING	LIST SKIRTING	 18:23:25 18-Agu-2025	 18:23:47 18-Agu-2025	 18:24:08 18-Agu-2025
4	18-08-2025	LANTAI 1	GENERAL CLEANING	GLASS CANOPY ESCALATOR	 11:45:38 18-Agu-2025	 11:45:48 18-Agu-2025	 11:46:08 18-Agu-2025
5	18-08-2025	LANTAI 1	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 18:28:32 18-Agu-2025	 18:29:01 18-Agu-2025	 18:29:15 18-Agu-2025
6	18-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH	 18:29:58 18-Agu-2025	 18:30:16 18-Agu-2025	 18:30:33 18-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	18-08-2025	LANTAI 1	GLASS CLEANING	KACA	 11:22:45 18-Agu-2025	 11:22:59 18-Agu-2025	 11:23:19 18-Agu-2025
8	18-08-2025	LANTAI 2	POLISHING	CLOSET	 11:23:49 18-Agu-2025	 11:24:17 18-Agu-2025	 11:24:33 18-Agu-2025
9	18-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 18:25:37 18-Agu-2025	 18:26:05 18-Agu-2025	 18:26:54 18-Agu-2025
10	18-08-2025	LANTAI 2	POLISHING	KUBIKAL	 11:32:20 18-Agu-2025	 11:32:33 18-Agu-2025	 11:32:44 18-Agu-2025
11	18-08-2025	LANTAI 2	GENERAL CLEANING	GLASS CANOPY ESCALATOR	 11:45:06 18-Agu-2025	 11:45:14 18-Agu-2025	 11:45:23 18-Agu-2025
12	18-08-2025	LANTAI 2	BRUSHING	GUTTER	 18:31:24 18-Agu-2025	 18:31:40 18-Agu-2025	 18:31:59 18-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	18-08-2025	LANTAI 2	WALL CLEANING	PLANTER BOX	 18:32:43 18-Agu-2025	 18:34:00 18-Agu-2025	 18:34:16 18-Agu-2025
14	18-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH STAINLESS	 11:21:30 18-Agu-2025	 11:21:45 18-Agu-2025	 11:22:07 18-Agu-2025
15	18-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 18:31:06 18-Agu-2025	 18:31:30 18-Agu-2025	 18:31:54 18-Agu-2025
16	18-08-2025	LANTAI 3	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 11:25:11 18-Agu-2025	 11:25:41 18-Agu-2025	 11:26:22 18-Agu-2025
17	18-08-2025	LANTAI 3	POLISHING	KUBIKAL	 11:33:07 18-Agu-2025	 11:33:20 18-Agu-2025	 11:33:37 18-Agu-2025
18	18-08-2025	LANTAI 3	GENERAL CLEANING	PLANTER BOX	 11:44:15 18-Agu-2025	 11:44:25 18-Agu-2025	 11:44:35 18-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	18-08-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE			
20	18-08-2025	LANTAI 3	WALL CLEANING	HAND RAILING			
21	18-08-2025	LANTAI 3	POLISHING	MEJA			
22	18-08-2025	LANTAI 3	POLISHING	KURSI			
23	18-08-2025	LANTAI 3	GLASS CLEANING	MIRROR			
24	18-08-2025	LANTAI 3	POLISHING	WASTAFEL			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	18-08-2025	LANTAI 3	SPOTTING	SOFA			
26	18-08-2025	LANTAI 3	GENERAL CLEANING	TRANSPARENT CANOPY			
27	18-08-2025	EXTERNAL	POLISHING	DINDING CAT			
28	18-08-2025	EXTERNAL	GENERAL CLEANING	GUTTER			
29	18-08-2025	EXTERNAL	BRUSHING	LOGO JKTP0			
30	18-08-2025	EXTERNAL	WALL CLEANING	BATU ALAM			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	18-08-2025	BASEMENT	HIGH DUSTING	CEILING FAN	 18:39:22 18-Agu-2025	 18:39:46 18-Agu-2025	 18:40:06 18-Agu-2025
32	18-08-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 18:24:09 18-Agu-2025	 18:24:28 18-Agu-2025	 18:24:46 18-Agu-2025
33	18-08-2025	BASEMENT	PLAFON CLEANING	CEILING	 18:35:15 18-Agu-2025	 18:35:35 18-Agu-2025	 18:35:53 18-Agu-2025
34	18-08-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 18:11:46 18-Agu-2025	 18:12:03 18-Agu-2025	 18:12:27 18-Agu-2025
35	18-08-2025	BASEMENT	GENERAL CLEANING	DINDING PLANTER BOX	 18:14:09 18-Agu-2025	 18:14:23 18-Agu-2025	 18:14:38 18-Agu-2025
36	18-08-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX	 18:37:51 18-Agu-2025	 18:38:06 18-Agu-2025	 18:38:24 18-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	18-08-2025	BASEMENT	WASHING	LANTAI EPOXY			
38	18-08-2025	BASEMENT	POLISHING	TUTUP SAMPIT			
39	18-08-2025	BASEMENT	WASHING	TEMPAT SAMPAH			
40	18-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI			
41	18-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET			
42	18-08-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
43	18-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 11:29:36 18-Agu-2025	 11:29:45 18-Agu-2025	 11:30:02 18-Agu-2025
44	18-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI	 18:12:08 18-Agu-2025	 18:12:38 18-Agu-2025	 18:13:16 18-Agu-2025
45	18-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 11:28:31 18-Agu-2025	 11:28:49 18-Agu-2025	 11:29:02 18-Agu-2025
46	18-08-2025	CARPARK P1-P2	POLISHING	RAILING	 18:21:36 18-Agu-2025	 18:21:52 18-Agu-2025	 18:22:09 18-Agu-2025
47	18-08-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR	 11:38:24 18-Agu-2025	 11:38:34 18-Agu-2025	 11:38:44 18-Agu-2025
48	18-08-2025	CARPARK P1-P2	BRUSHING	LANTAI KERAMIK	 18:17:22 18-Agu-2025	 18:17:38 18-Agu-2025	 18:17:57 18-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
49	18-08-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	20-08-2025	LANTAI 1	BRUSHING	LANTAI CONCRETE	 20:15:05 20-Agu-2025	 20:15:30 20-Agu-2025	 20:15:59 20-Agu-2025
2	20-08-2025	LANTAI 1	POLISHING	KUBIKAL	 11:28:36 20-Agu-2025	 11:28:48 20-Agu-2025	 11:29:03 20-Agu-2025
3	20-08-2025	LANTAI 1	POLISHING	PINTU EXIT	 20:18:22 20-Agu-2025	 20:18:48 20-Agu-2025	 20:19:13 20-Agu-2025
4	20-08-2025	LANTAI 2	GENERAL CLEANING	TEMPAT SAMPAH	 20:19:57 20-Agu-2025	 20:20:36 20-Agu-2025	 20:20:57 20-Agu-2025
5	20-08-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR	 20:21:39 20-Agu-2025	 20:22:03 20-Agu-2025	 20:22:29 20-Agu-2025
6	20-08-2025	LANTAI 2	POLISHING	CLOSET	 20:34:30 20-Agu-2025	 20:34:46 20-Agu-2025	 20:35:10 20-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	20-08-2025	LANTAI 2	POLISHING	CLOSET	 20:35:42 20-Agu-2025	 20:35:59 20-Agu-2025	 20:36:20 20-Agu-2025
8	20-08-2025	LANTAI 3	POLISHING	CLOSET	 20:38:58 20-Agu-2025	 20:39:19 20-Agu-2025	 20:39:44 20-Agu-2025
9	20-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS	 11:26:54 20-Agu-2025	 11:27:43 20-Agu-2025	 11:28:01 20-Agu-2025
10	20-08-2025	LANTAI 3	POLISHING	TRAY	 11:31:06 20-Agu-2025	 11:31:36 20-Agu-2025	 11:31:54 20-Agu-2025
11	20-08-2025	LANTAI 1	GENERAL CLEANING	PLANTER BOX	 20:23:43 20-Agu-2025	 20:24:07 20-Agu-2025	 20:24:30 20-Agu-2025
12	20-08-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN	 11:29:29 20-Agu-2025	 11:29:40 20-Agu-2025	 11:30:06 20-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	20-08-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 20:27:43 20-Agu-2025	 20:28:18 20-Agu-2025	 20:28:48 20-Agu-2025
14	20-08-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 20:29:26 20-Agu-2025	 20:29:47 20-Agu-2025	 20:30:06 20-Agu-2025
15	20-08-2025	BASEMENT	WALL CLEANING	PILAR BETON	 20:31:01 20-Agu-2025	 20:31:22 20-Agu-2025	 20:31:51 20-Agu-2025
16	20-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 20:32:55 20-Agu-2025	 20:33:17 20-Agu-2025	 20:33:38 20-Agu-2025
17	20-08-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER	 20:37:29 20-Agu-2025	 20:37:46 20-Agu-2025	 20:38:07 20-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	21-08-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK			
2	21-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS			
3	21-08-2025	LANTAI 1	POLISHING	WASTAFEL			
4	21-08-2025	LANTAI 1	SWEEPING	TANGGA			
5	21-08-2025	LANTAI 2	SPOTTING	SOFA			
6	21-08-2025	LANTAI 2	WALL CLEANING	PINTU LIFT			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	21-08-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE			
8	21-08-2025	LANTAI 2	POLISHING	RAK ACCESORIS			
9	21-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA			
10	21-08-2025	LANTAI 2	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN			
11	21-08-2025	LANTAI 3	BRUSHING	LANTAI GRANIT BAKAR			
12	21-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	21-08-2025	LANTAI 3	GLASS CLEANING	KACA RAILING			
14	21-08-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR			
15	21-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK			
16	21-08-2025	BASEMENT	PLAFON CLEANING	CEILING			
17	21-08-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR			
18	21-08-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	21-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING	 11:18:57 21-Agu-2025	 11:19:21 21-Agu-2025	 11:19:35 21-Agu-2025
20	21-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 18:42:32 21-Agu-2025	 18:42:46 21-Agu-2025	 18:43:09 21-Agu-2025
21	21-08-2025	CARPARK P1-P2	HIGH DUSTING	OUTDOOR AC	 11:20:01 21-Agu-2025	 11:20:14 21-Agu-2025	 11:20:26 21-Agu-2025
22	21-08-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 18:32:54 21-Agu-2025	 18:33:10 21-Agu-2025	 18:33:27 21-Agu-2025
23	21-08-2025	CARPARK P1-P2	GENERAL CLEANING	DRAIN COVER METAL COVER CEMENT	 11:15:52 21-Agu-2025	 11:16:24 21-Agu-2025	 11:16:38 21-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	22-08-2025	LANTAI 1	POLISHING	PINTU LIFT			
2	22-08-2025	LANTAI 1	HIGH DUSTING	CEILING FAN			
3	22-08-2025	LANTAI 1	POLISHING	CLOSET			
4	22-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH			
5	22-08-2025	LANTAI 2	HIGH DUSTING	CEILING FAN			
6	22-08-2025	LANTAI 3	POLISHING	URINOIR			


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	22-08-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 14:17:20 22-Agu-2025	 14:17:30 22-Agu-2025	 14:17:44 22-Agu-2025
8	22-08-2025	LANTAI 3	WALL CLEANING	PINTU LIFT	 14:16:47 22-Agu-2025	 14:16:58 22-Agu-2025	 14:17:07 22-Agu-2025
9	22-08-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 19:14:54 22-Agu-2025	 19:15:16 22-Agu-2025	 19:15:34 22-Agu-2025
10	22-08-2025	EXTERNAL	POLISHING	PIPA HYDRANT	 14:22:06 22-Agu-2025	 14:22:17 22-Agu-2025	 14:22:32 22-Agu-2025
11	22-08-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT	 19:17:27 22-Agu-2025	 19:17:42 22-Agu-2025	 19:18:02 22-Agu-2025
12	22-08-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH	 19:15:56 22-Agu-2025	 19:16:12 22-Agu-2025	 19:16:41 22-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	22-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 19:57:24 22-Agu-2025	 19:57:41 22-Agu-2025	 19:58:03 22-Agu-2025
14	22-08-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 20:03:20 22-Agu-2025	 20:03:48 22-Agu-2025	 20:04:04 22-Agu-2025
15	22-08-2025	BASEMENT	POLISHING	STAINLESS BULAT	 19:19:02 22-Agu-2025	 19:19:24 22-Agu-2025	 19:19:42 22-Agu-2025
16	22-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 14:14:20 22-Agu-2025	 14:14:30 22-Agu-2025	 14:14:44 22-Agu-2025
17	22-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 14:22:57 22-Agu-2025	 14:23:07 22-Agu-2025	 14:23:16 22-Agu-2025
18	22-08-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 14:15:00 22-Agu-2025	 14:15:12 22-Agu-2025	 14:15:27 22-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	22-08-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT	 14:24:13 22-Agu-2025	 14:24:25 22-Agu-2025	 14:24:36 22-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	25-08-2025	LANTAI 1	WALL CLEANING	DINDING LIFT	 19:07:11 25-Agu-2025	 19:07:32 25-Agu-2025	 19:07:56 25-Agu-2025
2	25-08-2025	LANTAI 1	SPOTTING	KURSI	 11:36:57 25-Agu-2025	 11:37:08 25-Agu-2025	 11:37:20 25-Agu-2025
3	25-08-2025	LANTAI 1	SPOTTING	LIST SKIRTING	 19:01:11 25-Agu-2025	 19:01:32 25-Agu-2025	 19:01:58 25-Agu-2025
4	25-08-2025	LANTAI 1	GENERAL CLEANING	GLASS CANOPY ESCALATOR	 11:31:53 25-Agu-2025	 11:32:14 25-Agu-2025	 11:32:26 25-Agu-2025
5	25-08-2025	LANTAI 1	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 19:43:58 25-Agu-2025	 19:44:17 25-Agu-2025	 19:44:39 25-Agu-2025
6	25-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH	 19:12:51 25-Agu-2025	 19:13:09 25-Agu-2025	 19:13:32 25-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	25-08-2025	LANTAI 1	GLASS CLEANING	KACA	 11:35:20 25-Agu-2025	 11:35:20 25-Agu-2025	 11:36:05 25-Agu-2025
8	25-08-2025	LANTAI 2	POLISHING	CLOSET	 11:44:05 25-Agu-2025	 11:44:17 25-Agu-2025	 11:44:29 25-Agu-2025
9	25-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA	 19:15:27 25-Agu-2025	 19:17:04 25-Agu-2025	 19:15:50 25-Agu-2025
10	25-08-2025	LANTAI 2	POLISHING	KUBIKAL	 11:47:35 25-Agu-2025	 11:47:43 25-Agu-2025	 11:47:53 25-Agu-2025
11	25-08-2025	LANTAI 2	GENERAL CLEANING	GLASS CANOPY ESCALATOR	 11:39:07 25-Agu-2025	 11:39:16 25-Agu-2025	 11:39:30 25-Agu-2025
12	25-08-2025	LANTAI 2	BRUSHING	GUTTER	 19:20:34 25-Agu-2025	 19:20:52 25-Agu-2025	 19:21:13 25-Agu-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	25-08-2025	LANTAI 2	WALL CLEANING	PLANTER BOX	 21:15:25 25-Agu-2025	 21:15:40 25-Agu-2025	 21:15:59 25-Agu-2025
14	25-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH STAINLESS	 11:38:01 25-Agu-2025	 11:38:14 25-Agu-2025	 11:38:31 25-Agu-2025
15	25-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 19:22:25 25-Agu-2025	 19:22:45 25-Agu-2025	 19:23:08 25-Agu-2025
16	25-08-2025	LANTAI 3	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN	 11:45:00 25-Agu-2025	 11:45:19 25-Agu-2025	 11:45:33 25-Agu-2025
17	25-08-2025	LANTAI 3	POLISHING	KUBIKAL	 11:45:58 25-Agu-2025	 11:46:17 25-Agu-2025	 11:46:39 25-Agu-2025
18	25-08-2025	LANTAI 3	GENERAL CLEANING	PLANTER BOX	 11:51:36 25-Agu-2025	 11:51:48 25-Agu-2025	 11:52:01 25-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	25-08-2025	LANTAI 3	BRUSHING	LANTAI CONCRETE	 11:40:18 25-Agu-2025	 11:40:38 25-Agu-2025	 11:41:01 25-Agu-2025
20	25-08-2025	LANTAI 3	WALL CLEANING	HAND RAILING	 11:50:42 25-Agu-2025	 11:50:54 25-Agu-2025	 11:51:08 25-Agu-2025
21	25-08-2025	LANTAI 3	POLISHING	MEJA	 11:49:27 25-Agu-2025	 11:49:43 25-Agu-2025	 11:49:53 25-Agu-2025
22	25-08-2025	LANTAI 3	POLISHING	KURSI	 11:48:46 25-Agu-2025	 11:49:00 25-Agu-2025	 11:49:10 25-Agu-2025
23	25-08-2025	LANTAI 3	GLASS CLEANING	MIRROR	 19:11:00 25-Agu-2025	 19:11:23 25-Agu-2025	 19:11:41 25-Agu-2025
24	25-08-2025	LANTAI 3	POLISHING	WASTAFEL	 19:17:51 25-Agu-2025	 19:18:12 25-Agu-2025	 19:18:34 25-Agu-2025





No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
25	25-08-2025	LANTAI 3	SPOTTING	SOFA			
26	25-08-2025	LANTAI 3	GENERAL CLEANING	TRANSPARENT CANOPY			
27	25-08-2025	EXTERNAL	POLISHING	DINDING CAT			
28	25-08-2025	EXTERNAL	GENERAL CLEANING	GUTTER			
29	25-08-2025	EXTERNAL	BRUSHING	LOGO JKTP0			
30	25-08-2025	EXTERNAL	WALL CLEANING	BATU ALAM			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
31	25-08-2025	BASEMENT	HIGH DUSTING	CEILING FAN	 18:43:23 25-Agu-2025	 18:43:56 25-Agu-2025	 18:44:17 25-Agu-2025
32	25-08-2025	BASEMENT	POLISHING	BODY STAINLESS ESCALATOR	 18:46:37 25-Agu-2025	 18:47:01 25-Agu-2025	 18:47:26 25-Agu-2025
33	25-08-2025	BASEMENT	PLAFON CLEANING	CEILING	 18:37:13 25-Agu-2025	 18:37:33 25-Agu-2025	 18:37:58 25-Agu-2025
34	25-08-2025	BASEMENT	WALL CLEANING	DINDING CAT PARKIR BASEMENT	 21:16:29 25-Agu-2025	 21:16:54 25-Agu-2025	 21:17:18 25-Agu-2025
35	25-08-2025	BASEMENT	GENERAL CLEANING	DINDING PLANTER BOX	 19:52:05 25-Agu-2025	 19:52:41 25-Agu-2025	 19:53:12 25-Agu-2025
36	25-08-2025	BASEMENT	BRUSHING	DINDING PLANTER BOX	 19:54:15 25-Agu-2025	 19:54:33 25-Agu-2025	 19:54:56 25-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
37	25-08-2025	BASEMENT	WASHING	LANTAI EPOXY			
38	25-08-2025	BASEMENT	POLISHING	TUTUP SAMPIT			
39	25-08-2025	BASEMENT	WASHING	TEMPAT SAMPAH			
40	25-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI			
41	25-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET			
42	25-08-2025	MANAGEMENT OFFICE	GLASS CLEANING	KACA			




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
43	25-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 11:33:05 25-Agu-2025	 11:33:20 25-Agu-2025	 11:33:35 25-Agu-2025
44	25-08-2025	MANAGEMENT OFFICE	BRUSHING	LANTAI	 18:56:49 25-Agu-2025	 18:57:10 25-Agu-2025	 18:57:33 25-Agu-2025
45	25-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TOILET	 11:11:22 25-Agu-2025	 11:11:39 25-Agu-2025	 11:11:53 25-Agu-2025
46	25-08-2025	CARPARK P1-P2	POLISHING	RAILING	 18:53:53 25-Agu-2025	 18:54:10 25-Agu-2025	 18:54:38 25-Agu-2025
47	25-08-2025	CARPARK P1-P2	POLISHING	LANDING ESCALATOR	 11:27:50 25-Agu-2025	 11:28:07 25-Agu-2025	 11:28:25 25-Agu-2025
48	25-08-2025	CARPARK P1-P2	BRUSHING	LANTAI KERAMIK	 18:49:49 25-Agu-2025	 18:51:38 25-Agu-2025	 18:52:06 25-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
49	25-08-2025	CARPARK P1-P2	BRUSHING	DINDING PLANTER BOX	 20:00:40 25-Agu-2025	 19:59:21 25-Agu-2025	 20:01:03 25-Agu-2025



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	27-08-2025	LANTAI 1	BRUSHING	LANTAI CONCRETE	 19:36:06 27-Agu-2025	 19:36:23 27-Agu-2025	 19:36:58 27-Agu-2025
2	27-08-2025	LANTAI 1	POLISHING	KUBIKAL	 19:38:07 27-Agu-2025	 19:38:26 27-Agu-2025	 19:38:56 27-Agu-2025
3	27-08-2025	LANTAI 1	POLISHING	PINTU EXIT	 19:41:24 27-Agu-2025	 19:41:45 27-Agu-2025	 19:42:18 27-Agu-2025
4	27-08-2025	LANTAI 2	GENERAL CLEANING	TEMPAT SAMPAH	 19:43:08 27-Agu-2025	 19:43:28 27-Agu-2025	 19:43:52 27-Agu-2025
5	27-08-2025	LANTAI 2	BRUSHING	LANTAI GRANIT BAKAR	 19:44:33 27-Agu-2025	 19:44:50 27-Agu-2025	 19:45:10 27-Agu-2025
6	27-08-2025	LANTAI 2	POLISHING	CLOSET	 19:46:28 27-Agu-2025	 19:46:49 27-Agu-2025	 19:47:19 27-Agu-2025


No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	27-08-2025	LANTAI 2	POLISHING	CLOSET			
8	27-08-2025	LANTAI 3	POLISHING	CLOSET			
9	27-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH STAINLESS			
10	27-08-2025	LANTAI 3	POLISHING	TRAY			
11	27-08-2025	LANTAI 1	GENERAL CLEANING	PLANTER BOX			
12	27-08-2025	EXTERNAL	POLISHING	SIGN RAMBU JALAN			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	27-08-2025	BASEMENT	POLISHING	LANDING ESCALATOR	 19:55:11 27-Agu-2025	 19:55:33 27-Agu-2025	 19:56:05 27-Agu-2025
14	27-08-2025	BASEMENT	HIGH DUSTING	SIGN GANTUNG	 21:09:40 27-Agu-2025	 21:10:02 27-Agu-2025	 21:10:24 27-Agu-2025
15	27-08-2025	BASEMENT	WALL CLEANING	PILAR BETON	 19:57:27 27-Agu-2025	 19:57:52 27-Agu-2025	 19:58:22 27-Agu-2025
16	27-08-2025	MANAGEMENT OFFICE	GENERAL CLEANING	TEMPAT WUDHU	 20:01:14 27-Agu-2025	 20:01:34 27-Agu-2025	 20:01:57 27-Agu-2025
17	27-08-2025	CARPARK P1-P2	POLISHING	PINTU DAN DOOR CLOSER	 19:59:39 27-Agu-2025	 19:59:58 27-Agu-2025	 20:00:22 27-Agu-2025




No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	28-08-2025	LANTAI 1	BRUSHING	LANTAI KERAMIK			
2	28-08-2025	LANTAI 1	POLISHING	TEMPAT SAMPAH STAINLESS			
3	28-08-2025	LANTAI 1	POLISHING	WASTAFEL			
4	28-08-2025	LANTAI 1	SWEEPING	TANGGA			
5	28-08-2025	LANTAI 2	SPOTTING	SOFA			
6	28-08-2025	LANTAI 2	WALL CLEANING	PINTU LIFT			



No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	28-08-2025	LANTAI 2	BRUSHING	LANTAI CONCRETE			
8	28-08-2025	LANTAI 2	POLISHING	RAK ACCESORIS			
9	28-08-2025	LANTAI 2	GLASS CLEANING	PINTU KACA			
10	28-08-2025	LANTAI 2	GENERAL CLEANING	DRAIN COVER CERAMIC SEMEN FLOOR DRAIN			
11	28-08-2025	LANTAI 3	BRUSHING	LANTAI GRANIT BAKAR			
12	28-08-2025	LANTAI 3	POLISHING	TEMPAT SAMPAH			

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	28-08-2025	LANTAI 3	GLASS CLEANING	KACA RAILING	 11:43:53 28-Agu-2025	 11:44:01 28-Agu-2025	 11:44:14 28-Agu-2025
14	28-08-2025	EXTERNAL	BRUSHING	BOX HYDRANT DAN APAR	 19:19:44 28-Agu-2025	 19:20:01 28-Agu-2025	 19:20:23 28-Agu-2025
15	28-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP NAIK	 19:21:21 28-Agu-2025	 19:21:41 28-Agu-2025	 19:21:59 28-Agu-2025
16	28-08-2025	BASEMENT	PLAFON CLEANING	CEILING	 19:23:16 28-Agu-2025	 19:23:33 28-Agu-2025	 19:23:52 28-Agu-2025
17	28-08-2025	BASEMENT	GLASS CLEANING	SAFETY MIRROR	 19:32:06 28-Agu-2025	 19:32:26 28-Agu-2025	 19:32:39 28-Agu-2025
18	28-08-2025	BASEMENT	HIGH DUSTING	OUTDOOR AC	 19:34:33 28-Agu-2025	 19:34:50 28-Agu-2025	 19:35:08 28-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	28-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	CEILING	 11:37:19 28-Agu-2025	 11:38:18 28-Agu-2025	 11:38:37 28-Agu-2025
20	28-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	COVER LAMP	 19:39:39 28-Agu-2025	 19:39:57 28-Agu-2025	 19:40:13 28-Agu-2025
21	28-08-2025	CARPARK P1-P2	HIGH DUSTING	OUTDOOR AC	 11:26:34 28-Agu-2025	 11:26:48 28-Agu-2025	 11:27:12 28-Agu-2025
22	28-08-2025	CARPARK P1-P2	BRUSHING	LANTAI CONCRETE	 19:26:52 28-Agu-2025	 19:27:11 28-Agu-2025	 19:27:28 28-Agu-2025
23	28-08-2025	CARPARK P1-P2	GENERAL CLEANING	DRAIN COVER METAL COVER CEMENT	 11:24:15 28-Agu-2025	 11:25:23 28-Agu-2025	 11:25:35 28-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
1	29-08-2025	LANTAI 1	POLISHING	PINTU LIFT	 13:38:58 29-Agu-2025	 13:39:22 29-Agu-2025	 13:39:42 29-Agu-2025
2	29-08-2025	LANTAI 1	HIGH DUSTING	CEILING FAN	 13:40:36 29-Agu-2025	 13:40:55 29-Agu-2025	 13:41:14 29-Agu-2025
3	29-08-2025	LANTAI 1	POLISHING	CLOSET	 13:46:28 29-Agu-2025	 13:46:42 29-Agu-2025	 13:46:52 29-Agu-2025
4	29-08-2025	LANTAI 2	POLISHING	TEMPAT SAMPAH	 13:51:16 29-Agu-2025	 13:51:29 29-Agu-2025	 13:51:42 29-Agu-2025
5	29-08-2025	LANTAI 2	HIGH DUSTING	CEILING FAN	 18:39:51 29-Agu-2025	 18:40:28 29-Agu-2025	 18:40:52 29-Agu-2025
6	29-08-2025	LANTAI 3	POLISHING	URINOIR	 13:47:10 29-Agu-2025	 13:47:23 29-Agu-2025	 13:47:41 29-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
7	29-08-2025	LANTAI 3	WALL CLEANING	DINDING ACP	 13:41:52 29-Agu-2025	 13:42:41 29-Agu-2025	 13:42:59 29-Agu-2025
8	29-08-2025	LANTAI 3	WALL CLEANING	PINTU LIFT	 13:44:07 29-Agu-2025	 13:44:24 29-Agu-2025	 13:48:15 29-Agu-2025
9	29-08-2025	LANTAI 3	GENERAL CLEANING	DISWASHING	 18:46:28 29-Agu-2025	 18:46:52 29-Agu-2025	 18:47:12 29-Agu-2025
10	29-08-2025	EXTERNAL	POLISHING	PIPA HYDRANT	 13:48:43 29-Agu-2025	 13:48:53 29-Agu-2025	 13:49:12 29-Agu-2025
11	29-08-2025	EXTERNAL	BRUSHING	LANTAI ANDESIT	 18:41:24 29-Agu-2025	 18:41:45 29-Agu-2025	 18:42:10 29-Agu-2025
12	29-08-2025	EXTERNAL	WALL CLEANING	TEMPAT SAMPAH	 18:42:50 29-Agu-2025	 18:43:07 29-Agu-2025	 18:43:33 29-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
13	29-08-2025	BASEMENT	JET SPRAYING	LANTAI RAMP TURUN	 18:44:52 29-Agu-2025	 18:45:13 29-Agu-2025	 18:45:32 29-Agu-2025
14	29-08-2025	BASEMENT	PLAFON CLEANING	PIPA PLUMBING	 18:48:33 29-Agu-2025	 18:48:58 29-Agu-2025	 18:49:19 29-Agu-2025
15	29-08-2025	BASEMENT	POLISHING	STAINLESS BULAT	 18:50:10 29-Agu-2025	 18:50:30 29-Agu-2025	 18:50:49 29-Agu-2025
16	29-08-2025	MANAGEMENT OFFICE	WALL CLEANING	DINDING	 13:37:18 29-Agu-2025	 13:37:45 29-Agu-2025	 13:38:10 29-Agu-2025
17	29-08-2025	MANAGEMENT OFFICE	PLAFON CLEANING	PIPA PLUMBING	 13:49:44 29-Agu-2025	 13:49:53 29-Agu-2025	 13:50:08 29-Agu-2025
18	29-08-2025	CARPARK P1-P2	POLISHING	BODY STAINLESS ESCALATOR	 13:35:44 29-Agu-2025	 13:36:09 29-Agu-2025	 13:36:29 29-Agu-2025

No	Tanggal	Area	Item Pekerjaan	Detail Pekerjaan	Before	Progress	After
19	29-08-2025	CARPARK P1-P2	POLISHING	BOX HYDRANT			